

23/02/2003

ASS. REC. BY:

REF: CS/FCI 1800378 3/Krd3n2

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

CWS

From (Person):

Sereine Ler

of

FCI

Date/Time:

27/2/18 @ 9:52am

Estimated Cost:

Bill to:

OD-TP-WS+TP RES / OD RES / EVA / INV / MV+CS

To Inspect Vehicle No:

SHD 267G

Insured:

SH 9009A

at Workshop m/s

Trans- Cab

Tel:

G 287 6666

of

No. 2 Ank St. 63

Policy No:

Claim No:

D18001599 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

21/2/18

CA / REV / REP. / REV 24 HRS

lup'

H.O.D. Endorsement:

Date/Time:

1:49pm @ 27/2/18

Person Contacted:

jing how

Vehicle: IN/OUT

Date/Time

Action/Instruction () Estimate

SHD 267G-CC3/CTI16002602/Kvbn2

D.O.A.: 7/2/16

SH 9009A-CC3/CTI16003713/Hlpb3n2

D.O.A.: 10/12/16

sent preli thru email.

ASS. REC. BY:

REF:

FCL /

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

QD / TP / WS / TP RES / QD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.:

Yes or No

Lum Sum:

1.8.1

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SID 287E

Yr Regn:

11, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Perant Lotuda

c.c

1995

Colour

M. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

359669

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VIFIABLISAUC 282311

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: Giti

215/60R16

R: Felken

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

7

mm

L/Bal.

9

mm

L/Bal.

7

mm

D.O.A.

2.12.18

D.O.I.

27/2/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

28/2

Rm pay to Customer

5782.81 5782.81, 3 days

(Red: 31,123.15 ,, 24.)

RECEIVED 15 AUG 2018

Date/Time, File Pass to?



: Prell. Report



: Final Report

1) typist
Date/Time, File Return to?

2)

Report Format:

TP

Lump Sum / I.B.I. (\$) 5821.31

5782.81

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech Invs (\$)



: Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

26x15=390

170+390

50

50

17

677



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18003783/Krd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 27-02-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SH 9009A	Veh. Inspected	SHD 267G
Policy No.		Coverage (\$)	0.00
Claim No.	D1800159MFSH	Excess (\$)	0.00
Assign From	CWS (SERENE LER)	Assign Date	27/02/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	21/02/2018	Inspection Date	27/02/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D1800159MFSH

Our Ref: CS/FCI18003783/Krd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 267G .

Please be informed that we had conducted the inspection of the above mentioned vehicle on 27/02/2018 at the premises of M/s TRANS CAB PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>36,905.96</u> .
Revised Estimate Amount	: S\$ <u>5,821.31</u> .
"Check" Items Amount	: S\$ <u> </u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages
at o/s rear portion.



Yours faithfully
KENNETH
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	23-02-2018	Our Ref No. D18001599MFSH
Accident Date	21-02-2018	Claim Type. Third Party
Insured Vehicle	SH9009A	Third Party Vehicle. SHD267G
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	JIONG HOW NG	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	WITHOUT PREJUDICE: EST. COR - \$36,905.96	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/235298)



PRI Documents



Close X

PRI Header Details

Claim No	D18001599MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & TRANS-C/
Workshop Name	TRANS-CAB AUTO SERVICES PTE LTD (Contact Person : JIONG HOW NG)	Survey Location & Contact Details	NO. 2 ANG MO KIO STREET 63 Mobile: 0 , Phone: 62876666 , Fax: 62571330 EmailId: JIONGHOW.NG@TRASCAB.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: EST. COR - \$36,905.96		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SH9009A	TP Vehicle No	SHD267G
PRI Recieved Date	26-02-2018 08:58:38 PM	Surveyor Appointed Date	27-02-2018 09:51:24 AM	Surveyor Accept Date	

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	27-02-2018	Upload Survey Report *:	Choose File
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Janice Lee (LKKAUTO)

From: Janice Lee (LKKAUTO)
Sent: Thursday, March 08, 2018 5:10 PM
To: 'Claim Workflow System'
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18001599MFSH/1
Attachments: SHD 267G.pdf

Dear Sir/ Madam,

Enclosed preliminary revised for **SHD 267G**

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

Sent: Tuesday, 27 February 2018 9:52 AM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SERENELER@MSFIRSTCAPITAL.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D18001599MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHD267G
Vehicle to be Exported:	Yes
Intended De-registration Date:	26 Feb 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C002921
Chassis No.:	VF1ABL15AUC282311
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	20 Nov 2015
First Registration Date:	20 Nov 2015
Transfer Count:	0
Actual ARF Paid:	\$19,998.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Nov 2023
PARF Rebate Amount:	\$14,998.00
Intended COE Rebate Details	

COE Expiry Date:	19 Nov 2023
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$45,267.00
COE Rebate Amount:	\$32,438.00
Total Rebate Amount:	\$47,436.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 26 Feb 2018

OK

TRANS-CAB AUTO SERVICES PTE LTD

AAD1802-217

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD267G - FCIL

Not Authored
Recovery B4 claim 85782.81

Vehicle No.:

SHD267G - JHOW

Chassis No.:

VF1ABL15AUC282311

Vehicle Make:

RENAULT

Vehicle Model:

LATITUDE

Date of Accident :

21.02.2018

Third Party Insurer :

FCIL

PART**LIST**

1	1	BUMPER COVER REAR	\$	<i>Br/lat</i> 1,108.46 ✓
2	1	BUMPER LOWER REAR	\$	<i>Sn</i> 768.84
3	1	BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47
4	1	BUMEPR BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97
5	1	BUMEPR RETAINER RH REAR	\$	<i>Sn</i> 44.99
6	1	BUMPER REFLECTOR RH	\$	<i>Sn</i> 43.61
7	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97
8	1	BUMEPR RETAINER LH REAR	\$	<i>Sn</i> 44.99
9	1	ROCKER PANEL OUTER RH	\$	<i>N</i> 987.49
10	1	FENDER PANEL REAR RH	\$	<i>N</i> 3,299.13
11	1	FENDER PANEL INNER TRIM REAR	\$	<i>Sn</i> 671.45
12	1	WHEELARCH REAR RH	\$	<i>Sn</i> 543.47
13	1	TAILLAMP RH	\$	<i>Sn</i> 552.55
14	1	TAILLAMP PANEL RH	\$	<i>N</i> 986.70
15	1	EXHAUST REAR	\$	<i>N</i> 7,489.05
16	1	EXHAUST CAP REAR	\$	<i>N</i> 230.49
17	1	DOOR PANEL REAR RH	\$	<i>N</i> 2,844.66 ✓
18	1	DOOR GUIDE REAR RH	\$	<i>Sn</i> 176.82
19	1	DOOR HINGE UPPER RH	\$	<i>N</i> 274.50
20	1	DOOR HINGE LOWER RH	\$	<i>N</i> 300.55
21	1	DOOR CHECK REAR RH	\$	<i>N</i> 203.06
22	1	DOOR LOCK REAR RH	\$	<i>N</i> 908.75
23	1	DOOR GRAB HANDLE REAR RH	\$	<i>Sn</i> 210.96
24	1	DOOR HANDLE OUTER REAR RH	\$	<i>Sn</i> 126.49
25	1	DOOR HANDLE CAP REAR RH	\$	<i>Sn</i> 35.52
26	1	DOOR HANDLE SEAL REAR RH	\$	<i>Sn</i> 7.89
27	1	DOOR HANDLE COVER REAR RH	\$	<i>Sn</i> 13.22
28	1	DOOR HANDLE MODULE REAR RH	\$	<i>Sn</i> 133.60
29	1	DOOR FINISHER REAR RH	\$	<i>Sn</i> 423.10
30	1	DOOR WHEATHESTRIIP REAR RH	\$	<i>Sn</i> 410.66
31	1	DOOR SEAL REAR RH	\$	<i>Sn</i> 162.02
32	1	DOOR WAIST SEAL OUTER REAR RH	\$	<i>Sn</i> 334.69
33	1	DOOR MOULDING REAR RH	\$	<i>Sn</i> 176.82
34	1	DOOR PANEL FRT RH	\$	<i>N</i> 2,844.66 ✓

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD267G - FCIL**AAD1802-217**

TOTAL	\$	26,744.60
10%	\$	2,674.46
	\$	24,070.14

Specical Nett

1	1SET	PARKING AID	\$	Sn	700.00	X
2	1SET	REAR BUMPER CLIP	\$	nn	66.00	—
3	1SET	BUMPER BRACKET CTR CLIP	\$	nn	33.00	—
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	nn	10.00	} X
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	nn	20.00	
6	1SET	BUMPER LOWER REAR RIVET	\$	nn	22.00	
7	1SET	BUMPER LOWER REAR CLIP	\$	nn	66.00	
8	1	EXHAUST MOUNTING REAR	\$	Sn	17.82	
9	1	TAILLAMP CLIP RH	\$	nn	5.00	
10	1SET	WHEELARCH CLIP RR RH	\$	nn	66.00	
11	2	REAR WINDSCREEN SELANT	\$	nn	80.00	} Fohn 231
12	1	WINDSCREEN MOULDING	\$	nn	100.00	
13	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	
14	1	CAP HUB RH RR	\$	Sn	35.00	} ✓
15	1	RIM RH RR	\$	nn	385.00	
16	1	TYRE RH RR	\$	nn	330.00	} X
17	1	DOOR STICKER "Trans-cab"	\$	nn	80.00	
18	1	DOOR STICKER "Classic"	\$	nn	30.00	
19	1	DOOR STICKER "6555-3333"	\$	nn	80.00	60.00

TOTAL	\$	2,225.82
TOTAL PARTS	\$	26,295.96

Putty And Spray Painting Of The Affected Portion.

\$ 4,500.00 6601

To reinstall rear bumper parking sensor.

\$ 170.00 601

To Rust-Proofing Of The Affected Areas.

\$ 170.00 301

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 4,200.00 5001

To transfer of bootlid fittings, attachments and perform water seepage test.

\$ nn 170.00 X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1802-217**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD267G - FCIL

To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00 X
Towing Fees	\$	<i>nn</i> 120.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00 <i>60</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nn</i> 170.00 X
To check steering geometry and computer wheel alignment	\$	220.00 <i>60</i>
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00 <i>60</i>
To transfer of tire, rim and on wheel balancing.	\$	170.00 <i>20</i>

TOTAL	\$	10,610.00
Over All Total	\$	36,905.96

(PARTS BY PARTS)**Repair Days****15 Days***3 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18003783/Krd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 20-08-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 9009A	Veh. Inspected	SHD 267G	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18001599MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	27/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	VF1ABL15AUC282311	Colour	METALLIC WHITE / RED	
Odometer	359669	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	9 mm	
L/H Front Tyre	215/60 R16	GITI	9 mm	
R/H Rear Tyre	215/60 R16	FALKEN	7 mm	
L/H Rear Tyre	215/60 R16	FALKEN	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/02/2018	Inspection Date	27/02/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 267G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER REAR	BUCKLED / CUT	1,108.46	1,108.46
1	BUMPER LOWER REAR	SERVICEABLE	768.84	-
1	BUMPER BRACKET CTR REAR	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	-
1	ROCKER PANEL OUTER RH	TO REPAIR SEE LABOUR	987.49	-
1	FENDER PANEL REAR RH	TO REPAIR SEE LABOUR	3,299.13	-
1	FENDER PANEL INNER TRIM REAR	SERVICEABLE	671.45	-
1	WHEELARCH REAR RH	SERVICEABLE	543.47	-
1	TAILLAMP RH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	-
1	EXHAUST REAR	TO REPAIR SEE LABOUR	7,489.05	-
1	EXHAUST CAP REAR	TO REPAIR SEE LABOUR	230.49	-
1	DOOR PANEL REAR RH	BENT	2,844.66	2,844.66
1	DOOR GUIDE REAR RH	SERVICEABLE	176.82	-
1	DOOR HINGE UPPER RH	TO REPAIR SEE LABOUR	274.50	-
1	DOOR HINGE LOWER RH	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK REAR RH	TO REPAIR SEE LABOUR	203.06	-
1	DOOR LOCK REAR RH	TO REPAIR SEE LABOUR	908.75	-
1	DOOR GRAB HANDLE REAR RH	SERVICEABLE	210.96	-
1	DOOR HANDLE OUTER REAR RH	SERVICEABLE	126.49	-
1	DOOR HANDLE CAP REAR RH	SERVICEABLE	35.52	-

Report Ref No. CS/FCI18003783/Krd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR HANDLE SEAL REAR RH	SERVICEABLE	7.89	-
1	DOOR HANDLE COVER REAR RH	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE REAR RH	SERVICEABLE	133.60	-
1	DOOR FINISHER REAR RH	SERVICEABLE	423.10	-
1	DOOR WEATHERSTRIP REAR RH	SERVICEABLE	410.66	-
1	DOOR SEAL REAR RH	SERVICEABLE	162.02	-
1	DOOR WAIST SEAL OUTER REAR RH	SERVICEABLE	334.69	-
1	DOOR MOULDING REAR RH	SERVICEABLE	176.82	-
1	DOOR PANEL FRT RH	TO REPAIR SEE LABOUR	2,844.66	-
	LESS 10% DISCOUNT		-2,674.46	-395.31
			24,070.14	3,557.81
	SPECIAL NETT ITEMS			
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NOT NECESSARY	66.00	-
1	EXHAUST MOUNTING REAR (SN)	SERVICEABLE	17.82	-
1	TAILLAMP CLIP RH (SN)	NOT NECESSARY	5.00	-
1	SET WHEELARCH CLIP RR RH (SN)	NOT NECESSARY	66.00	-
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	CAP HUB RH RR (SN)	SERVICEABLE	35.00	-
1	RIM RH RR (SN)	DENTED	385.00	385.00
1	TYRE RH RR (70%)(SN)	CUT	330.00	231.00
1	DOOR STICKER "TRANS-CAB" (SN)	NOT NECESSARY	80.00	-
1	DOOR STICKER "CLASSIC" (SN)	NOT NECESSARY	30.00	-
1	DOOR STICKER "6555-3333" (SN)	NECESSARY	80.00	60.00
			2,225.82	775.00

Report Ref No. CS/FCI18003783/Krd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,500.00	660.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF ROCKER PANEL OUTER RH,FENDER PANEL REAR RH,TAILLAMP PANEL RH,EXHAUST REAR,EXHAUST CAP REAR,DOOR HINGE UPPER RH,DOOR HINGE LOWER RH,DOOR CHECK REAR RH,DOOR LOCK REAR RH AND DOOR PANEL FRT RH.		4,200.00	500.00
	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TOWING FEES.	NOT NECESSARY	120.00	-
	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		380.00	60.00
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00
	TO TRANSFER OF DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.		170.00	20.00
			10,610.00	1,450.00
	GRAND TOTAL		36,905.96	5,782.81
	RECOMMENDED COST OF REPAIRS			5,782.81

Report Ref No. CS/FC18003783/Krd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.