



60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

MSIG

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No

SHC4968X

Ref. No

TAX/02/18/2127

Reg. Date

25/04/2011

Vehicle Type

TAXI

Make

CHEVROLET EPICA 2.0 VCDI

Model

EPICA-2.0

Name of Driver

LEE JIMMY(LI JIMMY)

Type of Accident

HEAD TO REAR

Date / Time of Accident

21/02/2018 12:45:00 PM

Accident Reported Date / Time:

21/02/2018 12:00:00 AM

Surveyor is Required?

Survey by

Vehicle is Towed Back?

No

Towed Back Date/Time

No

Replacement Vehicle issued?: Accident Repair Job Card No :

000024094694

.Special Instruction to ARC, if any :

S2415CD

Prepared Date

21/02/2018 03:39:14 PM

- Lung Sun Repair. - Omstien Mark Item Photo - Photo After Paint

LKK Auto Consultants hence notify

the Repairer of the following: • To resurvey before/after spray painting

Care & STINIT

6555 8888

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No:

KL1LA69RJBB028991

Mileage

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

Quotation from ARC

Adjusted by Surveyor, if applicable

Total Labout Charges

338.00

0.00

Total Spray Painting Charges

558.00

0.00

Total Material Charges

1,994.73

2,035.44

Other Charges

716.88

0.00

TOTAL

7 10.00

0.00

Lum Sum Total

3,607.61

0.00

No. of Repair Days

3,600.00

0.00

Prepared / Adjusted By

4.00

5050

Arc / Surveyor Sing Off Date

: 22/02/2018 07:11:22 AM

2 days

01/01/¥900 12:00:00 AM

Prepared / Adjusted Date

Remarks

•

Prepared Date :

22/02/2018 07:11:22 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No

Invoice No

Quotation Date

Invoice Date :

Invoice Amount :

Prepared Date:

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable 0.00 0.00		
TO REPAIR REAR PORTION	338.00			
Total Labour	338.00			

Part 2 - Spray Painting & Panel Beating Related Works

Total Spray Painting & Panel Beating	180.00 558.00	0.00 7		
TO REPSRAY REAR BUMPER TO RESPRAY BUMPER BEAM	378.00	0.00 200		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable		

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	0.00
TO PROVIDE LABOUR & MATERIAL TO REPLACE SHIELD REAR BUMPER (NET)	140.00	0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 38
TO REPLACE SUNDRY PARTS	100.00	0.00 🗴
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	716.88	0.00

TAX/02/18/2127

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price	Discount	Final Price	ARC	Surveyor	Photos
					(\$)	(%)	(\$)	Recommen d	Approved	Attached
93745100	REAR	6504569	BUMPER RR	1	1,238.00	10.00	1,114.20	Replace	Replace K	No
j	REAR		SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace ?	No
I	REAR		BRACKET RR BUMPER SIDE LH	1	49.00	10.00	44.10	Replace	Replace ×	No
96633534	REAR		BRACKET RR BUMPER SIDE RH	1	49.00	10.00	44.10	Replace	Replace ×	No
96873838 (REAR		ABSORBER ENGY RR BUMPER	1	70.00	10.00	63.00	Replace	Replace	No
96941154 F	REAR	6504571	BEAM RR BUMPER IMPACT	1	1,221.00	10.00	1,098.90	Replace	Replace 7	No
TOTAL MATERIALS							2,544.30	2,544.30		
TOTAL MATERIALS(Discounted)							1,994.73	2.035.44		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS							<u> </u>		- Onlook