

REF:

NS/TNC18003813 /SVber

SINZUR

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHB 5105T.

Yr Regn:

19/12/2017.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius 4.

c.c 1798.

Colour

Maroon.

A/C: Insured / Std / NI / NA

Sp. Reading

24197

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTEB 3F4 403570929

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NI / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

19/2/18.

D.O.A.

21/2/18.

Survey held at

SMRT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time / Action / Instruction

SHB 5105T - NS/TNC18003813 /SVber

CA 2034.60

TAX/02/18/2110

2034.60 -

LKK

NTUC

7/3/18 Sebastian confirmed \$ 2034.60 (Red 2843, 5892)

SLC 7621D

Date/Time, File Pass to?

Preli. Report

Days Of Repair:

3

1) Date/Time, File Return to?

Final Report

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

2) 8/3 - typist

Add Fee:

Site Insp (\$

S + RS. SI

Interview (\$

Photos

Tech. Invs (\$

Others

Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$) 2034.60

TOTAL

160

35

195

Survey Department Check List (Case Handler)

Reference No. : **NS/INC18003813/Svb**
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By:

VERON

7/3/18

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/2014



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18003813/Svb				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 27-02-2018	
Code: INC4				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLC 7621D	Veh. Inspected	SHB 5105T	
Policy No.	5080443531-01	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	21/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	19/02/2018	Inspection Date	21/02/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

TP Claims again

S/No	Inc	M	M	M	M	M
1						
2						
3						
4						
5						

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#) [Change Password](#) [Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No. Date of Accident

Vehicle No.(For Motor)

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5080443531-01	ONG POH CHOO	S7112387A	GPC	drivo PREMIUM	SLC7621D	SLC7621D	25/05/2017	24/05/2018

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 5369K

Vehicle Details

Vehicle No.: SHB5105T

Vehicle to be Exported: No

Intended De-registration Date: 22 Feb 2018

Vehicle Make: TOYOTA

Vehicle Model: PRIUS HYBRID 1.8 CVT

Primary Colour: Maroon

Manufacturing Year: 2017

Engine No.: 2ZR8262958

Chassis No.: JTDKB3FU403576929

Maximum Power Output: 90.0 kW (120 bhp)

Open Market Value: \$29,007.00

Original Registration Date: 19 Dec 2017

First Registration Date: 19 Dec 2017

Transfer Count: 0

Actual ARF Paid: \$5,000.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 18 Dec 2025

PARF Rebate Amount: \$3,750.00

Intended COE Rebate Details

COE Expiry Date: 18 Dec 2025

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 8

PQP Paid: \$34,159.00

COE Rebate Amount: \$33,393.00

Total Rebate Amount: \$37,143.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 22 Feb 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/02/2018 14:35
Date Of Accident	19/02/2018 14:50
Exact Location Of Accident	YISHUN AVE 2 TOWARDS YISHUN MRT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB5105T
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-800000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-17087562MFSH
Cover Note Number	

Driver

Name of Driver	CHIEW FOOK KEE @ ALVIN CHIEW
NRIC No	S0230904A
Date Of Birth	28/05/1954
Occupation	OUTDOOR
Date Of Driving Pass	20/07/1979
Driving Experience	38 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	274 BANGKIT ROAD 06-58
Postcode	670274
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	
	NAME: : UNKNOWN
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS STATIONARY ALONG YISHUN AVE 2 TOWARDS YISHUN MRT WITH ONE PASSENGER(MALE CHINESE) ON BOARD AS IT WAS THE RED TRAFFIC LIGHT. WHEN THE TRAFFIC TURNED GREEN AND I WAS WAITING FOR THE FRONT VEHICLE TO MOVE. SUDDENLY I FELT AN IMPACT AT THE REAR OF MY TAXI. A VEHICLE SLC7621D HAD COLLIDED ONTO THE REAR RIGHT PORTION OF MY TAXI.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO LARGE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLC7621D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ONG POH CHOO
NRIC/Passport Number	S7112387A
Contact Number	84982766
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Yishun Ave 2 towards Yishun MRT

A- SHB5105T


B - SLC7621D

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

[illegible]

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature _____

Date & Time:

Driver's Signature

(if driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SMRT Accident Vehicle Repair Estimates

NTUC

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5105T
Ref. No : TAX/02/18/2110
Reg. Date : 19/12/2017
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS4
Name of Driver : CHIEW FOOK KEE @ ALVIN CHIEW
Type of Accident : HEAD TO REAR
Date / Time of Accident : 19/02/2018 02:50:00 PM
Accident Reported Date / Time : 20/02/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by :
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024094662
Special Instruction to ARC, if any :
SLC7621D
Prepared Date : 20/02/2018 12:49:04 PM



Sebastian
21/2/18

- Part by part repair

- Question Mark Item

Photo

- Photo Before Paint

[Handwritten signature]
20/2/18

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Chassis No : JTDKB3FU403576929

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 676.00	0.00
Total Spray Painting Charges	: 918.00	0.00
Total Material Charges	: 2,335.02	2,335.02
Other Charges	: 280.00	0.00
TOTAL	: 4,209.02	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 5.00	0.00
Prepared / Adjusted By	:	3 days
Arc / Surveyor Sign Off Date	: 21/02/2018 11:17:00 AM	01/01/1900 12:00:00 AM

M

Prepared / Adjusted Date :

Remarks :

Prepared Date : 21/02/2018 11:17:00 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount : 0.00	Prepared Date : 2/21/2018 11:20:52 AM

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH REAR PORTION	676.00	0.00 400
Total Labour	676.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY FILLER RR BUMPER RH	180.00 ?	0.00
TO RESPRAY BUMPER BEAM	180.00 ?	0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0.00 100
Total Spray Painting & Panel Beating	918.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 30
TO WASH AND VACUUM	60.00	0.00 X
TO REPLACE SUNDRY PARTS	100.00	0.00 X
Total Other Costs	280.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
5215947913			COVER, RR BUMPER ASSY	1	423.90	25.00	317.92	Replace	Replace	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No
5246247030			PAD, RR BUMPER, RH & LH, 1	2	3.80	25.00	5.70	Replace	Replace	No
5246247020			PAD, RR BUMPER, RH & LH, 2	2	3.80	25.00	5.70	Replace	Replace	No
5246247010			PAD, RR BUMPER, RH & LH, 3	2	3.80	25.00	5.70	Replace	Replace	No
5219147030			SEAL, RR BUMPER ARM, RH & LH	2	11.00	25.00	16.50	Replace	Replace	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No
5256547900			FILLER, RR BUMPER, RH	1	119.90	25.00	89.92	Replace	Replace	No
5202347030			REAR BUMPER REINFORCEMENT	1	318.80	25.00	239.10	Replace	Replace	No
5259147050			SEAL, RR BUMPER, RH	1	85.20	25.00	63.90	Replace	Replace	No
5245347010			GUARD, RR BUMPER, LOWER	1	558.30	25.00	418.72	Replace	Replace	No
5216947020			COVER, GUARD RR BUMPER LOWER	1	14.80	25.00	11.10	Replace	Replace	No
7680147110A1			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	25.00	668.40	Replace	Replace	No
			STICKER SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No
7544147030			NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace	No
7544247130			NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace	No
25754700			RETAINER, RR BUMPER, RH	1	112.70	25.00	84.52	Replace	Replace	No
TOTAL MATERIALS								2,335.05	2,335.02	
TOTAL MATERIALS(Discounted)							2,335.02	2,335.02		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									




24-2-18 / 11:45

24-2-18 / 15:45

21-2-18 / 15:45

SMRT Accident Vehicle Repair Estimates**Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre**

Reg. No : SHB5105T
 Ref. No : TAX/02/18/2110
 Reg. Date : 19/12/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : CHIEW FOOK KEE @ ALVIN CHIEW
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 19/02/2018 02:50:00 PM
 Accident Reported Date / Time : 20/02/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : Sebastian
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024094662
 Special Instruction to ARC if any :
 SLC7621D NTAL P/P
 BEFORE PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR SEBASTIAN (LKK)
 & Email : sebastianyeang@lkkauto.com HP: 90036121
 Prepared Date : 20/02/2018 12:49:04 PM



Recording Camera



Radio Antenna


1st witness

Date

21-2-18

2nd witness

Date



QC 24/2/18 9.03 Reject, 10:41 Pass de Radar to the Supplementary part 1st ✓

RR Bumper Reinforcement

Vehicle Return Date: 23/02/2018

Vehicle Return Time: 16:43

SMRT staff sign:

Chassis No : JTDKB3FU403576929

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, If applicable
Total Labour Charges	: 676.00	400.00
Total Spray Painting Charges	: 918.00	300.00
Total Material Charges	: 1,602.73	1,304.60
Other Charges	: 280.00	30.00
TOTAL	: 3,476.73 4877.60	2,034.60
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 5.00	3.00 /
Prepared / Adjusted By	:	SEBASTIAN (LKK)
Arc / Surveyor Sign Off Date	: 21/02/2018 11:17:00 AM	21/02/2018 03:45:50 PM

M

LKK

Prepared / Adjusted Date :

Remarks :

Prepared Date : 21/02/2018 11:17:00 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No	: QN-1802-0659	Invoice No	:
Quotation Date	: 26/2	Invoice Date	:
Invoice Amount	: 0.00	Prepared Date	: 2/21/2018 11:20:52 AM

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH REAR PORTION	676.00	400.00 /
Total Labour	676.00	400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	200.00 /
TO RESPRAY FILLER RR BUMPER RH	180.00	0.00
TO RESPRAY BUMPER BEAM	180.00	0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	100.00 /
Total Spray Painting & Panel Beating	918.00	300.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TEST AND REFIX REVERSE SENSOR	120.00	30.00 /
TO WASH AND VACUUM	60.00	0.00
TO REPLACE SUNDRY PARTS	100.00	0.00
Total Other Costs	280.00	30.00

4877.60

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
21594793			COVER, RR BUMPER ASSY	1	423.90	25.00	317.93	Replace	Replace	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No
246247010			PAD, RR BUMPER, RH & LH, 1	2	3.80	25.00	5.70	Replace	Check	No
246247010			PAD, RR BUMPER, RH & LH, 2	2	3.80	25.00	5.70	Replace	Check	No
24624700			PAD, RR BUMPER, RH & LH, 3	2	3.80	25.00	5.70	Replace	Check	No
219147010			SEAL, RR BUMPER ARM, RH & LH	2	11.00	25.00	16.50	Replace	Check	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Check	No
256547910			FILLER, RR BUMPER, RH	1	119.90	25.00	89.93	Replace	Replace	No
202347010			REAR BUMPER REINFORCEMENT	1	318.80	25.00	239.10	Replace	Replace	No
259147010			SEAL, RR BUMPER, RH	1	85.20	100.00	0.00	Replace	Repair	No
24534700			GUARD, RR BUMPER, LOWER	1	558.30	25.00	418.72	Replace	Replace	No
216947010			COVER, GUARD RR BUMPER LOWER	1	14.80	25.00	11.10	Replace	Replace	No
68014710A1			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	100.00	0.00	Replace	Repair	No
			STICKER SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No
544147010			NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace	No
544247110			NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace	No
257547010			RETAINER, RR BUMPER, RH	1	112.70	25.00	84.53	Replace	Check	No
TOTAL MATERIALS							1,602.75	1,304.60		
TOTAL MATERIALS(Discounted)							1,602.73	1,304.60		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

1304.60 /
+ 400.00 /
+ 330.00 /

2034.60 /

Sebastian
7/3/18

Veron Chen (LKKAuto)

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <YeoPohsuan@smrt.com.sg>
Sent: Wednesday, 7 March 2018 1:34 PM
To: Sebastian Yeang (LKK Auto)
Cc: SUR; CS A Team
Subject: RE: SHB5105T

Hi

Amount confirmed as per your recommendation, thanks.

Regards
Poh Suan

-----Original Message-----

From: Sebastian Yeang (LKK Auto) [mailto:SebastianYeang@lkkauto.com]
Sent: Wednesday, 7 March 2018 9:45 AM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Cc: SUR; CS A Team
Subject: RE: SHB5105T

Dear Poh Suan

Please refer to attachment for the finalization.

Thank You

Best Regards,
Sebastian | Automotive Assessor
LKK Auto Consultants
phone: 6256-3561 email: sebastianyeang@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Saturday, 3 March 2018 11:03 AM
To: Sebastian Yeang (LKK Auto)
Cc: SUR; CS A Team
Subject: SHB5105T

Hi Sebastian,

Attached herewith the repair estimate of SHB 5105T having Case No: TAX/02/18/2110.

There is no change to the approved amount of \$2,034.60 @ 3 working days under part by part repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)

Sent: Saturday, 3 March 2018 10:44 AM

To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)

Subject: Scan Data from FX-D421D6


**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

Thatcham *escribe*

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18003813/Svbe2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 13-03-2018	
Code: INC4				
1. Policy Particulars - THIRD PARTY CLAIM				
Insured Veh.	SLC 7621D	Veh. Inspected	SHB 5105T	
Policy No.	5080443531-01	Coverage (\$)	0.00	
Claim No.	MT/0982825-003	Excess (\$)	0.00	
Assign From		Assign Date	21/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FU403576929	Colour	MAROON	
Odometer	24197	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	YOKOHAMA	6 mm	
L/H Front Tyre	195/65 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/02/2018	Inspection Date	21/02/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 5105T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	COVER, RR BUMPER ASSY (DISC 25%)	TORN	423.90	317.92
1	FILLER, RR BUMPER, RH (DISC 25%)	CRACKED	119.90	89.92
1	REAR BUMPER REINFORCEMENT (DISC 25%)	DENTED	318.80	239.10
1	GUARD, RR BUMPER, LOWER (DISC 25%)	DEFORMED	558.30	418.72
1	COVER, GUARD RR BUMPER LOWER (DISC 25%)	BENT	14.80	11.10
1	NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR (DISC 25%)	NECESSARY	52.30	39.22
1	NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR (DISC 25%)	NECESSARY	52.30	39.22
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	STICKER SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
2	PAD, RR BUMPER, RH & LH, 1 @\$3.80	NOT NECESSARY	7.60	-
2	PAD, RR BUMPER, RH & LH, 2 @\$3.80	NOT NECESSARY	7.60	-
2	PAD, RR BUMPER, RH & LH, 3 @\$3.80	NOT NECESSARY	7.60	-
2	SEAL, RR BUMPER ARM, RH & LH @\$11.00	NOT NECESSARY	22.00	-
1	SENSOR REVERSE	NOT NECESSARY	180.00	-
1	RETAINER, RR BUMPER, RH	NOT NECESSARY	112.70	-
1	SEAL, RR BUMPER RH	TO REPAIR	85.20	-
1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	TO REPAIR	891.20	-
			3,003.60	1,304.60
LABOUR				
THATCHAM STANDARD REPAIR TIME ON BODY WORKS.			796.00	430.00
THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.			918.00	300.00
TO REPLACE SUNDRY PARTS.			100.00	-
TO WASH AND VACUUM.			60.00	-
			1,874.00	730.00
GRAND TOTAL			4,877.60	2,034.60

RECOMMENDED COST OF REPAIRS (CONFIRMED)			2,034.60
--	--	--	-----------------

Report Ref No. NS/INC18003813/Svbe2



Report Ref No. NS/INC18003813/Svbe2

YEANG WAI KEEN

Automotive Assessor

K.K.LAU CPT(RET)

**BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE**

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.