

REF:

NS/INC18003815 / Srbnz

SINCE

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SG 8978XPolicy No. 5084324724-01 260917Claims No. MT/0982845-002

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHF 746 Yr Regn: 3/11/17Type: M.Car / M.Cycle / Bus / Van / Lorry / ☒ Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toyota Prius 4 C.C. 1798Colour Maroon A/C: Insured / Std / NI / NASp. Reading 47844 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKB 3F4 103575745Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NA / S/Rim / STD A/Rim orTyre Size: F: 175/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 15/2/18 D.O.I. 20/2/18Survey held at SMR

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction

SHF 746 - CS / 16022014 09h30m2 OCA: 301116 TA x/02/18 / 2107SG 8978X - X UIC NINEConfirm \$1221.85, 4 daysRed: \$5127.89, 81% SG 8978X

RECEIVED 03 MAR 2018

Date/Time, File Pass to? ☐ : Preli. Report1) typist ☒ : Final Report

Date/Time, File Return to?

2) _____

Report Format :

Lump Sum / I.B.I: (\$) TP 1221.85Days Of Repair: 4Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others

TOTAL

160

35

195




National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



| | | | |
|----------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|------------------|-------------------------------------------------------------------------------------|
| NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18003815/Srb | | | |
| 73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556 | | Date: 27-02-2018 |  |
| Code: INC4 | | | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | |
| Insured Veh. | SJG 8978X | Veh. Inspected | SHF 74K |
| Policy No. | 5084324724-01 | Coverage (\$) | 0.00 |
| Claim No. | | Excess (\$) | 0.00 |
| Assign From | | Assign Date | 20/02/2018 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | | c.c | 0 |
| Engine No. | HIDDEN | Year of Reg. | |
| Chassis No. | | Colour | |
| Odometer | - | Steering | |
| Brakes | | Modification | |
| General | | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | | | mm |
| L/H Front Tyre | | | mm |
| R/H Rear Tyre | | | mm |
| L/H Rear Tyre | | | mm |
| 4. Description of Damages | | | |
| | | | |
| 5. General Information | | | |
| Accident Date | 15/02/2018 | Inspection Date | 20/02/2018 |
| Survey held at | SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705 | | |
| 5a. Remarks | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |

eBaoTech

General Claim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

| | | | | | | | | | |
|-----------------------------------------|---------------------------------------|-------------------|-----------------------------------------------|---------|-------------|-------------|----------------|---------------|-------------|
| Policy No. | <input type="text"/> | Date of Accident | <input type="text" value="15/02/2018 17:21"/> | | | | | | |
| Vehicle No. (For Motor) | <input type="text" value="SJG8978X"/> | | | | | | | | |
| <input type="button" value="Search"/> | | | | | | | | | |
| Select | Policy No. | Policyholder Name | Policyholder NRIC | Product | Cover Type | Vehicle No. | Insured Object | Commence Date | Expiry Date |
| <input checked="" type="radio"/> | 5084324724-01 | EFFICIENT | 53345722W | GFT | Third Party | SJG8978X | SJG8978X | 26/09/2017 | |
| <input type="button" value="Continue"/> | | | | | | | | | |

TP Claims against NTUC Income: Follow-Through Survey

Date: 07/03/2018

| S/No | Income Reference | Claimant (Owner / Taxi Company) | Claimant Vehicle No. | Income Vehicle No. | Date of Accident | Time of Accident | Estimate | Tentative repair cost |
|------|------------------|---------------------------------|----------------------|--------------------|------------------|------------------|-------------|-----------------------|
| 1 | MT/0982884-002 | SMRT AUTOMOTIVE | SHB 1554G | GBF 8697G | 17/02/2018 | 9:40 | \$ 2,962.68 | \$ 1,050.00 |
| 2 | MT/0982845-002 | SMRT AUTOMOTIVE | SHF 74K | SJG 8978X | 15/02/2018 | 23:40 | \$ 6,339.74 | \$ 1,221.85 |
| 3 | MT/0985155-001 | SMRT AUTOMOTIVE | SMB 1414T | SGZ 5400B | 06/11/2017 | 23:52 | \$ 1,758.00 | \$ 700.00 |
| 4 | MT/0901189-001 | SMRT AUTOMOTIVE | SMB 237U | SGZ 2829T | 15/05/2017 | 19:00 | \$ 976.00 | \$ 589.00 |
| 5 | MT/0982495-002 | SMRT AUTOMOTIVE | SHD 6304T | SGJ 8622S | 08/02/2018 | 16:40 | \$ 2,121.00 | \$ 350.00 |
| 6 | MT/0981868-002 | SMRT AUTOMOTIVE | SHD 6454T | SKG 4629T | 09/02/2018 | 14:30 | \$ 2,968.00 | \$ 1,700.00 |
| 7 | MT/0985159-001 | COMFORT | SH 8764J | FH9765D | 24/02/2018 | 7:30 | \$ 6,563.72 | \$ 2,800.00 |

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|----------------------------------|
| Date Of Report | 19/02/2018 15:56 |
| Date Of Accident | 15/02/2018 23:40 |
| Exact Location Of Accident | KEPPEL ROAD & TANJONG PAGAR ROAD |
| Country/State of Loss | MALAYSIA/WILAYAH PERSEKUTUAN |

DETAILS OF OWN VEHICLE

| | |
|------------------------------------------------------------------------------|--------------------------------|
| Vehicle Registration Number | SHF74K |
| Insured/Policyholder | |
| Name Of Registered Owner | SMRT TAXIT PTE LTD |
| Co Reg No | 198905369K |
| Email Address | NOEMAIL |
| Mobile Phone No | |
| Alternative Phone No | OFFICE-80000000 |
| Vehicle Particulars | |
| Manufacturer | TOYOTA |
| Model | PRIUS TAXI-1.8 (A) |
| Exact Purpose for which vehicle was being used at time of accident | HIRE AND REWARD |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | REPORTING ONLY |
| Vehicle Category | TAXI |
| Insurance Company | |
| Name of Insurance Company | MS FIRST CAPITAL INSURANCE LTD |
| Type Of Coverage | THIRD PARTY FIRE AND/OR THEFT |
| Fleet Policy | YES |
| Policy Number | D-17087562MFSH |
| Cover Note Number | |
| Driver | |
| Name of Driver | ANG THIAM TENG |
| NRIC No | S1448572D |
| Date Of Birth | 23/12/1960 |
| Occupation | OUTDOOR |
| Date Of Driving Pass | 02/11/1982 |
| Driving Experience | 35 YEARS AND 3 MONTHS |
| Gender | MALE |
| Mobile Number | |
| Fax Number | |
| Contact Number | |
| Email Address | NOEMAIL |

Address 160A PUNGGOL CENTRAL
07-103

Postcode 821160

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - HIRER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident SIDE SWIPE

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

I WAS TRAVELLING STRAIGHT ALONG KEPPEL ROAD ON THE FIRST LANE. AS I DROVE AHEAD ALMOST PASSED THROUGH THE YELLOW BOX SUDDENLY A PTE CAR ON MY LEFT COMING FROM TANJONG PAGAR ROAD COLLIDED ON TO THE LEFT REAR PORTION OF MY TAXI.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJG8978X

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver TAY KOK HAI

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

15/02/2018


23. 40 hrs.

Keppel Rd

Tim Kok Hal

$$\leq 1156894$$

~~534 8978*~~

[illegible]

DECLARATION

DECLARATION
I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature: _____
Date & Time: _____

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 5369K

Vehicle Details

Vehicle No.: SHF74K

Vehicle to be Exported: No

Intended De-registration Date: 21 Feb 2018

Vehicle Make: TOYOTA

Vehicle Model: PRIUS HYBRID 1.8 CVT

Primary Colour: Maroon

Manufacturing Year: 2017

Engine No.: 2ZRS102297

Chassis No.: JTDKB3FU103573745

Maximum Power Output: 90.0 kW (120 bhp)

Open Market Value: \$29,007.00

Original Registration Date: 03 Nov 2017

First Registration Date: 03 Nov 2017

Transfer Count: 0

Actual ARF Paid: \$5,000.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 02 Nov 2025

PARF/COE Rebate Enquiry

| | |
|-----------------------------|--------------------------------------|
| PARF Rebate Amount: | \$3,750.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 02 Nov 2025 |
| COE Category: | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years): | 8 |
| PQP Paid: | \$33,596.00 |
| COE Rebate Amount: | \$32,332.00 |
| Total Rebate Amount: | \$36,082.00 |

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 21 Feb 2018

OK



SMRT Automotive Service Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Attached
Supplementary
Guan

28-2-18 / 10:47
+1 day
23-2-18 / 14:47

SMRT Accident Vehicle Repair Estimates

20-2-18 / 14:47

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHF74K
Ref. No : TAX/02/18/2107
Reg. Date : 03/11/2017
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS4
Name of Driver : ANG THIAM TENG
Type of Accident : HEAD TO SIDE
Date / Time of Accident : 15/02/2018 11:40:00 PM
Accident Reported Date / Time : 19/02/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by : Sebastian
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024094656
Special Instruction to ARC, if any :
SJG8978X Nmc - P/P
BEFORE PAINT PHOTO FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR SEBASTIAN (LKK)
& Email : sebastianyeang@lkkauto.com HP:90036121
Prepared Date : 20/02/2018 09:01:38 AM



E (1) 1/2 F
KM 47843

Recording Camera ☒ ☐

Radio Antenna ☒ ☐

1st witness [Signature] Date 20-2-18

2nd witness _____ Date _____

Vehicle sent to Vega Data In: 21/2/18 Towing: _____
Time In: _____ Driver: Guan
Vega Job No: 02/0134
Vehicle sent to SMRT Data In: 23/2/18 Towing: _____
Time In: 1100 Driver: [Signature]
Received by (SMRT): [Signature]

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU103573745

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

| | Quotation from ARC | Adjusted by Surveyor, if applicable |
|------------------------------|--------------------------|-------------------------------------|
| Total Labour Charges | : 845.00 | 0.00 |
| Total Spray Painting Charges | : 738.00 | 0.00 |
| Total Material Charges | : 2,820.72 | 2,820.72 |
| Other Charges | : 700.00 | 0.00 |
| TOTAL | : 5,103.72 | 0.00 |
| Lum Sum Total | : 0.00 | 0.00 |
| No. of Repair Days | : 5.00 | 0.00 3 days |
| Prepared / Adjusted By | : | |
| Arc / Surveyor Sign Off Date | : 20/02/2018 09:13:47 AM | 01/01/1900 12:00:00 AM |



Prepared / Adjusted Date :

Remarks :

Prepared Date : 20/02/2018 09:13:47 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates**Part 1 - Labour Works**

| Job Scope | Quotation from ARC | Adjusted by Surveyor, if applicable |
|---------------------------|--------------------|-------------------------------------|
| TO REPAIR LH REAR PORTION | 845.00 | 0.00 400 |
| Total Labour | 845.00 | 0.00 |

Part 2 - Spray Painting & Panel Beating Related Works

| Job Scope | Quotation from ARC | Adjusted by Surveyor, if applicable |
|-------------------------------------------------|--------------------|-------------------------------------|
| TO RESPRAY REAR FENDER LH | 378.00 | 0.00 200 |
| TO RESPRAY FILLER RR BUMPER LH | 180.00 ? | 0.00 |
| TO RESPRAY RIM | 180.00 | 0.00 50 |
| Total Spray Painting & Panel Beating | 738.00 | 0.00 |

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

| Job Scope | Quotation from ARC | Adjusted by Surveyor, if applicable |
|-------------------------------------------------|--------------------|-------------------------------------|
| TO CHECK WIRING AND SYSTEM FUNCTION | 80.00 | 0.00 X |
| TO APPLY RUST-PROOFING ON AFFECTED AREA | 100.00 | 0.00 30 |
| TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE) | 120.00 | 0.00 30 |
| TO REMOVE AND REFIT TYRE | 120.00 | 0.00 X |
| TO REPLACE SUNDRY PARTS | 100.00 | 0.00 X |
| TO WASH AND VACUUM | 60.00 | 0.00 X |
| TO DO WHEEL ALIGNMENT / TYRE BALANCING | 120.00 | 0.00 60 |
| Total Other Costs | 700.00 | 0.00 |

Part 4 - Spare Parts / Material Usage

| Part Number | Portion | Stock No | Part Name | Qty | List Price (\$) | Discount (%) | Final Price (\$) | ARC Recommendation | Surveyor Approved | Photos Attached |
|------------------------------------|---------|----------|--------------------------------|-----|-----------------|--------------|------------------|--------------------|-------------------|-----------------|
| 6160247160 | | | PANEL SUB-ASSY, FENDER REAR LH | 1 | 824.80 | 25.00 | 618.60 | Replace | Replace R | No |
| 6563847060 | | | LINER, REAR FENDER, LH | 1 | 135.80 | 25.00 | 101.85 | Replace | Replace ? | No |
| 5215947913 | | | COVER, RR BUMPER ASSY | 1 | 423.90 | 25.00 | 317.92 | Replace | Replace R | No |
| 5257647040 | | | RETAINER, RR BUMPER, LH | 1 | 111.50 | 25.00 | 83.62 | Replace | Replace ? | No |
| 5259247040 | | | SEAL, RR BUMPER, LH | 1 | 85.20 | 25.00 | 63.90 | Replace | Replace ? | No |
| 5256647900 | | | FILLER, RR BUMPER, LH | 1 | 119.90 | 25.00 | 89.92 | Replace | Replace ? | No |
| 4261147450 | | | WHEEL, DISC | 1 | 1,555.10 | 25.00 | 1,166.32 | Replace | Replace R | No |
| 4260247180 | | | CAP SUB-ASSY, WHEEL | 1 | 175.80 | 25.00 | 131.85 | Replace | Replace ✓ CRK | No |
| | | | TYRE | 1 | 126.74 | 0.00 | 126.74 | Replace | Replace X | No |
| | | | PIXEL STICKER | 2 | 60.00 | 0.00 | 120.00 | Replace | Replace ✓ MFC | No |
| TOTAL MATERIALS | | | | | | | 2,820.74 | 2,820.72 | | |
| TOTAL MATERIALS(Discounted) | | | | | | | 2,820.72 | 2,820.72 | | |

Added Spare Parts / Material Usage After Surveyor Signed off

| Part Number | Portion | Part Name | Qty | List Price (\$) | Discount (%) | Final Price (\$) | ARC Check | Surveyor Check | LT Check |
|--------------------------------------|---------|-----------|-----|-----------------|--------------|------------------|-----------|----------------|----------|
| TOTAL SUPPLEMENTARY MATERIALS | | | | | | | | | |

SMRT Accident Vehicle Repair Estimates

NTUC

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHF74K
 Ref. No : TAX/02/18/2107
 Reg. Date : 03/11/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : ANG THIAM TENG
 Type of Accident : HEAD TO SIDE
 Date / Time of Accident : 15/02/2018 11:40:00 PM
 Accident Reported Date / Time : 19/02/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024094656
 Special Instruction to ARC, if any :
 SJG8978X
 Prepared Date : 20/02/2018 09:01:38 AM


Sebastian
20/2/18

- Part by part repair
- Question Mark Item
- Photo
- Photo Before Paint


20/2/18

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU103573745

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

| | Quotation from ARC | Adjusted by Surveyor, if applicable |
|------------------------------|---------------------------|-------------------------------------|
| Total Labour Charges | : 845.00 | 400.00 |
| Total Spray Painting Charges | : 1,116.00 3678.74 | 450.00 |
| Total Material Charges | : 591.15 | 251.85 |
| Other Charges | : 700.00 | 120.00 |
| TOTAL | : 3,252.15 6339.74 | 1,221.85 |
| Lum Sum Total | : 0.00 | 0.00 |
| No. of Repair Days | : 5.00 | 4.00 |
| Prepared / Adjusted By | : | SEBASTIAN (LKK) |
| Arc / Surveyor Sing Off Date | : 20/02/2018 09:13:47 AM | 20/02/2018 02:47:17 PM |



Prepared / Adjusted Date :

Remarks :

Prepared Date : 20/02/2018 09:13:47 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : GN-1802-0399

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 2/20/2018 2:47:14 PM

Section D - Details of Repair Estimates

Part 1 - Labour Works

| Job Scope | Quotation from ARC | Adjusted by Surveyor, if applicable |
|---------------------------|--------------------|-------------------------------------|
| TO REPAIR LH REAR PORTION | 845.00 | 400.00 / |
| Total Labour | 845.00 | 400.00 |

Part 2 - Spray Painting & Panel Beating Related Works

| Job Scope | Quotation from ARC | Adjusted by Surveyor, if applicable |
|-------------------------------------------------|--------------------|-------------------------------------|
| TO RESPRAY REAR FENDER LH | 378.00 | 200.00 / |
| TO RESPRAY FILLER RR BUMPER LH | 180.00 | 0.00 |
| TO RESPRAY RIM | 180.00 | 50.00 / |
| TO REPSRAY REAR BUMPER | 378.00 | 200.00 S. / |
| Total Spray Painting & Panel Beating | 1,116.00 | 450.00 |

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

| Job Scope | Quotation from ARC | Adjusted by Surveyor, if applicable |
|-------------------------------------------------|--------------------|-------------------------------------|
| TO CHECK WIRING AND SYSTEM FUNCTION | 80.00 | 0.00 |
| TO APPLY RUST-PROOFING ON AFFECTED AREA | 100.00 | 30.00 / |
| TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE) | 120.00 | 30.00 / |
| TO REMOVE AND REFIT TYRE | 120.00 | 0.00 |
| TO REPLACE SUNDRY PARTS | 100.00 | 0.00 |
| TO WASH AND VACUUM | 60.00 | 0.00 |
| TO DO WHEEL ALIGNMENT / TYRE BALANCING | 120.00 | 60.00 / |
| Total Other Costs | 700.00 | 120.00 |

Part 4 - Spare Parts / Material Usage

| Part Number | Portion | Stock No | Part Name | Qty | List Price (\$) | Discount (%) | Final Price (\$) | ARC Recommendation | Surveyor Approved | Photos Attached |
|-----------------------------|---------|----------|--------------------------------|-----|-----------------|--------------|------------------|--------------------|-------------------|-----------------|
| 6160247160 | | | PANEL SUB-ASSY, FENDER REAR LH | R 1 | 824.80 | 100.00 | 0.00 | Replace | Repair | No R |
| 6563847060 | | | LINER, REAR FENDER, LH | X 1 | 135.80 | 25.00 | 101.85 | Replace | Check | No X |
| 5215947913 | | | COVER, RR BUMPER ASSY | R 1 | 423.90 | 100.00 | 0.00 | Replace | Repair | No R |
| 5257647040 | | | RETAINER, RR BUMPER, LH | X 1 | 111.50 | 25.00 | 83.63 | Replace | Check | No X |
| 5259247040 | | | SEAL, RR BUMPER, LH | X 1 | 85.20 | 25.00 | 63.90 | Replace | Check | No X |
| 5256647900 | | | FILLER, RR BUMPER, LH | X 1 | 119.90 | 25.00 | 89.93 | Replace | Check | No X |
| 4261147450 | | | WHEEL, DISC | R 1 | 1,555.10 | 100.00 | 0.00 | Replace | Repair | No R |
| 4260247180 | | | CAP SUB-ASSY, WHEEL | ✓ | 175.80 | 25.00 | 131.85 | Replace | Replace | No ✓ |
| | | | TYRE | X 0 | 126.74 | 0.00 | 0.00 | Replace | Not given | No X |
| | | | PIXEL STICKER | ✓ 2 | 60.00 | 0.00 | 120.00 | Replace | Replace | No ✓ |
| TOTAL MATERIALS | | | | | | | | 591.15 | 251.85 | |
| TOTAL MATERIALS(Discounted) | | | | | | | | 591.15 | 251.85 | |

Added Spare Parts / Material Usage After Surveyor Signed off

| Part Number | Portion | Part Name | Qty | List Price (\$) | Discount (%) | Final Price (\$) | ARC Check | Surveyor Check | LT Check |
|-------------------------------|---------|-----------|-----|-----------------|--------------|------------------|-----------|----------------|----------|
| TOTAL SUPPLEMENTARY MATERIALS | | | | | | | | | |

751.85
 400
 + 570

 1221.85

Sebastian
 28/2/18

6339.74



Thatcham escribe


National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



| | | | |
|-------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|------------|
| NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18003815/Srbn2 | | | |
| 73 BRAS BASAH ROAD | | Date: 12-03-2018 | |
| #05-01 NTUC TRADE UNION HOUSESINGAPORE | | Code: INC4 | |
| 189556 | |  | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | |
| Insured Veh. | SJG 8978X | Veh. Inspected | SHF 74K |
| Policy No. | 5084324724-01 | Coverage (\$) | 0.00 |
| Claim No. | MT/0982845-002 | Excess (\$) | 0.00 |
| Assign From | | Assign Date | 20/02/2018 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | TOYOTA PRIUS | c.c | 1798 |
| Engine No. | HIDDEN | Year of Reg. | 2017 |
| Chassis No. | JTDKB3FU103573745 | Colour | MAROON |
| Odometer | 47844 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | NIL |
| General | FAIR | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | 195/65 R15 | YOKOHAMA | 6 mm |
| L/H Front Tyre | 195/65 R15 | YOKOHAMA | 6 mm |
| R/H Rear Tyre | 195/65 R15 | YOKOHAMA | 6 mm |
| L/H Rear Tyre | 195/65 R15 | YOKOHAMA | 6 mm |
| 4. Description of Damages | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. | | | |
| DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | |
| Accident Date | 15/02/2018 | Inspection Date | 20/02/2018 |
| Survey held at | SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705 | | |
| 5a. Remarks | | | |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | 4 Working Days | |



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 74K

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------------------|-------------------------------------------------------|---------------|---------------------------|-------------------|
| REPLACEMENT OF PARTS | | | | |
| 1 | CAP SUB-ASSY,WHEEL (DISC 25%) | CRACKED | 175.80 | 131.85 |
| 2 | PIXEL STICKER @\$60.00 (SN) | NECESSARY | 120.00 | 120.00 |
| 1 | LINER,REAR FENDER,LH | NOT NECESSARY | 135.80 | - |
| 1 | RETAINER,RR BUMPER,LH | NOT NECESSARY | 111.50 | - |
| 1 | SEAL,RR BUMPER,LH | NOT NECESSARY | 85.20 | - |
| 1 | FILLER RR BUMPER,LH | NOT NECESSARY | 119.90 | - |
| 1 | TYRE | NOT NECESSARY | 126.74 | - |
| 1 | PANEL SUB-ASSY,FENDER REAR LH | TO REPAIR | 824.80 | - |
| 1 | COVER,RR BUMPER ASSY | TO REPAIR | 423.90 | - |
| 1 | WHEEL,DISC | TO REPAIR | 1,555.10 | - |
| | | | 3,678.74 | 251.85 |
| LABOUR | | | | |
| | THATCHAM STANDARD REPAIR TIME ON BODY WORKS. | | 1,285.00 | 490.00 |
| | THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR. | | 1,216.00 | 480.00 |
| | TO REPLACE SUNDRY PARTS. | NOT NECESSARY | 100.00 | - |
| | TO WASH AND VACUUM. | NOT NECESSARY | 60.00 | - |
| | | | 2,661.00 | 970.00 |
| GRAND TOTAL | | | 6,339.74 | 1,221.85 |
| RECOMMENDED COST OF REPAIRS (CONFIRMED) | | | | 1,221.85 |

Report Ref No. NS/INC18003815/Srbn2

YEANG WAI KEEN
Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.