NS/INC18003820 /Shbn2

	SIGNMENT
From Date:	Neh No. SH B 1554 G Pagn: 6/8/4
Estimated Dost	Type: M.Car / M.Cycle / Bus / Van / Lorry / Cox / Prime Mover /
DD ITP / WS/ITP RES / CD RES / EVA / INV / MV	Truck / Traffer of
To inspect Vehicle No.	Make Toupty Prins as 1798
as Workshop m/s	Colour YV Negar A/C: Insured / Std / NI / NA
4	Sp.Reading 460330 T/Radio: Insured / Std / NI / NA
GBF 8697 G	Eng/No:
5074863750-02 15-10-17	ONO. JTOKN 364 865747456
Claims No. MT/0982884-002	Gen. Cond: Good / Por / Burnt
Sum insured: Excess:	Steering: In 6rder / Jammed / Leaked / Burnt or
(Stient's Record)	Brake: Inforder / Jammed / Leaked / Burnt or
Make of Verti	Modi: NP S/Rim / STD A/Rim or
	Tyre Stze: F: /95/65/615
(Policy Condition)	R:
Remark: The veh had commonced its N/S O/S repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the distribution.	TOYOTYOKO or Jallan
Bis. or Market Value:	Fron! Rear
DAC Acoldent Roort: Consisient? : Yes or No	R/Bal 6 mm R/Bal 6 mm
GIA / PR Seen: Consistent7 : Yes or No Est. Repairs: days Res.: Yes or No	L/Bal. 6 mm L/Bal. 6 mm
	D.O.A. 16/2/18. DOL 30/2/18.
	Survey held at SWIRT
GA / REV / REP. / 24 HRS Vehicle: IN/OUT	Des of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Diale: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date/Time Action/Instruction SHB 1854 G - NS/TNC16021180/Kig	
Confirm LIS \$1050, 3 days Bed: \$1912.68,65%	
	GB1=86979
Due Time, Fle Pass lot : Proli. Report	Days Of Repair: 3
Date/Time File Return to?	Resurvey No. of Trip: - Survey Fee: 160
Add Fee:	Site Insp (\$)_s+RSSI
Band I Former: TP	Interview (S) Photos
Lump Sum / LB.I: (S 1050	Tech Invs (3) Uses (Weskend (S)
cump same _ are 1030	1 IGN



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





NTU	ITUC INCOME INSURANCE CO-OPERATIVE LTD		Ref:	NS/INC1800382	8003820/Srb	
		D UNION HOUSESINGAPORE	Date:	27-02-2018 INC4		
1.		Policy Particulars	:- THIR	0.000,000		
****	Insured Veh.	GBF 8697G		nspected	SHB 1554G	
	Policy No.	5074863750-02	Cover	age (\$)	0.00	
-	Claim No.		Exces	s (\$)	0.00	
	Assign From		Assign Date 20/02/2018		20/02/2018	
2.		Vehicle Parti	culars &	& Condition		
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year o	of Reg.		
	Chassis No.		Colou	r		
	Odometer	at a second	Steeri	ng		
	Brakes		Modif	ication		
	General					
3.		Condit	ions of	Tyres		
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.		Descripti	on of D	amages		
5.		Genera	al Inforn	nation		
J.	Accident Date	17/02/2018	F29-0-0000000000000000000000000000000000	ction Date	20/02/2018	
	Survey held at	SMRT AUTOMOTIVE SERVICE		20/11/21		
		60 WOODLANDS INDUSTRIAL	PARK E	4 SINGAPORE 757	7705	
5a.		F	Remarks			
	A)THE INSPECTION	ON WAS CONDUCTED ON A"WI	THOUT F	PREJUDICE" BASIS NOT AUTHORISE	S. ED REPAIRS.	

eBao Tech									Gene	ralClaim
Hello, NAC_PAYA_UBI_80	0601						Change La	nguage	Change Passwor	d · Log Out
My Desktop	Policy	Query								,
Notice of Loss	Policy No.					Date of Acc	ident	17/02	/2018 17:21	
	Vehicle No	(For Motor)	G8F8697G							
						Search				
	Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
	6 507	74863750-02	PAN PACIFIC VAN & TRUCK LEASING PTE LTD	201511635R	GFT	Comprehensive	GBF8697G	GBF8697G	15/10/2017	
					1	Continue				

TP Claims against NTUC Income: Follow-Through Survey

Date: 07/03/2018

	The second secon			transmit Walisha Ma	Date of Accident	Time of Accident	Estimate	Tentative repair cost
ı	- Dafamana	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	income venicle No.	Date of Accident			000000
S/No Inco	income Reference	Claumant Council Counc	CUD 155AG	GRE 8697G	17/02/2018	9:40	\$ 2,962.68	5 1,050.00
MT/0	MAT/0987884-002	SMRT AUTOMOTIVE	SHEET BUS	0		0.01	AT 0553 3	c 1 221 85
2		District Control of State of	CHE 7AK	SIG 8978X	15/02/2018	73:40	5 0,333,14	-
MT/0	MT/0982845-002	SMRI AUTOMOTIVE	21.5		The fact that	03.00	0 1758 00	200.00
-		SWITCHAUTIN TOARS	SMB 1414T	SGZ 5400B	06/11/201/	72:27	DO:00:14	
MT/0	AT/0985155-001	SMIKE AUTOMOTIVE			1.00/10/11	10.00	00 926 00	\$ 589.00
-		SVITORACTUR TORAC	SMR 237U	SGZ 28291	15/05/501/	13.00	201010	
MT/0	MT/0901189-001	SMRI AUTOMOTIVE			Carlos faces	46.40	\$ 2121.00	350.00
-		District and a second	CHI KRMT	56186225	08/07/2018	10:40	CONTRACTOR CO	
MT/0	AT/0982495-002	SMKI AUTOMOTIVE	TOO OH			00.44	00 990 0	1 700 00
2		DUITOR ACTUAL TON AN	CHD 6454T	SKG 4629T	09/02/2018	14:30	2,300.00	-
MT/0	MT/0981868-002	SMRI AUTOMOTIVE	200000		or the fact of	00.7	6 656373	2.800.00
		TOCAMOO	SH 8764J	FH976SD	24/02/2018	7:30	2 1.coc.0 ¢	-
N N	MT/0985159-001	COMPON						

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

ACCIDENT STATEMENT

Date Of Report

19/02/2018 17:45

Date Of Accident

16/02/2018 09:40

Exact Location Of Accident

COMMONWEALTH AVE WEST TOWARDS CLEMENTI RD

SINGAPORE Country/State of Loss

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SHB1554G

Insured/Policyholder

Name Of Registered Owner

SMRT TAXIS PTE LTD

Co Reg No

198905369K

Email Address

NOEMAIL

Mobile Phone No

Alternative Phone No

OFFICE-80000000

Vehicle Particulars

Manufacturer

TOYOTA

Model

PRIUS TAXI-1.8 (A)

Exact Purpose for which vehicle was being used at

time of accident

HIRE AND REWARD

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

TAXI

Insurance Company

Name of Insurance Company

MS FIRST CAPITAL INSURANCE LTD THIRD PARTY FIRE AND/OR THEFT

Type Of Coverage Fleet Policy

YES

Policy Number

D-17087562MFSH

Cover Note Number

Name of Driver

LEU KOK CHONG

NRIC No

S6835887F

04/08/1968

Date Of Birth

OUTDOOR

Occupation

Date Of Driving Pass

17/06/1987

Driving Experience

30 YEARS AND 7 MONTHS

Gender

MALE

Mobile Number

Fax Number

Contact Number

EMail Address

NOEMAIL

Page 1 of 10

Address

347 CLEMENTI AVE 5

02-66

Postcode

120347

Was driver an employee of the Insured's Company NO

If No Relationship of the Driver with the Insured OTHER -?

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

*

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident

SIDE SWIPE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

NO

soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

AS I WAS MAKING A RIGHT TURN FROM COMMONWEALTH AVE WEST TO CLEMENTI ROAD TOWARDS CLEMENTI AVE 2/5. A SBS8158C HAVE HIT ON MY LEFT PASSENGER DOOR. THE IMPACT HAS CAUSED SOME SCRATCHES AND DENTS ON THE LEFT SIDE PASSENGER DOOR. AT THE PONT OF TIME THE TRAFFIC LIGHT WAS IN GREEN ARROW AND IT WAS IN MY FAVOUR TO MAKE A TURN TOWARDS CLEMENTI AVE 2/5 TO MY BEST OF KNOWLEDGE. THE LATTER(SBS8158C BUS) WAS BEHIND ANOTHER SBS BUS (UNKNOWN NUMBER) WHEN THE FRONT SBS BUS MAKE A LEFT TURN INTO CLEMENTI AVE 2/5. THE LATTER (SBS8158C) ACCELERATED AND HIT ONTO MY VEHICLE. AS MY INSTINCT RESPONDED, I STOPPED MY VEHICLE IMMEDIATELY AND IT WAS THEN THE SBS8158C BUS HAS TRIED TO STOPP TOO AND BUMP INTO MY VEHICLE.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SBS8158C

Vehicle Make/Model/Colour

Details Of Properties

BUS

Vehicle Category Name of Driver

LIU SHUGANG

NRIC/Passport Number

G8528544R

Contact Number

Address

Postcode

Insurance Company Name

Page 2 of 10

Nature Of Damage No. Of Passenger (Including Driver)

		Chemond's Rol Towards	
Commonwealth at the Powereds. Devices and.	NC WEST.	Clement: Rd SHEISF469 TowardS Ave 2/5	 Chement Ave - Chement M - Chement M - Chement M - Chement M - Chement M - Chement M

Date & Time:

NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN



IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- 5. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

5369K

Vehicle Details

Vehicle No.:

SHB1554G

Vehicle to be Exported:

No

Intended De-registration Date:

21 Feb 2018

Vehicle Make:

TOYOTA

Vehicle Model:

PRIUS TAXI (SMRT)

Primary Colour:

Maroon

Manufacturing Year:

2014

Engine No.:

2ZR6105180

Chassis No.:

JTDKN36U505747456

Maximum Power Output:

100.0 kW (134 bhp)

Open Market Value:

\$32,920.00

Original Registration Date:

06 Aug 2014

First Registration Date:

06 Aug 2014

Transfer Count:

0

Actual ARF Paid:

\$8,088.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

05 Aug 2022

PARF Rebate Amount:

\$6,066.00

Intended COE Rebate Details

COE Expiry Date:

05 Aug 2022

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

8

PQP Paid:

\$50,088.00

COE Rebate Amount:

\$27,905.00

Total Rebate Amount:

\$33,971.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be deregistered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 21 Feb 2018

OK



60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

Nuc

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No

SHB1554G

Ref. No

TAX/02/18/2104

Reg. Date

06/08/2014

Vehicle Type

TAXI

Make

TOYOTA PRIUS

Model

PRIUS

Name of Driver

LEU KOK CHONG

Type of Accident

SIDE SWIPE

Date / Time of Accident

16/02/2018 09:40:00 AM

Accident Reported Date / Time :

19/02/2018 12:00:00 AM

Surveyor is Required?

Yes

Survey by

Vehicle is Towed Back?

No

Towed Back Date/Time

Replacement Vehicle issued? :

Accident Repair Job Card No :

000024094647

Special Instruction to ARC, if any :

GBF8697G/CASE II

Prepared Date

20/02/2018 08:29:54 AM

Osman @ Santa 6555 8888

- Photo After Point

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U505747456 Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

Quotation from ARC

Adjusted by Surveyor, if applicable

Total Labout Charges

507.00

0.00

Total Spray Painting Charges

558.00

0.00

Total Material Charges

764.86

780.47

Other Charges

756.88

TOTAL

0.00

Lum Sum Total

2,586.74

0.00

No. of Repair Days

2,600.00

0.00

4.00

0.00

Prepared / Adjusted By

3 4-75

Arc / Surveyor Sing Off Date

20/02/2018 08:36:01 AM

01/01/1900 12:00:00 AM

Prepared / Adjusted Date

Remarks

Prepared Date : 20/02/2018 08:36:01 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No

Invoice No

Quotation Date

Invoice Date :

Invoice Amount

Prepared Date:

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	507.00	0.00, 300
Total Labour	507.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY BUMPER BEAM	180.00	2 0.00 %
Total Spray Painting & Panel Beating	558.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable	
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 ×	
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 ×	
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 30	
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	0.00 ~ 296.88 nec	
TO REPLACE SUNDRY PARTS	100.00	0.00 ×	
TO WASH AND VACUUM	60.00	0.00 ×	
Total Other Costs	756.88	0.00	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommen d	Surveyor Approved	Photos Attached
52159- 47905	1	6505548	BUMPER REAR	:1	458.60	25.00	343.95	Replace	Replace (w+	No
90467- 07211			BUMPER CLIPS	1	2.10	25.00	1.57	Replace	Replace NE	No
52023- 12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.27	Replace	Replace	No
52015- 47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Replace 7	NON
52575- 47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace 7	No
			SENSOR REVERSE	- 1	180.00	0.00	180.00	Replace	Replace ?	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No
		-1	TOTAL MATERIALS	•				975.60	975.59	
		TOTAL	MATERIALS(Discou	nted)				764.86	780.47	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
	TOTA	L SUPPLEMENTARY	MATERIA	ALS			100		

3013.68



SMRT Automotive Service Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

23-2-18/10:55 (ADV

FAX Number : 63685592


stimator Telephone Number : 68662623

22-2-18 / 14:55

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

14:55 20-2-1d



Recording Camera	
Radio Antenna	
1 st witness	Date 30-2-18
2 nd witness	Date

	20/2/18
	Time la: 1500 Driver: 141
Tohialo se	nt to SAMIT Date in 29/24 Tuveling:
Rugeivo	o by (CTTT):

Chassis No: JTDKN36U505747456

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

Quotation from ARC

Adjusted by Surveyor, if applicable

Total Labout Charges

507.00

300.00

Total Spray Painting Charges

558.00

200.00

Total Material Charges

297.94 140 8

465.52

Other Charges

756.88

84.48

TOTAL

2,119.82 7962.68

Lum Sum Total

1,050.00

No. of Repair Days

0.00

0.00

4.00

3.00

Prepared / Adjusted By

SEBASTIAN (LKK)

Arc / Surveyor Sing Off Date

20/02/2018 08:36:01 AM

20/02/2018 02:55:05 PM

Prepared / Adjusted Date

Remarks

Prepared Date : 20/02/2018 08:36:01 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No

: UN-1802-0592

Invoice No

Quotation Date : 23 2

Invoice Date :

Invoice Amount : 0.00

Prepared Date:

2/20/2018 2:55:02 PM

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable			
TO REPAIR REAR PORTION	507.00	300.00			
Total Labour	507.00	300.00			

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	200.00
TO RESPRAY BUMPER BEAM	180.00	0.00
Total Spray Painting & Panel Beating	558.00	200.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable		
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00		
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00		
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30.00		
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	296.88 /		
TO REPLACE SUNDRY PARTS	100.00	0.00		
TO WASH AND VACUUM	60.00	0.00		
Lump Sum Adjustment by Surveyor	0.00	-242.40		
Total Other Costs	756.88	84.48		

Page:

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommen d	Surveyor Approved	Photos Attached
52159- 47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace	No/
90467- 07211			BUMPER CLIPS	1	2.10	25.00	1.57	Replace	Replace	No/
52023- 12240		6505547	BUMPER REINFORCEMENT REAR	0	205.70	25.00	0.00	Replace	Not given	No X
52015- 47050			ARM SUB-ASSY, RR BUMPER RH	0	139.60	25.00	0.00	Replace	Not given	No X
52575- 47020		6505549	BUMPER SIDE RETAINER RR/RH	0	94.80	25.00	0.00	Replace	Not given	No X
			SENSOR REVERSE	0	180.00	0.00	0.00	Replace	Not given	No X
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No/
TOTAL MATERIALS 465.53								465,53	465.52	
TOTAL MATERIALS(Discounted)								297.94	465.52	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor	LT Check
	TOTA	AL SUPPLEMENTARY	MATERIA	ALS					

+ 300:00 + 300:00 + 526.88 + 526.88 - 207 - 207 - 207 - 207 - 33.92 / - 1050 - /



Thatcham escribe

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18003820/Srbn2 73 BRAS BASAH ROAD 12-03-2018 #05-01 NTUC TRADE UNION HOUSESINGAPORE Code: INC4 Policy Particulars :- THIRD PARTY CLAIM 1. **GBF 8697G** Veh. Inspected SHB 1554G Insured Veh. 0.00 Policy No. 5074863750-02 Coverage (\$) 0.00 MT/0982884-002 Excess (\$) Claim No. 20/02/2018 Assign Date Assign From Vehicle Particulars & Condition 2. 1798 TOYOTA PRIUS Make & Model 2014 HIDDEN Year of Reg. Engine No. MAROON JTDKN36U505747456 Colour Chassis No. Steering Odometer 460330 IN ORDER NIL IN ORDER Modification Brakes FAIR General **Conditions of Tyres** 3. Make **Balance** Size 195/65 R15 **FALKEN** 6 mm R/H Front Tyre 195/65 R15 **FALKEN** 6 mm L/H Front Tyre FALKEN 6 mm R/H Rear Tyre 195/65 R15 195/65 R15 **FALKEN** 6 mm L/H Rear Tyre **Description of Damages** 4. THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS. General Information 5. 20/02/2018 Accident Date Inspection Date 16/02/2018 SMRT AUTOMOTIVE SERVICES PTE LTD Survey held at 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705 Remarks 5a. A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. **Estimate Days of Repair** 5b.

ESTIMATED NORMAL PERIOD FOR REPAIR:

3 Working Days



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 1554G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER REAR (DISC 25%)	CUT	458.60	343.95
1	BUMPER CLIPS (DISC 25%)	NECESSARY	2.10	1.57
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	ADVERTISEMENT STICKER (SN)	NECESSARY	296.88	296.88
1	BUMPER REINFORCEMENT REAR	NOT NECESSARY	205.70	3-
1	ARM SUB-ASSY,RR BUMPER RH	NOT NECESSARY	139.60	-
- 1	BUMPER SIDE RETAINER RR/RH	NOT NECESSARY	94.80	
1	SENSOR REVERSE	NOT NECESSARY	180.00	
			1,497.68	762.40
	LABOUR			
	THATCHAM STANDARD REPAIR TIME ON BODY WORKS.		707.00	330.00
	THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.		658.00	200.00
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			1,525.00	530.00
	GRAND TOTAL		3,022.68	1,292.40
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,050.00

Report Ref No. NS/INC18003820/Srbn2

YEANG WAI KEEN

Automotive Assessor

(CONFIRMED)

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part, Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.