

REF: NS/INIC 1800 3821 / Suber

ASSIGNMENT

2014

From: \_\_\_\_\_ Date: \_\_\_\_\_

Veh No: SHC 4698 A Yr Regn: 25/4/1014

Estimated Cost: \_\_\_\_\_

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To inspect Vehicle No: \_\_\_\_\_

Make: Toyota Prius c.c. 1798

at Workshop m/s \_\_\_\_\_

Colour: Maroon A/C: Insured / Std / NI / NA

of \_\_\_\_\_

Sp. Reading: No Display T/Radio: Insured / Std / NI / NA

Insured: YP 62078

Eng/No: \_\_\_\_\_

Policy No. 5090750114 010817 - 030518

C/No: JTDK1W3660575 088

Claims No. MT/0985203-002

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or


Make of Veh: \_\_\_\_\_

Mod: NI / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size: F: 195/65R15

Remark: The veh had commenced its repair at the time of inspection.



R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Felton

Bal. or Market Value: \_\_\_\_\_

Front

Rear

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

R/Bal. 6 mm

R/Bal. 6 mm

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

L/Bal. 6 mm

L/Bal. 6 mm

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

D.O.A. 21/2/18

D.O.I. 22/2/18

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

Survey held at SMART

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
19/3/18	SHC 4698 A - 203 / TMT 11 23795 (Rin)
19/3/18	YP 62078 - NS/INIC 1800 3821 Sub
	REF: 120711
	REF: 21018
	TAX/02/18/2118
	LKK
	NTR

19/3/18 LS \$ 4450 confirmed by email (Ref 14,96564, 778)

RECEIVED

YP 62078

Date/Time, File Pass to? : Preli. Report

Days Of Repair: 7

1) : Final Report

Resurvey No. of Trip: 1

Survey Fee: 160

Date/Time, File Return to?

Transportation:

2) 20/3 - typist

Add Fee: : Site Insp (\$ ) S+RS. SI

: Interview (\$ ) Phone

: Tech. Invs (\$ ) Opans

: Weekend (\$ )

Report Format: TP  
Lump Sum / I.B.I. (\$) 4450/2

TOTAL 195

## Survey Department Check List (Case Handler)

Reference No. : NS/INC/18003821/Svb  
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin ( ):** Case handler to make sure all information created by the assignment team are ACCURATE.

(1) Office Assign Form		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

**Surveyor ( ):** Case handler to make sure the surveyor completed all required information.

(1) Assignment Form		Y-Date	N-Date	Y-Date	N-Date
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

**(2) System - (Views/Merimen)**

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

**(3) Workshop Estimate/Assignment Form**

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

**(4) System - (Views/Merimen)**

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 20/3/18  
 Case Handler Date



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18003821/Svb	
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556	Date: 27-02-2018
Code: INC4	



### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YP 6207B	Veh. Inspected	SHC 4698A
Policy No.	5090750114	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	22/02/2018

### 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

### 4. Description of Damages

--	--

### 5. General Information

Accident Date	21/02/2018	Inspection Date	22/02/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

**TP Claims against NTUC Income: Follow-Through Survey**

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Estimate	Tentative repair cost
1	MT/0982899-002	COMFORT TRANSPORTATION PTE LTD	SHC 8242E	SJM 629A	14/02/2018	\$ 5,313.12	\$ 2,550.00
2	MT/0986777-001	COMFORT TRANSPORTATION PTE LTD	SHD 6526U	SJJ9670K	14/02/2018	\$ 1,585.04	\$ 280.00
3	MT/0980219-003	SMRT TAXIS PTE LTD	SHB 5294E	SHC 6991P	30/01/2018	\$ 3,231.20	\$ 1,720.89
4	MT/0974759-002	SMRT BUSES PTE LTD	SMB 3550U	SGL 8186Z	21/12/2017	\$ 4,021.13	\$ 2,550.00
5	MT/0986780-001	SMRT BUSES PTE LTD	SMB 88H	FW 1364B	10/01/2018	\$ 8,830.84	\$ 2,750.00
6	MT/0985203-002	SMRT TAXIS PTE LTD	SHC 4698A	YP 6207B	21/02/2018	\$ 19,415.64	\$ 4,450.00

Claim received from LKK Auto

Hello, NAC\_PAYA\_UBI\_800601

Change Language Change Password Log Out

My Desktop  
Notice of Loss

Policy Query

Policy No.  Date of Accident

Vehicle No.(For Motor)

Search

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5090750114	RAFFLES RELOCATION AND MOBILITY PTE LTD	201523806H	GCV	Comprehensive	YP6207B	YP6207B	04/05/2017	03/05/2018

Continue

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 5369K

### Vehicle Details

Vehicle No.: SHC4698A

Vehicle to be Exported: No

Intended De-registration Date: 23 Feb 2018

Vehicle Make: TOYOTA

Vehicle Model: PRIUS TAXI (SMRT)

Primary Colour: Maroon

Manufacturing Year: 2014

Engine No.: 2ZR6177416

Chassis No.: JTDKN36U005751088

Maximum Power Output: 100.0 kW (134 bhp)

Open Market Value: \$32,920.00

Original Registration Date: 24 Sep 2014

First Registration Date: 24 Sep 2014

Transfer Count: 0

Actual ARF Paid: \$8,088.00

### Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 23 Sep 2022

PARF Rebate Amount:	\$6,066.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	23 Sep 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,704.00
COE Rebate Amount:	\$29,049.00
<b>Total Rebate Amount:</b>	<b>\$35,115.00</b>

#### Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 23 Feb 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	21/02/2018 09:32
Date Of Accident	21/02/2018 06:45
Exact Location Of Accident	LORNIE ROAD TOWARDS BISHAN
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC4698A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

### Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-17087562MFSH
Cover Note Number	

### Driver

Name of Driver	TAN KOON HIAN
NRIC No	S1723233I
Date Of Birth	28/08/1965
Occupation	OUTDOOR
Date Of Driving Pass	05/12/1990
Driving Experience	27 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
E Mail Address	NOEMAIL

Address BLK 671 WOODLANDS DR 71  
06-49

Postcode 730671

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - HIRER

Vehicle Registration Number of Driver's Own Vehicle -  
-  
-

Insurance Company of Driver's Own Vehicle -  
-  
-

#### General Information of the Accident

Type Of Accident SIDE SWIPE

Weather Conditions CLEAR

Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Passenger 1 NAME: : UNKNOWN  
GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

#### Circumstances of Accident

I WAS TRAVELLING ON THE EXTREME RIGHT LANE ALONG LORNIE ROAD TOWARDS BISHAN WITH ONE PASSENGER (FEMALE CHINESE) ON BOARD. SUDDENLY A LORRY YP6207B WHICH WAS TRAVELLING ON MY LEFT CUT TOWARDS MY LANE ABRUPTLY AND COLLIDED ONTO THE LEFT PORTION OF MY TAXI. THIRD PARTY MENTIONED THAT THE ROAD IS TOO NARROW WHICH RESULTED IN THE COLLISION.

#### Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YP6207B

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category GOODS VEHICLE

Name of Driver EZWANN BIN TOMIN

NRIC/Passport Number S8211524B

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)



Sketch Plan Pg. 2

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


  
 Policyholder's Signature
   
 Date & Time:


  
 Driver's Signature
   
 (If driver is not the policyholder)
   
 Date & Time: 2/2/2018
   
 O.R.T.H.R.


  
 Reporting Centre Personnel's Signature
   
 Name:
   
 NRIC/FIN No.:


Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo




# SMRT Accident Vehicle Repair Estimates

NTUC

## Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4698A  
 Ref. No : TAX/02/18/2118  
 Reg. Date : 01/01/1900 24/9/14  
 Vehicle Type : TAXI  
 Make : TOYOTA PRIUS  
 Model : PRIUS  
 Name of Driver : TAN KOON HIAN  
 Type of Accident : SIDE SWIPE  
 Date / Time of Accident : 21/02/2018 06:45:00 AM  
 Accident Reported Date / Time : 21/02/2018 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by :  
 Vehicle is Towed Back? : Yes  
 Towed Back Date/Time : 21/02/2018  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No : 000024094671  
 Special Instruction to ARC,if any :  
 TOWED \$40/YP6207B  
 Prepared Date : 21/02/2018 10:16:30 AM



Sebastian  
22/2/18

- Lump Sum Repair
- Question Mark Item Photo
- Photo After Paint

*[Signature]*  
28/2/18

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Chassis No : Mileage : 0

Work Shop : Repair Completed Date / Time :

**Summary of Repair Estimates**

	<b>Quotation from ARC</b>	<b>Adjusted by Surveyor, if applicable</b>
Total Labour Charges :	1,690.00	0.00
Total Spray Painting Charges :	3,348.00	0.00
Total Material Charges :	7,771.66	7,771.66
Other Charges :	1,730.00	0.00
<b>TOTAL :</b>	<b>14,539.66</b>	<b>0.00</b>
<b>Lum Sum Total :</b>	<b>14,550.00</b>	<b>0.00</b>
No. of Repair Days :	10.00	<del>0.00</del>
Prepared / Adjusted By :		7 days
Arc / Surveyor Sing Off Date :	21/02/2018 02:09:22 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 21/02/2018 02:09:22 PM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	1,690.00	<del>0.00</del> 800
<b>Total Labour</b>	<b>1,690.00</b>	<b>0.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	<del>0.00</del> 200
TO RESPRAY FRONT FENDER LH	378.00	<del>0.00</del> 200
TO RESPRAY APRON PANEL LH	180.00	0.00
TO RESPRAY RIM	360.00	<del>0.00</del> 50
TO RESPRAY FRONT PILLAR LH	180.00	0.00
TO RESPRAY FRONT DOOR LH	378.00	<del>0.00</del> 200
TO RESPRAY ROCKER PANEL MOULDING	180.00	<del>0.00</del> 100
TO RESPRAY REAR DOOR LH	378.00	<del>0.00</del> 200
TO RESPRAY REAR FENDER LH	378.00	<del>0.00</del> 200
TO REPSRAY REAR BUMPER	378.00	0.00 X
TO RESPRAY VIEW MIRROR	180.00	<del>0.00</del> 50
<b>Total Spray Painting &amp; Panel Beating</b>	<b>3,348.00</b>	<b>0.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	80.00	0.00 X
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	<del>0.00</del> 30
TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	<del>0.00</del> 40
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	240.00	<del>0.00</del> 30
TO REMOVE AND REFIT TYRE	120.00	0.00 X
TO REMOVE & REFIX FRONT LHS/RHS QUATER GLASS	120.00	<del>0.00</del> 50
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	250.00	0.00 ✓
TO TRANSFER DOOR MECHANISM	240.00	<del>0.00</del> 120
TO REMOVE & REFIT REAR QUARTER GLASS LH	120.00	0.00 X
TO REPLACE SUNDRY PARTS	100.00	<del>0.00</del> 20
TO WASH AND VACUUM	60.00	0.00 X
TO REMOVE AND REFIX WING MIRROR	120.00	<del>0.00</del> 30
<b>Total Other Costs</b>	<b>1,730.00</b>	<b>0.00</b>

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
52119-47930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace R	No
90467-07211			BUMPER CLIPS	1	2.10	25.00	1.57	Replace	Replace ✓ NEC	No
53802-47050		6505558	FENDER FRT/LH	1	723.40	25.00	542.55	Replace	Replace ✓ PUN	No
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace ✓ NEC	No
53876-47030		6505554	FENDER LINER FRT/LH	1	171.70	25.00	128.77	Replace	Replace X	No
53852-47020			FENDER LINER PAD, FR WHEEL. LH	1	49.30	25.00	36.97	Replace	Replace X	No
53702-47050			FENDER APRON SUB FRT/LH	1	637.80	25.00	478.35	Replace	Replace ?	No
42611--47140 (Frt)		6505658	WHEEL DISC. FRONT	1	1,484.20	25.00	1,113.15	Replace	Replace R	No
		6503707	TYRE	1	126.74	0.00	126.74	Replace	Replace X	No
62120-47021			QUARTER GLASS FRT/LH	1	234.90	25.00	176.17	Replace	Replace ✓ NEC	No
	COMMON		SEALANT W/SCREEN	1	37.00	0.00	37.00	Replace	Replace ✓ NEC	No
67002-47070		6505529	DOOR FRT/LH	1	894.40	25.00	670.80	Replace	Replace ✓ Deform	No
61132-47030			PILLAR, FR BODY, LH	1	363.10	25.00	272.32	Replace	Replace ?	No
68740-12120			HINGE LOWER LHF, DOOR	1	90.10	25.00	67.57	Replace	Replace ✓ BT	No
68720-15151			HINGE UPPER LHF, DOOR	1	80.50	25.00	60.37	Replace	Replace ✓ BT	No
68610-47021			CHECK ASSY, FR DOOR,	1	150.30	25.00	112.72	Replace	Replace ?	No
75720-47021			DOOR BELT FRT/LH	1	69.20	25.00	51.90	Replace	Replace ✓ NEC	No
69802-52070			DOOR REGULATOR SUB-ASSY, FRT/REAR LH	1	224.80	25.00	168.60	Replace	Replace ?	No
69210-74030			DOOR OUTER HANDLE FRT/LH	1	370.80	25.00	278.10	Replace	Replace R	No
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace ✓ NEC	No
75852-47900			MOULDING BODY, LH	1	673.60	25.00	505.20	Replace	Replace R	No
57004-47080		6505487	DOOR RR/LH	1	954.50	25.00	715.87	Replace	Replace R	No
			PIXEL STICKER	1	60.00	0.00	60.00	Replace	Replace ✓	No
58760-20122			HINGE UPPER LHR, DOOR	1	81.70	25.00	61.27	Replace	Replace X	No
58780-52031			HINGE LOWER LHR, DOOR	1	72.20	25.00	54.15	Replace	Replace X	No
58630-17031			CHECK ASSY, RR DOOR,	1	150.30	25.00	112.72	Replace	Replace X	No
59211-4020			DOOR OUTER HANDLE RR/LH	1	69.80	25.00	52.35	Replace	Replace R	No
51602-7091		6505476	FENDER RR/LH	1	766.80	25.00	575.10	Replace	Replace R	No

Number			Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
	COMMON		1	7.80	0.00	7.80	Replace	Replace ✓ ARC	No
	COMMON		1	21.60	0.00	21.60	Replace	Replace ✓ ARC	No
62720-47031			1	168.10	25.00	126.07	Replace	Replace X	No
	COMMON		1	37.00	0.00	37.00	Replace	Replace X	No
42611-47140		6505658	1	1,490.20	25.00	1,117.65	Replace	Replace X	No
52159-47905		6505548	1	458.60	25.00	343.95	Replace	Replace X	No
			1	60.00	0.00	60.00	Replace	Replace X	No
87940-47310		6505599	1	1,224.90	25.00	918.67	Replace	Replace ✓ DM	No
87945-74010		6505597	1	107.40	25.00	80.55	Replace	Replace R	No
<b>TOTAL MATERIALS</b>						<b>9,634.09</b>	<b>9,634.02</b>		
<b>TOTAL MATERIALS(Discounted)</b>						<b>7,771.66</b>	<b>7,771.66</b>		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
<b>TOTAL SUPPLEMENTARY MATERIALS</b>									




+ 1 DAY 2-3-18 / 10:34  
check 2-3-18 / 14:34

# SMRT Accident Vehicle Repair Estimates

22-2-18 / 14:34

## Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4698A  
 Ref. No : TAX/02/18/2118  
 Reg. Date : 01/01/1900 24/09/2014  
 Vehicle Type : TAXI  
 Make : TOYOTA PRIUS  
 Model : PRIUS  
 Name of Driver : TAN KOON HIAN  
 Type of Accident : SIDE SWIPE  
 Date / Time of Accident : 21/02/2018 06:45:00 AM  
 Accident Reported Date / Time : 21/02/2018 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by : Sebastian  
 Vehicle is Towed Back? : Yes  
 Towed Back Date/Time : 21/02/2018  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No : 000024094671



Special Instruction to ARC, if any :

TOWED \$40/YP6207B NTUC 45  
BEFORE PAINT PHOTO AND AFTER PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR SEBASTIAN (LKK) & Email : sebastianyeang @lkkauto.com HP:90036121 LUMPSUM REPAIR

Prepared Date : 21/02/2018 10:16:30 AM

9700 25577 Tan. 1310V

Recording Camera

Radio Antenna

1<sup>st</sup> witness


M

Date

22-2-18

2<sup>nd</sup> witness

Date



Vehicle sent to SMRT Date In: 23/2/18 Towing: \_\_\_\_\_  
 Time In: 12:50 Driver: don  
 Mega Job No: 02/0104  
 Vehicle sent to SMRT Date In: 2/3/18 Towing: \_\_\_\_\_  
 Time In: 11:05 Driver: W  
 Received by (SMRT): \_\_\_\_\_

QC 2/8/18 12.32 Paul

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : Mileage : 0  
Work Shop : Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,690.00	950.00
Total Spray Painting Charges	: 3,348.00	1,300.00
Total Material Charges	: 3,761.10	2,729.10
Other Charges	: 1,650.00	-529.10
<b>TOTAL</b>	<b>: 10,449.10 19,415.64</b>	<b>4,450.00</b>
<b>Lum Sum Total</b>	<b>: 0.00</b>	<b>0.00</b>
No. of Repair Days	: 10.00	7.00 /
Prepared / Adjusted By	:	SEBASTIAN (LKK)
Arc / Surveyor Sing Off Date	: 21/02/2018 02:09:22 PM	22/02/2018 02:34:16 PM

Prepared / Adjusted Date :  
Remarks :

Prepared Date : 21/02/2018 02:09:22 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1803-0248 Invoice No :  
Quotation Date : 13/3 Invoice Date :  
Invoice Amount : Prepared Date :

Section D - Details of Repair Estimates

**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	1,690.00	950.00 /
<b>Total Labour</b>	<b>1,690.00</b>	<b>950.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	200.00 /
TO RESPRAY FRONT FENDER LH	378.00	200.00 /
TO RESPRAY APRON PANEL LH	180.00	0.00
TO RESPRAY RIM	360.00	50.00 /
TO RESPRAY FRONT PILLAR LH	180.00	100.00 /
TO RESPRAY FRONT DOOR LH	378.00	200.00 /
TO RESPRAY ROCKER PANEL MOULDING	180.00	100.00 /
TO RESPRAY REAR DOOR LH	378.00	200.00 /
TO RESPRAY REAR FENDER LH	378.00	200.00 /
TO REPSRAY REAR BUMPER	378.00	0.00
TO RESPRAY VIEW MIRROR	180.00	50.00 /
<b>Total Spray Painting &amp; Panel Beating</b>	<b>3,348.00</b>	<b>1,300.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30.00 /
TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	40.00 /
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	240.00	30.00 /
TO REMOVE AND REFIT TYRE	120.00	0.00
TO REMOVE & REFIX FRONT LHS/RHS QUATER GLASS	120.00	50.00 /
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	250.00	250.00 /
TO TRANSFER DOOR MECHANISM	240.00	120.00 /
TO REMOVE & REFIT REAR QUARTER GLASS LH	120.00	0.00
TO REPLACE SUNDRY PARTS	100.00	20.00 /
TO WASH AND VACUUM	60.00	0.00
TO REMOVE AND REFIX WING MIRROR	120.00	30.00 /
Lump Sum Adjustment by Surveyor	0.00	-1,099.10
<b>Total Other Costs</b>	<b>1,650.00</b>	<b>-529.10</b>

19415.64

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached	
52119-47930		6505517	BUMPER FRT	1	482.00	100.00	0.00	Replace	Repair	No	R
90467-07211			BUMPER CLIPS	10	2.10	25.00	15.75	Replace	Replace	No	NEC
53802-47050		6505558	FENDER FRT/LH	1	723.40	25.00	542.55	Replace	Replace	No	PLW
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace	No	NEC
53876-47030		6505554	FENDER LINER FRT/LH	0	171.70	25.00	0.00	Replace	Not given	No	X
53852-47020			FENDER LINER PAD, FR WHEEL LH	0	49.30	25.00	0.00	Replace	Not given	No	X
53702-47050			FENDER APRON SUB FRT/LH	1	637.80	25.00	478.35	Replace	Check	No	X
42611-47140 (Frt)		6505658	WHEEL DISC. FRONT	1	1,484.20	100.00	0.00	Replace	Repair	No	R
		6503707	TYRE	0	126.74	0.00	0.00	Replace	Not given	No	X
62120-47021			QUARTER GLASS FRT/LH	1	234.90	25.00	176.17	Replace	Replace	No	NEC
	COMMO N		SEALANT W/SCREEN	1	37.00	0.00	37.00	Replace	Replace	No	NEC
67002-47070		6505529	DOOR FRT/LH	1	894.40	25.00	670.80	Replace	Replace	No	DETOM
61132-47030			PILLAR, FR BODY, LH	1	363.10	25.00	272.33	Replace	Check	No	X
68740-12120			HINGE LOWER LHF, DOOR	1	90.10	25.00	67.57	Replace	Replace	No	BT
68720-15151			HINGE UPPER LHF, DOOR	1	80.50	25.00	60.37	Replace	Replace	No	BT
68610-47021			CHECK ASSY, FR DOOR,	1	150.30	25.00	112.73	Replace	Check	No	X
75720-47021			DOOR BELT FRT/LH	1	69.20	25.00	51.90	Replace	Replace	No	NEC
69802-52070			DOOR REGULATOR SUB-ASSY, FRT/REAR LH	1	224.80	25.00	168.60	Replace	Check	No	X
69210-74030			DOOR OUTER HANDLE FRT/LH	1	370.80	100.00	0.00	Replace	Repair	No	R
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace	No	NEC
75852-47900			MOULDING BODY, LH	1	673.60	100.00	0.00	Replace	Repair	No	R
37004-47080		6505487	DOOR RR/LH	1	954.50	100.00	0.00	Replace	Repair	No	R
			PIXEL STICKER	1	60.00	0.00	60.00	Replace	Replace	No	NEC
38760-20122			HINGE UPPER LHR, DOOR	0	81.70	25.00	0.00	Replace	Not given	No	X
38780-52031			HINGE LOWER LHR, DOOR	0	72.20	25.00	0.00	Replace	Not given	No	X
38630-47031			CHECK ASSY, RR DOOR,	0	150.30	25.00	0.00	Replace	Not given	No	X
39211-74020			DOOR OUTER HANDLE RR/LH	1	69.80	100.00	0.00	Replace	Repair	No	R
31602-47091		6505476	FENDER RR/LH	1	766.80	100.00	0.00	Replace	Repair	No	R

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No
62720-47031			QUARTER GLASS RR/LH	0	168.10	25.00	0.00	Replace	Not given	No
	COMMON		SEALANT W/SCREEN	0	37.00	0.00	0.00	Replace	Not given	No
42611-47140		6505658	WHEEL, DISC	0	1,490.20	25.00	0.00	Replace	Not given	No
52159-47905		6505548	BUMPER REAR	0	458.60	25.00	0.00	Replace	Not given	No
			PIXEL STICKER	0	60.00	0.00	0.00	Replace	Not given	No
87940-47310		6505599	MIRROR ASSY, LH	1	1,224.90	25.00	918.67	Replace	Replace	No
87945-74010		6505597	COVER, OUTER MIRROR, LH	1	107.40	100.00	0.00	Replace	Repair	No
<b>TOTAL MATERIALS</b>							<b>3,761.13</b>	<b>2,729.10</b>		
<b>TOTAL MATERIALS(Discounted)</b>							<b>3,761.10</b>	<b>2,729.10</b>		

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
<b>TOTAL SUPPLEMENTARY MATERIALS</b>									

+ 2729.10 /  
 + 950.00 /  
 + 1870.00 /  


---

 5549.10 /  
 - 20%  


---

 4439.28 /  
 L/S \$4450/- /

Sebastian  
 12/3/18

**Veron Chen (LKKAuto)**

---

**From:** Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <YeoPohsuan@smrt.com.sg>  
**Sent:** Monday, 19 March 2018 11:16 AM  
**To:** Sebastian Yeang (LKK Auto)  
**Cc:** SUR; CS A Team; 'Leong Chee kwong'  
**Subject:** RE: SHC4698A

Hi

Amount confirmed as per your recommendation, thanks.

Regards  
Poh Suan

-----Original Message-----

**From:** Sebastian Yeang (LKK Auto) [mailto:SebastianYeang@lkkauto.com]  
**Sent:** Monday, 19 March 2018 9:43 AM  
**To:** Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)  
**Cc:** SUR; CS A Team; 'Leong Chee kwong'  
**Subject:** RE: SHC4698A

Dear Poh Suan

Please refer to attachment for the finalization.

Thank You

Best Regards,  
Sebastian | Automotive Assessor  
LKK Auto Consultants  
phone: 6256-3561 email: sebastianyeang@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

**From:** Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) [mailto:YeoPohsuan@smrt.com.sg]  
**Sent:** Wednesday, 14 March 2018 11:29 AM  
**To:** Sebastian Yeang (LKK Auto)  
**Cc:** SUR; CS A Team; 'Leong Chee kwong'  
**Subject:** SHC4698A

Hi Sebastian,

Attached herewith the repair estimate of SHC 4698A having Case No: TAX/02/18/2118.

There is no change to the approved amount of \$4,450 @ 7 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Aside Kwong,

Please provide the before / after paint photos as per surveyor's request.

Thanks & Regards  
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)

Sent: Tuesday, 13 March 2018 3:53 PM

To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)

Subject: Scan Data from FX-D421D6



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Thatcham *escribe*

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18003821/Svbe2	
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556	Date: 23-03-2018
Code: INC4	



### 1. Policy Particulars - THIRD PARTY CLAIM

Insured Veh.	YP 6207B	Veh. Inspected	SHC 4698A
Policy No.	5090750114	Coverage (\$)	0.00
Claim No.	MT/0985203-002	Excess (\$)	0.00
Assign From		Assign Date	22/02/2018

### 2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JTDKN36U005751088	Colour	MAROON
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	6 mm
L/H Front Tyre	195/65 R15	FALKEN	6 mm
R/H Rear Tyre	195/65 R15	FALKEN	6 mm
L/H Rear Tyre	195/65 R15	FALKEN	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.  
DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	21/02/2018	Inspection Date	22/02/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **7 Working Days**



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4698A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
10	BUMPER CLIPS (DISC 25%)	NECESSARY	21.00	15.75
1	FENDER FRT / LH (DISC 25%)	PUNCTURE	723.40	542.55
1	NAME PLATE (HYBRID) (DISC 25%)	NECESSARY	51.90	38.92
1	QUARTER GLASS FRT / LH (DISC 25%)	NECESSARY	234.90	176.17
1	DOOR FRT / LH (DISC 25%)	DEFORMED	894.40	670.80
1	HINGE LOWER LHF, DOOR (DISC 25%)	BENT	90.10	67.57
1	HINGE UPPER LHF, DOOR (DISC 25%)	BENT	80.50	60.37
1	DOOR BELT FRT/LH (DISC 25%)	NECESSARY	69.20	51.90
1	MIRROR ASSY, LH (DISC 25%)	DAMAGED	1,224.90	918.67
1	SEALANT W/SCREEN (SN)	NECESSARY	37.00	37.00
1	STICKER DECAL SMRT (DOOR) (SN)	NECESSARY	60.00	60.00
1	PIXEL STICKER (SN)	NECESSARY	60.00	60.00
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	FENDER LINER FRT / LH	NOT NECESSARY	171.70	-
1	FENDER LINER PAD, FR WHEEL, LH	NOT NECESSARY	49.30	-
1	FENDER APRON SUB FRT/LH	NOT NECESSARY	637.80	-
1	TYRE	NOT NECESSARY	126.74	-
1	PILLAR, FR BODY, LH	NOT NECESSARY	363.10	-
1	CHECK ASSY, FR DOOR	NOT NECESSARY	150.30	-
1	DOOR REGULATOR SUB-ASSY, FRT / REAR LH	NOT NECESSARY	224.80	-
1	HINGE UPPER LHR, DOOR	NOT NECESSARY	81.70	-
1	HINGE LOWER LHR, DOOR	NOT NECESSARY	72.20	-
1	CHECK ASSY, RR DOOR	NOT NECESSARY	150.30	-
1	QUARTER GLASS RR/LH	NOT NECESSARY	168.10	-
1	SEALANT W/SCREEN	NOT NECESSARY	37.00	-
1	WHEEL, DISC	NOT NECESSARY	1,490.20	-
1	BUMPER REAR	NOT NECESSARY	458.60	-
1	PIXEL STICKER	NOT NECESSARY	60.00	-
1	BUMPER FRT	TO REPAIR	482.00	-

Report Ref No. NS/INC18003821/Svbe2



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	WHEEL DISC FRONT	TO REPAIR	1,484.20	-
1	DOOR OUTER HANDLE FRT / LH	TO REPAIR	370.80	-
1	MOULDING BODY, LH	TO REPAIR	673.60	-
1	DOOR RR/LH	TO REPAIR	954.50	-
1	DOOR OUTER HANDLE RR/LH	TO REPAIR	69.80	-
1	FENDER RR/LH	TO REPAIR	766.80	-
1	COVER, OUTER MIRROR, LH	TO REPAIR	107.40	-
			12,727.64	2,729.10
	<b>LABOUR</b>			
	THATCHAM STANDARD REPAIR TIME ON BODY WORKS.		2,980.00	1,460.00
	THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.		3,548.00	1,340.00
	TO REPLACE SUNDRY PARTS.		100.00	20.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			6,688.00	2,820.00
	<b>GRAND TOTAL</b>		<b>19,415.64</b>	<b>5,549.10</b>

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>			<b>4,460.00</b>
---	--	--	-----------------

Report Ref No. NS/INC18003821/Svbe2

YEANG WAI KEEN  
Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,  
MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.