

ASS. REC. BY:

REF:

TM/ CC3/TMU8003824/Kgbn2

## ASSIGNMENT

S/ID 263S

From:

Date:

Estimated Cost:

Veh No:

SHG 5483

Yr Regn:

11, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry (Taxi) / Prime Mover /

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

Truck / Trailer or

To Inspect Vehicle No:

Make:

Peravit Caribdy c.c 1985

at Workshop m/s

Colour

White / Red A/C: Insured / Std / NI / NA

of

Sp. Reading

210804 T/Radio: Insured / Std / NI / NA

Insured:

SLP 3944E

Policy No.

M4006141

Claims No.

M1800946


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Front

R/Bal.

9 mm

L/Bal.

9 mm

D.O.A.

12/2/18

Rear

R/Bal.

5 mm

L/Bal.

5 mm

D.O.I.

19/2/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

20/2

M4 2334.57

SHD 263S - CC3 / ALH 13006506 / R1eb392

SLP 3944E - x

DCA: D10413

28/2/18 @ 4.25pm

Email EIA report, police report &amp; Estimate to Shirley.

RECEIVED 01 MAR 2018

Date/Time, File Pass to?



: Prell. Report

1) 01/3 11:15



: Final Report

Date/Time, File Return to?

Days Of Repair: 2

Resurvey No. of Trlp:

Survey Fee:

250

Transportation:

10

S - RS - SI

Photos

Others

TOTAL

260

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Report Format:

M4-TP

Lump Sum / I.B.I: (\$

2334.57



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
TOKIO MARINE INSURANCE SINGAPORE LTD		Ref : CC3/TMI18003824/Kqb	
20 MCCALLUM STREET #09-01 TOKIO MARINE CENTRESINGAPORE 069046		Date : 27-02-2018	
		Code : TMI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SLP 3944E	Veh. Inspected	SHD 263S
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	19/02/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	12/02/2018	Inspection Date	19/02/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

# Survey Department Check List (Case Handler)

Reference No. :

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin** ( *Carth* ): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

## (1) Office Assign Form

	Y-Date	N-Date	Y-Date	N-Date
C Reference No.	<input checked="" type="checkbox"/>			
C Customer Code	<input checked="" type="checkbox"/>			
N Assign From				
C Assign Date	<input checked="" type="checkbox"/>			
C Veh No (Inspected)	<input checked="" type="checkbox"/>			
C Veh No (Insured)	<input checked="" type="checkbox"/>			
C D.O.A	<input checked="" type="checkbox"/>			
C Policy No	<input checked="" type="checkbox"/>			
C Claim No	<input checked="" type="checkbox"/>			
C Insurance Authorisation (CA /REV/REP)				
C Report Type	<input checked="" type="checkbox"/>			
C Weekend Charges				
N Survey held at/Repairer	<input checked="" type="checkbox"/>			
C Excess				

**Surveyor** ( *Kenneth* ): Case handler to make sure the surveyor completed all required information.

## (1) Assignment Form

C Vehicle No	<input checked="" type="checkbox"/>			
C Regn Month/Year	<input checked="" type="checkbox"/>			
N Vehicle Type	<input checked="" type="checkbox"/>			
N Make & Model	<input checked="" type="checkbox"/>			
C Engine Capacity. (C.C)	<input checked="" type="checkbox"/>			
N Colour	<input checked="" type="checkbox"/>			
C Odometer. (Sp.Reading)	<input checked="" type="checkbox"/>			
C Chassis No	<input checked="" type="checkbox"/>			
N General Condition	<input checked="" type="checkbox"/>			
N Steering	<input checked="" type="checkbox"/>			
N Brake	<input checked="" type="checkbox"/>			
N Modification (Modi)	<input checked="" type="checkbox"/>			
C Tyre Size	<input checked="" type="checkbox"/>			
N Tyre Make	<input checked="" type="checkbox"/>			
C Tyre Balance	<input checked="" type="checkbox"/>			
C Date of Inspection	<input checked="" type="checkbox"/>			
N Survey held	<input checked="" type="checkbox"/>			
N Des.of Damages	<input checked="" type="checkbox"/>			

## (2) System - (Views/Merimen)

C Damaged Vehicle Photographs Uploaded	<input checked="" type="checkbox"/>			
--	-------------------------------------	--	--	--

## (3) Workshop Estimate/Assignment Form

N ALL Parts condition	<input checked="" type="checkbox"/>			
C Market Value for OD cases				
C Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C Days of repair	<input checked="" type="checkbox"/>			
C Finalised Amount				
C Re-inspection Cases to Finalize within 5 Days				

## (4) System - (Views/Merimen)

C Resurvey photo Uploaded				
---------------------------	--	--	--	--

Check By:

Case Handler

Date

\*C: Critical \*N: Non-Critical

21/05/2014

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Wednesday, 28 February 2018 4:25 PM  
**To:** Too Joon Hwa  
**Cc:** Priscilla Tan; SUR  
**Subject:** DIRECT SURVEY INSPECTION ON WORKSHOP - TRANS-CAB AUTO SERVICES PTE LTD, DOA: 12/02/2018, SHD 263S (TP VEHICLE), SLP 3944E (OI VEHICLE)  
**Attachments:** SHD263 GIA.pdf, SHD263 EST.pdf

Dear Shirley,

Please be informed that we had inspected the vehicle SHD 263S M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63 SINGAPORE 569111 on 19/02/2018.

Enclosed herewith a copy of TP's GIA report, police report and estimated cost of repair.

Meanwhile, kindly create claim in merimen for our necessary action.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHD263S
Vehicle to be Exported:	Yes
Intended De-registration Date:	15 Feb 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C002868
Chassis No.:	VF1ABL15AUC282307
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	20 Nov 2015
First Registration Date:	20 Nov 2015
Transfer Count:	0
Actual ARF Paid:	\$19,998.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Nov 2023
PARF Rebate Amount:	\$14,998.00
Intended COE Rebate Details	

COE Expiry Date:	19 Nov 2023
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$45,267.00
COE Rebate Amount:	\$32,598.00
<b>Total Rebate Amount:</b>	<b>\$47,596.00</b>
<b>Message</b>	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 15 Feb 2018

OK

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report	14/02/2018 10:27
Date Of Accident	12/02/2018 17:45
Exact Location Of Accident	BALESTIER ROAD TOWARDS THOMSON ROAD
Country/State of Loss	SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD263S
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666
<b>Vehicle Particulars</b>	
Manufacturer	RENAULT
Model	LATITUDE-2.0 DCI AUTO D/AB 4DR (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

#### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

#### Driver

Name of Driver	MOHAMAD RAZIEF BIN MOHD ALI
NRIC No	S1764592G
Date Of Birth	09/03/1966
Occupation	OUTDOOR
Date Of Driving Pass	15/05/1998
Driving Experience	19 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88123253
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 175 WOODLANDS STREET 13 #03-325
Postcode	730175
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

On the 12.02.2018 at about 1745hours, i was travelling straight along the first lane of Balestier road towards thomson rd, When vehicle in front of me slow down and made a stop and i followed suit. Moment later, i felt an impact from my rear and alighted to check. I realized that Vehicle B(SLP3944E) front portion had hit onto my taxi's rear portion.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLP3944E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LEE SUNG WOOL ANDREW
NRIC/Passport Number	S1793365E
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	



**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## Sketch Plan #2 Pg. 1

### SKETCH PLAN

SKETCH PLAN

A - SHD 263S

B - SLP 3944E

Belwater Rd  
towards  
Thomson Rd

↑ | ↑ | ↑ | ↑

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

- Please refer to GIA report -

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

**TRANS-CAB AUTO SERVICES PTE LTD**

NO. 2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHD263S -****AAD1802-149**

*Not Authorized*  
*Preserving B4 paint* **82334.57**

Vehicle No.:  
 Chassis No.:  
 Vehicle Make:  
 Vehicle Model:  
 Date of Accident :  
 Third Party Insurer :

**SHD263S - JHOW**

VF1ABL15AUC282307

RENAULT

LATITUDE

12.02.2018

**TOKIO****PART****LIST**

1	1	BUMPER COVER REAR	\$	<i>Bul</i> 1,108.46	✓
2	1	BUMPER LOWER REAR	\$	<i>Not</i> 768.84	✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47	}
4	1	BUMEPR BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97	
5	1	BUMEPR RETAINER RH REAR	\$	<i>Sn</i> 44.99	
6	1	BUMPER REFLECTOR RH	\$	<i>Sn</i> 43.61	
7	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97	
8	1	BUMEPR RETAINER LH REAR	\$	<i>Sn</i> 44.99	
9	1	BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61	
10	1	BUMPER BEAM REAR	\$	<i>N</i> 777.52	
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>N</i> 225.95	
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>N</i> 225.95	
13	1	BOOT REAR	\$	<i>N</i> 2,872.68	} X
14	1	BOOT FINISHER	\$	<i>Sn</i> 470.06	
15	1	BOOT WHEATERSTRIP	\$	<i>Sn</i> 323.05	
16	1	BOOT REFLECTOR LAMP LH	\$	<i>Sn</i> 493.35	
17	1	BOOT REFLECTOR LAMP RH	\$	<i>Sn</i> 493.35	
18	1	BOOT BADGE 'RENAULT'	\$	<i>N</i> 225.36	
19	1	BOOT BADGE	\$	<i>N</i> 225.36	
20	1	BOOT STRUT LH	\$	<i>N</i> 276.08	
21	1	BOOT STRUT RH	\$	<i>Sn</i> 276.08	
22	1	BOOT HINGE LH	\$	<i>N</i> <i>Sn</i> 367.84	
23	1	BOOT HINGE RH	\$	<i>N</i> 367.84	
24	1	BOOT SWITCH	\$	<i>Sn</i> 168.13	
25	1	BOOT LOCK	\$	<i>N</i> 202.67	
26	1	BOOT LOCK CATCH	\$	<i>N</i> 74.40	
27	2	LICENCE PLATE LAMP	\$	<i>Sn</i> 50.52	
28	2	BOOT RUBBER PLUG	\$	<i>Sn</i> 221.81	
29	1	FENDER PANEL REAR LH	\$	<i>N</i> 3,299.13	
30	1	WHEELARCH REAR LH	\$	<i>Sn</i> 543.47	
31	1	FENDER PANEL REAR RH	\$	<i>N</i> 3,299.13	
32	1	WHEELARCH REAR RH	\$	<i>Sn</i> 543.47	
33	1	TAILLAMP RH	\$	<i>Sn</i> 552.55	
34	1	TAILLAMP PANEL RH	\$	<i>N</i> 986.70	

**TRANS-CAB AUTO SERVICES PTE LTD****AAD1802-149**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHD263S -**

35	1	TAILLAMP LH	\$	Sn	552.55	} X
36	1	TAILLAMP PANEL LH	\$	n	986.70	
37	1	OUTER PANEL REAR (End Panel)	\$	n	1,471.77	
38	1	OUTER PANEL REAR (End Panel)TRIM	\$	Sn	404.56	
39	1	EXHAUST REAR	\$	n	7,489.05	
40	1	EXHAUST CAP REAR	\$	n	230.49	} X
					48	
<b>TOTAL</b>			\$		<b>31,137.51</b>	
<b>10%</b>			\$		<b>3,113.75</b>	
			\$		<b>28,023.76</b>	

**Specical Nett**

1	1SET	PARKING AID	\$	Sn	700.00	X
2	1SET	REAR BUMPER CLIP	\$	~	66.00	—
3	1SET	BUMPER BRACKET CTR CLIP	\$	~	33.00	—
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	~	10.00	X
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	~	20.00	X
6	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	~	10.00	X
7	1SET	BUMEPR RETAINER CLIP LH RR	\$	~	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	~	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	~	66.00	✓
10	1	EXHAUST MOUNTING REAR	\$	Sn	17.82	} X
11	1SET	BOOT FINISHER CLIP	\$	~	24.20	
12	1	BOOT STICKER "Trans-cab"	\$	~	30.00	
13	1	BOOT STICKER "6555-3333"	\$	~	30.00	
14	1SET	FENDER WHEELARCH REAR RH CLIP	\$	~	35.00	
15	1SET	FENDER WHEELARCH REAR LH CLIP	\$	~	35.00	} X
16	1	TAILLAMP CLIP RH	\$	~	5.00	
17	1	TAILLAMP CLIP LH	\$	~	5.00	
18	2	REAR WINDSCREEN SELANT	\$	~	80.00	
19	1	WINDSCREEN MOULDING	\$	Sn	100.00	
20	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	~	100.00	
21	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	Sn	385.00	
22	1	SPARE TYRE	\$	~	330.00	
<b>TOTAL</b>			\$		<b>2,124.02</b>	
<b>TOTAL PARTS</b>			\$		<b>30,147.78</b>	

Putty And Spray Painting Of The Affected Portion.

\$ 3,000.00 2201

To Rust-Proofing Of The Affected Areas.

\$ ~ 170.00 X

**TRANS-CAB AUTO SERVICES PTE LTD**

AAD1802-149

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHD263S -**

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,800.00	<i>2007</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>607</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>~ 170.00</i>	<i>X</i>
To repair and realign rear exhaust pipe.	\$	<i>~ 170.00</i>	<i>X</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>~ 170.00</i>	<i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>~ 170.00</i>	<i>X</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>~ 380.00</i>	<i>X</i>
Towing Fees	\$	<i>~ 120.00</i>	<i>X</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>~ 170.00</i>	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>~ 220.00</i>	<i>X</i>

**TOTAL \$ 7,710.00****Over All Total \$ 37,857.78****(PARTS BY PARTS)****Repair Days****10 Days***2 days*LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company.

Acknowledged by Repairer

Signature:

Date:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI18003824/KQBN2

Date: 05/03/2018

## REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MU006141
Claimant Vehicle No :	SHD263S	Insured Vehicle No :	SLP3944E
Date of Loss:	13/02/2018	Nature of Claim:	TP
		Claim No:	M1800946

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SHD263S	Engine No:	M9R8839C002868
Make & Model:	RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A)	Chassis No:	VF1ABL15AUC282307
Reg. Date:	20/11/2015 (Man. Year: 2015)	Odometer:	210804 km
Colour:	Red/White		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Giti 9 mm	Rear Left Side:	Linglong 5 mm
Front Right Side:	Giti 9 mm	Rear Right Side:	Linglong 5 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	30,147.75	1,854.57	28,293.18	93.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,710.00	480.00	7,230.00	93.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>37,857.75</b>	<b>2,334.57</b>	<b>35,523.18</b>	<b>93.83</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>2,650.04</b>	<b>163.42</b>	<b>2,486.62</b>	<b>93.83</b>
<b>Nett Amount (S\$)</b>	<b>40,507.79</b>	<b>2,497.99</b>	<b>38,009.80</b>	<b>93.83</b>

## INSPECTION

Date of Assignment:	01/03/2018	
Date Inspected:	19/02/2018 Inspected At:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 05 Mar 2018)
<b>Parts:</b>	143	RENAULT LATITUDE 2.0 DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHD263S)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled	1,108.46 FL	*1,108.46 FL
2	1		*BUMPER LOWER REAR	Dented	768.84 FL	*768.84 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	113.47 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*- FL
6	1		*BUMPER REFLECTOR RH	Serviceable	43.61 FL	*- FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	135.97 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*- FL
9	1		*BUMPER REFLECTOR LH	Serviceable	43.61 FL	*- FL
10	1		*BUMPER BEAM REAR	Repair	777.52 FL	*- FL
11	1		*BUMPER BEAM BRACKET LH REAR	Repair	225.95 FL	*- FL
12	1		*BUMPER BEAM BRACKET RH REAR	Repair	225.95 FL	*- FL
13	1		*BOOT REAR	Repair	2,872.68 FL	*- FL
14	1		*BOOT FINISHER	Serviceable	470.06 FL	*- FL
15	1		*BOOT WEATHERSTRIP	Serviceable	323.05 FL	*- FL
16	1		*BOOT REFLECTOR LAMP LH	Serviceable	493.35 FL	*- FL
17	1		*BOOT REFLECTOR LAMP RH	Serviceable	493.35 FL	*- FL
18	1		*BOOT BADGE RENAULT	Not Necessary	225.36 FL	*- FL
19	1		*BOOT BADGE	Not Necessary	225.36 FL	*- FL
20	1		*BOOT STRUT LH	Not Necessary	276.08 FL	*- FL
21	1		*BOOT STRUT RH	Serviceable	276.08 FL	*- FL
22	1		*BOOT HINGE LH	Repair	367.84 FL	*- FL
23	1		*BOOT HINGE RH	Repair	367.84 FL	*- FL
24	1		*BOOT SWITCH	Serviceable	168.13 FL	*- FL
25	1		*BOOT LOCK	Repair	202.67 FL	*- FL
26	1		*BOOT LOCK CATCH	Repair	74.40 FL	*- FL
27	2		*LICENCE PLATE LAMP	Serviceable	50.52 FL	*- FL
28	2		*BOOT RUBBER PLUG	Serviceable	221.81 FL	*- FL
29	1		*FENDER PANEL REAR LH	Repair	3,299.13 FL	*- FL
30	1		*WHEELARCH REAR LH	Serviceable	543.47 FL	*- FL
31	1		*FENDER PANEL REAR RH	Repair	3,299.13 FL	*- FL
32	1		*WHEELARCH REAR RH	Serviceable	543.47 FL	*- FL
33	1		*TAILLAMP RH	Serviceable	552.55 FL	*- FL
34	1		*TAILLAMP PANEL RH	Repair	986.70 FL	*- FL
35	1		*TAILLAMP LH	Serviceable	552.55 FL	*- FL
36	1		*TAILLAMP PANEL LH	Repair	986.70 FL	*- FL
37	1		*OUTER PANEL REAR (END PANEL)	Repair	1,471.77 FL	*- FL
38	1		*OUTER PANEL REAR (END PANEL) TRIM	Serviceable	404.56 FL	*- FL
39	1		*EXHAUST REAR	Repair	7,489.05 FL	*- FL
40	1		*EXHAUST CAP REAR	Repair	230.49 FL	*- FL
41	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
42	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
43	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
44	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
46	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
47	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
48	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
49	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
50	1		*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	*- FS
51	1		*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*- FS
52	1		*BOOT STICKER TRANS-CAB	Not Necessary	30.00 FS	*- FS
53	1		*BOOT STICKER 6555-3333	Not Necessary	30.00 FS	*- FS
54	1		*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	35.00 FS	*- FS
55	1		*SET FENDER WHEELARCH REAR LH CLIP	Not Necessary	35.00 FS	*- FS
56	1		*TAILLAMP CLIP RH	Not Necessary	5.00 FS	*- FS
57	1		*TAILLAMP CLIP LH	Not Necessary	5.00 FS	*- FS
58	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
59	1		*WINDSCREEN MOULDING	Serviceable	100.00 FS	*- FS
60	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
61	1		*SPARE TYRE RIM (ROUE 7J 16H 2547)	Serviceable	385.00 FS	*- FS
62	1		*SPARE TYRE	Serviceable	330.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>33,261.50</b>	<b>2,042.30</b>
- List Item Discount on L Items 10.00/10.00% (\$\$)	3,113.75	187.73
<b>Total Parts (\$\$)</b>	<b>30,147.75</b>	<b>1,854.57</b>

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	220.00
2	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	-
3	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	2,800.00	200.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
5	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	-
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	-
7	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	-
8	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	-
9	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	-
10	TOWING FEES	New	120.00	-
11	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	-
12	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	-
<b>Gross Labour Cost (\$\$)</b>			<b>7,710.00</b>	<b>480.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >