

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0238/2018/GW
Date	:	26-Feb-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Goh Jin Wen, Danny
Address	:	4 Jalan Hikayat Singapore 769849
Telephone	:	HP +65 96327153
Type of Claim	:	Own Damage Claim
Policy No.	:	1700015551
Vehicle No	:	SLP 5509 R
Model Code	:	Audi A4 Sedan 1.4 TFSI S
Model / Year	:	Jun-17
Engine No	:	CVN 039032
Chassis No	:	WAUZZZF46HA164531
Mileage	:	-
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	23-Feb-18
Place of Accident	:	24 Ghim Moh Link

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLP 5509 R.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid & rear boot lid sensor.	S/N \$ 360.00 ✓	
2	To remove trunk fittings, dismantle and renew rear bumper and lower spoiler. Inspect for damages on reinforcement and end panelling. Re-install all parts removed. Repair lhs rear fender, taillamp panel.	\$ 1,500.00 1000	
3	To respray paint on rear bumper, lhs rear fender, taillamp panel and rear lid. X . X	\$ 2,700.00 1100	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: <u>\$ 4,752.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLP 5509 R.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>Reformed</i>	\$ 1,907.00	✓
2	REAR BUMPER FIXING PARTS <i>renew</i>	\$ 63.00	✗
3	REAR BUMPER SPOILER <i>At</i>	\$ 216.00	✓
4	REAR LIGHT REFLECTOR -LH <i>changed</i>	\$ 35.00	✓
5	REAR BUMPER SENSOR SEAL RING <i>new</i>	\$ 15.00	✓
6	REAR BUMPER SENSOR <i>Repd</i>	\$ 211.00	✓
7	REAR BUMPER GUIDE SECTION-LH <i>new</i>	\$ 37.00	✗
8	REAR BUMPER BRACKET GUIDE SECTION-LH <i>new</i>	\$ 19.00	✗
9	VENT TRIM <i>new</i>	\$ 60.00	✗
10	OUTER LED TAIL LIGHT-LH <i>changed</i>	\$ 915.00	✓
11	OUTER LED TAIL LIGHT TRIM-LH <i>new</i>	\$ 26.00	✗
12	INNER LED TAILLIGHT - LHS <i>new</i>	\$ 815.00	✗
13	INNER LED TAILLIGHT TRIM - LHS <i>new</i>	TBC	✗
14	SUNDRIES	\$ 300.00	?
TOTAL SPARE PARTS		\$ 4,619.00	
TOTAL LABOUR CHARGES		\$ 4,752.00	
GRAND TOTAL		\$ 9,371.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Ng
Surveyed Date : 07/02/18
Authorised Date :
Excess Cost :
Liability : Nil
Remarks : Authorised Repairs, 04 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant