


ASSIGNMENT

From: _____ Date: **05-07-2018**
 Estimated Cost: _____
 OD / WS / TP RES / OD RES / EVA / INV / MY
 To inspect Vehicle No: **SGH 9181B**
 at Workshop in a: **Accord Auto**
 of: **Amk**
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Van/Id: **SGH 9181B** Vr Page: **08 08**
 Type: Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: **Toy** ^{1A} **Was** Yr: **1997**
 Colour: **Wh. Gold** A/C: _____ Insured: _____ Std: _____ Nil: _____ NA
 So. Reading: **123508** T. P. No: _____ Insured: _____ Std: _____ Nil: _____ NA
 Eng. No: _____
 C. No: **MR053HY4204193716**
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Mod: Nil / B/Rim / STD R/Rim or _____
 Tyre Size: F: **185/50R14**
 R: _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / BR / SUMI /
 TOYO / YOKO or **1414**
 Front: _____ Rear: _____
 R. Bal: **3** mm R. Bal: **7** mm
 L. Bal: **3** mm L. Bal: **7** mm
 D.O.A: **23/2/18** D.O.I: **5/3/18**
 Survey held at: _____ ✓
 Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or
Rear N/S
 The U/C / Chassis frame / Body Structure affected due to collision

Bal. or Market Value: _____
 IDAO Accident Report: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: **05** days Res: Yes or No
 Lum Sum: **20** % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date: Time: Action / Instruction
6/3 file pass to Catherine.
1/5: +2,000 (RED: +3,619.89 64%)

Date/Time: File Pass to: Prel. Report
 Final Report
 Date/Time: File Return to: _____
 Report Format: _____
 Lump Sum / I.B.H: 3

Days Of Repair: _____
 Resurvey No. of Trip: _____
 Add Fee: Site Insp: \$
 Inter. Insp: \$
 Test Insp: \$
 Weekend: \$
 Survey Fee: _____
 Transmittal: _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
INDIA INTERNATIONAL INSURANCE PL		Ref : CC4/III18003835/eb3	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 27-02-2018	
		Code : III2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SH 8311H	Veh. Inspected	SGH 9181B
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	27/02/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	23/02/2018	Inspection Date	
Survey held at	ACCORD AUTO SERVICES PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTO POINT #03-11 SINGAPORE 568047		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

ke

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

India International Insurance Pte Ltd

64 Cecil St

#04 #05 IOB Building

Singapore 049711

Attn: Motor Claims Department

*Not Notch
LH by B 2000
Rebody After Paint
4 days*

Date: 27/02/2018

Vehicle No: SGH9181B

Veh Make/Model: Toyota Vios 1.5E A

YOM: 2006

Chassis No: MR053HY4204193716

Date of Accident: 23/02/2018

No	Qty	Description	Amount S
List Items:-			
1	1	Bootlid	\$ R 601.75 X
2	1	Bootlid "1.5" emblem	\$ R 35.00 X
3	1	Bootlid "E" emblem	\$ R 35.00 X
4	1	Bootlid "VVT-I" emblem	\$ R 35.00 X
5	1	Bootlid "VIOS" emblem	\$ R 35.00 X
6	1	Bootlid logo	\$ R 35.00 X
7	1	Bootlid lock	\$ R 53.10 X
8	1	Bootlid striker	\$ R 43.90 X
9	1	Bootlid weatherstrip	\$ R 61.10 X
10	1	LH Tail lamp	\$ R 281.75 X
11	1	LH Tail lamp sealant	\$ R 50.00 X
12	2	LH Tail lamp clip	\$ R 25.80 X
13	1	LH Tail lamp base panel	\$ R 161.20 X
14	1	Rear LH fender	\$ R 544.30 X
15	1	Rear bumper	\$ R 383.80 X
16	2	Rear bumper side retainer	\$ R 87.80 X
17	10	Rear bumper clip	\$ R 35.00 X
18	2	Rear bumper bracket	\$ R 86.20 X
19	1	End panel	\$ R 689.75 X
20	1	End panel top trim	\$ R 67.80 X
21	6	End panel top trim clip	\$ R 51.60 X
Total - List Item			\$ 3,399.85
Less 25%			\$ 849.96
Total			\$ 2,549.89
Special Nett Items:-			
1	1 set	Rear bumper rever sensor	\$ R 380.00 X
2	1	Rear bootlid compartment waterproof sealant	\$ R 150.00 X
Total - SN Item			\$ 530.00
Balance b/f			\$ 3,079.89

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

India International Insurance Pte Ltd
64 Cecil St
#04 #05 IOB Building
Singapore 049711
Attn: Motor Claims Department

Not Notified
11 Day 87
Running After Paint
4 days

Date: 27/02/2018
Vehicle No: SGH9181B
Veh Make/Model: Toyota Vios 1.5E A
YOM: 2006
Chassis No: MR053HY4204193716
Date of Accident: 23/02/2018

No	Qty	Description	Amount S
List Items:-			
1	1	Bootlid	\$ R 601.75 X
2	1	Bootlid "1.5" emblem	\$ R 35.00 X
3	1	Bootlid "E" emblem	\$ R 35.00 X
4	1	Bootlid "VVT-1" emblem	\$ R 35.00 X
5	1	Bootlid "VIOS" emblem	\$ R 35.00 X
6	1	Bootlid logo	\$ R 35.00 X
7	1	Bootlid lock	\$ R 53.10 X
8	1	Bootlid striker	\$ R 43.90 X
9	1	Bootlid weatherstrip	\$ Sn 61.10 X
10	1	LH Tail lamp	\$ 281.75 ?
11	1	LH Tail lamp sealant	\$ 50.00 ?
12	2	LH Tail lamp clip	\$ 25.80 ?
13	1	LH Tail lamp base panel	\$ R 161.20 X
14	1	Rear LH fender	\$ R 544.30 X
15	1	Rear bumper	\$ Bu 383.80 ✓
16	2	Rear bumper side retainer	\$ N/A 87.80 ✓
17	10	Rear bumper clip	\$ R 35.00 ✓
18	2	Rear bumper bracket	\$ N/A 86.20 ✓
19	1	End panel	\$ R 689.75 ✓
20	1	End panel top trim	\$ Sn 67.80 X
21	6	End panel top trim clip	\$ R 51.60 X
Total - List Item			\$ 3,399.85
Less 25%			\$ 849.96
Total			\$ 2,549.89
Special Nett Items:-			
1	1 set	Rear bumper rever sensor	\$ Short 380.00 2006 X
2	1	Rear bootlid compartment waterproof selant	\$ R 150.00 X
Total - SN Item			\$ 530.00
Balance b/f			\$ 3,079.89

Enquire Transfer Fee

Vehicle Details	
Vehicle No. :	SGH9181B
Vehicle Type :	P10 - Passenger Motor Car
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	TOYOTA
Vehicle Model :	VIOS 1.5E A
Chassis No. :	MR053HY4204193716
Propellant :	Petrol
Engine No. :	1NZX446836
Engine Capacity :	1497 cc
Maximum Power Output :	80.0 kW (107 bhp)
Maximum Laden Weight :	1480 kg
Unladen Weight :	1020 kg
Year Of Manufacture :	2006
Original Registration Date :	27 Jun 2006
Lifespan Expiry Date :	-
COE Category :	E - Open Category
PQP Paid :	\$22,789.00
COE Expiry Date :	31 May 2021
Road Tax Expiry Date :	26 Jun 2018
Inspection Due Date :	26 Jun 2018
Intended Transfer Date :	26 Feb 2018
CO2 Emission :	-

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Tuesday, 6 March 2018 12:17 PM
To: Accord Auto(Claims); 'Accord Claims(AV)'
Cc: Vic (LKKAuto)
Subject: Accident Involving SGH 9181B & SH 8311H on 23/02/2018

WITHOUT PREJUDICE

Your Ref: SGH 9181B
Our Ref: CC4/III18003835/eb3

Dear Sir/Madam,

Accident Involving SGH 9181B & SH 8311H on 23/02/2018

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents for us (**LKK**) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL					By
No.	On	Action	Description		
1	27 Feb 2018 19:58	Cim Veh Model Changed	(200942) TOYOTA VIOS 1.5 E (A).		[A] Lau Shu Pei
2	27 Feb 2018 19:58	Cim Created	Reg No: SGH9181B, Acct Date: 2018/02/23, Claim Type: TP, Insurer: India International Insurance Pte Ltd (HQ), TP Insurer: NTUC Income Insurance Co-operative Ltd (HQ), Workshop: Accord Auto Services Pte Ltd (HQ)		[A] Lau Shu Pei
3	27 Feb 2018 19:58	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):		[A] Lau Shu Pei
4	27 Feb 2018 19:58	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/03/08		[A] Lau Shu Pei
5	27 Feb 2018 19:58	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.		[A] Lau Shu Pei
6	27 Feb 2018 19:58	Label Added	(30653):Direct Settlement.		[A] Lau Shu Pei
7	27 Feb 2018 19:58	Adj Adjuster Assigned	[None] -> MA CHIN FOOK		[A] Lau Shu Pei
8	02 Mar 2018 09:31	Cim Dtl Modified	Claimant's Name: -> COMFORT TRANSPORTATION PTE LTD.		[A] Lau Shu Pei
9	05 Mar 2018 10:55	Adj Mandate Request	Cur.Req:0.00:PODS: LIABILITY: 100% REMARK: B:27 O/D REAR ENDED TP		[A] Asher Sng Rong Yi
10	05 Mar 2018 12:04	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/03/08		[I] Sherini Pillal
11	05 Mar 2018 12:04	Adj Mandate Set	Approved:0.00.		[I] Sherini Pillal
12	06 Mar 2018 14:59	Adj Adjuster Assigned	MA CHIN FOOK -> KENNETH KONG		[A] Lau Shu Pei
13	06 Mar 2018 15:01	Adj Rpt Initiated			[A] Lau Shu Pei
14	06 Mar 2018 15:01	Cim Dtl Modified	Claimant's ID: -> -.		[A] Lau Shu Pei
15	06 Mar 2018 15:01	Cim Details Notified			[A] Lau Shu Pei
16	09 Nov 2018 11:19	Adj Mandate Request	Cur.Req:2447.45:PODS: LIABILITY: 100% QUANTUM: (a) CDR w/GST : \$2,140.00 + (b) LOU : \$300.00 (6days x \$50) + LTA : \$7.45 Total: a+b+c = \$2,447.45 VEH MODEL: TOYOTA VIOS 1497cc PLEASE REVERT WITH YOUR APPROVAL / MANDATE / INSTRUCTIONS, IF ANY.		[A] Asher Sng Rong Yi

Date From



Date To



Audit Type None

Go

ACTIVITY

[12/04/2018 14:12] Lau Shu Pei :
PENDING FINALIZE

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	ALU Type	Acc Name	On Name (Bill-Ctr)	Ref 1	Ref 2	Amount
1740724	06/03/2018 15:01	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SGH9181B		10.70

Print Received Message

This mail is associated with :

***SGH9181B (MCT18020796)**
[SH8311H]

TP

YEO HUIZHEN ESTHER

Feb 23 2018 10:00PM

[COMFORT TRANSPORTATION PTE LTD]

Accord Auto Services Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 09/11/2018 11:26 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$2447.45) - SGH9181B - Claim Handler: Zuhaidah Bte Samsuri

Approved:2447.45.

Drive

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8319277A



Name
FOO SUNG LIM
(HU SONGLIN)
胡松林
Race
CHINESE
Date of birth 23-06-1983 Sex M
Country of birth
SINGAPORE

S0319277A

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: S8319277A

FOO SUNG LIM
(HU SONGLIN)

Birth Date: 23 Jun 1983

Valid Date: 08 Sep 2014



0023432860



4877187

NRIC No S8319277A



Date of issue
28-08-2012

Address
APT BLK 618A PUNGGOL DRIVE
#12-703
SINGAPORE 621618

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES)

EFFECTIVE DATE

Class 1 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver, and other motor vehicles <= 2500kg 08 Sep 2014



Licence No. S8319277A

NP 425A



ACCORD AUTO SERVICES PTE LTD

BLOCK 1009 BUKIT MERAH LANE 3
#01-80 SINGAPORE 159723
TEL: 6271 5133/6271 7433 FAX: 6274 5715
GST Regn No: 201113141K

16 August 2018

India International Insurance Pte Ltd
64 Cecil St #04/#05
IOB Building
Singapore 049711

Attn: Motor Claims Department

Dear Sirs,

ACCIDENT INVOLVING VEHICLE: SGH9181B and SH8311H on 23.2.2018 Along Pasir Ris Drive 8.

We are the authorized repair workshop for the owner of motor vehicle no: **SGH9181B** which was involved in the captioned accident with your insured vehicle: **SH8311H**. The vehicle owner has requested and authorized us to assist him in presenting his/her claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving, we are submitting these claims for your consideration on behalf of the owner/claimant.

01) Cost Of Repair	\$	2,000.00
02) 7% GST	\$	140.00
03) Loss Of Use 4 days @ \$80	\$	320.00
05) Pre-Repair 2 days	\$	200.00
06) GIA/LTA Enquiry Fee	\$	7.45
	\$	2,667.45

We enclosed herewith the following documents to support the claims:-

- | | |
|----------------------------|--|
| a) GIA report | d) Insured & Driver NRIC & Driving License |
| b) Repair Statement AMK435 | e) Letter Of Authority |
| c) GIA/LTA Enquiry Fee | |

Kindly look into the matter and let us hear from you on the settlement of our customer's claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

Thank you
Yours faithfully

ACCORD
AUTO SERVICES PTE LTD

Celia Lai
Accord Auto Services Pte Ltd
Tel: 62717433 / 92740999
Email: avclaims@mycarworkshop.com.sg

LETTER OF AUTHORITY

To Whom It May Concern,

Accident Involving Vehicle: SGH 9181 B & SH 8311 H on 23.2.2018 along
Pasir Ris Drive 8.

I/We, Yeo Hui Zhen, Esther (Yao Huizhen, Esther) NRIC no. S8438409G
of Blk 560 Hougang St 51 # 13-404 Singapore 530560

owner of motor vehicle no. SGH 9181 B do hereby appoint **Accord Auto Services Pte Ltd**
as my/ours authorised representation and _____

as my/ours solicitors to write, to negotiate and settle my/our claims against the other party/parties
involved in the above mentioned accident. I/We, Yeo Hui Zhen, Esther (Yao Huizhen, Esther)
shall have absolute discretion to settle the matter at the best term.

I/We also confirm and instruct that any agreed settlement sum in respect my/our claims be paid
Accord Auto Services Pte Ltd and such payment will be constitute a full and final discharge of my
claims.



Signature of Owner

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

Without Prejudice on Injury Claims

India Ref: MCT18020796
Claimant Ref: SGH 9181B

We/I, ACCORD AUTO SERVICES PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 2,140.00 (repair cost), S\$ 300.00 (loss of use/rental), S\$ 7.45 (search fee), vehicle no. SGH 9181B that was damaged pursuant to the accident which occurred on 23/02/2018 (date) at PABER RES DRIVE 8 (location) involving vehicle no. 5H 8311H (insured vehicle). This is pursuant to the inspection conducted on 05/03/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner YEOW HUIZHEN ESTHER ("the third party claimant") of vehicle no. SGH 9181B to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SGH 9181B (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 2,447.45 to ACCORD AUTO SERVICES PTE LTD

Dated this 4 day of December 20 18

CLAIMANT:

Signature:



Signed by "the workshop" (with chop)

Name:

Accord Auto Services Pte Ltd

NRIC:

20113N61K

Address:

812-009 Bukit Merah Lane 3

01-80 Singapore 159723

Nationality:

Occupation:

WITNESS:

Signature:



KSC

Signed by appointed Surveyor

Name:

LKK AUTO CONSULTANTS PTE LTD

NRIC:

199607198R

Address:

51 UBI AVE 1, PAYA UBI INDUSTRIAL PARK

#02-25 SINGAPORE 408933

Nationality:

Occupation:

ACCORD AUTO SERVICES PTE LTD

BLOCK 1009 BUKIT MERAH LANE 3
#01-80 SINGAPORE 159723
TEL: 6271 5133/6271 7433 FAX: 6274 5715
GST Regn No: 201113141K

Date : 16 Aug 2018

India Internatinal Insurance Pte Ltd
64 Cecil St #04/#05
IOB Building
Singapore 049711

Our Ref No : AMK435
Insured : Yeo HuiZhen Esther
Insured NRIC : S8438409G
Make & Model : Toyota Vios 1.5 E A
DOA : 23.2.2018
Claim Type : Third Party

REPAIR STATEMENT

Re: Vehicle Registration No:

SGH9181B

Cost Of Repair	\$	2,000.00
7% GST	\$	140.00
	<u>\$</u>	<u>2,140.00</u>

Accord Auto Services Pte Ltd

ACCORD
AUTO SERVICES PTE LTD


Land Transport Authority

Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 26 Feb 2018 / 13:35:10

Receipt Date/Time : 26 Feb 2018 / 13:35:10

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180226-001162

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SH8311H As at 23 Feb 2018/22:55:00 Insurance Co: INDIA INT'L INS PTE LTD				
1	Insurance Enquiry - SH8311H Enquiry Fee 20180226133311878707	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	xxxxxxxxxxxx5538	Credit Card: Visa/MasterCard		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Mar 2018 Edit Reg		27 Feb 2018 00:00 Edit Adj Rpt	S\$2,000.00 Edit Estimates	S\$2,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: -								
Main Claimant:	YEO HUIZHEN ESTHER , ID: S8438409G								
Vehicle Reg. No.:	SGH9181B	Date of Loss:	23/02/2018 22:00 - :59 [139 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18020796	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SH8311H	Policy No. (Claimant):	5072493063-02						
		Excess:							
Repairer:	Accord Auto Services Pte Ltd (Bukit Merah) BLK 1009 BUKIT MERAH LANE 3, #01-80, 159723 Bukit Merah - Tel:								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 08/03/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> • III_SG (09/11/2018): Alert - Adj Mandate Approved (S\$2447.45) - SGH9181B - Claim Handler: Zuhaidah Bt... • III_SG (05/03/2018): Alert - Adj Mandate Approved (S\$0.00) - SGH9181B - Claim Handler: Zuhaidah Bte S... 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGH9181B (MCT18020796)
[SH8311H]
TP
YEO HUIZHEN ESTHER
Feb 23 2018 10:00PM
[COMFORT TRANSPORTATION PTE LTD]
Accord Auto Services Pte Ltd

Upload Documents Upload Photos Compose New Letter			View	View in Browser
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/11/18 11:14	General View		Load JPG <input checked="" type="checkbox"/>
2	09/11/18 11:14	General View		Load JPG <input checked="" type="checkbox"/>
3	09/11/18 11:14	General View		Load JPG <input checked="" type="checkbox"/>
4	09/11/18 11:14	General View		Load JPG <input checked="" type="checkbox"/>
5	09/11/18 11:14	General View		Load JPG <input checked="" type="checkbox"/>
6	09/11/18 11:14	General View		Load JPG <input checked="" type="checkbox"/>
7	09/11/18 11:14	General View		Load JPG <input checked="" type="checkbox"/>
8	09/11/18 11:14	General View		Load JPG <input checked="" type="checkbox"/>
9	09/11/18 11:14	General View		Load JPG <input checked="" type="checkbox"/>
10	09/11/18 11:14	General View		Load JPG <input checked="" type="checkbox"/>
11	09/11/18 11:14	General View		Load JPG <input checked="" type="checkbox"/>
12	09/11/18 11:14	Chassis Number		Load JPG <input checked="" type="checkbox"/>
13	09/11/18 11:14	General View		Load JPG <input checked="" type="checkbox"/>
14	09/11/18 11:14	General View		Load JPG <input checked="" type="checkbox"/>
15	09/11/18 11:14	Odometer Reading		Load JPG <input checked="" type="checkbox"/>
16	09/11/18 11:16	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
17	09/11/18 11:16	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
18	09/11/18 11:16	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
19	09/11/18 11:16	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
20	09/11/18 11:16	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
21	09/11/18 11:16	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
22	09/11/18 11:16	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/02/18 19:59	EMAIL FROM III DD 27022018		Load PDF
2	27/02/18 19:59	TP GIA REPORT		Load PDF
3	06/03/18 17:54	TP ESTIMATE- MARKED		Load PDF
4	30/10/18 10:55	WORKSHOP INVOICE		Load PDF
5	30/10/18 10:55	LTA SEARCH		Load PDF
6	30/10/18 10:55	LOD		Load PDF
7	17/12/18 11:13	DISCHARGE VOUCHER		Load PDF
8	17/12/18 11:13	AUTHORISATION TO ACT FORM		Load PDF
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	01/03/18 09:26	Singapore Accident Statement		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
----------------------------	-------	------	-------

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Cd. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18003835/KEB3Q2
Date: 17/12/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No: MCOM0015
Claimant Vehicle No : SGH9181B	Insured Vehicle No : SH8311H
Date of Loss: 23/02/2018	Nature of Claim: TP Claim No: MCT18020796

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGH9181B	Engine No: 1NZX446836
Make & Model: TOYOTA VIOS, 1.5 E (A)	Chassis No: MR053HY4204193716
Reg. Date: 27/06/2006 (Man. Year: 2006)	Odometer: 123508 km
Colour: Metallic Gold	
Engine Capacity: 1497 cc	
Market Value/New Car Price: N/A	
Sum Insured (S\$): Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/50 R14	Rear Tyre Size:	185/50 R14
Front Left Side:	HIFLY 3 mm	Rear Left Side:	HIFLY 7 mm
Front Right Side:	HIFLY 3 mm	Rear Right Side:	HIFLY 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,079.89	1,327.32	1,752.57	56.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,540.00	1,200.00	1,340.00	52.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,619.89	2,527.32	3,092.57	55.03
Approved Total (Overridden) (S\$)		2,000.00		
	(S\$) 5,619.89	2,000.00	3,619.89	64.41
+ GST 7.00/7.00% (S\$)	393.39	140.00	253.39	64.41
Nett Amount (S\$)	6,013.28	2,140.00	3,873.28	64.41
+ Loss of Use (6.0 x S\$50.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,447.45		

INSPECTION

Date of Assignment:	27/02/2018	
Date Inspected:	05/03/2018 Inspected At:	Accord Auto Services Pte Ltd(Bukit Merah) BLK 1009 BUKIT MERAH LANE 3, #01-

80,
159723 Bukit Merah

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 30 Oct 2018)
Parts: 143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGH9181B)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Repair	601.75 FL	*- FL
2	1		*BOOTLID 1.5 EMBLEM	Not Necessary	35.00 FL	*- FL
3	1		*BOOTLID E EMBLEM	Not Necessary	35.00 FL	*- FL
4	1		*BOOTLID VVT-I EMBLEM	Not Necessary	35.00 FL	*- FL
5	1		*BOOTLID VIOS EMBLEM	Not Necessary	35.00 FL	*- FL
6	1		*BOOTLID LOGO	Not Necessary	35.00 FL	*- FL
7	1		*BOOTLID LOCK	Repair	53.10 FL	*- FL
8	1		*BOOTLID STRIKER	Repair	43.90 FL	*- FL
9	1		*BOOTLID WEATHERSTRIP	Serviceable	61.10 FL	*- FL
10	1		*LH TAIL LAMP	Mtg Distorted	281.75 FL	*281.75 FL
11	1		*LH TAIL LAMP SEALANT	Not Necessary	50.00 FL	*- FL
12	2		*LH TAIL LAMP CLIP	Necessary	25.80 FL	*25.80 FL
13	1		*LH TAIL LAMP BASE PANEL	Repair	161.20 FL	*- FL
14	1		*REAR LH FENDER	Repair	544.30 FL	*- FL
15	1		*REAR BUMPER	Buckled	383.80 FL	*383.80 FL
16	1		*REAR BUMPER SIDE RETAINER	N/S Cracked	87.80 FL	*43.90 FL
17	10		*REAR BUMPER CLIP	Necessary	35.00 FL	*35.00 FL
18	1		*REAR BUMPER BRACKET	N/S Bent	86.20 FL	*43.10 FL
19	1		*END PANEL	Bent	689.75 FL	*689.75 FL
20	1		*END PANEL TOP TRIM	Serviceable	67.80 FL	*- FL
21	6		*END PANEL TOP TRIM CLIP	Not Necessary	51.60 FL	*- FL
22	1		*SET REAR BUMPER REVER SENSOR	Shoted	380.00 FS	*200.00 FS
23	1		*REAR BOOTLID COMPARTMENT WATERPROOF SELANT	Not Necessary	150.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 3,929.85 1,703.10
- List Item Discount on L Items 25.00/25.00% (S\$) 849.96 375.78

Total Parts (S\$) 3,079.89 1,327.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING ON ALL AFFECTED AREA	New	1,200.00	500.00
2	LABOUR REMOVE/REFIX ACCIDENT DAMAGES PARTS TO KNOCK ,JACK ,CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	1,000.00	600.00
3	TO APPLY ANTI RUST TREATMENT	New	100.00	30.00
4	TO CHECK WIRING SYSTEM & LIGHT	New	60.00	20.00
5	TO CHECK & ADJUST WHEEL ALIGNMENT	New	60.00	0.00
6	TO REMOVE AND REPLACE REVERSE SENSOR	New	120.00	50.00
Gross Labour Cost (S\$)			2,540.00	1,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >