

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

India International Insurance Pte Ltd
64 Cecil St
#04 #05 IOB Building
Singapore 049711
Attn: Motor Claims Department

*Not Not started
11 Sep 87
Pulvisy After Paint
4 days*

Date : 27/02/2018
Vehicle No : SGH9181B
Veh Make/Model : Toyota Vios 1.5E A
YOM : 2006
Chassis No : MR053HY4204193716
Date of Accident : 23/02/2018

No	Qty	Description	Amount \$
List Items:-			
1	1	Bootlid	\$ R 601.75 X
2	1	Bootlid "1.5" emblem	\$ n 35.00 X
3	1	Bootlid "E" emblem	\$ n 35.00 X
4	1	Bootlid "VVT-I" emblem	\$ n 35.00 X
5	1	Bootlid "VIOS" emblem	\$ n 35.00 X
6	1	Bootlid logo	\$ n 35.00 X
7	1	Bootlid lock	\$ R 53.10 X
8	1	Bootlid striker	\$ R 43.90 X
9	1	Bootlid weatherstrip	\$ Sn 61.10 X
10	1	LH Tail lamp	\$ 281.75 7
11	1	LH Tail lamp sealant	\$ 50.00 7
12	2	LH Tail lamp clip	\$ 25.80 7
13	1	LH Tail lamp base panel	\$ R 161.20 X
14	1	Rear LH fender	\$ R 544.30 X
15	1	Rear bumper	\$ Bn 383.80 C
16	2	Rear bumper side retainer	\$ N/S B 87.80 C
17	10	Rear bumper clip	\$ n 35.00 C
18	2	Rear bumper bracket	\$ N/S B 86.20 C
19	1	End panel	\$ B 689.75 C
20	1	End panel top trim	\$ Sn 67.80 X
21	6	End panel top trim clip	\$ n 51.60 X
Total - List Item			\$ 3,399.85
Less 25%			\$ 849.96
Total			\$ 2,549.89
Special Nett Items:-			
1	1 set	Rear bumper rever sensor	\$ Shert 380.00 2006 X
2	1	Rear bootlid compartment waterproof selant	\$ n 150.00 X
Total - SN Item			\$ 530.00
Balance b/f			\$ 3,079.89

