

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0265/2018/GW
Date : 2-Mar-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Ampalavanar Ratnaraja
Address : Blk 445 Sin Ming Avenue
#05-473
Singapore 570445
Telephone : HP +6581890478
Type of Claim : Own Damage Claim
Policy No. : 1700015962
Vehicle No : **SDU 2319 K**
Model Code : Audi A4 Sedan 1.4 TFSI S
Model / Year : Jun-17
Engine No : CVN 038564
Chassis No : WAUZZZF47HA161671
Mileage : 16011
Date In : 28-Feb-18
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 28-Feb-18
Place of Accident : ANG MO KIO AVE 4 & YIO CHU KANG RD JUNCTION

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDU 2319 K.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function.	S/N \$ 280.00	✓
2	To renew rhs 1/4 glass and rear windscreen to facillitate fender renewal.	S/N \$ 600.00	✓
3	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims, seat belts. Renew roof liner, curtain aig bag all safety belts, and air bag control unit include console box removal and installation.	S/N \$ 3,600.00	✓
4	To remove and renew passenger set back rest.	S/N \$ 360.00	✓
5	To remove and reinstall front suspension for cellette bench repairs.	S/N \$ 2,800.00	?
6	To remove and reinstall rear suspension assembly, including replacement of damaged parts, subframe.	S/N \$ 3,200.00	✓
SUB-TOTAL LABOUR CHARGES		: \$ 10,840.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDU 2319 K.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
7	To remove and reinstall fuel tank assy and rear exhaust systems. Renew damaged components where necessary.	S/N \$ 780.00	✓
8	To place vehicle on cellette bench.	S/N \$ 1,200.00	?
9	To remove rear bumper, rear lid, both lhs front and rear door. Cut out and reweld lhs rear fender, sill panel, rear lhs 'b and c pillar inner reinforcement, rear lhs wheelhouse, and bottom plate. Repair and align floor pan to original factory specification. renew lhs rear door, reinstall all parts removed.	\$ 9,600.00	5500
10	To respray rear bumper, lhs rear fender, lhs rear door, sill panel, drain panel, roof channel, boot floor panel, joint sealer work, end panel.	\$ 3,800.00	3500 3050
11	To remove and renew rhs rear wheel rim, check trye and alignment .	S/N \$ 280.00	✓
12	To remove and reinstall rear wire harness, relay, fuse boxes, audio equipment rhs rear window and lifting mechanism, rhs trims, luggage compartment trims.	S/N \$ 1,600.00	✓
13	To supply solar film on rear windscreen, 1/4 glass and rear lhs door glass	S/N \$ 400.00	?
14	To carry out diagnostic check.	S/N \$ 384.00	✓
TOTAL LABOUR CHARGES		: \$ 28,884.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDU 2319 K.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR DOOR-LH <i>distorted</i>	\$ 1,928.00	✓
2	REAR OUTER DOOR SEAL-LH <i>new</i>	\$ 176.00	✓
3	BONDING AGENT ?	\$ 43.00	?
4	CLEANING SOLUTION ?	\$ 64.00	?
5	SEAL STRIP ?	\$ 14.00	?
6	REAR DOOR ATTACHMENT PARTS-LH ?	\$ 488.00	?
7	REAR DOOR CATCH -LH <i>new</i>	\$ 105.00	X
8	REAR DOOR CATCH COVER-LH <i>new</i>	\$ 12.00	X
9	REAR DOOR HINGE UPPER PART-LH	\$ 40.00	X
10	REAR DOOR HINGE HALVES- LH LOWER <i>new</i>	2 \$ 80.00	✓
11	REAR DOOR HINGE HALVES- LH UPPER	\$ 40.00	X
12	BOOT WITH RETAINING FRAME ?	\$ 39.00	?
13	REAR EXTERIOR DOOR HANDLE-LH <i>missing</i>	\$ 33.00	✓
14	REAR DOOR HANDLE SENSOR-LH <i>new</i>	\$ 200.00	✓
16	REAR DOOR HANDLE TRIM PLATE-LH <i>new</i>	\$ 22.00	✓
17	REAR DOOR LAMP-LH ?	\$ 64.00	?
18	REAR DOOR MOUNTING BAR-LH ?	\$ 143.00	?
19	REAR DOOR LOCK-LH <i>new</i>	\$ 580.00	✓
20	REAR DOOR STRIKER-LH ?	\$ 66.00	?
SUB-TOTAL SPARE PARTS		\$ 4,137.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDU 2319 K.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	REAR DOOR BOWDEN CABLE-LH <i>new</i>	\$ 34.00	*
22	REAR DOOR INNER PANEL COVER-LH ?	\$ 29.00	?
23	REAR WINDOW TRIM STRIP-LH <i>new</i>	\$ 205.00	*
24	B-PILLAR TRIM } <i>new</i>	\$ 122.00	*
25	C-PILLAR TRIM }	\$ 122.00	*
26	REAR SIDE WINDOW GUIDE RAIL-LH <i>new</i>	\$ 62.00	*
27	REAR WINDOW GUIDE-LH ?	\$ 392.00	?
28	REAR WINDOW APERTURE SEAL-LH <i>new</i>	\$ 97.00	*
29	REAR WINDOW REGULATOR WITHOUT MOTOR-LH ?	\$ 242.00	?
30	REAR WINDOW REGULATOR MOTOR-LH ?	\$ 297.00	?
31	REAR BASS LOUDSPEAKER } <i>new</i>	\$ 88.00	*
32	REAR TREBLE SPEAKER }	\$ 77.00	*
33	REAR DOOR TRIM-LH ?	\$ 1,551.00	?
34	REAR ARM REST-LH <i>new</i>	\$ 543.00	*
35	REAR TRIM SWITCH -LH <i>new</i>	\$ 70.00	*
36	REAR INNER ACTUATOR WITH LIGHT-LH ?	\$ 208.00	?
37	REAR TRIM INSERT -LH ?	\$ 467.00	?
38	REAR LOUDSPEAKER TRIM-LH <i>new</i>	\$ 76.00	*
39	REAR HANDLE SHELL -LH ?	\$ 171.00	?
40	REAR HANDLE SHELL SEAL-LH ?	\$ 11.00	?
SUB-TOTAL SPARE PARTS		\$ 4,864.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDU 2319 K.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
41	REAR DOOR WINDOW TRIM-LH ?	\$ 116.00	?
42	REAR WINDOW SEAL-LH <i>new</i>	\$ 11.00	✓
43	REAR DOOR LIGHT BAR-LH ?	\$ 35.00	?
44	REAR DOOR LED MODULE-LH ?	\$ 31.00	?
45	REAR DOOR LIGHT -LH ?	\$ 64.00	?
46	SIDE PANEL FRAME-LH <i>Distorted</i>	\$ 2,787.00	✓
47	SIDE MEMBER SECTIONAL PART-LH <i>Distorted Repair</i>	\$ 1,907.00	✓
48	SIDE MEMBER WEBPLATE ?	\$ 131.00	?
49	NOISE INSULATION PLATE ?	\$ 11.00	?
50	REINFORCEMENT C- PILLAR ?	\$ 179.00	?
51	PANEL FILLER PLATE -LH ?	\$ 171.00	?
52	LOCK PILLAR REINFORCEMENT INSULATOR <i>new</i>	\$ 8.00	✓
53	REAR WHEEL HOUSING-LH <i>Repair</i>	\$ 545.00	✓
54	REAR B-PILLAR-LH ?	\$ 490.00	?
55	REAR WHEEL HOUSING LINER -LH <i>tom</i>	\$ 215.00	✓
56	WHEEL HOUSING LINER ATTACHMENT PART ?	\$ 78.00	?
57	REAR BUMPER COVER <i>Del</i>	\$ 1,907.00	✓
58	REAR BUMPER FIXING PART <i>new</i>	\$ 63.00	✓
59	REAR SPOILER ?	\$ 216.00	?
60	REAR LIGHT REFLECTOR-LH <i>new</i>	\$ 35.00	✓
SUB TOTAL SPARE PARTS		\$ 9,000.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDU 2319 K.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
61	REAR BUMPER UPPER GUIDE-LH <i>3 new</i>	\$ 37.00	+
62	REAR BUMPER LOWER GUIDE-LH	\$ 19.00	+
63	REAR SIDE WINDOW-LH ?	\$ 541.00	?
64	REAR WINDOW ?	\$ 1,014.00	?
65	PRIMER <i>2 new</i>	2 \$ 38.00	✓
66	HEAD AIRBAG UNIT -LH/RH <i>2 new Activated</i>	2 \$ 3,384.00	✓
67	CURTAIN AIR BAG BRACKET-LH/RH <i>2 new</i>	2 \$ 84.00	✓
68	SIDE AIRBAG UNIT-LH <i>Activated</i>	\$ 1,378.00	✓
69	BACKREST COVER-LH <i>torn</i>	\$ 2,142.00	✓
70	ROOF LINER <i>crushed</i>	\$ 1,682.00	✓
71	AIR BAG CONTROL UNIT <i>Activated</i>	\$ 1,870.00	✓
72	REAR AIR BAG CRASH SENSOR <i>3 Activated</i>	\$ 273.00	✓
73	THREE-PONT AUTOMATIC SEAT BELT-LH/RH	2 \$ 1,912.00	✓
74	SEAT BELT HEIGHT ADJUSTER ?	2 \$ 306.00	?
75	THREE-POINT SEAT BELT WITH INERTIAL REEL <i>Activated</i>	\$ 461.00	✓
76	SEAT BELT GUIDE-LH/RH ?	2 \$ 172.00	?
77	SEAT BELT COVER ?	\$ 47.00	?
78	DOUBLE BELT LATCH-LH ?	\$ 223.00	?
79	TRIM B- PILLAR -LH LOWER <i>3 new</i>	\$ 135.00	x
80	TRIM B- PILLAR -LH UPPER <i>3 new</i>	\$ 206.00	+
SUB -TOTAL SPARE PARTS		\$ 15,924.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDU 2319 K.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
81	REAR WHEEL HOUSING TRIM-LH <i>new</i>	\$ 132.00	<i>✓</i>
82	C-PILLAR TRIM-LH <i>new</i>	\$ 190.00	<i>✓</i>
83	D-PILLAR TRIM -LH <i>new</i>	\$ 202.00	<i>✓</i>
84	A-PILLAR TRIM -LH/RH UPPER ?	\$ 360.00	?
85	REAR ALUMINIUM RIM -LH <i>new</i>	\$ 563.00	<i>✓</i>
86	REAR ALUMINIUM HUB CAP-LH <i>new</i>	\$ 87.00	<i>✓</i>
87	REAR GAS SHOCKER ABSORBER-LH ?	\$ 260.00	?
88	REAR ANTI ROLL STABILIZER ?	\$ 358.00	?
89	REAR STABILIZER TIE ROD ?	\$ 77.00	?
90	REAR WISHBONE ALUMINIUM-LOWER ?	\$ 762.00	?
91	REAR TRACK BAR -LH ?	\$ 109.00	?
92	REAR WISHBONE-LH UPPER ?	\$ 492.00	?
93	REAR WHEEL BEARING HOUSING-LH ?	\$ 868.00	?
94	REAR WHEEL BEARING WITH ASSEMBLY PARTS-LH ?	\$ 394.00	?
95	REAR TRACK ROD -LH ?	\$ 149.00	?
96	REAR LATERAL ARM-LH ?	\$ 395.00	?
97	REAR STONE CHIP GUARD-LH <i>new</i>	\$ 38.00	<i>✓</i>
98	SOLID LUBRICANT PASTE <i>new</i>	\$ 39.00	<i>✓</i>
99	REAR SUBFRAME ?	\$ 2,804.00	?
100	REAR SUBFRAME BUSHING ?	2 \$ 121.00	?
SUB-TOTAL SPARE PARTS		\$ 8,400.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDU 2319 K.

S/N	Parts Description	Damage Parts & Prices		REMARKS
		S/NETT		
101	REAR SUSPENSION FRAME MOUNTING ?	2 \$	203.00	?
102	TYRE CONTI CONTACT 5 205/60/16 <i>Rehamed</i>	S/N \$	250.00	✓
103	ACRYLIC SEALER	S/N \$	360.00	✓
104	CAVITY WAX	S/N \$	280.00	✓
105	STONE CHIP	S/N \$	180.00	✓
106	METAL FILLER	S/N \$	280.00	✓
107	WINDSCREEN SEAL	S/N \$	200.00	✓
108	1/4 GLASS SEAL	S/N \$	100.00	✓
109	SUNDRIES ?	\$	1,000.00	?
TOTAL SPARE PARTS		:	\$ 45,178.00	
TOTAL LABOUR CHARGES		:	\$ 28,884.00	
GRAND TOTAL		:	\$ 74,062.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

:

Adrian Lj

Surveyed Date

:

05/03/18

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

:

Not Authorised, 28 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant