

REF: CC3 / ALH18003840 / Amber

OK

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

☒ QD / TP / WS / TP RES / QD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. 17000 15962

Claims No. _____

Sum Insured: _____ Excess: 600

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 150K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 35 47 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SD42319K Yr Regn: 2017 June

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Audi A4 cc 1395

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 16011 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAN22ZF47HA161671

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orMod: Nil / S/Rim ☒ STD A/Rim or

Tyre Size: F: 205/60R16

R: 205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. 28/2/18 D.O.I. 05/03/18

Survey held at Premium

Des. of Damages: Frt / Rear / O/S ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

25/10/19 @ 515pm Carline call up Tailamp outer RHS - X

11/11/19 Final fig \$ 58,151.80 (Red 25,995, 319) confirmed by email

RECEIVED 1 NOV 2019

Lump Sum / I.B.I: (\$ 58,151.80

☐ Weekend (\$ _____)

TOTAL

211

REF: CC3/AH18003840 / Amber

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

17000 15962

Claims No: _____

Sum Insured: _____

Excess: _____

600

(Client's Record)

Make of Veh: _____

Veh No: SD42319K

Yr Regn: 2017 June

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A4

CC 1395

Colour: Black

A/C: Insured / Std / NI / NA

Sp. Reading 16011

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

WAU222F47HA161671

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orMod: Nil / S/Rim ☒ STD A/Rim or

Tire Size: F: _____

205/60R16

Excess	\$0.00	Claim No.	
Amount / Coverage	\$0.00	Policy No.	
Veh. Inspected	SGH 6710U	Insured	
1. Policy Particulars :- THIRD PARTY CLAIM			
AUTOMOBILE INSPECTION REPORT			
Ref : S/TP/1527/06KC	Date : 05/10/2006	Code : QW007	
ER CHIAN MENG C/O: COMFORTDELGRO ENGINEERING PTE LTD 205 BRADDELL ROAD SINGAPORE 579701			
(Affiliated to Federation Internationale Des Experts En Automobiles)			

51 Ubi Ave 1, #01-25 Paya Ubi Industrial Park, Singapore 408933.
TEL: 6256 3561 FAX: 6256 4315

LKK SURVEY SERVICES

6/3/18 Revert by merimen
 6/3/18 Recd approved \$43,102 from Victor by merimen
 MV: 150K
 PV: 60.7K
 Net: 89.3K

6/3/18 Informed Nora CIA & \$600 by email

Date: 2/10/18

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair: 40

1)

☐

Final Report

Resurvey No. of Trip: 4

Survey Fee:

Date/Time, File Return to?

Transportation:

2) 20/11 - Typist

Add Fee: ☐ Site Insp (\$

3 - RS - \$

☐ Interview (\$

Phone

☐ Tech. Invs (\$

Other

☐ Weekend (\$

)

Report Format: merimen

Lump Sum / I.B.I: \$ 58,151.80

TOTAL

200

11

211



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG18003840/Avb

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 28-02-2018



Code : AIG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SDU 2319K
Policy No. 1700015962	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	05/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	28/01/2018	Inspection Date	05/03/2018
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1, SINGAPORE 408699		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

View Received Message

This mail is associated with :

***SDU2319K (2899090302SG)**

OD

Feb 28 2018 6:00AM

[AMPALAVANAR RATNARAJA]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 11/11/2019 13:27 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$58151.80) - SDU2319K - Claim Handler: Mohd Zawaye, Norsazani

Approved:58151.80:

DOCUMENTS SUMMARY

There are no documents.

Veron Chen (LKKAUTO)

From: Claims <claims@premiumauto.com.sg>
Sent: Thursday, 27 December 2018 5:53 PM
To: Veron Chen (LKKAUTO); 'Nora Khai'
Cc: SUR; claims@premiumauto.com.sg; 'Boo seng yak';
carrine.leong@premiumauto.com.sg
Subject: RE: SDU 2319 K - Own Damage Claim- DOA: 28/2/2018

Dear Veron,

Yes, This vehicle has been repaired. We will submit finalisation ASAP.

Aside to Mr. Boo,

FYI.

Thank you.

Best Regards,
Tony Foong
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



http://www.audi.com.sg/sea/brand/sg/audi_promotions/promotions/car_promotions/new-audi-q2-2017.html

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Thursday, 27 December, 2018 5:51 PM
To: Nora Khai <nora.khai@premiumauto.com.sg>; claims@premiumauto.com.sg
Cc: SUR <sur@lkkauto.com>
Subject: RE: SDU 2319 K - Own Damage Claim- DOA: 28/2/2018

Dear Nora,

Kindly advise vehicle status.

Vehicle has been repaired ?

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Tuesday, 6 March 2018 5:14 PM

To: 'Nora Khai' <nora.khai@premiumauto.com.sg>; claims@premiumauto.com.sg

Cc: SUR <sur@lkkauto.com>

Subject: FW: SDU 2319 K - Own Damage Claim- DOA: 28/2/2018

Dear Nora,

As instructed by our client AIG , please proceed to repair the insured vehicle **SDU 2319K (Excess \$600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Kindly assist to ask insured fill up the document attach.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Tuesday, 6 March 2018 11:03 AM

To: 'Nora Khai' <nora.khai@premiumauto.com.sg>; SUR <sur@lkkauto.com>

Cc: claims@premiumauto.com.sg

Subject: RE: SDU 2319 K - Own Damage Claim

Dear Nora,

Kindly assist to ask insured fill up the document attach.

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Nora Khai [mailto:nora.khai@premiumauto.com.sg]
Sent: Monday, 5 March 2018 4:29 PM
To: SUR <sur@lkkauto.com>
Cc: claims@premiumauto.com.sg
Subject: SDU 2319 K - Own Damage Claim
Importance: High

Dear All,

Kindly assist for Own Damage Claim approval. Vehicle has been surveyed by Adrian this morning.

Thank you.

Best Regards,

Norazima Khairuddin
Claims Manager

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9827 f. +65 6841 1183 e. nora.khai@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65
6836 2223

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

-----Original Message-----

From: copierscan@premiumauto.com.sg [mailto:copierscan@premiumauto.com.sg]
Sent: 05 March, 2018 4:32 PM
To: claims@premiumauto.com.sg
Subject: Aftersales-SA

Scan 2 Email
-Service Advisor
-Claim

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 8 March 2018 11:15 AM
To: 'Zawaye, Norsazani'
Cc: SUR
Subject: RE: OD / 2899090302SG / SDU2319K -midnight case

Dear Norsazani Zawaye,

Interview form and undertaking uploaded in merimen.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Zawaye, Norsazani [mailto:Norsazani.Zawaye@aig.com]
Sent: Tuesday, 6 March 2018 1:14 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: OD / 2899090302SG / SDU2319K -midnight case

Hi Veron,

Noted with thanks.

Thanks & Regards,

Norsazani Zawaye

AIG

Claims Adjuster | Express Auto Claims

Singapore Claims | AIG Shared Services

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]
Sent: Tuesday, March 06, 2018 12:50 PM
To: Zawaye, Norsazani
Cc: SUR
Subject: RE: OD / 2899090302SG / SDU2319K -midnight case

Dear Norsazani Zawaye,

We are unable to provide the video footage as we did not inspect the TP vehicle.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

From: Zawaye, Norsazani [mailto:Norsazani.Zawaye@aig.com]
Sent: Tuesday, 6 March 2018 10:44 AM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: RE: OD / 2899090302SG / SDU2319K -midnight case

Hi Veron,

As I checking TP GIA report had mention that they have video footage.

Kindly assist to retrieve and upload in merimen.

Thanks & Regards,

Norsazani Zawaye
AIG
Claims Adjuster | Express Auto Claims
Singapore Claims | AIG Shared Services

From: Zawaye, Norsazani
Sent: Tuesday, March 06, 2018 10:41 AM
To: 'Veron Chen (LKKAuto)'
Subject: OD / 2899090302SG / SDU2319K -midnight case

Hi Veron,

Kindly assist to ask insured fill up the document attach and upload in merimen.

This midnight case require this document.

Thanks & Regards,

Norsazani Zawaye
AIG
Claims Adjuster | Express Auto Claims
Singapore Claims | AIG Shared Services

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 6 March 2018 5:14 PM
To: 'Nora Khai'; claims@premiumauto.com.sg
Cc: SUR
Subject: FW: SDU 2319 K - Own Damage Claim- DOA: 28/2/2018
Attachments: Interview Form OD.PDF; OD Letter of Undertaking.pdf

Dear Nora,

As instructed by our client AIG , please proceed to repair the insured vehicle **SDU 2319K (Excess \$600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Kindly assist to ask insured fill up the document attach.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 6 March 2018 11:03 AM
To: 'Nora Khai' <nora.khai@premiumauto.com.sg>; SUR <sur@lkkauto.com>
Cc: claims@premiumauto.com.sg
Subject: RE: SDU 2319 K - Own Damage Claim

Dear Nora,

Kindly assist to ask insured fill up the document attach.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Nora Khai [mailto:nora.khai@premiumauto.com.sg]

Sent: Monday, 5 March 2018 4:29 PM

To: SUR <sur@lkkauto.com>

Cc: claims@premiumauto.com.sg

Subject: SDU 2319 K - Own Damage Claim

Importance: High

Dear All,

Kindly assist for Own Damage Claim approval. Vehicle has been surveyed by Adrian this morning.

Thank you.

Best Regards,

Norazima Khairuddin

Claims Manager

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9827 f. +65 6841 1183 e. nora.khai@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65

6836 2223

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

-----Original Message-----

From: copierscan@premiumauto.com.sg [mailto:copierscan@premiumauto.com.sg]

Sent: 05 March, 2018 4:32 PM

To: claims@premiumauto.com.sg

Subject: Aftersales-SA

Scan 2 Email

-Service Advisor

-Claim

View Sent Message

This mail is associated with :

***SDU2319K (2899090302SG)**

OD

Feb 28 2018 6:00AM

[AMPALAVANAR RATNARAJA]

Premium Automobiles Pte Ltd

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 06/03/2018 17:04 PM.

To AIG_SG; Victor_KohCK

Subject Re: Alert - Adj Mandate Approved (S\$43102.00) - SDU2319K - Claim Handler: Mohd Zawaye, Norsazani

Dear Sir/Madam,

Please note that 11 days of labour includes the replacement of rear fender, rear door, rear bumper and SILL PANEL.

However, in this case, the rear fender and sill panel come as a piece as reflected in Item No 46. (Side Panel Frame).

Hope that the above clarifies matter.

Best Regards,
Veron Chen

<-- Original Message -->

From: AIG_SG

To: LKK_HQ

Sent On: 06/03/2018 02:15 PM

Subject: Alert - Adj Mandate Approved (S\$43102.00) - SDU2319K - Claim Handler: Mohd Zawaye, Norsazani

Approved:43102.00:Why labour 11 days needed to replace Rear fender, LH rear door, Rear bumper, kindly re-adjust your labour, Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

***SDU2319K (28990903025G)**

OD

Feb 28 2018 6:00AM

[AMPALAVANAR RATNARAJA]

Premium Automobiles Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 06/03/2018 14:15 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$43102.00) - SDU2319K - Claim Handler: Mohd Zawaye, Norsazani

Approved:43102.00:Why labour 11 days needed to replace Rear fender, LH rear door, Rear bumper, kindly re-adjust your labour. Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

Please note that 11 days of labour includes the replacement of rear fender, rear door, rear bumper and SILL PANEL.

However, in this case, the rear fender and sill panel come as a piece as reflected in item No 46 (Side Panel Frame),

Hope that the above clarifies matter.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 6 March 2018 12:50 PM
To: 'Zawaye, Norsazani'
Cc: SUR
Subject: RE: OD / 2899090302SG / SDU2319K -midnight case

Dear Norsazani Zawaye,

We are unable to provide the video footage as we did not inspect the TP vehicle.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Zawaye, Norsazani [mailto:Norsazani.Zawaye@aig.com]
Sent: Tuesday, 6 March 2018 10:44 AM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: RE: OD / 2899090302SG / SDU2319K -midnight case

Hi Veron,

As I checking TP GIA report had mention that they have video footage.

Kindly assist to retrieve and upload in merimen.

Thanks & Regards,

Norsazani Zawaye
AIG
Claims Adjuster | Express Auto Claims
Singapore Claims | AIG Shared Services

From: Zawaye, Norsazani
Sent: Tuesday, March 06, 2018 10:41 AM
To: 'Veron Chen (LKKAuto)'
Subject: OD / 2899090302SG / SDU2319K -midnight case

Hi Veron,

Kindly assist to ask insured fill up the document attach and upload in merimen.

This midnight case require this document.

Thanks & Regards,

Norsazani Zawaye

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To:	AIG Asia Pacific Insurance Pte. Ltd. AIG Building 78 Shenton Way #07-16 Singapore 079120	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	Kesaval, Jaclyn-M	Date:	06 Mar 2018
<u>Preliminary Advice</u>			

Vehicle No	: SDU2319K	Accident Date	: 28/02/2018
Make	: AUDI A4	Policy No.	: 1700015962
Assignment Date	: 05/03/2018	Excess	: S\$0.00
Date of Inspection	: 05/03/2018	Est. Duration of Repair	: 28.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	74,062.00
Revised Amount	:S\$	43,102.00
Check Items (Estimated)	:S\$	20,866.00
Total	:S\$	63,968.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	150,000.00
COE / PARF Rebate	:S\$	67,174.00
Salvage Value	:S\$	
Margin for Repair	:S\$	82,826.00

Remarks

☒	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
☐	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
☐	Other comments :

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4733A
Vehicle Details	
Vehicle No.:	SDU2319K
Vehicle to be Exported:	No
Intended De-registration Date:	06 Mar 2018
Vehicle Make:	AUDI
Vehicle Model:	A4 1.4 TFSI S TRONIC (NAV)
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	CVN038564
Chassis No.:	WAUZZZF47HA161671
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$32,490.00
Original Registration Date:	22 Jun 2017
First Registration Date:	22 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$27,486.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Jun 2027
PARF Rebate Amount:	\$20,614.00
Intended COE Rebate Details	
COE Expiry Date:	21 Jun 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)

COE Period(Years):	10
QP Paid:	\$50,110.00
COE Rebate Amount:	\$46,560.00
Total Rebate Amount:	\$67,174.00

The information contained herein is correct as at 06 Mar 2018

OK

CHEAPEST CAR INSURANCE RENEWAL

Choice of
\$0 excessOptions of any
workshop

GET A CHEAPER QUOTE NOW!

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Mercedes-Benz B-Class B180 Style On Offer. Call Now



Lowest Price in Town! 100km
Call: 96466666, 96466666
Speedo Motoring

HIN LUNG AUTO
Ho Bee Group
One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars
30 years of car sale

Browse by Category

Sort by Date Posted 20 results/page

5 vehicles

Audi A4

Advanced Search

Photo	Model	Price	Depreciation	Reg. Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Audi A4	Any	Any	2017	Any	Any	Any	Available

**Audi A4 1.4A TFSI S-tronic**

\$135,800

\$13,770 /yr

18-Jan-2017

1,395 cc

28,000 km

Luxury

Available

5 Years Agent Warranty! Free Servicing Up To 45k Mileage. With The Apple Car Play, Consignment Unit, High Loan/Insurance Available. Trade-in Welcome, Strictly By Appointment.

Posted: 01-Mar-2018 Tags: 2017 Audi A4, Audi A4, Audi, A4, Used Audi

PREMIER AG

**Audi A4 1.4A TFSI S-tronic**

\$142,800

\$14,380 /yr

28-Feb-2017

1,395 cc

13,000 km

Luxury

Available

1 Owner, Agent Warranty Till Feb 2022 With Unlimited Mileage. Free Servicing Till Feb 2020 Or 45k Mileage. Servicing To Be Done Every 15k Km Or 1 Year. Petrol Consumption 19km Per Litre. Chrome Front ...

Prem Roy Motoring

Posted: 23-Feb-2018 Tags: 2017 Audi A4, Audi A4, Audi, A4, Used Audi

CONSUMER

**Audi A4 1.4A TFSI S-tronic**

\$143,800

\$14,350 /yr

11-Mar-2017

1,395 cc

19,000 km

Luxury

Available

1 Owner, Accident Free, Agent 5 Years Warranty, Free Servicing Till 45k Mileage. Well Maintained, Mostly Sheltered Parking. Viewing By Appointment. Please SMS/Call Now!

Posted: 02-Mar-2018 Tags: 2017 Audi A4, Audi A4, Audi, A4, Used Audi

**Audi A4 1.4A TFSI S-tronic**

\$153,888

\$14,950 /yr

25-Jul-2017

1,395 cc

10,000 km

Luxury

Available

Rare 1.4Turbo A4 As Premium Is No Longer Selling The 1.4T Variant. Comes With 3 Year Servicing + 5 Year Warranty With Premium Auto. Selling The Car To Switch To SUV For My 2 Little Ones.

Posted: 12-Feb-2018 Tags: 2017 Audi A4, Audi A4, Audi, A4, Used Audi

DIRECT OWNER

Car Buying

Car Selling

Car Aftermarket

Buying a pre-owned car, but unsure of its Condition?

Car Ownership

On The Move

Lifestyle

STA Car Evaluation

**Audi A4 1.4A TFSI S-tronic**

\$153,900

\$14,560 /yr

25-Oct-2017

1,395 cc

2,800 km

Luxury

Available

Sporty Red Audi A4, Excellent And Original Condition, Well Maintained Interior And Exterior, Call Now For Viewing.

Posted: 20-Feb-2018 Tags: 2017 Audi A4, Audi A4, Audi, A4, Used Audi

DIRECT OWNER

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg. Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	-----------	---------	---------	----------	--------

For old advertisements, view Expired ads

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars, or station wagons, SUVs, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Audi A4, Audi A4 Singapore, used Audi A4 Singapore, used Audi A4, used vehicles Singapore or even buy used Audi A4 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.



Name of Policyholder : AMPALAVANAR RATNARAJA
Period of Insurance : 22 Jun 2017 To 21 Jun 2018
Engine No. : CVN038564
Chassis No. : WAUZZZF47HA161671

Vehicle No. : SDU2319K
Policy No. : 1700015962
Endorsement No. :
Issued Date : 25 Jul 2017

Make/Model	AUDI A4 1.4 TFSI S tronic		
Engine Capacity/Tonnage	1,395.00 CC	Sum Insured	Market Value
Driver Restriction	NA	Off Peak Car	No
		First Year of Registration	2017
		Insuring with COE/PARF	Yes

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorized Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use (15 days)

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

Section 1
Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

AMPALAVANAR RATNARAJA - \$600 (Ovm Damage)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408689 63662329

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6336 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

[We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).]

0604125267

PREMIUM LEASING -TUC
281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938
Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Manila

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

5152014

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/02/2018 16:00
Date Of Accident	28/02/2018 06:20
Exact Location Of Accident	ANG MO KIO AVE 4 & YIO CHU KANG RD JUNCTION
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDU2319K
Insured/Policyholder	
Name Of Registered Owner	AMPALAVANAR RATNARAJA
NRIC No	S1324733A
Email Address	RATNA9009@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90090766
Alternative Phone No	HOME-64557927

Vehicle Particulars

Manufacturer	AUDI
Model	A4 SEDAN 1.4 TFSI S
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700015962
Cover Note Number	

Driver

Name of Driver	VIMALA D/O PUNNIAMOORTHY MRS. VIMALA RATNARAJA
NRIC No	S1667722A
Date Of Birth	16/04/1964
Occupation	INDOOR
Date Of Driving Pass	29/10/2004
Driving Experience	13 YEARS AND 4 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91839091
Fax Number	
Contact Number	
EMail Address	RATNA9009@GMAIL.COM

Address	BLK 445 SIN MING AVENUE #05-473
Postcode	570445
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS WAITING AT THE JUNCTION OF YIO CHU KANG ROAD AND ANG MO KIO AVE 4. THE LIGHT WAS GREEN WHEN I PROCEEDED TO TURN RIGHT TO AMK AVE 4. SUDDENLY, THERE WAS A CAR ON MY SIDE AND WAS TOO LATE TO REACT. THE CAR HIT MY REAR LEFT DOOR.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJW1309P
Vehicle Make/Model/Colour	KIA CERATO
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	JUAY CHIEW JOO
NRIC/Passport Number	S8209605A
Contact Number	96458167
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Lin Ka Sen
NRIC/IN No.: 68055949



SKETCH PLAN



A. SDU2319K
B. SJW1309P

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was waiting at the junction of Yio Chu Kang Road and Ang Mo Kio Ave 4. The light was green when I ~~proceed~~ proceeded to turn right to Amk Ave 4. Suddenly there was a car on my side and was too late to react. The car hit ~~to~~^{my} rear left door.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature _____

(If driver is not the policyholder)

Date & Time:



Reporting Centre Personnel's Signature

Name: Sec.

NRIC/TIN No. 6-25-CT-1804

Accident Photo





AIG Asia Pacific Insurance Pte. Ltd
AIG Building
78 Shenton Way
#07-16

MOTOR ACCIDENT INTERVIEW FORM

NAME : VIMALA RATNARAJA
VEHICLE NUMBER : SDU2319K
DATE/ TIME OF ACCIDENT : 28/2/18 0620
PLACE OF ACCIDENT : Junction of Yi. Chu kang & A.M.K. Ave 4
THIRD PARTY VEHICLE (IF ANY) : SJW1309P

.....
WHERE DID YOU START YOUR JOURNEY AND WHERE WAS THE INTENDED DESTINATION BEFORE THE ACCIDENT?

I started from my home at Blk 445, Jin Ming Ave.
I am a teacher and was heading for my School,
Anderson Primary School at A.M.K. Ave 9.

DID YOU DRINK ANY ALCOHOLIC DRINKS BEFORE YOU DRIVE ON THE DAY OF THE ACCIDENT? IF YES, DID THE TRAFFIC POLICE CONDUCT ANY BREATHE-ANALYSER TEST ON YOU? IF YES, WHAT WAS THE RESULTS?

NO.

WHAT IS THE TYPE OF COLLISION AND THE EXTENSIVENESS OF THE DAMAGES TO ALL VEHICLES INVOLVED?

Cross Junction Collision.
Damage to the rear left door, rim,
fender & suspension

WERE YOU OR YOUR PASSENGER/S INJURED? IF INJURED, WHICH HOSPITAL? WERE YOU TAKEN TO THE TRAFFIC POLICE FOR INVESTIGATION?

No I was not injured and there were
no passengers in my vehicle

VIMALA RATNARAJA

NAME:

I AFFIRMED THE ABOVE INFORMATION IS GIVEN TO MY BEST KNOWLEDGE

UNDERTAKING

I, VIMALA RATNARAJA, (NRIC No. S1667722A), hereby confirm that the Singapore Accident Statement lodged by me on 28/2/18 at 1430 hours pertaining to the accident involving motor car Reg. No: SDU2319K, in which I was the driver are true and accurate to the best of my knowledge, information and belief.

I acknowledge that my insurers are not liable under the contract of insurance if there is a breach of policy terms and conditions.

In the event that an unrelated/unreported third party property or injury claim arises or there is evidence emerges that there is a breach of policy terms and conditions, I irrevocably undertake to absolve my insurer from all liability under the contract of insurance and I undertake to re-pay any sums paid by my insurers pursuant to the contract of insurance upon receipt of written demand by my insurers.

Signature : Vimala
Name of Insured / Driver : VIMALA RATNARAJA
Nric No. : S1667722A
Date : 6/3/18

Signature : [Signature]
Name of Policyholder : AMPALAVANAR RATNARAJA
Nric No. : S1324733A
Date : 6/3/18

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0265/2018/GW
Date	:	2-Mar-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Ampalavanar Ratnaraja
Address	:	Blk 445 Sin Ming Avenue #05-473 Singapore 570445
Telephone	:	HP +6581890478
Type of Claim	:	Own Damage Claim
Policy No.	:	1700015962
Vehicle No	:	SDU 2319 K
Model Code	:	Audi A4 Sedan 1.4 TFSI S
Model / Year	:	Jun-17
Engine No	:	CVN 038564
Chassis No	:	WAUZZZF47HA161671
Mileage	:	16011
Date In	:	28-Feb-18
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	28-Feb-18
Place of Accident	:	ANG MO KIO AVE 4 & YIO CHU KANG RD JUNCTION

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDU 2319 K.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function.	S/N \$ 280.00 ✓	✓
2	To renew rhs 1/4 glass and rear windscreen to facillitate fender renewal.	S/N \$ 600.00 ✓	✓
3	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims, seat belts. Renew roof liner, curtain aig bag all safety belts, and air bag control unit include console box removal and reinstallation.	S/N \$ 3,600.00 ✓	✓
4	To remove and renew passenger set back rest.	S/N \$ 360.00 ✓	✓
5	To remove and reinstall front suspension for cellette bench repairs.	S/N \$ 2,800.00 ?	✗
6	To remove and reinstall rear suspension assembly, including replacement of damaged parts, subframe.	S/N \$ 3,200.00 ✓	✓
SUB-TOTAL LABOUR CHARGES		: \$ 10,840.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDU 2319 K.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
7	To remove and reinstall fuel tank assy and rear exhaust systems. Renew damaged components where necessary.	S/N \$ 780.00	✓
8	To place vehicle on cellette bench.	S/N \$ 1,200.00	✓
9	To remove rear bumper, rear lid, both lhs front and rear door. Cut out and reweld lhs rear fender, sill panel, rear lhs 'b and c pillar inner reinforcement, rear lhs wheelhouse, and bottom plate. Repair and align floor pan to original factory specification. renew lhs rear door, reinstall all parts removed.	\$ 9,600.00	5500 7000
10	To respray rear bumper, lhs rear fender, lhs rear door, sill panel, drain panel, roof channel, boot floor panel, joint sealer work, end panel.	\$ 3,800.00	3050, 3350
11	To remove and renew rhs rear wheel rim, check trye and alignment.	S/N \$ 280.00	✓
12	To remove and reinstall rear wire harness, relay, fuse boxes, audio equipment rhs rear window and lifting mechanism, rhs trims, luggage compartment trims.	S/N \$ 1,600.00	✓
13	To supply solar film on rear windscreen, 1/4 glass and rear lhs door glass	S/N \$ 400.00	✓
14	To carry out diagnostic check.	S/N \$ 384.00	✓
TOTAL LABOUR CHARGES		: \$ 28,884.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDU 2319 K.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR DOOR-LH <i>Distorted</i>	\$ 1,928.00	✓ 1543.40
2	REAR OUTER DOOR SEAL-LH <i>new</i>	\$ 176.00	✓ 140.40
3	BONDING AGENT <i>new</i>	\$ 43.00	? 34.16
4	CLEANING SOLUTION <i>new</i>	\$ 64.00	? X
5	SEAL STRIP <i>new</i>	\$ 14.00	? X
6	REAR DOOR ATTACHMENT PARTS-LH <i>new</i>	\$ 488.00	? X
7	REAR DOOR CATCH -LH <i>new But</i>	\$ 105.00	184
8	REAR DOOR CATCH COVER-LH <i>new Dmgd.</i>	\$ 12.00	19.04
9	REAR DOOR HINGE UPPER PART-LH <i>2 But</i>	\$ 40.00	31.68
10	REAR DOOR HINGE HALVES- LH LOWER <i>new</i>	2 \$ 80.00	63.12
11	REAR DOOR HINGE HALVES- LH UPPER	\$ 40.00	31.68
12	BOOT WITH RETAINING FRAME <i>new</i>	\$ 39.00	? X
13	REAR EXTERIOR DOOR HANDLE-LH <i>missing</i>	\$ 33.00	✓ 26.24
14	REAR DOOR HANDLE SENSOR-LH <i>Dmgd</i>	\$ 200.00	✓ 160
16	REAR DOOR HANDLE TRIM PLATE-LH <i>Dmgd</i>	\$ 22.00	✓ 17.20
17	REAR DOOR LAMP-LH <i>new</i>	\$ 64.00	? X
18	REAR DOOR MOUNTING BAR-LH <i>Dmgd.</i>	\$ 143.00	? 114
19	REAR DOOR LOCK-LH <i>Dmgd</i>	\$ 580.00	✓ 463.60
20	REAR DOOR STRIKER-LH <i>new</i>	\$ 66.00	? X
SUB-TOTAL SPARE PARTS		\$ 4,137.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDU 2319 K.

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
21	REAR DOOR BOWDEN CABLE-LH <i>new</i>	S	34.00 <i>x</i>	
22	REAR DOOR INNER PANEL COVER-LH <i>Not new</i>	S	29.00 ?	X
23	REAR WINDOW TRIM STRIP-LH <i>new</i>	S	205.00 <i>+</i>	
24	B-PILLAR TRIM <i>new</i>	S	122.00	97.60
25	C-PILLAR TRIM <i>new</i>	S	122.00	97.60
26	REAR SIDE WINDOW GUIDE RAIL-LH <i>new</i>	S	62.00 <i>+</i>	
27	REAR WINDOW GUIDE-LH <i>Distorted</i>	S	392.00 ?	313.60
28	REAR WINDOW APERTURE SEAL-LH <i>new</i>	S	97.00 <i>+</i>	
29	REAR WINDOW REGULATOR WITHOUT MOTOR-LH <i>Damaged</i>	S	242.00 ?	193.60
30	REAR WINDOW REGULATOR MOTOR-LH <i>Damaged</i>	S	297.00 ?	237.60
31	REAR BASS LOUDSPEAKER <i>new</i>	S	88.00 <i>+</i>	
32	REAR TREBLE SPEAKER	S	77.00 <i>+</i>	
33	REAR DOOR TRIM-LH <i>Not new</i>	S	1,551.00 ?	X
34	REAR ARM REST-LH <i>new</i>	S	543.00 <i>+</i>	
35	REAR TRIM SWITCH -LH <i>new</i>	S	70.00 <i>+</i>	
36	REAR INNER ACTUATOR WITH LIGHT-LH <i>Not new</i>	S	208.00 ?	X
37	REAR TRIM INSERT -LH <i>Not new</i>	S	467.00 ?	X
38	REAR LOUDSPEAKER TRIM-LH <i>new</i>	S	76.00 <i>+</i>	
39	REAR HANDLE SHELL -LH <i>Not new</i>	S	171.00 ?	X
40	REAR HANDLE SHELL SEAL-LH <i>Not new</i>	S	11.00 ?	X
SUB-TOTAL SPARE PARTS		:	\$ 4,864.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDU 2319 K.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
41	REAR DOOR WINDOW TRIM-LH <i>Not new</i>	\$ 116.00	? X
42	REAR WINDOW SEAL-LH <i>new</i>	\$ 11.00	✓ 8.64
43	REAR DOOR LIGHT BAR-LH <i>Not new</i>	\$ 35.00	? X
44	REAR DOOR LED MODULE-LH <i>Not new</i>	\$ 31.00	? X
45	REAR DOOR LIGHT -LH <i>Not new</i>	\$ 64.00	? X
46	SIDE PANEL FRAME-LH <i>Distorted</i>	\$ 2,787.00	✓ 2229.60
47	SIDE MEMBER SECTIONAL PART-LH <i>Distorted Repair</i>	\$ 1,907.00	✓
48	SIDE MEMBER WEBPLATE <i>Distorted</i>	\$ 131.00	? 104.40
49	NOISE INSULATION PLATE <i>Not new</i>	\$ 11.00	? X
50	REINFORCEMENT C-PILLAR <i>Best</i>	\$ 179.00	? 143.80
51	PANEL FILLER PLATE -LH <i>Not new</i>	\$ 171.00	? X
52	LOCK PILLAR REINFORCEMENT INSULATOR <i>new</i>	\$ 8.00	✓ X
53	REAR WHEEL HOUSING-LH <i>Repair Distorted</i>	\$ 545.00	1436
54	REAR B-PILLAR-LH <i>Repair</i>	\$ 490.00	? X
55	REAR WHEEL HOUSING LINER -LH <i>ton</i>	\$ 215.00	✓ 171.60
56	WHEEL HOUSING LINER ATTACHMENT PART <i>new</i>	\$ 78.00	? 62
57	REAR BUMPER COVER <i>Distorted</i>	\$ 1,907.00	✓ 1525.60
58	REAR BUMPER FIXING PART <i>new</i>	\$ 63.00	X
59	REAR SPOILER <i>Distorted</i>	\$ 216.00	? 173.80
60	REAR LIGHT REFLECTOR-LH <i>Not new</i>	\$ 35.00	127.76
SUB TOTAL SPARE PARTS		\$ 9,000.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDU 2319 K.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
61	REAR BUMPER UPPER GUIDE-LH <i>2 new</i>	\$ 37.00	+
62	REAR BUMPER LOWER GUIDE-LH <i>2 new</i>	\$ 19.00	144.88
63	REAR SIDE WINDOW-LH <i>new</i>	\$ 541.00	1432.40
64	REAR WINDOW <i>new</i>	\$ 1,014.00	811.00
65	PRIMER <i>new</i>	2 \$ 38.00	14.56
66	HEAD AIRBAG UNIT -LH/RH <i>new Activated</i>	2 \$ 3,384.00	3707.20
67	CURTAIN AIR BAG BRACKET-LH/RH <i>new</i>	2 \$ 84.00	66.76
68	SIDE AIRBAG UNIT-LH <i>Activated</i>	\$ 1,378.00	1102.40
69	BACKREST COVER-LH <i>new</i>	\$ 2,142.00	1713.60
70	ROOF LINER <i>new</i>	\$ 1,682.00	1345.60
71	AIR BAG CONTROL UNIT <i>Activated</i>	\$ 1,870.00	1496
72	REAR AIR BAG CRASH SENSOR <i>Activated</i>	\$ 273.00	218
73	THREE-POINT AUTOMATIC SEAT BELT-LH/RH <i>Activated</i>	2 \$ 1,912.00	1529.60
74	SEAT BELT HEIGHT ADJUSTER <i>new</i>	2 \$ 306.00	344.80
75	THREE-POINT SEAT BELT WITH INERTIAL REEL <i>Activated</i>	\$ 461.00	X
76	SEAT BELT GUIDE-LH/RH <i>new</i>	2 \$ 172.00	X
77	SEAT BELT COVER <i>new</i>	\$ 47.00	X
78	DOUBLE BELT LATCH-LH <i>new</i>	\$ 223.00	X
79	TRIM B- PILLAR -LH LOWER <i>new</i>	\$ 135.00	107.60
80	TRIM B- PILLAR -LH UPPER <i>new</i>	\$ 206.00	+
SUB -TOTAL SPARE PARTS		\$ 15,924.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDU 2319 K.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
81	REAR WHEEL HOUSING TRIM-LH <i>new</i>	\$ 132.00	105.60
82	C-PILLAR TRIM-LH <i>new</i>	\$ 190.00	+
83	D-PILLAR TRIM -LH <i>new</i>	\$ 202.00	+
84	A-PILLAR TRIM -LH/RH UPPER <i>new</i>	\$ 360.00	? 357.00
85	REAR ALUMINIUM RIM -LH <i>new</i>	\$ 563.00	✓ 450
86	REAR ALUMINIUM HUB CAP-LH <i>new</i>	\$ 87.00	✓ X
87	REAR GAS SHOCKER ABSORBER-LH <i>Bent</i>	\$ 260.00	? 208
88	REAR ANTI ROLL STABILIZER <i>Bent</i>	\$ 358.00	? 286
89	REAR STABILIZER TIE ROD <i>Bent</i>	\$ 77.00	? 60.96
90	REAR WISHBONE ALUMINIUM-LOWER <i>Bent</i>	\$ 762.00	? 609.00
91	REAR TRACK BAR -LH <i>Bent</i>	\$ 109.00	? 87.00
92	REAR WISHBONE-LH UPPER <i>Bent</i>	\$ 492.00	? 393.00
93	REAR WHEEL BEARING HOUSING-LH <i>new</i>	\$ 868.00	? 694.40
94	REAR WHEEL BEARING WITH ASSEMBLY PARTS-LH <i>new</i>	\$ 394.00	? 314.80
95	REAR TRACK ROD -LH <i>Bent</i>	\$ 149.00	? 119.00
96	REAR LATERAL ARM-LH <i>Bent</i>	\$ 395.00	? 316
97	REAR STONE CHIP GUARD-LH <i>new</i>	\$ 38.00	✓ 30
98	SOLID LUBRICANT PASTE <i>new</i>	\$ 39.00	✓ 30.88
99	REAR SUBFRAME <i>Bent</i>	\$ 2,804.00	? 5543.00
100	REAR SUBFRAME BUSHING <i>new</i>	2 \$ 121.00	? X
SUB-TOTAL SPARE PARTS		\$ 8,400.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDU 2319 K.

S/N	Parts Description	Damage Parts & Prices		REMARKS
		S/NETT		
101	REAR SUSPENSION FRAME MOUNTING <i>Note new</i>	2 S	203.00	?
102	TYRE CONTI CONTACT 5 205/60/16 <i>Delivered</i>	S/N S	250.00	✓ 175
103	ACRYLIC SEALER	S/N S	360.00	✓ 360
104	CAVITY WAX	S/N S	280.00	✓ 280
105	STONE CHIP	S/N S	180.00	✓ 180
106	METAL FILLER	S/N S	280.00	✓ 280
107	WINDSCREEN SEAL	S/N S	200.00	✓ 200
108	1/4 GLASS SEAL	S/N S	100.00	✓ 100
109	SUNDRIES <i>Na</i>	S	1,000.00	? 4445.84
TOTAL SPARE PARTS		:	\$ 45,178.00	
TOTAL LABOUR CHARGES		:	\$ 28,884.00	
GRAND TOTAL		:	\$ 74,062.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

34146.80

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lj
Surveyed Date : 05/03/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 28 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0265/2018/GW
Date : 2-Mar-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

You recommended 28 days

We took 47 days exclude 9 Sundays

jb - ok - 28 Dec 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Ampalavanar Ratnaraja
Address : Blk 445 Sin Ming Avenue
#05-473
Singapore 570445
Telephone : HP +6581890478
Type of Claim : Own Damage Claim
Policy No. : 1700015962
Vehicle No : **SDU 2319 K**
Model Code : Audi A4 Sedan 1.4 TFSI S
Model / Year : Jun-17
Engine No : CVN 038564
Chassis No : WAUZZZF47HA161671
Mileage : 16011
Date In : 28-Feb-18
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 28-Feb-18
Place of Accident : ANG MO KIO AVE 4 & YIO CHU KANG RD JUNCTION

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDU 2319 K.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function.	S/N	\$ 280.00	\$ 280.00
2	To renew rhs 1/4 glass and rear windscreen to facillitate fender renewal.	S/N	\$ 600.00	\$ 600.00
3	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims, seat belts. Renew roof liner, curtain aig bag all safety belts, and air bag control unit include console box removal and reinstallation.	S/N	\$ 3,600.00	\$ 3,600.00
4	To remove and renew passenger set back rest.	S/N	\$ 360.00	\$ 360.00
5	To remove and reinstall front suspension for cellette bench repairs.	S/N	\$ 2,800.00	
6	To remove and reinstall rear suspension assembly, including replacement of damaged parts, subframe.	S/N	\$ 3,200.00	\$ 3,200.00
SUB-TOTAL LABOUR CHARGES		:	\$ 10,840.00	\$ 8,040.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDU 2319 K.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
		<i>c/f</i>		\$ 8,040.00
7	To remove and reinstall fuel tank assy and rear exhaust systems. Renew damaged components where necessary.	S/N	\$ 780.00	\$ 780.00
8	To place vehicle on cellette bench.	S/N	\$ 1,200.00	\$ 1,200.00
9	To remove rear bumper, rear lid, both lhs front and rear door. Cut out and reweld lhs rear fender, sill panel, rear lhs 'b and c pillar inner reinforcement, rear lhs wheelhouse, and bottom plate. Repair and align floor pan to original factory specification. renew lhs rear door, reinstall all parts removed. (Added 3 days for Wheelhouse, bottom plate, C pillar reinforcement etc)		\$ 9,600.00	\$ 7,000.00
10	To respray rear bumper, lhs rear fender, lhs rear door, sill panel, drain panel, roof channel, boot floor panel, joint sealer work. (Added \$300.00 for wheelhouse, bottom plate)		\$ 3,800.00	\$ 3,350.00
11	To remove and renew rhs rear wheel rim, check trye and alignment .	S/N	\$ 280.00	\$ 280.00
12	To remove and reinstall rear wire harness, relay, fuse boxes, audio equipment rhs rear window and lifting mechanism, rhs trims, luggage compartment trims.	S/N	\$ 1,600.00	\$ 1,600.00
13	To supply solar film on rear windscreen, 1/4 glass and rear lhs door glass	S/N	\$ 400.00	\$ 400.00
14	To carry out diagnostic check.	S/N	\$ 384.00	\$ 384.00
TOTAL LABOUR CHARGES		:	<u>\$ 28,884.00</u>	<u>\$ 23,034.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDU 2319 K.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR DOOR-LH	\$ 1,928.00	\$ 1,542.40
2	REAR OUTER DOOR SEAL-LH	\$ 176.00	\$ 140.40
3	BONDING AGENT	\$ 43.00	\$ 34.16
4	CLEANING SOLUTION	\$ 64.00	
5	SEAL STRIP	\$ 14.00	
6	REAR DOOR ATTACHMENT PARTS-LH	\$ 488.00	
7	REAR DOOR CATCH -LH	\$ 105.00	\$ 84.00
8	REAR DOOR CATCH COVER-LH	\$ 12.00	\$ 9.04
9	REAR DOOR HINGE UPPER PART-LH	\$ 40.00	\$ 31.68
10	REAR DOOR HINGE HALVES- LH LOWER	2 \$ 80.00	\$ 63.12
11	REAR DOOR HINGE HALVES- LH UPPER	\$ 40.00	\$ 31.68
12	BOOT WITH RETAINING FRAME	\$ 39.00	
13	REAR EXTERIOR DOOR HANDLE-LH	\$ 33.00	\$ 26.24
14	REAR DOOR HANDLE SENSOR-LH	\$ 200.00	\$ 160.00
16	REAR DOOR HANDLE TRIM PLATE-LH	\$ 22.00	\$ 17.20
17	REAR DOOR LAMP-LH	\$ 64.00	
18	REAR DOOR MOUNTING BAR-LH	\$ 143.00	\$ 114.00
19	REAR DOOR LOCK-LH	\$ 580.00	\$ 463.60
20	REAR DOOR STRIKER-LH	\$ 66.00	
SUB-TOTAL SPARE PARTS		\$ 4,137.00	\$ 2,717.52

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDU 2319 K.

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
		<i>c/f</i>	\$	2,717.52
21	REAR DOOR BOWDEN CABLE-LH	\$	34.00	
22	REAR DOOR INNER PANEL COVER-LH	\$	29.00	
23	RAER WINDOW TRIM STRIP-LH	\$	205.00	
24	B-PILLAR TRIM	\$	122.00	\$ 97.60
25	C-PILLAR TRIM	\$	122.00	\$ 97.60
26	REAR SIDE WINDOW GUIDE RAIL-LH	\$	62.00	
27	REAR WINDOW GUIDE-LH	\$	392.00	\$ 313.60
28	REAR WINDOW APERTURE SEAL-LH	\$	97.00	
29	REAR WINDOW REGULATOR WITHOUT MOTOR-LH	\$	242.00	\$ 193.60
30	REAR WINDOW REGULATOR MOTOR-LH	\$	297.00	\$ 237.60
31	REAR BASS LOUDSPEAKER	\$	88.00	
32	REAR TREBLE SPEAKER	\$	77.00	
33	REAR DOOR TRIM-LH	\$	1,551.00	
34	REAR ARM REST-LH	\$	543.00	
35	REAR TRIM SWITCH -LH	\$	70.00	
36	REAR INNER ACTUATOR WITH LIGHT-LH	\$	208.00	
37	REAR TRIM INSERT -LH	\$	467.00	
38	REAR LOUDSPEAKER TRIM-LH	\$	76.00	
39	REAR HANDLE SHELL -LH	\$	171.00	
40	REAR HANDLE SHELL SEAL-LH	\$	11.00	
SUB-TOTAL SPARE PARTS		:	\$ 4,864.00	\$ 3,657.52

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDU 2319 K.

S/N	Parts Description	Damage Parts & Prices		
		S/NETT	REMARKS	
			\$	3,657.52
41	REAR DOOR WINDOW TRIM-LH	\$ 116.00		
42	REAR WINDOW SEAL-LH	\$ 11.00	\$	8.64
43	REAR DOOR LIGHT BAR-LH	\$ 35.00		
44	REAR DOOR LED MODULE-LH	\$ 31.00		
45	REAR DOOR LIGHT -LH	\$ 64.00		
46	SIDE PANEL FRAME-LH	\$ 2,787.00	\$	2,229.60
47	SIDE MEMBER SECTIONAL PART-LH	\$ 1,907.00		
48	SIDE MEMBER WEBPLATE	\$ 131.00	\$	104.40
49	NOISE INSULATION PLATE	\$ 11.00		
50	REINFORCEMENT C- PILLAR	\$ 179.00	\$	142.80
51	PANEL FILLER PLATE -LH	\$ 171.00		
52	LOCK PILLAR REINFORCEMENT INSULATOR	\$ 8.00		
53	REAR WHEEL HOUSING-LH	\$ 545.00	\$	436.00
54	REAR B-PILLAR-LH	\$ 490.00		
55	REAR WHEEL HOUSING LINER -LH	\$ 215.00	\$	171.60
56	WHEEL HOUSING LINER ATTACHMENT PART	\$ 78.00	\$	62.00
57	REAR BUMPER COVER	\$ 1,907.00	\$	1,525.60
58	REAR BUMPER FIXING PART	\$ 63.00		
59	REAR SPOILER	\$ 216.00	\$	172.80
60	REAR LIGHT REFLECTOR-LH	\$ 35.00	\$	27.76
	SUB TOTAL SPARE PARTS	\$ 9,000.00	\$	8,538.72

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDU 2319 K.

S/N	Parts Description	c/f	Damage Parts & Prices	
			S/NETT	REMARKS
			\$	8,538.72
61	REAR BUMPER UPPER GUIDE-LH		\$ 37.00	
62	REAR BUMPER LOWER GUIDE-LH		\$ 19.00	\$ 14.88
63	REAR SIDE WINDOW-LH		\$ 541.00	\$ 432.40
64	REAR WINDOW		\$ 1,014.00	\$ 811.20
65	PRIMER	2	\$ 38.00	\$ 14.56
66	HEAD AIRBAG UNIT -LH/RH	2	\$ 3,384.00	\$ 2,707.20
67	CURTAIN AIR BAG BRACKET-LH/RH	2	\$ 84.00	\$ 65.76
68	SIDE AIRBAG UNIT-LH		\$ 1,378.00	\$ 1,102.40
69	BACKREST COVER-LH		\$ 2,142.00	\$ 1,713.60
70	ROOF LINER		\$ 1,682.00	\$ 1,345.60
71	AIR BAG CONTROL UNIT		\$ 1,870.00	\$ 1,496.00
72	REAR AIR BAG CRASH SENSOR		\$ 273.00	\$ 218.00
73	THREE-PONT AUTOMATIC SEAT BELT-LH/RH	2	\$ 1,912.00	\$ 1,529.60
74	SEAT BELT HEIGHT ADJUSTER	2	\$ 306.00	\$ 244.80
75	THREE-POINT SEAT BELT WITH INERTIAL REEL		\$ 461.00	
76	SEAT BELT GUIDE-LH/RH	2	\$ 172.00	
77	SEAT BELT COVER		\$ 47.00	
78	DOUBLE BELT LATCH-LH		\$ 223.00	
79	TRIM B- PILLAR -LH LOWER		\$ 135.00	\$ 107.60
80	TRIM B- PILLAR -LH UPPER		\$ 206.00	
SUB -TOTAL SPARE PARTS			\$ 15,924.00	\$ 20,342.32

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDU 2319 K.

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
		<i>c/f</i>	\$	20,342.32
81	REAR WHEEL HOUSING TRIM-LH		\$ 132.00	\$ 105.60
82	C-PILLAR TRIM-LH		\$ 190.00	
83	D-PILLAR TRIM -LH		\$ 202.00	
84	A-PILLAR TRIM -LH/RH UPPER		\$ 360.00	\$ 287.20
85	REAR ALUMINIUM RIM -LH		\$ 563.00	\$ 450.00
86	REAR ALUMINIUM HUB CAP-LH		\$ 87.00	
87	REAR GAS SHOCKER ABSORBER-LH		\$ 260.00	\$ 208.00
88	REAR ANTI ROLL STABILIZER		\$ 358.00	\$ 286.00
89	REAR STABILIZER TIE ROD		\$ 77.00	\$ 60.96
90	REAR WISHBONE ALUMINIUM-LOWER		\$ 762.00	\$ 609.20
91	REAR TRACK BAR -LH		\$ 109.00	\$ 87.20
92	REAR WISHBONE-LH UPPER		\$ 492.00	\$ 393.20
93	REAR WHEEL BEARING HOUSING-LH		\$ 868.00	\$ 694.40
94	REAR WHEEL BEARING WITH ASSEMBLY PARTS-LH		\$ 394.00	\$ 314.80
95	REAR TRACK ROD -LH		\$ 149.00	\$ 119.20
96	REAR LATERAL ARM-LH		\$ 395.00	\$ 316.00
97	REAR STONE CHIP GUARD-LH		\$ 38.00	\$ 30.00
98	SOLID LUBRICANT PASTE		\$ 39.00	\$ 30.88
99	REAR SUBFRAME		\$ 2,804.00	\$ 2,243.20
100	REAR SUBFRAME BUSHING	2	\$ 121.00	
	SUB-TOTAL SPARE PARTS		\$ 8,400.00	\$ 26,578.16

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDU 2319 K.

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
		<i>c/f</i>	\$	26,578.16
101	REAR SUSPENSION FRAME MOUNTING	2	\$ 203.00	
102	TYRE CONTI CONTACT 5 205/60/16	S/N	\$ 250.00	\$ 175.00
103	ACRYLIC SEALER	S/N	\$ 360.00	\$ 360.00
104	CAVITY WAX	S/N	\$ 280.00	\$ 280.00
105	STONE CHIP	S/N	\$ 180.00	\$ 180.00
106	METAL FILLER	S/N	\$ 280.00	\$ 280.00
107	WINDSCREEN SEAL	S/N	\$ 200.00	\$ 200.00
108	1/4 GLASS SEAL	S/N	\$ 100.00	\$ 100.00
109	Added parts - see attached		\$ 10,522.00	\$ 7,250.80
110	SUNDRIES		\$ 1,000.00	\$ 445.84
	TOTAL SPARE PARTS	:	\$ 55,700.00	\$ 35,849.80
	TOTAL LABOUR CHARGES	:	\$ 28,884.00	\$ 23,034.00
	GRAND TOTAL	:	\$ 84,584.00	\$ 58,883.80

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

58,151.80

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0265/2018/GW

19-Apr-18

Johnny Boo

SDU2319K

A4 Sedan 1.4 TFSI

Quantity	Description	Unit Price	Amount
Parts			
1	Exhaust Muffler <i>Noted X - NE NE</i>	\$ 875.00	\$ 700.00 <i>X</i>
2	Silencer <i>Noted Bent</i>	\$ 970.00	\$ 775.60 <i>X</i>
3	Roof handle <i>NN</i>	\$ 496.00	\$ 396.80 <i>X</i>
4	Door slot shield - rear LHS door <i>Damaged</i>	\$ 317.00	\$ 253.20 <i>X</i>
5	Brake hose LHS rear <i>ok</i>	\$ 67.00	\$ 53.36 <i>✓</i>
6	Brake line LHS rear <i>Bent</i>	\$ 48.00	\$ 37.68 <i>✓</i>
7	Caliper housing LHS rear <i>Damaged</i>	\$ 889.00	\$ 711.20 <i>✓</i>
8	Caliper LHS rear <i>ok</i>	\$ 303.00	\$ 242.40 <i>✓</i>
8	Dust cover LHS rear <i>Bent</i>	\$ 101.00	\$ 80.80 <i>✓</i>
9	Door wire harness <i>Damaged</i>	\$ 335.00	\$ 267.60 <i>✓</i>
10	Control unit bracket <i>Damaged</i>	\$ 31.00	\$ 24.08 <i>✓</i>
11	Tailight outer LHS <i>ok</i>	\$ 915.00	\$ 732.00 <i>✓</i>
12	Tailight outer RHS <i>NE NE (No Photo) X</i>	\$ 915.00	\$ 732.00 <i>X</i>
13	Brake fluid <i>ok</i>	\$ 28.00	\$ 22.40 <i>✓</i>
14	Fuse unit <i>Activated</i>	\$ 470.00	\$ 376.00 <i>✓</i>
15	Bumper spoiler strip - kick open sensor line <i>ok</i>	\$ 191.00	\$ 152.80 <i>✓</i>
14	TOTAL	\$ 6,951.00	\$5,557.92

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

Quantity	Description	Unit Price	Amount
Parts	c/f	\$6,951.00	\$5,557.92
16	Coil spring bearing <i>2nd</i>	\$ 94.00	\$ 74.96 ✓
17	Coil spring mounting	\$ 56.00	\$ 44.24 ✓
18	Level sensor LHS rear <i>2nd</i>	\$ 286.00	\$ 228.80 ✓
19	Convenience system control unit <i>caused</i>	\$ 1,357.00	\$ 1,085.60 ✓
20	Exhaust heat shield <i>crumpled</i>	\$ 134.00	\$ 106.00 ✓
21	Tailight trim LHS/RHS <i>2nd</i>	\$ 51.00	\$ 40.16 ✓
22	Wheelhouse LHS rear <i>distorted</i>	\$ 1,064.00	\$ 851.20 ✓
23	Exhaust clamp <i>2nd</i>	\$ 43.00	\$ 34.00 ✓
25	Exhaust bracket	\$ 37.00	\$ 29.04 ✓
26	Bottom plate LHS rear <i>v. shield</i>	\$ 428.00	\$ 342.00 ✓
27	Sticker <i>new</i>	\$ 21.00	\$ 16.72 ✓
LABORS		\$ 10,522.00	\$8,410.64
1	To remove and renew exhaust assy, damaged brake components S/N	\$ 1,200.00	\$ 900.00 X
TOTAL		\$11,722.00	\$9,310.64

For Premium Automobiles Pte Ltd

Authorised Signature

10054.80

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0265/2018/GW
19-Apr-18
Johnny Boo
SDU2319K
A4 Sedan 1.4 TFSI

Quantity	Description	Unit Price	Amount
Parts			
1	Exhaust Muffler	\$ 875.00	\$ -
2	Silencer	\$ 970.00	\$ 775.60
3	Roof handle	\$ 496.00	\$ -
4	Door slot shield - rear LHS door	\$ 317.00	\$ 253.20
5	Brake hose LHS rear	\$ 67.00	\$ 53.36
6	Brake line LHS rear	\$ 48.00	\$ 37.68
7	Caliper housing LHS rear	\$ 889.00	\$ 711.20
8	Caliper LHS rear	\$ 303.00	\$ 242.40
8	Dust cover LHS rear	\$ 101.00	\$ 80.80
9	Door wire harness	\$ 335.00	\$ 267.60
10	Control unit bracket	\$ 31.00	\$ 24.08
11	Tailight outer LHS	\$ 915.00	\$ 732.00
12	Tailight outer RHS	\$ 915.00	\$ 732.00
13	Brake fluid	\$ 28.00	\$ 22.40
14	Fuse unit	\$ 470.00	\$ 376.00
15	Bumper spoiler strip - kick open sensor line	\$ 191.00	\$ 152.80
14	TOTAL	\$ 6,951.00	\$4,461.12

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

Quantity	Description	Unit Price	Amount
Parts	<i>c/f</i>	\$6,951.00	\$4,461.12
16	Coil spring bearing	\$ 94.00	\$ 74.96
17	Coil spring mounting	\$ 56.00	\$ 44.24
18	Level sensor LHS rear	\$ 286.00	\$ 228.80
19	Convenience system control unit	\$ 1,357.00	\$ 1,085.60
20	Exhaust heat shield	\$ 134.00	\$ 106.00
21	Tailight trim LHS/RHS	\$ 51.00	\$ 40.16
22	Wheelhouse LHS rear	\$ 1,064.00	\$ 851.20
23	Exhaust clamp	\$ 43.00	\$ -
25	Exhaust bracket	\$ 37.00	\$ -
26	Bottom plate LHS rear	\$ 428.00	\$ 342.00
27	Sticker	\$ 21.00	\$ 16.72
LABORS		\$ 10,522.00	\$7,250.80
1	To remove and renew exhaust assy, damaged brake components	S/N \$ 1,200.00	\$ -
TOTAL		\$11,722.00	\$7,250.80

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 11 November 2019 2:13 PM
To: Carrine Leong; SUR
Cc: jiayee.yap@premiumauto.com.sg; 'Chang Chee Sing'; 'Boo seng yak'; nora.khai@premiumauto.com.sg
Subject: RE: FINAL REVISION - SDU2319K - OD AIG - SURVEYED 5 MAR 18

Dear Carrine,

Confirm repair cost of **\$58,151.80** before excess \$600 and GST @ **40 days**

Kindly send us invoice and discharge voucher for us to close file.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Carrine Leong <carrine.leong@premiumauto.com.sg>
Sent: Thursday, 31 October 2019 1:42 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: jiayee.yap@premiumauto.com.sg; 'Chang Chee Sing' <claims@premiumauto.com.sg>; 'Boo seng yak' <boojohnny@gmail.com>; nora.khai@premiumauto.com.sg
Subject: RE: FINAL REVISION - SDU2319K - OD AIG - SURVEYED 5 MAR 18

Hi Veron,

Ok, For days of repair we counter propose 40days.

Thanks & Best Regard

Carrine Leong

Claims Administrator


Premium Automobiles Pte Ltd (Reg No: 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183

e. carrine.leong@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Thursday, 31 October, 2019 12:52 PM
To: Carrine Leong <carrine.leong@premiumauto.com.sg>; SUR <sur@lkkauto.com>
Cc: jiayee.yap@premiumauto.com.sg; 'Chang Chee Sing' <claims@premiumauto.com.sg>; 'Boo seng yak' <boojohnny@gmail.com>; nora.khai@premiumauto.com.sg
Subject: RE: FINAL REVISION - SDU2319K - OD AIG - SURVEYED 5 MAR 18

Dear Carrine,

After surveyor's has review, kindly take out

1) TAILLIGHT OUTER RHS-\$732

Please confirm repair cost of **\$58,151.80** before excess \$600 and GST @ 35 days instead of 47 days.

We need to get approval from AIG.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Carrine Leong <carrine.leong@premiumauto.com.sg>
Sent: Friday, 11 October 2019 2:54 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>; Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>
Cc: jiayee.yap@premiumauto.com.sg; 'Chang Chee Sing' <claims@premiumauto.com.sg>; 'Boo seng yak' <boojohnny@gmail.com>; nora.khai@premiumauto.com.sg
Subject: RE: FINAL REVISION - SDU2319K - OD AIG - SURVEYED 5 MAR 18

Hi Adrian/Veron,

Please find attachment photo for your attention.

Revised estimate is attached.

Please confirm repair cost of \$58,883.80 @ 47 days of repairs exclude 9 Sundays.

Thanks & Best Regard
Carrine Leong
Claims Administrator


Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183

e. carrine.leong@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]

Sent: Monday, 2 September, 2019 2:58 PM

To: Carrine Leong <carrine.leong@premiumauto.com.sg>; SUR <sur@lkkauto.com>

Cc: jiayee.yap@premiumauto.com.sg; 'Chang Chee Sing' <claims@premiumauto.com.sg>; Boo seng yak <boojohnny@gmail.com>; (nora.khai@premiumauto.com.sg) <nora.khai@premiumauto.com.sg>

Subject: RE: FINAL REVISION - SDU2319K - OD AIG - SURVEYED 5 MAR 18

Dear Carrine,

As spoken.

Items no photos, please take out and re-finalise

- 1) Exhaust muffler-\$700
- 2) Silencer-\$775.60
- 3) Roof handle-\$396.80
- 4) Taillight outer RHS-\$732
- 5) Fuse unit-\$376
- 6) Convenience system control unit-\$1085.60
- 7) Exhaust clamp-\$34
- 8) Exhaust bracket-\$29.04
- 9) To remove and renew exhaust assy,damage brake components-\$900

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Carrine Leong <carrine.leong@premiumauto.com.sg>

Sent: Thursday, 29 August 2019 4:43 PM

To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>

Cc: jiayee.yap@premiumauto.com.sg; 'Chang Chee Sing' <claims@premiumauto.com.sg>

Subject: RE: FINAL REVISION - SDU2319K - OD AIG - SURVEYED 5 MAR 18

Hi Adrian and All,

Reminder

We have yet receive your confirmation of repair cost and days of repair for above vehicle.

Revised estimate was mailed to you on 28 Dec 2018, 22 Jan, 21 Feb & 15 Jul 2019.

We sincerely appreciate your early closure.

Thanks & Best Regard

Carrine Leong

Claims Administrator

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183

e. carrine.leong@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Carrine Leong [mailto:carrine.leong@premiumauto.com.sg]

Sent: Monday, 15 July, 2019 3:12 PM

To: 'Adrian Ling' <adrianling@lkkauto.com>; 'Veron Chen' <veronchen@lkkauto.com>; 'sur@lkkauto.com' <sur@lkkauto.com>

Cc: 'jiayee.yap@premiumauto.com.sg' <jiayee.yap@premiumauto.com.sg>; 'Chang Chee Sing' <claims@premiumauto.com.sg>

Subject: RE: FINAL REVISION - SDU2319K - OD AIG - SURVEYED 5 MAR 18

Importance: High

Hi Adrian and All,

Reminder

We have yet receive your confirmation of repair cost and days of repair for above vehicle.
Revised estimate was mailed to you on 28 Dec 2018, 22 Jan & 21 Feb 2019.
We sincerely appreciate your early closure.

Thanks & Best Regard
Carrine Leong
Claims Administrator

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183
e. carrine.leong@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Carrine Leong [mailto:carrine.leong@premiumauto.com.sg]
Sent: Thursday, 21 February, 2019 4:09 PM
To: 'Adrian Ling' <adrianling@lkkauto.com>; 'Veron Chen' <veronchen@lkkauto.com>; 'sur@lkkauto.com' <sur@lkkauto.com>
Cc: 'jiayee.yap@premiumauto.com.sg' <jiayee.yap@premiumauto.com.sg>; 'Chang Chee Sing' <claims@premiumauto.com.sg>
Subject: RE: FINAL REVISION - SDU2319K - OD AIG - SURVEYED 5 MAR 18


Hi Adrian and All,

Reminder

We have yet receive your confirmation of repair cost and days of repair for above vehicle.
Revised estimate was mailed to you on 28 Dec 2018 & 22 Jan 2019.
We sincerely appreciate your early closure.

Thanks & Best Regard
Carrine Leong
Claims Administrator

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183
e. carrine.leong@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Carrine Leong [mailto:carrine.leong@premiumauto.com.sg]
Sent: Tuesday, 22 January, 2019 1:51 PM
To: 'Adrian Ling' <adrianling@lkkauto.com>; 'Veron Chen' <veronchen@lkkauto.com>; 'sur@lkkauto.com' <sur@lkkauto.com>
Cc: 'jiayee.yap@premiumauto.com.sg' <jiayee.yap@premiumauto.com.sg>; 'Chang Chee Sing' <cclaims@premiumauto.com.sg>
Subject: RE: FINAL REVISION - SDU2319K - OD AIG - SURVEYED 5 MAR 18

Hi Adrian and All,

Reminder

We have yet receive your confirmation of repair cost and days of repair for above vehicle.
Revised estimate was mailed to you on 28 Dec 2018.
We sincerely appreciate your early closure.

Thanks & Best Regard
Carrine Leong
Claims Administrator

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183
e. carrine.leong@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Boo seng yak [mailto:boojohnny@gmail.com]
Sent: Friday, 28 December, 2018 4:47 PM

To: Adrian Ling <adrianling@lkkauto.com>; Veron Chen <veronchen@lkkauto.com>; sur@lkkauto.com; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiajee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>
Subject: FINAL REVISION - SDU2319K - OD AIG - SURVEYED 5 MAR 18

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$60,880.60 @ 47 days of repairs exclude 9 Sundays.

Photographs is obtainable in our share folder here from SA

Your early closure is well appreciated.

Best regards - jb

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SDU 2319 K

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0265/2018/NH

12 Nov 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SDU 2319 K, Audi A4 SEDAN 1.4 TFSI.

With reference to the above-mentioned vehicle, no. **SDU 2319 K**, claimant, **Ms. Ampalavanar Ratnajaya**, please find the related document per attached.

1. A copy of the Original invoice no. 85014449 – S\$ 61,580.43.
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG – SDU 2319 K

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Mar 2018		05 Mar 2018 16:18 Edit Adj Rpt	\$558,151.80 Edit Estimates	\$558,151.80 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	AMPALAVANAR RATNARAJA, ID: S1324733A, Tel: +6590090766								
Vehicle Reg. No.:	SDU2319K	Date of Loss:	28/02/2018 06:00 - :59 [8 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 2899090302SG	Policy/Cover Note No.:	1700015962 (Comprehensive)						
		Excess:	\$5600.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Mohd Zawaye, Norsazani] Norsazani.Zawaye@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 14/03/2018]								
Driver/Custodian:	VIMALA D/O PUNNIAMOORTHY MRS. VIMALA RATNARAJA (53 / Female), NRIC: S1667722A, Tel: +6591839091 Email: RATNA9009@GMAIL.COM								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (11/11/2019): Alert - Adj Mandate Approved (\$58151.80) - SDU2319K - Claim Handler: Mohd Zaway... - AIG_SG (06/03/2018): Alert - Adj Mandate Approved (\$43102.00) - SDU2319K - Claim Handler: Mohd Zaway... - AIG_SG (06/03/2018): SDU2319K / OD / 28/02/2018 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SDU2319K (2899090302SG)
OD
Feb 28 2018 6:00AM
[AMPALAVANAR RATNARAJA]
Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser	
Assessment Reports														1 per page		☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print		
1	06/03/18 12:21	Adjuster Immediate Advice										1	Load HTM			
Photos/Images														3 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print		
1	06/03/18 10:19	General View										1	Load JPG	☒		
2	06/03/18 10:19	General View										1	Load JPG	☒		
3	06/03/18 10:19	General View										1	Load JPG	☒		
4	06/03/18 10:19	General View										1	Load JPG	☒		
5	06/03/18 10:19	General View										1	Load JPG	☒		
6	06/03/18 10:19	General View										1	Load JPG	☒		
7	06/03/18 10:19	General View										1	Load JPG	☒		
8	06/03/18 10:19	General View										1	Load JPG	☒		
9	06/03/18 10:19	General View										1	Load JPG	☒		
10	06/03/18 10:19	General View										1	Load JPG	☒		
11	06/03/18 10:19	General View										1	Load JPG	☒		
12	06/03/18 10:19	General View										1	Load JPG	☒		
13	06/03/18 10:19	General View										1	Load JPG	☒		
14	06/03/18 10:19	General View										1	Load JPG	☒		
15	06/03/18 10:19	General View										1	Load JPG	☒		
16	06/03/18 10:19	General View										1	Load JPG	☒		
17	06/03/18 10:19	General View										1	Load JPG	☒		
18	06/03/18 10:19	General View										1	Load JPG	☒		
19	06/03/18 10:19	General View										1	Load JPG	☒		
20	06/03/18 10:19	General View										1	Load JPG	☒		
21	06/03/18 10:19	General View										1	Load JPG	☒		
22	06/03/18 10:19	General View										1	Load JPG	☒		
23	06/03/18 10:19	General View										1	Load JPG	☒		
24	06/03/18 10:19	General View										1	Load JPG	☒		
25	06/03/18 10:19	General View										1	Load JPG	☒		
26	06/03/18 10:19	General View										1	Load JPG	☒		
27	06/03/18 10:19	General View										1	Load JPG	☒		
28	06/03/18 10:19	General View										1	Load JPG	☒		
29	06/03/18 10:19	General View										1	Load JPG	☒		
30	06/03/18 10:19	General View										1	Load JPG	☒		
31	06/03/18 10:19	General View										1	Load JPG	☒		
32	06/03/18 10:19	General View										1	Load JPG	☒		
33	06/03/18 10:19	General View										1	Load JPG	☒		
34	06/03/18 10:19	General View										1	Load JPG	☒		
35	06/03/18 10:19	General View										1	Load JPG	☒		
36	06/03/18 10:19	General View										1	Load JPG	☒		
37	06/03/18 10:19	General View										1	Load JPG	☒		
38	06/03/18 10:19	General View										1	Load JPG	☒		
39	06/03/18 10:19	General View										1	Load JPG	☒		
40	06/03/18 10:19	General View										1	Load JPG	☒		
41	06/03/18 10:19	General View										1	Load JPG	☒		

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
42	06/03/18 10:19	General View	 Load JPG	☒
43	06/03/18 10:19	General View	 Load JPG	☒
44	06/03/18 10:19	General View	 Load JPG	☒
45	06/03/18 10:19	General View	 Load JPG	☒
46	06/03/18 10:19	General View	 Load JPG	☒
47	06/03/18 10:19	General View	 Load JPG	☒
48	06/03/18 10:19	General View	 Load JPG	☒
49	06/03/18 10:19	General View	 Load JPG	☒
50	06/03/18 10:19	General View	 Load JPG	☒
51	06/03/18 10:19	General View	 Load JPG	☒
52	06/03/18 10:19	General View	 Load JPG	☒
53	06/03/18 10:19	General View	 Load JPG	☒
54	06/03/18 10:19	General View	 Load JPG	☒
55	06/03/18 10:19	General View	 Load JPG	☒
56	06/03/18 10:19	General View	 Load JPG	☒
57	06/03/18 10:19	General View	 Load JPG	☒
58	06/03/18 10:19	General View	 Load JPG	☒
59	06/03/18 10:19	General View	 Load JPG	☒
60	06/03/18 10:19	General View	 Load JPG	☒
61	06/03/18 10:19	General View	 Load JPG	☒
62	25/10/19 11:32	Reinspection Photo	 Load JPG	☒
63	25/10/19 11:32	Reinspection Photo	 Load JPG	☒
64	25/10/19 11:32	Reinspection Photo	 Load JPG	☒
65	25/10/19 11:32	Reinspection Photo	 Load JPG	☒
66	25/10/19 11:32	Reinspection Photo	 Load JPG	☒
67	25/10/19 11:32	Reinspection Photo	 Load JPG	☒
68	25/10/19 11:32	Reinspection Photo	 Load JPG	☒
69	25/10/19 11:32	Reinspection Photo	 Load JPG	☒
70	25/10/19 11:32	Reinspection Photo	 Load JPG	☒
71	25/10/19 11:32	Reinspection Photo	 Load JPG	☒
72	25/10/19 11:32	Reinspection Photo	 Load JPG	☒
73	25/10/19 11:32	Reinspection Photo	 Load JPG	☒
74	25/10/19 11:32	Reinspection Photo	 Load JPG	☒
75	25/10/19 11:32	Reinspection Photo	 Load JPG	☒
76	25/10/19 11:32	Reinspection Photo	 Load JPG	☒
77	25/10/19 11:32	Reinspection Photo	 Load JPG	☒
78	25/10/19 11:32	Reinspection Photo	 Load JPG	☒
79	25/10/19 11:32	Reinspection Photo	 Load JPG	☒
80	25/10/19 11:32	Reinspection Photo	 Load JPG	☒
81	25/10/19 11:32	Reinspection Photo	 Load JPG	☒
82	25/10/19 11:32	Reinspection Photo	 Load JPG	☒
83	25/10/19 11:32	Reinspection Photo	 Load JPG	☒
84	25/10/19 11:32	Reinspection Photo	 Load JPG	☒
85	25/10/19 11:32	Reinspection Photo	 Load JPG	☒
86	25/10/19 11:32	Reinspection Photo	 Load JPG	☒
87	25/10/19 11:32	Reinspection Photo	 Load JPG	☒
88	25/10/19 11:32	Reinspection Photo	Load JPG	☒
89	25/10/19 11:32	Reinspection Photo	Load JPG	☒
90	25/10/19 11:32	Reinspection Photo	Load JPG	☒
91	25/10/19 11:32	Reinspection Photo	Load JPG	☒
92	25/10/19 11:33	Reinspection Photo	Load JPG	☒
93	25/10/19 11:33	Reinspection Photo	Load JPG	☒
94	25/10/19 11:33	Reinspection Photo	Load JPG	☒
95	25/10/19 11:33	Reinspection Photo	Load JPG	☒
96	25/10/19 11:33	Reinspection Photo	Load JPG	☒
97	25/10/19 11:33	Reinspection Photo	Load JPG	☒

Assessment Reports				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
98	25/10/19 11:33	Reinspection Photo		Load JPG	☒
99	25/10/19 11:33	Reinspection Photo		Load JPG	☒
100	25/10/19 11:33	Reinspection Photo		Load JPG	☒
101	25/10/19 11:33	Reinspection Photo		Load JPG	☒
102	25/10/19 11:33	Reinspection Photo		Load JPG	☒
103	25/10/19 11:33	Reinspection Photo		Load JPG	☒
104	25/10/19 11:33	Reinspection Photo		Load JPG	☒
105	25/10/19 11:33	Reinspection Photo		Load JPG	☒
106	25/10/19 11:33	Reinspection Photo		Load JPG	☒
107	25/10/19 11:33	Reinspection Photo		Load JPG	☒
108	25/10/19 11:33	Reinspection Photo		Load JPG	☒
109	25/10/19 11:33	Reinspection Photo		Load JPG	☒
110	25/10/19 11:33	Reinspection Photo		Load JPG	☒
111	25/10/19 11:33	Reinspection Photo		Load JPG	☒
112	25/10/19 11:33	Reinspection Photo		Load JPG	☒
113	25/10/19 11:33	Reinspection Photo		Load JPG	☒
114	25/10/19 11:33	Reinspection Photo		Load JPG	☒
115	25/10/19 11:33	Reinspection Photo		Load JPG	☒
116	25/10/19 11:33	Reinspection Photo		Load JPG	☒
117	25/10/19 11:33	Reinspection Photo		Load JPG	☒
118	25/10/19 11:33	Reinspection Photo		Load JPG	☒
119	25/10/19 11:33	Reinspection Photo		Load JPG	☒
120	25/10/19 11:33	Reinspection Photo		Load JPG	☒
121	25/10/19 11:33	Reinspection Photo		Load JPG	☒
122	25/10/19 11:33	Reinspection Photo		Load JPG	☒
123	25/10/19 11:33	Reinspection Photo		Load JPG	☒
124	25/10/19 11:33	Reinspection Photo		Load JPG	☒
125	25/10/19 11:33	Reinspection Photo		Load JPG	☒
126	25/10/19 11:33	Reinspection Photo		Load JPG	☒
127	25/10/19 11:33	Reinspection Photo		Load JPG	☒
128	25/10/19 11:33	Reinspection Photo		Load JPG	☒
129	25/10/19 11:33	Reinspection Photo		Load JPG	☒
130	25/10/19 11:33	Reinspection Photo		Load JPG	☒
131	25/10/19 11:33	Reinspection Photo		Load JPG	☒
132	25/10/19 11:33	Reinspection Photo		Load JPG	☒
133	25/10/19 11:33	Reinspection Photo		Load JPG	☒
134	25/10/19 11:33	Reinspection Photo		Load JPG	☒
135	25/10/19 11:33	Reinspection Photo		Load JPG	☒
136	25/10/19 11:33	Reinspection Photo		Load JPG	☒
137	25/10/19 11:33	Reinspection Photo		Load JPG	☒
138	25/10/19 11:33	Reinspection Photo		Load JPG	☒
139	25/10/19 11:33	Reinspection Photo		Load JPG	☒
140	25/10/19 11:33	Reinspection Photo		Load JPG	☒
141	25/10/19 11:33	Reinspection Photo		Load JPG	☒
142	25/10/19 11:33	Reinspection Photo		Load JPG	☒
143	25/10/19 11:33	Reinspection Photo		Load JPG	☒
144	25/10/19 11:33	Reinspection Photo		Load JPG	☒
145	25/10/19 11:33	Reinspection Photo		Load JPG	☒
146	31/10/19 09:06	Reinspection Photo		Load JPG	☒
147	31/10/19 09:06	Reinspection Photo		Load JPG	☒
148	31/10/19 09:06	Reinspection Photo		Load JPG	☒
149	31/10/19 09:06	Reinspection Photo		Load JPG	☒
150	31/10/19 09:06	Reinspection Photo		Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print

Assessment Reports				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	06/03/18 10:42	Singapore Accident Statement		Load PDF	
2	06/03/18 10:42	Certificate of Insurance		Load PDF	
3	06/03/18 10:42	Driver's Driving License		Load PDF	
4	06/03/18 10:43	MARK ESTIMATE		Load PDF	
5	08/03/18 11:13	INTERVIEW FORM AND UNDERTAKING		Load PDF	
6	31/12/18 12:28	SUPPLEMENTARY		Load PDF	
7	31/10/19 15:05	FINAL MARKING		Load PDF	
8	31/10/19 15:05	SUPPLEMENTARY MARKING		Load PDF	
9	21/11/19 17:25	Workshop Invoice		Load PDF	
10	21/11/19 17:25	Discharge Voucher		Load PDF	

Linked Accident Report Documents

Assessment Reports				1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	28/02/18 16:54	Accident Statement		Load HTM	
Photos/Images				3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	28/02/18 16:48	Accident Photo		Load JPG	☒
2	28/02/18 16:48	Accident Photo		Load JPG	☒
3	28/02/18 16:48	Accident Photo		Load JPG	☒
4	28/02/18 16:48	Accident Photo		Load JPG	☒
5	28/02/18 16:48	Accident Photo		Load JPG	☒
6	28/02/18 16:48	Accident Photo		Load JPG	☒
7	28/02/18 16:48	Accident Photo		Load JPG	☒
8	28/02/18 16:48	Accident Photo		Load JPG	☒
9	28/02/18 16:48	Accident Photo		Load JPG	☒
10	28/02/18 16:48	Accident Photo		Load JPG	☒
11	28/02/18 16:48	Accident Photo		Load JPG	☒
12	28/02/18 16:48	Accident Photo		Load JPG	☒
13	28/02/18 16:48	Accident Photo		Load JPG	☒
14	28/02/18 16:48	Accident Photo		Load JPG	☒
15	28/02/18 16:48	Accident Photo		Load JPG	☒
16	28/02/18 16:48	Accident Photo		Load JPG	☒
17	28/02/18 16:48	Accident Photo		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	28/02/18 16:36	Sketch Plan		Load JPG	☒
2	28/02/18 16:36	Sketch Plan #2		Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG18003840/AVBE2

Date: 21/11/2019

REFERENCE

Insured/Claimant: AMPALAVANAR RATNARAJA Policy No: 1700015962
Date of Loss: 28/02/2018 Nature of Claim: OD Claim No: 2899090302SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDU2319K**
Make & Model: AUDI A4, 1.4 TFSI S TRONIC (A) Engine No: CVN038564
Reg. Date: 22/06/2017 (Man. Year: 2017) Chassis No: WAUZZZF47HA161671
Colour: Black Odometer: 16011 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$150,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	54,062.80	35,117.80	18,945.00	35.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	30,084.00	23,034.00	7,050.00	23.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	84,146.80	58,151.80	25,995.00	30.89
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	83,546.80	57,551.80	25,995.00	31.11
+ GST 7.00/7.00% (S\$)	5,848.28	4,028.63	1,819.65	31.11
Nett Amount (S\$)	89,395.08	61,580.43	27,814.65	31.11

INSPECTION

Date of Assignment: 05/03/2018
Date Inspected: 05/03/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 40.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR - LH	Distorted	1,928.00 FS	*1,542.40 FS
2	1		*REAR POUTER DOOR SEAL - LH	Necessary	176.00 FS	*140.40 FS
3	1		*BONDING AGENT	Necessary	43.00 FS	*34.16 FS
4	1		*CLEANING SOLUTION	Not Necessary	64.00 FS	*- FS
5	1		*SEAL STRIP	Not Necessary	14.00 FS	*- FS
6	1		*REAR DOOR ATTACHMENT PARTS - LH	Not Necessary	488.00 FS	*- FS
7	1		*REAR DOOR CATCH - LH	Bent	105.00 FS	*84.00 FS
8	1		*REAR DOOR CATCH COVER - LH	Damaged	12.00 FS	*9.04 FS
9	1		*REAR DOOR HINGE UPPER PART - LH	Bent	40.00 FS	*31.68 FS
10	2		*REAR DOOR HINGE HALVES - LH LOWER	Bent	80.00 FS	*63.12 FS
11	1		*REAR DOOR HINGE HALVES - LH UPPER	Bent	40.00 FS	*31.68 FS
12	1		*BOOT WITH RETAINING FRAME	Not Necessary	39.00 FS	*- FS
13	1		*REAR EXTERIOR DOOR HANDLE - LH	Missing	33.00 FS	*26.24 FS
14	1		*REAR DOOR HANDLE SENSOR - LH	Damaged	200.00 FS	*160.00 FS
15	1		*REAR DOOR HANDLE TRIM PLATE - LH	Damaged	22.00 FS	*17.20 FS
16	1		*REAR DOOR LAMP - LH	Not Necessary	64.00 FS	*- FS
17	1		*REAR DOOR MOUNTING BAR - LH	Damaged	143.00 FS	*114.00 FS
18	1		*REAR DOOR LOCK - LH	Damaged	580.00 FS	*463.60 FS
19	1		*REAR DOOR STRIKER - LH	Not Necessary	66.00 FS	*- FS
20	1		*REAR DOOR BOWDEN CABLE - LH	Not Necessary	34.00 FS	*- FS
21	1		*REAR DOOR INNER PANEL COVER - LH	Not Necessary	29.00 FS	*- FS
22	1		*REAR WINDOW TRIM STRIP - LH	Not Necessary	205.00 FS	*- FS
23	1		*B-PILLAR TRIM	Deformed	122.00 FS	*97.60 FS
24	1		*C-PILLAR TRIM	Deformed	122.00 FS	*97.60 FS
25	1		*REAR SIDE WINDOW GUIDE RAIL - LH	Not Necessary	62.00 FS	*- FS
26	1		*REAR WINDOW GUIDE - LH	Distorted	392.00 FS	*313.60 FS
27	1		*REAR WINDOW APERTURE SEAL - LH	Not Necessary	97.00 FS	*- FS
28	1		*REAR WINDOW REGULATOR WITHOUT MOTOR - LH	Damaged	242.00 FS	*193.60 FS
29	1		*REAR WINDOW REGULATOR MOTOR - LH	Damaged	297.00 FS	*237.60 FS
30	1		*REAR BASS LOUDSPEAKER	Not Necessary	88.00 FS	*- FS
31	1		*REAR TREBLE SPEAKER	Not Necessary	77.00 FS	*- FS
32	1		*REAR DOOR TRIM - LH	Not Necessary	1,551.00 FS	*- FS
33	1		*REAR ARM REST - LH	Not Necessary	543.00 FS	*- FS
34	1		*REAR TRIM SWITCH - LH	Not Necessary	70.00 FS	*- FS
35	1		*REAR INNER ACTUATOR WITH LIGHT - LH	Not Necessary	208.00 FS	*- FS
36	1		*REAR TRIM INSERT - LH	Not Necessary	467.00 FS	*- FS
37	1		*REAR LOUDSPEAKER TRIM - LH		76.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
38	1		*REAR HANDLE SHELL - LH	Not Necessary	171.00 FS	*- FS
39	1		*REAR HANDLE SHELL SEAL - LH	Not Necessary	11.00 FS	*- FS
40	1		*REAR DOOR WINDOW TRIM - LH	Not Necessary	116.00 FS	*- FS
41	1		*REAR WINDOW SEAL - LH	Necessary	11.00 FS	*8.64 FS
42	1		*REAR DOOR LIGHT BAR - LH	Not Necessary	35.00 FS	*- FS
43	1		*REAR DOOR LED MODULE - LH	Not Necessary	31.00 FS	*- FS
44	1		*REAR DOOR LIGHT - LH	Not Necessary	64.00 FS	*- FS
45	1		*SIDE PANEL FRAME - LH	Distorted	2,787.00 FS	*2,229.60 FS
46	1		*SIDE MEMBER SECTIONAL PART - LH	Repair	1,907.00 FS	*- FS
47	1		*SIDE MEMBER WEBPLATE	Damaged	131.00 FS	*104.40 FS
48	1		*NOISE INSULATION PLATE	Not Necessary	11.00 FS	*- FS
49	1		*REINFORCEMENT C-PILLAR	Bent	179.00 FS	*142.80 FS
50	1		*PANEL FILLER PLATE - LH	Not Necessary	171.00 FS	*- FS
51	1		*LOCK PILLAR REINFORCEMENT INSULATOR	Not Necessary	8.00 FS	*- FS
52	1		*REAR WHEEL HOUSING - LH	Distorted	545.00 FS	*436.00 FS
53	1		*REAR B-PILLAR-LH	Repair	490.00 FS	*- FS
54	1		*REAR WHEEL HOUSING LINER - LH	Torn	215.00 FS	*171.60 FS
55	1		*WHEEL HOUSING LINER ATTACHMENT PART	Necessary	78.00 FS	*62.00 FS
56	1		*REAR BUMPER COVER	Deformed	1,907.00 FS	*1,525.60 FS
57	1		*REAR BUMPER FIXING PART	Not Necessary	63.00 FS	*- FS
58	1		*REAR SPOILER	Deformed	216.00 FS	*172.80 FS
59	1		*REAR LIGHT REFLECTOR - LH	Cut	35.00 FS	*27.76 FS
60	1		*REAR BUMPER UPPER GUIDE - LH	Not Necessary	37.00 FS	*- FS
61	1		*REAR BUMPER LOWER GUIDE - LH	Necessary	19.00 FS	*14.88 FS
62	1		*REAR SIDE WINDOW - LH	Necessary	541.00 FS	*432.40 FS
63	1		*REAR WINDOW	Necessary	1,014.00 FS	*811.20 FS
64	2		*PRIMER	Necessary	38.00 FS	*14.56 FS
65	2		*HEAD AIRBAG UNIT - LH / RH	Activated	3,384.00 FS	*2,707.20 FS
66	2		*CURTAIN AIR BAG BRACKET - LH / RH	Necessary	84.00 FS	*65.76 FS
67	1		*SIDE AIRBAG UNIT - LH	Activated	1,378.00 FS	*1,102.40 FS
68	1		*BACKREST COVER - LH	Torn	2,142.00 FS	*1,713.60 FS
69	1		*ROOF LINER	Crumpled	1,682.00 FS	*1,345.60 FS
70	1		*AIR BAG CONTROL UNIT	Activated	1,870.00 FS	*1,496.00 FS
71	1		*REAR AIR BAG CRASH SENSOR	Activated	273.00 FS	*218.00 FS
72	2		*THREE-POINT AUTOMATIC SEAT BELT - LH / RH	Activated	1,912.00 FS	*1,529.60 FS
73	2		*SEAT BELT HEIGHT ADJUSTER	Damaged	306.00 FS	*244.80 FS
74	1		*THREE-POINT SEAT BELT WITH INERTIAL REEL	Not Necessary	461.00 FS	*- FS
75	2		*SEAT BELT GUIDE - LH / RH	Not Necessary	172.00 FS	*- FS
76	1		*SEAT BELT COVER	Not Necessary	47.00 FS	*- FS
77	1		*DOUBLE BELT LATCH - LH	Not Necessary	223.00 FS	*- FS
78	1		*TRIM B-PILLAR - LH LOWER	Deformed	135.00 FS	*107.60 FS
79	1		*TRIM B-PILLAR - LH UPPER		206.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Not Necessary		
80	1		*REAR WHEEL HOUSING TRIM - LH	Damaged	132.00 FS	*105.60 FS
81	1		*C-PILLAR TRIM - LH	Not Necessary	190.00 FS	*- FS
82	1		*D-PILLAR TRIM - LH	Not Necessary	202.00 FS	*- FS
83	1		*A-PILLAR TRIM - LH / RH UPPER	Deformed	360.00 FS	*287.20 FS
84	1		*REAR ALUMINIUM RIM - LH	Cut	563.00 FS	*450.00 FS
85	1		*REAR ALUMINIUM HUB CAP - LH	Not Necessary	87.00 FS	*- FS
86	1		*REAR GAS SHOCKER ABSORBER - LH	Bent	260.00 FS	*208.00 FS
87	1		*REAR ANTI ROLL STABILIZER	Bent	358.00 FS	*286.00 FS
88	1		*REAR STABILIZER TIE ROD	Bent	77.00 FS	*60.96 FS
89	1		*REAR WISHBONE ALUMINIUM - LOWER	Bent	762.00 FS	*609.20 FS
90	1		*REAR TRACK BAR - LH	Bent	109.00 FS	*87.20 FS
91	1		*REAR WISHBONE - LH UPPER	Bent	492.00 FS	*393.20 FS
92	1		*REAR WHEEL BEARING HOUSING - LH	Damaged	868.00 FS	*694.40 FS
93	1		*REAR WHEEL BEARING WITH ASSEMBLY PARTS - LH	Damaged	394.00 FS	*314.80 FS
94	1		*REAR TRACK ROD - LH	Bent	149.00 FS	*119.20 FS
95	1		*REAR LATERAL ARM - LH	Bent	395.00 FS	*316.00 FS
96	1		*REAR STONE CHIP GUARD - LH	Necessary	38.00 FS	*30.00 FS
97	1		*SOLID LUBRICANT PASTE	Necessary	39.00 FS	*30.88 FS
98	1		*REAR SUBFRAME	Bent	2,804.00 FS	*2,243.20 FS
99	2		*REAR SUBFRAME BUSHING	Not Necessary	121.00 FS	*- FS
100	2		*REAR SUSPENSION FRAME MOUNTING	Not Necessary	203.00 FS	*- FS
101	1		*TYRE CONTI CONTACT 5 205/60/16	Deformed	250.00 FS	*175.00 FS
102	1		*ACRYLIC SEALER	Necessary	360.00 FS	*360.00 FS
103	1		*CAVITY WAX	Necessary	280.00 FS	*280.00 FS
104	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
105	1		*METAL FILLER	Necessary	280.00 FS	*280.00 FS
106	1		*WINDSCREEN SEAL	Necessary	200.00 FS	*200.00 FS
107	1		*1/4 GLASS SEAL	Necessary	100.00 FS	*100.00 FS
108	1		*SUNDRIES	Necessary	1,000.00 FS	*445.84 FS
109	1		*EXHAUST MUFFLER	Not Necessary	875.00 FS	*- FS
110	1		*SILENCER	Dented	775.60 FS	*775.60 FS
111	1		*ROOF HANDLE	Not Necessary	496.00 FS	*- FS
112	1		*DOOR SLOT SHIELD - REAR LHS DOOR	Damaged	253.20 FS	*253.20 FS
113	1		*BRAKE HOSE LHS REAR	Cut	53.36 FS	*53.36 FS
114	1		*BRAKE LINE LHS REAR	Bent	37.68 FS	*37.68 FS
115	1		*CALIPER HOUSING LHS REAR	Damaged	711.20 FS	*711.20 FS
116	1		*CALIPER LHS REAR	Damaged	242.40 FS	*242.40 FS
117	1		*DUST COVER LHS REAR	Bent	80.80 FS	*80.80 FS
118	1		*DOOR WIRE HARNESS	Damaged	267.60 FS	*267.60 FS
119	1		*CONTROL UNIT BRACKET	Damaged	24.08 FS	*24.08 FS
120	1		*TAILLIGHT OUTER LHS	Cut	732.00 FS	*732.00 FS
121	1		*TAILLIGHT OUTER RHS	Not Necessary	915.00 FS	*- FS
122	1		*BRAKE FLUID	Necessary	22.40 FS	*22.40 FS
123	1		*FUSE UNIT	Activated	376.00 FS	*376.00 FS
124	1		*BUMPER SPOILER STRIP - KICK OPEN SENSOR LINE	Necessary	152.80 FS	*152.80 FS
125	1		*COIL SPRING BEARING	Damaged	74.96 FS	*74.96 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
126	1		*COIL SPRING MOUNTING	Damaged	44.24 FS	*44.24 FS
127	1		*LEVEL SENSOR LHS REAR	Damaged	228.80 FS	*228.80 FS
128	1		*CONVENIENCE SYSTEM CONTROL UNIT	Cracked	1,085.60 FS	*1,085.60 FS
129	1		*EXHAUST HEAT SHIELD	Crumpled	106.00 FS	*106.00 FS
130	1		*TAILLIGHT TRIM LHS / RHS	Damaged	40.16 FS	*40.16 FS
131	1		*WHEELHOUSE LHS REAR	Distorted	851.20 FS	*851.20 FS
132	1		*EXHAUST CLAMP	Not Necessary	43.00 FS	*- FS
133	1		*EXHAUST BRACKET	Not Necessary	37.00 FS	*- FS
134	1		*BOTTOM PLATE LHS REAR	Distorted	342.00 FS	*342.00 FS
135	1		*STICKER	Necessary	16.72 FS	*16.72 FS
Total Parts (S\$)					54,062.80	35,117.80

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION	New	280.00	280.00
2	TO RENEW RHS 1/4 GLASS AND REAR WINDSCREEN TO FACILITATE FENDER RENEWAL	New	600.00	600.00
3	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS, SEAT BELTS. RENEW ROOF LINER, CURTAIN AIR BAG ALL SAFETY BELTS, AND AIR BAG CONTROL UNIT INCLUDE CONSOLE BOX REMOVAL AND REINSTALLATION	New	3,600.00	3,600.00
4	TO REMOVE AND RENEW PASSENGER SET BACK REST	New	360.00	360.00
5	TO REMOVE AND REINSTALL FRONT SUSPENSION FOR CELLETTE BENCH REPAIRS	New	2,800.00	0.00
6	TO REMOVE AND REINSTALL REAR SUSPENSION ASSEMBLY, INCLUDING REPLACEMENT OF DAMAGED PARTS, SUBFRAME	New	3,200.00	3,200.00
7	TO REMOVE AND REINSTALL FUEL TANK ASSY AND REAR EXHAUST SYSTEMS. RENEW DAMAGED COMPONENTS WHERE NECESSARY	New	780.00	780.00
8	TO PLACE VEHICLE ON CELLETTE BENCH	New	1,200.00	1,200.00
9	TO REMOVE REAR BUMPER, REAR LID, BOTH LHS FRONT AND REAR DOOR. CUT OUT AND REWELD LHS REAR FENDER, SILL PANEL, REAR LHS B AND C PILLAR INNER REINFORCEMENT, REAR LHS WHEELHOUSE, AND BOTTOM PLATE. REPAIR AND ALIGN FLOOR PAN TO ORIGINAL FACTORY SPECIFICATION. RENEW LHS REAR DOOR, REINSTALL ALL PARTS REMOVED	New	9,600.00	7,000.00
10	TO REMOVE AND RENEW RHS REAR WHEEL RIM, CHECK TYRE AND ALIGNMENT	New	280.00	280.00
11	TO REMOVE AND REINSTALL REAR WIRE HARNESS, RELAY, FUSE BOXES, AUDIO EQUIPMENT RHS REAR WINDOW AND LIFTING MECHANISM, RHS TRIM, LUGGAGE COMPARTMENT TRIMS	New	1,600.00	1,600.00
12	TO SUPPLY SOLAR FILM ON REAR WINDSCREEN, 1/4 GLASS AND REAR LHS DOOR GLASS	New	400.00	400.00
13	TO CARRY OUT DIAGNOSTIC CHECK	New	384.00	384.00
14	TO REMOVE AND RENEW EXHAUST ASSY, DAMAGED BRAKE COMPONENTS	New	1,200.00	0.00
15	TO RESPRAY REAR BUMPER, LHS REAR FENDER, LHS REAR DOOR, SILL PANEL, DRAIN PANEL, ROOF CHANNEL, BOOT FLOOR PANEL, JOINT SEALER WORK, END PANEL	New	3,800.00	3,350.00
Gross Labour Cost (\$\$)			30,084.00	23,034.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >