

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315	Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0265/2018/GW 19-Apr-18 Johnny Boo SDU2319K A4 Sedan 1.4 TFSI
--	---	--

Quantity	Description	Unit Price	Amount
Parts			
1	Exhaust Muffler Detent X. NR NR	\$ 875.00	\$ 700.00 X
2	Silencer. Detent Detent	\$ 970.00	\$ 775.60 X
3	Roof handle	\$ 496.00	\$ 396.80 X
4	Door slot shield - rear LHS door Dand	\$ 317.00	\$ 253.20 ✓
5	Brake hose LHS rear ut	\$ 67.00	\$ 53.36 ✓
6	Brake line LHS rear Best	\$ 48.00	\$ 37.68 ✓
7	Caliper housing LHS rear Dand	\$ 889.00	\$ 711.20 ✓
8	Caliper LHS rear Dand	\$ 303.00	\$ 242.40 ✓
8	Dust cover LHS rear Best	\$ 101.00	\$ 80.80 ✓
9	Door wire harness Dand	\$ 335.00	\$ 267.60 ✓
10	Control unit bracket Dand	\$ 31.00	\$ 24.08 ✓
11	Taillight outer LHS ut	\$ 915.00	\$ 732.00 ✓
12	Taillight outer RHS NR NR (No Photo) X.	\$ 915.00	\$ 732.00 X
13	Brake fluid Key	\$ 28.00	\$ 22.40 ✓
14	Fuse unit Activated	\$ 470.00	\$ 376.00 ✓
15	Bumper spoiler strip - kick open sensor line NR	\$ 191.00	\$ 152.80 ✓
14	TOTAL	\$ 6,951.00	\$ 5,557.92

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

Quantity	Description	Unit Price	Amount
<u>Parts</u>	c/f	\$6,951.00	\$5,557.92
16	Coil spring bearing <i>2nd</i>	\$ 94.00	\$ 74.96 ✓
17	Coil spring mounting	\$ 56.00	\$ 44.24 ✓
18	Level sensor LHS rear <i>2nd</i>	\$ 286.00	\$ 228.80 ✓
19	Convenience system control unit <i>caulnd</i>	\$ 1,357.00	\$ 1,085.60 ✓
20	Exhaust heat shield <i>crumpled</i>	\$ 134.00	\$ 106.00 ✓
21	Tailight trim LHS/RHS <i>2nd</i>	\$ 51.00	\$ 40.16 ✓
22	Wheelhouse LHS rear <i>Distorted</i>	\$ 1,064.00	\$ 851.20 ✓
23	Exhaust clamp <i>2nd</i>	\$ 43.00	\$ 34.00 ✓
25	Exhaust bracket <i>2nd</i>	\$ 37.00	\$ 29.04 ✓
26	Bottom plate LHS rear <i>v. steel</i>	\$ 428.00	\$ 342.00 ✓
27	Sticker <i>new</i>	\$ 21.00	\$ 16.72 ✓
<u>LABORS</u>			
		\$ 10,522.00	\$8,410.64
<u>1</u>	To remove and renew exhaust assy, damaged brake components S/N	\$ 1,200.00	\$ 900.00 X
TOTAL		\$11,722.00	\$9,310.64

For Premium Automobiles Pte Ltd

Authorised Signature