

REPAIR ESTIMATE*

VEHICLE NO : SHD 4269A

DATE 23/2/2018 15:24

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>X 1/2</i>			\$ 538.80
	Front Bumper Bracket (RH) ?			\$ 20.10
	Front Fender (RH) ✓			\$ 593.00
	Front Fender Shield (RH) X			\$ 86.00
	Front Wheel Hub Cap (RH) ✓			\$ 145.00
	SUB TOTAL			\$ 1,382.90
	LESS 20%			\$ 276.58
	DISCOUNTED TOTAL			\$ 1,106.32
	Front Fender Advertisement Logo (RH) ✓			\$ 100.00 Nett
				\$ 100.00
	Labour Charge			
	Panel Beating			\$ 560.00 <i>300</i>
	Spray Painting Charge			\$ 400.00 <i>360</i>
	Tuff Kote			\$ 50.00 <i>20</i>
	FRT Wheel Alignment			\$ 120.00 <i>X</i>
	TOTAL LABOUR			\$ 1,130.00
	ESTIMATE TOTAL			\$ 2,336.32

Ka/uh (1/1/14)
 26/2/18 1000h
 2 Pm
 4/5
 Affk Rm 1st

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party surveys on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
 Signature
 Date

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.