

REPAIR ESTIMATE*

Angitia - (P/P)

DATE 19/2/2018

LARRY

MAKE :

MODEL : HYUNDAI i40

LKR - Rasul

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Radiator Grille			\$ 1,480.00
	Radiator Grille H Emblem			\$ 290.80
	Radiator Grille Chrome Moulding			\$ 395.50
	Front Bumper Cover			\$ 1,052.20
	Front Bumper Sponge			\$ 142.20
	Front Bumper Reinforcement			\$ 526.10
	Front Bumper Bracket Top (LH/RH)		\$ LH new 22.40	\$ 44.80
	Front Bumper Retainer Mounting		\$ LH new 9.20	\$ 18.40
	Headlamp (LH)			\$ 1,388.00
	Front Fender (LH)			\$ 619.00
	Front Fender Shield (LH)			\$ 169.80
	Front Fender Retainer			\$ 9.20
	Front Wheel Rim (LH)			\$ 351.90
	Front Wheel Hub Cap (LH)			\$ 150.70
	Front Wheel Bearing			\$ 258.50
	Front Shock Absorber (Assy) (LH)			\$ 342.20
	Front Shock Absorber Mounting (LH)			\$ 75.10
	Front Drive Shaft (LH)			\$ 1,069.55
	Rack & Pinion Assy			\$ 2,184.00
	STG Tie End			\$ 69.50
	Stabilizer Bar			\$ 252.30
	Stabilizer Bar Bush (LH)			\$ 14.20
	Stabilizer Bar Link			\$ 81.70
	Stabilizer Bracket			\$ 24.00
	Front Suspension Lower Arm (LH)			\$ 715.10
	Knuckle Arm (LH)			\$ 582.95
	SUB TOTAL			\$ 12,307.70
	LESS 20%			\$ 2,461.54
	DISCOUNTED TOTAL			\$ 9,846.16
	Front Tyre (LH)			\$ 216.00
	Labour Charge			
	Panel Beating			\$ 560.00
	Spray Painting Charge			\$ 400.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Undercarriage (ERT)			\$ 400.00
	FRT Wheel Alignment			\$ 120.00
	Tow Charge			50.00
	TOTAL LABOUR			\$ 1,580.00
	ESTIMATE TOTAL			\$ 11,642.16

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.