

ASS. REC. BY:

REF: CS/FCI180038491 Krd3n2

Surveyor:

Kenneth

ASSIGNMENT (Office)

CWS

From (Person):

Lerene jaw

of

FCI

Date/Time:

23/2/18 @ 4:41pm

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLU 4214X

Insured:

SHA 88292

at Workshop m/s

Motor Image

Tel:

9299 2693

of

19 Long & Toa Payoh

Policy No:

Claim No:

D18001480 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

19/02/18

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time:

4:10pm 06/3/18

Person Contacted:

Sayed

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SLU 4214X-X
	SHA 88292 - NA MS108009458/W N.O.A: 12/2/2007
	Sent parti thru email
	Confirm \$1572, 1.5 days (Pd: \$1763.76, 491.)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18003849/Krd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 28-02-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 8829Z	Veh. Inspected	SLU 4214X
Policy No.		Coverage (\$)	0.00
Claim No.	D18001480MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	28/02/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	19/02/2018	Inspection Date	27/02/2018
Survey held at	MOTOR IMAGE ENTERPRISES PTE LTD 19 TOA PAYOH LORONG 8 SINGAPORE 319255		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18001480MFSH

Our Ref: CS/FCI18003849/Krd3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLU 4214X .

Please be informed that we had conducted the inspection of the above mentioned vehicle on 27/02/2018 at the premises of M/s MOTOR IMAGE PTE LTD and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 3,635.76</u> .
Revised Estimate Amount	: <u>S\$ 880.00</u> .
"Check" Items Amount	: <u>S\$</u> .
Market Value	: <u>S\$ -</u> .
LTA Reimbursement Value	: <u>S\$ -</u> .
Nett Value	: <u>S\$ -</u> .

Description of Damage:
The vehicle sustained damages
at rear portion.



Yours faithfully
KENNETH
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	20-02-2018	Our Ref No. D18001480MFSH
Accident Date	19-02-2018	Claim Type. Third Party
Insured Vehicle	SHA8829Z	Third Party Vehicle. SLU4214X
Survey Location	19 LORONG 8 TOA PAYOH	
Contact Person.	OLIVER ZUBIRI	
Contact No.	0/ 90903323	Fax No. 0
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MOTOR IMAGE ENTERPRISES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/235158)

PRI Documents

Close X

PRI Header Details

Claim No	D18001480MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & MOTOR IM
Workshop Name	MOTOR IMAGE ENTERPRISES PTE LTD (Contact Person : OLIVER ZUBIRI)	Survey Location & Contact Details	19 LORONG 8 TOA PAYOH Mobile: 90903323 , Phone: 0 , Fax: 0 EmailId: OLIVERGRACILLA@MOTORIMAGE.NET		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHA8829Z	TP Vehicle No	SLU4214X
PRI Recieved Date	21-02-2018 02:04:33 PM	Surveyor Appointed Date	23-02-2018 04:41:12 PM	Surveyor Accept Date	06-03-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	06-03-2018	Upload Survey Report *:	<input type="button" value="Choose File"/>
------------------------------------	---	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make ▾	Model	Please Select Model ▾	Year	Select Year ▾
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Thursday, March 08, 2018 2:31 PM
To: 'Claim Workflow System'
Cc: LURENEJAW@msfirstcapital.com.sg; SUR
Subject: RE: SURVEY ASSESSMENT - D18001480MFSH/1
Attachments: SLU 4214X.pdf

Dear Sir/ Madam,

Enclosed preliminary revised for **SLU 4214X**

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 23 February 2018 4:41 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18001480MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0637/2018
DATE : 19-FEB-2018

FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 62222311 / 65063848
FAX : 62223547 / 65073849

OWNER'S NAME : PAK CHUN HUA
ADDRESS : BLK 428 PASIR RIS DRIVE 6
#07-25
S(510428)
TELEPHONE NO : 9048 0525

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1700083937
VEHICLE NO : SLU4214X
MODEL CODE : SJGKK8
MODEL/YEAR : FORESTER 2.0XT AWD CVT
ENGINE NO : FA20CB59098
CHASSIS NO : JF1SJK85JG102104
MILEAGE : 1 KM
DATE IN : 19/02/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SAYEDINAH ALI**
ACCIDENT DATE : 19/02/2018

Print Date : 21/02/2018
Print Time : 10:35:25

MOTORIMAGE ENTERPRISES PTE. LTD.
 19 LORONG 8, TOA PAYOH
 SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLU4214X

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM)		
2	ZZ/001	CONDUCT THIRD PARTY CLAIM FIRST CAPITAL LOCATION: PIE EXIT TO PASIR RIS DATE:19/02/2018 TIME:1040HRS		
3	ZZ/002	REMOVE/REPLACE REAR BUMPER, END PANEL	<i>nn</i> 1120.00	<i>X</i> <i>560</i>
4	ZZ/003	RESPRAY REAR BUMPER, END PANEL	840.00	<i>420</i> <i>420</i>
5	ZZ/004	TO CONDUCT REAR LIGHTING TEST	50.00	<i>20</i> <i>20</i>
6	ZZ/005	TO SUPPLY AND INSTALL REVERSE SENSOR - 2 EYES	<i>NN</i> 300.00	<i>X</i> <i>X</i>
7	ZZ/006	SUNDRIES	<i>nn</i> 100.00	<i>X</i> <i>X</i>
TOTAL LABOUR CHARGES			2410.00	

MOTORIMAGE ENTERPRISES PTE. LTD.
 19 LORONG 8, TOA PAYOH
 SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLU4214X

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
1	SKIRT COMPL R	5.2F 52401SG0109P	R 288.00	X		
2	BUMPER FACE REAR FORESTER IL	57704SG012	R 540.00	X		✓ deformed
3	BRKT CORNER R RH	57707SG060	Sm 18.00	X		
4	BRKT CORNER R LH	57707SG070	Sm 18.00	X		
5	BRKT SD R RH	(1) 57707SG080	Sm 14.40	X		
6	BRKT SD R LH	57707SG090	Sm 14.40	X		
7	COVER HOOK R	57731SG010NN	Sm 12.60	X		
8	REFLEC AY RH	84281SC000	Sm 20.40	X		
9	REFLEX AY LH	84281SC010	Sm 20.40	X		
10	TRIM PNL AY SKIRTR	94026SG000VH	Sm 36.00	X		
11	CARGO STEP PANEL S/S	E7710SG000	Sm 550.00			
SUB TOTAL			1532.20	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)			306.44	0.00	0.00	0.00
GRAND TOTAL			1225.76	0.00	0.00	0.00
OVERALL TOTAL			1225.76			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLU4214X

TOTAL LABOUR CHARGES	2410.00
TOTAL SPARE PARTS CHARGES	1225.76
GRAND TOTAL	3635.76 *

* All charges do not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

*Not Authorized
Resurvey After Paint
Hiday
1/4/2014*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after body painting.
- To display damaged parts during re-survey
- Parts prices are subject to confirmation
- Third party survey is on a "No Fault" repair basis
- No illegal modification allowed
- Supplementary claim (if any) is subject to final approval from insurance Company.

Acknowledged by Repairer:

Signature:

Date:

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

Kr

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0637/2018
DATE : 19-FEB-2018

FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 62222311 / 65063848
FAX : 62223547 / 65073849

OWNER'S NAME : PAK CHUN HUA
ADDRESS : BLK 428 PASIR RIS DRIVE 6
#07-25
S(510428)
TELEPHONE NO : 9048 0525

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1700083937
VEHICLE NO : SLU4214X
MODEL CODE : SJGEK8
MODEL/YEAR : FORESTER 2.0XT AWD CVT
ENGINE NO : FA20CB59098
CHASSIS NO : JF1SJGK85JG102104
MILEAGE : 4241 KM
DATE IN : 19/02/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SAYEDINAH ALI**
ACCIDENT DATE : 19/02/2018

Print Date : 04/06/2018
Print Time : 13:00:07

* MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLU4214X

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM)		
2	ZZ/001	CONDUCT THIRD PARTY CLAIM FIRST CAPITAL LOCATION: PIE EXIT TO PASIR RIS DATE:19/02/2018 TIME:1040HRS		
3	ZZ/002	REMOVE/REPLACE REAR BUMPER, END PANEL	1120.00	560.00
4	ZZ/003	RESPRAY REAR BUMPER, END PANEL	840.00	420.00
5	ZZ/004	TO CONDUCT REAR LIGHTING TEST	50.00	20.00
6	ZZ/005	TO SUPPLY AND INSTALL REVERSE SENSOR - 2 EYES	300.00	.00
7	ZZ/006	SUNDRIES	100.00	.00
		TOTAL LABOUR CHARGES	2410.00	1000.00

MOTORIMAGE ENTERPRISES PTE. LTD.
 19 LORONG 8, TOA PAYOH
 SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLU4214X

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
1	SKIRT COMPL R	5.2F 52401SG0109P	288.00			X
2	BUMPER FACE REAR FORESTER IL	57704SG012	540.00			OK
3	BRKT CORNER R RH	57707SG060	18.00			X
4	BRKT CORNER R LH	57707SG070	18.00			X
5	BRKT SD R RH	(1) 57707SG080	14.40			X
6	BRKT SD R LH	57707SG090	14.40			X
7	COVER HOOK R	57731SG010NN	12.60			X
8	REFLEC AY RH	84281SC000	20.40			X
9	REFLEX AY LH	84281SC010	20.40			X
10	TRIM PNL AY SKIRTR	94026SG000VH	36.00			X
11	GARGO STEP PANEL S/S	E7710SG000	550.00			OK
SUB TOTAL			1090.00	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)			218.00	0.00	0.00	0.00
GRAND TOTAL			872.00	0.00	0.00	0.00
OVERALL TOTAL			872.00			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.

19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SLJ4214X

NETT ITEM	1090.00
LESS 20 %	-218.00
NETT AMOUNT	872.00
LIST ITEM	0.00
LESS 50 %	0.00
LIST AMOUNT	0.00
SPECIAL NETT AMOUNT	0.00
S/LIST ITEM	0.00
LESS 30 %	0.00
S/LIST AMOUNT	0.00
TOTAL LABOUR CHARGES	1000.00
TOTAL SPARE PARTS CHARGES	872.00
TOTAL CHARGES	1872.00
ADD 7 % GST	131.04
GRAND TOTAL	2003.04



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18003849/Krd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 07-06-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 8829Z	Veh. Inspected	SLU 4214X	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18001480MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	23/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	SUBARU FORESTER (A)	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JF1SJGK85JG102104	Colour	METALLIC GREY	
Odometer	4241	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R18	BRIDGESTONE	9 mm	
L/H Front Tyre	225/55 R18	BRIDGESTONE	9 mm	
R/H Rear Tyre	225/55 R18	BRIDGESTONE	9 mm	
L/H Rear Tyre	225/55 R18	BRIDGESTONE	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/02/2018	Inspection Date	27/02/2018	
Survey held at	MOTOR IMAGE ENTERPRISES PTE LTD 19 TOA PAYOH LORONG 8 SINGAPORE 319255			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		1.500 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 4214X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SKIRT COMPL R (N)	TO REPAIR SEE LABOUR	288.00	-
1	BUMPER FACE REAR FORESTER IL (N)	DEFORMED	540.00	540.00
1	BRKT CORNER R RH (N)	SERVICEABLE	18.00	-
1	BRKT CORNER R LH (N)	SERVICEABLE	18.00	-
1	BRKT SD R RH (N)	SERVICEABLE	14.40	-
1	BRKT SD R LH (N)	SERVICEABLE	14.40	-
1	COVER HOOK R (N)	SERVICEABLE	12.60	-
1	REFLEC AY RH (N)	SERVICEABLE	20.40	-
1	REFLEX AY LH (N)	SERVICEABLE	20.40	-
1	TRIM PNL AY SKIRTR (N)	SERVICEABLE	36.00	-
1	CARGO STEP PANEL S/S (N)	NECESSARY	550.00	550.00
	LESS 20% DISCOUNT		-306.44	-218.00
			1,225.76	872.00
SPECIAL NETT ITEMS				
1	SUNDRIES (SN)	NOT NECESSARY	100.00	-
			100.00	-
LABOUR				
	REMOVE/REPLACE REAR BUMPER, END PANEL INCLUSIVE OF THE REPAIR OF SKIRT COMPL R.		1,120.00	560.00
	RESPRAY REAR BUMPER, END PANEL.		840.00	420.00
	TO CONDUCT REAR LIGHTING TEST.		50.00	20.00
	TO SUPPLY AND INSTALL REVERSE SENSOR-2 EYES.	NOT NECESSARY	300.00	-
			2,310.00	1,000.00
GRAND TOTAL			3,635.76	1,872.00
RECOMMENDED COST OF REPAIRS				1,872.00

Report Ref No. CS/FC118003849/Krd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.