

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0637/2018
DATE : 19-FEB-2018

FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 62222311 / 65063848
FAX : 62223547 / 65073849

OWNER'S NAME : PAK CHUN HUA
ADDRESS : BLK 428 PASIR RIS DRIVE 6
#07-25
S(510428)
TELEPHONE NO : 9048 0525

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1700083937
VEHICLE NO : SLU4214X
MODEL CODE : SJGEKK8
MODEL/YEAR : FORESTER 2.0XT AWD CVT
ENGINE NO : FA20CB59098
CHASSIS NO : JF1SJGK85JG102104
MILEAGE : 1 KM
DATE IN : 19/02/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SAYEDINAH ALI**
ACCIDENT DATE : 19/02/2018

Print Date : 21/02/2018
Print Time : 10:35:25

MOTORIMAGE ENTERPRISES PTE. LTD.
 19 LORONG 8, TOA PAYOH
 SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLU4214X

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM)		
2	ZZ/001	CONDUCT THIRD PARTY CLAIM FIRST CAPITAL LOCATION: PIE EXIT TO PASIR RIS DATE:19/02/2018 TIME:1040HRS		
3	ZZ/002	REMOVE/REPLACE REAR BUMPER, END PANEL	<i>nr</i> 1120.00	<i>X</i>
4	ZZ/003	RESPRAY REAR BUMPER, END PANEL	840.00	<i>42d</i>
5	ZZ/004	TO CONDUCT REAR LIGHTING TEST	50.00	<i>2d</i>
6	ZZ/005	TO SUPPLY AND INSTALL REVERSE SENSOR - 2 EYES	<i>na</i> 300.00	<i>X</i>
7	ZZ/006	SUNDRIES	<i>nr</i> 100.00	<i>X</i>
TOTAL LABOUR CHARGES			2410.00	

MOTORIMAGE ENTERPRISES PTE. LTD.
 19 LORONG 8, TOA PAYOH
 SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLU4214X

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
1	SKIRT COMPL R	5.2F 52401SG0109P	288.00	X		
2	BUMPER FACE REAR FORESTER IL	57704SG012	540.00	X		
3	BRKT CORNER R RH	57707SG060	18.00	X		
4	BRKT CORNER R LH	57707SG070	18.00	X		
5	BRKT SD R RH	(1) 57707SG080	14.40	X		
6	BRKT SD R LH	57707SG090	14.40	X		
7	COVER HOOK R	57731SG010NN	12.60	X		
8	REFLEC AY RH	84281SC000	20.40	X		
9	REFLEX AY LH	84281SC010	20.40	X		
10	TRIM PNL AY SKIRTR	94026SG000VH	36.00	X		
11	CARGO STEP PANEL S/S	E7710SG000	550.00	X		
SUB TOTAL			1532.20	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)			306.44	0.00	0.00	0.00
GRAND TOTAL			1225.76	0.00	0.00	0.00
OVERALL TOTAL			1225.76			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLU4214X

TOTAL LABOUR CHARGES	2410.00
TOTAL SPARE PARTS CHARGES	1225.76
GRAND TOTAL	3635.76 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

*Not Authorized
Resurvey After Paint
Holiday
1' Holiday*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.