

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

27-Feb-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6017 C

1 pc	Rear bumper <i>X repair</i>	\$	696.00
1 pc	Rear bumper lower cover <i>X</i>	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 <i>X</i>	\$	58.00
		\$	960.00
Less 10%		\$	96.00
		\$	864.00

S/NETT

1 set	Rear bumper clips <i>X</i>	\$	48.00
1 set	Reverse sensor <i>X</i>	\$	280.00
<i>1 pc</i>	<i>rear bum top protector</i> <i>—</i>	\$	80.00 <i>50</i>
	Sundry	\$	50.00 <i>X</i>
	To dismantle / replace/test reverse sensor to new bumper and reset to the same	\$	120.00 <i>X</i>
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the rear bumper, etc	\$	550.00 <i>100</i>
	To putty and spray painting on rear bumper, end panel	\$	500.00 <i>180</i>
	To apply rustproofing on the repaired and replaced panels.	\$	150.00 <i>X</i>
		\$	2,562.00

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Kalvin LKK
27/2/18 1535hrs
2 days.
4/5
After Repair photo.