



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS



OK
01/04/2018

EQ INSURANCE COMPANY LTD 5 Maxwell Road #17-00 Tower Block MND Complex, Singapore 069110 ATTN. : MOTOR CLAIMS FAX :		NAME : Ms Lin Chunyan ADDRESS : 12 Arumugam Road #05-03 LION BLDG Singapore 409958 TEL : 90662028	WIP : 62394 EXCESS : DATE: 13-Feb-18
---	--	--	---

VEH NO :	SKR2959X	DATE IN :		CONTACT PERSON :	RONALD 6395 7875
CHASSIS NO :	JM6KE1071F0275541	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA CX5 2L	DATE REG.:	29-Jan-15	POLICY NO. :	

NATURE OF WORKS

Parts Description

NO		QTY		REVISED	PRICES
1	REAR BUMPER ✓ SR	1	MKDY7-50-22XDBB		\$ 1,218.00
2	RIVET, REAR BUMPER ✓ NEC	4	ML33X-13-209		\$ 11.20
3	RIVET, REAR BUMPER ✓ NEC	2	ML33X-13-209		\$ 5.60
4	GROMMET, REAR BUMPER ✓ NEC	6	MH260-50-841		\$ 16.80
5	TAPE PROTECTOR, REAR BUMPER ✓ NEC	2	MG043-62-864A		\$ 6.60
6	MAZDA, EMBLEM ✓ NEC	1	MKD53-51-721		\$ 45.30
7	MASCOT, REAR ✓ NEC	1	MKD53-51-731		\$ 51.70
8	SKYACTIV, EMBLEM ✓ NEC	1	MKD53-51-771		\$ 71.60
9	GASKET(LHS), TAILLAMP ✓ NEC	1	MKD54-51-163A		\$ 35.20
10	GASKET(RHS), TAILLAMP ✓ NEC	1	MKD54-51-153A		\$ 35.20
11	RHS TAILLAMP ✓ CRA	1	MKD54-51-150E		\$ 560.00
12	FASTENER, TAILLAMP ✓ NEC	2	MKD53-51-146B		\$ 7.80
13	GROMMET, TAILLAMP ✓ / NEC	2	MGJ6A-51-14Y		\$ 29.80
14	GASKET(LHS), TAILGATE LAMP X NN	1	MKD53-51-3J8A		\$ 43.70
15	GASKET(RHS), TAILGATE LAMP ✓ NEC	1	MKD53-51-3H8A		\$ 43.70
16	RHS TAILGATE LAMP ✓ CRA	1	MKD53-51-3F0E		\$ 360.80
17	BRACKET(RHS), TAILGATE LAMP ?	1	MKD53-51-3HXA		\$ 30.40
			TOTAL PARTS		\$ 2,573.40
			LESS 10%		\$ 257.34
			TOTAL PARTS COST		\$ 2,316.06

Labour Description

1	TO REPLACE REAR BUMPER. TO REPAIR TAILGATE, RHS REAR FENDER AND ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 1,980.00
2	TO RESPRAY REAR BUMPER, TAILGATE AND RHS REAR FENDER.	\$ 2,520.00

1320
1260

3	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.		\$ 250.00 150
4	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.		\$ 660.00 330
5	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		\$ 250.00 150
6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		\$ 350.00 180
7	MZ-BR-SUNDRI	SUNDRIES.	NETT	\$ 100.00 30
			TOTAL LABOUR	\$ - \$ 6,110.00
			TOTAL PARTS	\$ - \$ 2,316.06
			TOTAL	\$ - \$ 8,426.06
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ -
			GST 7%	\$ - \$ -
			GRAND TOTAL	\$ - \$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature

Without Prejudice
Parts By Parts.
Parts Price Subject To Confirmation
Parts / Resurvey Before Paint
4-5 Days Repaid.
Wilson, LKK
Tel: 67418434 / 6404178
Wilson@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[Signature]
2/3/18