

SawTung

CC4/AXA1800

3869

1/1/18

Surveyor:

MTH

DOI:

ASSIGNMENT

1/1/18

Date / Time:

26/1/18

Registered in Merimen:

26/1/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHB 7730A

Name of Insured:

TRANS LAB SERVICES PTE

Insured Tel No.:

HP:

Excess Sec II :SS

\$5000

D.O.A.:

27/1/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

LEE Ah JIEW FAN

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

10471282

Policy No.:

VPX1P16805W

Make / Model:

LUXEVOLET

Place of Accident:

DARTMOUTH DR TWP3 WESTMTE

OI GIA REPORT: YES / NO

YES

NO

TP GIA REPORT: YES / NO

YES

NO

Insured Liability:

%

Final? Yes / No

SUMMARY



INSRS:

WSP:

Tel:

Liability:

RMKS:

VOLKSWAGEN



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

1/1/18  
2018

SUMMARY - SHB 7730A - X

Email liability unclear.

FILES REVIEWED. CON. of conflicting version.

EXHIBITS STATED that TP turned right and valid

and OI vehicle, which was travelling straight.

Send email to OI to notify TP claim.

18/3/19

FROM FOR CLAIMANT DID NOT SEND IN THE VEH FOR REPAIR TILL DATE.

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

1903208

After call Itr to OI:

21 (By email)

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

SS

Loss of Rental (LOR):

SS

(

days)

Loss of Use (LOU):

SS

(\$

x

days)

Loss of Income (LOI):

SS

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/Independent)

Legal Cost

SS

Total:

SS

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

Name 1:

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT  
10/6/19620 travelling straight and  
turning into main road.

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP/OP

3) Survey fee:

+250

2017 April

The UIC | Chassis frame | Body Structure affected due to collision

Price: \$7,087.80 (250) + \$1,528.79 43% Exclude (450) (75) + \$1,036.79.

Lump Sum: 18.13




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/AXA18003869/kb3	
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date : 28-02-2018	
		Code : AXA2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SHB 7730A	Veh. Inspected	SLM 9041P
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	28/02/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	23/02/2018	Inspection Date	
Survey held at	VOLKSWAGEN GROUP SINGAPORE PTE LTD 247 ALEXANDRA ROAD SINGAPORE 159934		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIR			

Tanaka 97495749  
1/3/18 @ 1130  
WP  
5 days

\* Resurvey before paint  
sur@lkkauto.com

PDI TUAS

Phone No.  
Fax No.  
E-Mail

VAT Registration No. M20098505-2  
Tax No. 199101494Z

PDI TUAS

ZHANG HUI  
815C CHOA CHU KANG AVENUE 7  
#19-47  
Singapore, 683815  
Singapore

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:

## Service Quote

Customer No. CV037100  
Quote No. SER/QUO/1800331  
QuoteDate 26/02/18  
Salesperson Darren Peh  
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	SPORTSVAN 1.4 TSI CL	15,155	Kong Charmaine
License No.	VIN	Initial Registration	Sales Advisor
SLM9941P	WVWZZZAUZGW562688	19/04/17	Darren Peh
Engine Code	Labor Type	Engine No.	Model Code
	1T	CZC 427740	AM13HZ

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P ALEX LABOUR	LABOUR	5	UNIT		1680 4,200.00
P B&P ALEX PAINT	SPRAY PAINT	4	UNIT		1600 3,200.00
P B&P NUMBER PLATE	B&P NUMBER PLATE -NETT	1	pcs		bt 80.00
P B&P DIAG	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC	1	Time Un		✓ 480.00
P B&P MECH	ELECT WIRING & MECH COMPO Nett	1	Time Un		✓ 280.00
	<b>Sum Labor</b>				<b>8,240.00</b>
P 510805931	HEADLAMP SUPPORT LH	1	Pieces		? 40.63
P 510805915A 9B9	RETAINER/SPOILER	1	Pieces		? 217.03
P 510807049A	BUMPER LH	1	Pieces		? 19.04
P 510807217AMGRU	FRT BUMPER COVER	1	Pieces		de ✓ 999.96
P 510807248A	FOAM INSERT Predecessor 510807248	1	Pieces		? 48.82
P 510807723D	BUMPER SUPP.PART LH	1	Pieces		? 26.13
P 510807724D	BUMPER SUPP.PART RH	1	Pieces		? 39.66
P 510823031M	BONET HOOD Use Predecessor 510823031G	1	Pieces		bt ✓ 869.93
P 510853211C 9B9	COVER PART LH	1	Pieces		? 23.92
P 510853651M ZLL	RADIATOR GRILLE	1	Pieces		con ✓ 345.95
P 510853665C 9B9	GRILLE	1	Pieces		con ✓ 77.01
P 510853677E 9B9	LOWER GRILLE	1	Pieces		cut ✓ 142.28
P 518941005C	HEADLAMP LH Predecessor 518941005B	1	Pieces		cut ✓ 526.89
P 5G0804593	HEADLAMP BRACKET LH	1	Pieces		net ✓ 5.79
	<b>Sum carried forward</b>				<b>11,623.04</b>

Payments to: - BBN: - Acc.-No.:

PDI TUAS

PDI TUAS

ZHANG HUI  
815C CHOA CHU KANG AVENUE 7  
#19-47  
Singapore, 683815  
Singapore

Phone No.  
Fax No.  
E-Mail

VAT Registration No. M20098505-2  
Tax No. 199101494Z

## Service Quote

Customer No. CV037100  
Quote No. SER/QUO/1800331  
QuoteDate 26/02/18  
Salesperson Darren Peh  
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	SPORTSVAN 1.4 TSI CL	15,155	Kong Charmaine
License No.	VIN	Initial Registration	Sales Advisor
SLM9941P	WVWZZZAUZGW562688	19/04/17	Darren Peh
Engine Code	Labor Type	Engine No.	Model Code
	1T	CZC 427740	AM13HZ
Continued			11,623.04
P 5G0807109H	BEAM	1 Pieces	460.95
	Use Predecessor 5G0807109B		
P 5G0807651A	MEMBER	1 Pieces	162.61
	Sum Item		4,006.60
Sum Labor			8,240.00
Sum Item			4,006.60
Total SGD			12,246.60
7% GST			857.26
Total SGD Incl. GST			13,103.86

### Explanations

P = Proportionately Charged

Payment Terms No Credit

Payments to: - BBN: - Acc.-No.:

## Zaini (LKK Auto)

---

**From:** Zaini (LKK Auto)  
**Sent:** Thursday, 15 March 2018 3:20 PM  
**To:** claims@transcab.com.sg  
**Cc:** Hsiao Tong (LKKAuto); 'carrisalee@ava-ins.com'; 'icewong@ava-ins.com'; 'ireneng@ava-ins.com'; 'foonghon@ava-ins.com'  
**Subject:** YOUR REF : P1680520 (SHB 7730A)\_ACCIDENT INVOLVING SHB 7730A & SLM 9941P ALONG GATEWAY DRIVE ON 23/02/2018

15 MARCH 2018

Transcab Taxi  
Singapore

Dear Sir/Madam,

**OUR REF : CC4/AXA18003869/T1kb3**  
**YOUR REF : P1680520 (SHB 7730A)**  
**ACCIDENT INVOLVING SHB 7730A & SLM 9941P ALONG GATEWAY DRIVE ON 23/02/2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from VOLKSWAGEN CENTRE SINGAPORE acting on behalf of the owner of SLM 9941P against your motor insurance policy.

Based on the accident report, accident scenario, this is a conflicting version pending concrete evidence from both parties to determine the liable party.

We also wish to advise that there is an excess of **\$55,000.00** attached with Third Party Claims. Please be informed that you shall be liable for the excess following any settlement of the third party claim.

AXA shall keep you informed of the third party claim settlement and thereafter kindly let AXA have the excess payment in your cheque payable to "AXA Insurance Pte Ltd". Please indicate your vehicle registration number and the date of accident on the back of the cheque.

Notwithstanding the excess being applied and/or received by AXA for the above subject matter, AXA expressly reserves all their rights under the policy to refund the excess payment in the event that there arises any known policy breach and or exclusion material to coverage.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this email. Your intent must be formally expressed to us and acknowledged by AXA.

Your full co-operation in the handling of the claim is required and kindly submit the following **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)

- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without our prior knowledge and consent. If you receive any correspondence or legal document such as a Writ of Summons in connection with this accident, please forward it to us immediately. You may email it to [cst@axa.com.sg](mailto:cst@axa.com.sg) / [Zaini@lkkauto.com](mailto:Zaini@lkkauto.com) or deliver it by hand to our Customer Care Centre.

This email should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorized driver may have committed.

In the event of receiving and handling of any third party injury claim(s), we shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact our Claims Service Team at 1800-880 4888 at our operating hours 9:00am to 5:30pm (press 1 for GI and option 3 for claims) or [cst@axa.com.sg](mailto:cst@axa.com.sg) / [Zaini@lkkauto.com](mailto:Zaini@lkkauto.com). Please quote our claim reference when you contact us that we can assist you more effectively.

Thank you.

Best Regards,

**Zaini Kusaini** | Case Handler

**LKK Auto Consultants Pte Ltd**

DID: 6841-2132 | email: [Zaini@lkkauto.com](mailto:Zaini@lkkauto.com) | fax: 6741-4108

Blk 51 Poyatol Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Print Sent Message

This mail is associated with :

**\*SLM9941P (C0471282)**

**[SHB7730A]**

**TP**

**ZHANG HUI**

**Feb 23 2018 12:00AM**

**[TRANS-CAB SERVICES PTE LTD]**

**Volkswagen Group Singapore Pte Ltd**

**From** LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on 18/03/2019 16:14 PM.  
**To** stacey.ng@axa.com.sg  
**CC** AXA\_SG; ashersng@lkkauto.com  
**Subject** Re: New TP Assignment - C0471282/P1680520

Hi Stacey,

We refer to the above matter.

Wsp inform that the claimant did not came back for repair up to date.

In view of above we will process to submit our w/p report and close of the case.

Thank you  
Asher Sng  
LKK auto consultants

<-- Original Message -->

**From:** AXA\_SG  
**To:** LKK\_HQ;sur@lkkauto.com;assignments@lkkauto.com  
**CC:** AXA\_SG  
**Sent On:** 28/02/2018 12:11 PM  
**Subject:** New TP Assignment - C0471282/P1680520

Dear LKK Auto Consultants Pte Ltd,

Please survey the vehicle and proceed for direct settlement if damages consistent.

Workshop Name: Volkswagen Group Singapore Pte Ltd  
Policy Number: P1680520  
Vehicle Number: SLM9941P  
Date of Accident:23/02/2018  
Estimated Claim Amount:  
Excess: 5000.00  
Claim Handler Name: Khor Saw Theng



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Feb 2018		28 Feb 2018 12:11 <a href="#">Edit Adj Rpt</a>	<b>\$47,087.81</b> <a href="#">Edit Estimates</a>	<b>\$47,087.81</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: <b>TRANS-CAB SERVICES PTE LTD</b> , Co. Reg. No.: -									
Main Claimant: <b>ZHANG HUI</b> , ID: S2731525I									
Vehicle Reg. No.:	<b>SLM9941P</b>	Date of Loss:	23/02/2018 00:00 - :59 [10 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / C0471282</b>	Policy/Cover Note No.:	P1680520 (Third Party Only)						
Vehicle Reg. No. (Insured):	<b>SHB7730A</b>	Policy No. (Claimant):	A28946151AVW						
		Excess:	S\$5,000.00						
Repairer:	<b>Volkswagen Group Singapore Pte Ltd (-)</b> 247 ALEXANDRA ROAD, 159934 Alexandra - Tel: 63057293								
Handling Insurer:	<b>AXA Insurance Pte Ltd (HQ)</b> - Tel: 6338 7288 ... [Handled by <b>Stacey Ng</b> - 6880 4351]								
Claimant's Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... [Final Rpt due 09/03/2018]								
Adj Asg. Remarks:	TP is ARC workshop.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AXA_SG (28/02/2018): <b>New TP Assignment - C0471282/P1680520</b></li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLM9941P (C0471282)  
 [SHB7730A]  
 TP  
 ZHANG HUI  
 Feb 23 2018 12:00AM  
 [TRANS-CAB SERVICES PTE LTD]  
 Volkswagen Group Singapore Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

Upload Video

Upload Audio

View

View in Browser

Assessment Reports

1 per page

☒

No	Finalized On	AXA Insurance Pte Ltd (HQ)		Thumbnail	Print
1	28/02/18 12:10	<b>Accident Statement</b> From: SC - Reg. No: SHB7730A, Claimant: TRANS-CAB SERVICES PTE LTD		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	02/03/18 14:18	<b>Adjuster Immediate Advice</b>		Load HTM	

Photos/Images

3 per page

☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	04/06/19 18:21	<b>LKK Survey Photo</b>		Load PDF	

Documentation

1 per page

☒

No	Finalized On	AXA Insurance Pte Ltd (HQ)		Thumbnail	Print
1	26/02/18 12:03	<b>EMAIL_ABS</b>		Load PDF	
2	26/02/18 12:03	<b>CO CLAIMANT TP_ABS</b>		Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	02/03/18 15:16	<b>TP ESTIMATE- MARKED</b>		Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA18003869/T1EB3Q2

Date: 17/06/2019

### REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No:

P1680520

Claimant Vehicle No : SLM9941P

Insured Vehicle No :

SHB7730A

Date of Loss: 23/02/2018

Nature of Claim:

TP

Claim No: C0471282

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLM9941P

Make &amp; Model: VOLKSWAGEN SPORTSVAN, 1.4 (A)

Engine No: CZC427740

Reg. Date: 19/04/2017 (Man. Year: 2015)

Chassis No: WVVZZZAUZGW562688

Colour: White

Odometer: 22271 km

Engine Capacity: 1395 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size:

225/45 R17

Front Left Side: Bridgestone 6 mm

Rear Left Side:

Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side:

Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,086.60	3,047.81	1,038.79	25.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,160.00	4,040.00	4,120.00	50.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>12,246.60</b>	<b>7,087.81</b>	<b>5,158.79</b>	<b>42.12</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>857.26</b>	<b>496.15</b>	<b>361.11</b>	<b>42.12</b>
<b>Nett Amount (S\$)</b>	<b>13,103.86</b>	<b>7,583.96</b>	<b>5,519.90</b>	<b>42.12</b>

### INSPECTION

Date of Assignment: 28/02/2018

Date Inspected: 01/03/2018 Inspected At:

Volkswagen Group Singapore Pte Ltd (-)  
247 ALEXANDRA ROAD  
Singapore 159934

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 16 Jun 2019)	
<b>Parts:</b>	N/A	VOLKSWAGEN SPORTSVAN 1.4 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLM9941P)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP SUPPORT LH (CONSISTENT)	*Check	40.63 FS	*- FS
2	1		*RETAINER /SPOILER (CONSISTENT)	*Check	217.03 FS	*- FS
3	1		*BUMPER LH (CONSISTENT)	*Check	19.04 FS	*- FS
4	1		*FRT BUMPER COVER (CONSISTENT)	Deformed	999.96 FS	*999.96 FS
5	1		*FOAM INSERT (CONSISTENT)	*Check	48.82 FS	*- FS
6	1		*BUMPER SUPP,PART LH (CONSISTENT)	*Check	26.13 FS	*- FS
7	1		*BUMPER SUPP,PART RH (CONSISTENT)	*Check	39.66 FS	*- FS
8	1		*BONET HOOD (CONSISTENT)	Bent	869.93 FS	*869.93 FS
9	1		*COVER PART LH (CONSISTENT)	*Check	23.92 FS	*- FS
10	1		*RADIATOR GRILLE (CONSISTENT)	Cracked	345.95 FS	*345.95 FS
11	1		*GRILLE (CONSISTENT)	Cracked	77.01 FS	*77.01 FS
12	1		*LOWER GRILLE (CONSISTENT)	Cut	142.28 FS	*142.28 FS
13	1		*HEADLAMP LH (CONSISTENT)	Cut	526.89 FS	*526.89 FS
14	1		*HEADLAMP BRACKET LH (CONSISTENT)	Necessary	5.79 FS	*5.79 FS
15	1		*B&P NUMBER PLATE (CONSISTENT)	Bent	80.00 FS	*80.00 FS
16	1		*BEAM (CONSISTENT)	*Check	460.95 FS	*- FS
17	1		*MEMBER (CONSISTENT)	*Check	162.61 FS	*- FS
<b>Total Parts (\$\$)</b>					<b>4,086.60</b>	<b>3,047.81</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR	New	4,200.00	1,680.00
2	SPRAY PAINT	New	3,200.00	1,600.00
3	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC	New	480.00	480.00
4	ELECT WIRING & MECH COMPO	New	280.00	280.00
Gross Labour Cost (S\$)			8,160.00	4,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >