



HUA HONG PRIVATE LIMITED

25D Sungel Kadut Street 1 Singapore 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

23 April 2018

HHTPClaims18-31

AXA Insurance Pte Ltd
8 Shenton Way
#27-01 AXA Tower
Singapore 068811

Attn: Motor Claims Department

ACCIDENT INVOLVING SKW 9413 G & SBL 9349 Z ON 26/2/2018 AT BLK 41 HOLLAND DRIVE CARPARK AT ABOUT 1800 HOURS

Insured : LEE SIEW PENG MARGARET
Vehicle Registration No : SKW 9413 G
Vehicle Make : SUBARU
Vehicle Model : FORESTER 2.0I-L CVT AWD SR
Vehicle Chassis No : JF18J5KC8FG059607
Policy No : P1669435
Date of Accident : 26/2/2018

			Type of Claim: Third Party	
S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Front Bumper ✓ Defor.		\$ 600.30
2	10	Front Bumper Clip ✓ N/E C	\$ 3.90	\$ 39.00
3	2	Front Bumper Retainer (LH/RH) ✓ N/E C	\$ 27.10	\$ 54.20
4	1	Front Bumper Foam X NSP		\$ 140.30
5	1	Front Reinforcement ✓ DT		\$ 320.30
				\$ 1,154.10
			Less 10%	\$ (115.41)
				\$ 1,038.69
6	1	Front Number Plate ✓ DT	NETT	\$ 35.00

To dismantle, change front bumper, front bumper foam, front reinforcement, knocking and pull straight front panel and all area affected by accident. \$ ~~600.00~~ 400.

To perform wire checking. \$ 20.00 ✓

To spray front bumper and front reinforcement. \$ ~~600.00~~ 400.

4 days.

\$ 2,293.69
7% GST \$ 160.56
Total \$ 2,454.25

Authorised by Claims Dept
Mrs Tan @ 9639 9195



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Sebastian.
27/4/18.
- Part by part repair.
- Photo Before Paint
90036121
sebastian.yang@lkkauto.com

28/4/18
about PIP \$1767.42 / 3 days.

PIP \$1767.42 / 3 days