

ASS. REC. BY:

REF:

CS / FCL 800 3888 / Kiber

Special Instruction:

Surveyor:

Vinith

ASSIGNMENT (Office)

From (Person):

CWS Lurina Jaw

of

FCL

Date/Time:

27/02/2018 6:11 pm

Estimated Cost:

Bill to:

OD / ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 53603

Insured:

SH A 37P

at Workshop m/s

Trans Cab

Tel:

of

No. 2 Amk st 63

Policy No:

Claim No:

D18001674MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

26022018

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SHC 53603 - 100 (AY) 17003873 Job3 Dop - 2017
	SH A 37P - 100 (AY) 17003873 Job3 Dop - 2018



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18003888/Ktb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 28-02-2018



Code : FCI2

1. Policy Particulars - THIRD PARTY CLAIM

Insured Veh.	SHA 39P	Veh. Inspected	SHC 5360S
Policy No.		Coverage (\$)	0.00
Claim No.	D18001674MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	27/02/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	26/02/2018	Inspection Date	28/02/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

MOTOR SURVEY ASSIGNMENT

Date 27-02-2018 **Our Ref No.** D18001674MFSH

Accident Date 26-02-2018 **Claim Type.** Third Party

Insured Vehicle SHA0039P **Third Party Vehicle.** SHC5360S

Survey Location NO. 2 ANG MO KIO STREET 63

Contact Person. JIONG HOW NG

Contact No. 62876666/ 0 **Fax No.** 62571330

Survey Type WITHOUT PREJUDICE:

Appointed Surveyor LKK AUTO CONSULTANTS PTE LTD

Contact Person NA **Fax No.** 68416315

Contact Number. NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop TRANS-CAB AUTO SERVICES PTE LTD **Attention.** NIL

Cc : TP Solicitor NA **TP Solicitor Fax No.** NA

Officer Incharge LURENE

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/235403) PRI Documents Close	
---	--

PRI Header Details

Claim No	D18001674MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & TR PTE LTI
Workshop Name	TRANS-CAB AUTO SERVICES PTE LTD (Contact Person : JIONG HOW NG)	Survey Location & Contact Details	NO. 2 ANG MO KIO STREET 63 Mobile: 0 , Phone: 62876666 , Fax: 6257133 EmailId: JIONGHOW.NG@TRASCAB.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHA0039P	TP Vehicle No	SHC53
PRI Recieved Date	27-02-2018 06:32:02 PM	Surveyor Appointed Date	27-02-2018 06:14:01 PM	Surveyor Accept Date	28-02-

Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	28-02-2018	Upload Survey Report *:	<input type="text"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	----------------------

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

<input type="button" value="Upload Multiple Documents"/>	
File Name	Action

Surveyor Job Remarks

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 3878K

Vehicle Details

Vehicle No.: SHC53605

Vehicle to be Exported: Yes

Intended De-registration Date: 26 Feb 2018

Vehicle Make: RENAULT

Vehicle Model: LATITUDE 2.0L DCI AUTO D/AB 4DR

Primary Colour: Red

Manufacturing Year: 2014

Engine No.: M9R8839C001716

Chassis No.: VF1ABL15AUC279599

Maximum Power Output: 127.0 kW (170 bhp)

Open Market Value: \$19,998.00

Original Registration Date: 14 Oct 2014

First Registration Date: 14 Oct 2014

Transfer Count: 0

Actual ARF Paid: \$12,498.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 13 Oct 2022

PARF Rebate Amount: \$9,373.00

Intended COE Rebate Details

COE Expiry Date:	13 Oct 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,938.00
COE Rebate Amount:	\$29,476.00
Total Rebate Amount:	\$38,849.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 26 Feb 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/02/2018 09:12
Date Of Accident	26/02/2018 05:15
Exact Location Of Accident	AIRPORT T3 TAXI QUEUE CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC5360S
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666
Vehicle Particulars	
Manufacturer	RENAULT
Model	LATITUDE-2.0 DCI AUTO D/AB 4DR (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	
Driver	
Name of Driver	TEO POH CHAI
NRIC No	S1814047J
Date Of Birth	10/07/1967
Occupation	OUTDOOR
Date Of Driving Pass	02/06/1994
Driving Experience	23 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90020228
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address BLK 520B TAMPINES CENTRAL 8
#07-47

Postcode 522520

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - HIRER

Vehicle Registration Number of Driver's Own Vehicle -
-
-

Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident CHAIN COLLISION

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident 3

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

On the 26.02.2018 at about 0514hours, i was stationary along the center lane of airport Terminal 3 taxi stand queue carpark. Suddenly i felt an impact. I alighted and realized that Vehicle B(SHA39P) had hit onto my taxi's rear portion and i was engaged i n a chain collision accident involving Vehicle B and Vehicle C(SHD2276S)

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category TAXI

Name of Driver TAY GIM CHEW

NRIC/Passport Number S1789333E

Contact Number 82187676

Address BLK 146 BISHAN STREET 11
#05-55

Postcode 570146

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SHD2276S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	SUI SEE TECK
NRIC/Passport Number	S7629523f
Contact Number	97838968
Address	BLK 309 SERANGOON AVENUE 2 #08-148
Postcode	550309
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **reputate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please refer to GID report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

[Signature]
Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO 201019626G

SHC5360S -

AAD1802-233

*Not Authored
L/Lm \$8450p*

Vehicle No.:	SHC5360S - JHOW
Chassis No.:	VF1ABL15AUC279599
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	26.02.2018
Third Party Insurer :	FCIL

	PART		LIST
1	1 BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46 ✓
2	1 BUMPER LOWER REAR	\$	<i>D/1/1/1</i> 768.84 ✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>D/1/1</i> 113.47 ✓
4	1 BUMEP R BRACKET SIDE RH REAR	\$	<i>Su</i> 135.97 X
5	1 BUMEP R RETAINER RH REAR	\$	<i>Su</i> 44.99 X
6	1 BUMPER REFLECTOR RH	\$	<i>Su</i> 43.61 X
7	1 BUMEP R BRACKET SIDE LH REAR	\$	<i>Su</i> 135.97 X
8	1 BUMEP R RETAINER LH REAR	\$	<i>Su</i> 44.99 X
9	1 BUMPER REFLECTOR LH	\$	<i>C/D/1</i> 43.61 ✓
10	1 BUMPER BEAM REAR	\$	<i>B/1</i> 777.52 ✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>B/1</i> 225.95 ✓
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>D/1/1</i> 225.95 ✓
13	1 BOOT REAR	\$	<i>Bu</i> 2,872.68 ✓
14	1 BOOT FINISHER	\$	<i>Su</i> 470.06 X
15	1 BOOT WHEATERSTRIP	\$	<i>Su</i> 323.05 X
16	1 BOOT REFLECTOR LAMP LH	\$	<i>Su</i> 493.35 X
17	1 BOOT REFLECTOR LAMP RH	\$	<i>Su</i> 493.35 X
18	1 BOOT BADGE 'RENAULT'	\$	<i>Nu</i> 225.36 ✓
19	1 BOOT BADGE	\$	<i>Nu</i> 225.36 ✓
20	1 BOOT STRUT LH	\$	<i>Su</i> 276.08 X
21	1 BOOT STRUT RH	\$	<i>Su</i> 276.08 X
22	1 BOOT HINGE LH	\$	<i>R</i> 367.84 X ⊗
23	1 BOOT HINGE RH	\$	<i>R</i> 367.84 X ⊗
24	1 BOOT INNER TRIM	\$	<i>Su</i> 586.45 X
25	1 BOOT SWITCH	\$	<i>Su</i> 168.13 X
26	1 BOOT LOCK	\$	<i>R</i> 202.67 X ⊗
27	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40 X ⊗
28	2 LICENCE PLATE LAMP	\$	<i>Su</i> 50.52 X
29	2 BOOT RUBBER PLUG	\$	<i>Su</i> 221.81 X
30	1 FENDER PANEL INNER TRIM REAR LH	\$	<i>Su</i> 671.45 X
31	1 FENDER PANEL REAR LH	\$	<i>R</i> 3,299.13 X ⊗
32	1 WHEELARCH REAR LH	\$	<i>Su</i> 543.47 X
33	1 FENDER PANEL INNER TRIM REAR RH	\$	<i>Su</i> 671.45 X
34	1 FENDER PANEL REAR RH	\$	<i>R</i> 3,299.13 X ⊗

TRANS-CAB AUTO SERVICES PTE LTD

AAD1802-233

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO 201019626G

SHC5360S -

35	1	WHEELARCH REAR RH	\$	Sm	543.47	X
36	1	TAILLAMP RH	\$	Sm	552.55	X
37	1	TAILLAMP PANEL RH	\$	R	986.70	X
38	1	TAILLAMP LH	\$	Mjerm	552.55	X
39	1	TAILLAMP PANEL LH	\$	R	986.70	X
40	1	OUTER PANEL REAR (End Panel)	\$	R	1,471.77	—
41	1	OUTER PANEL REAR (End Panel)TRIM	\$	CMA	404.56	—
42	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88	X
43	1	SPARE WHEEL PANEL TRIM	\$	Sm	612.21	X
44	1	EXHAUST REAR	\$	R	7,489.05	X
45	1	EXHAUST CAP REAR	\$	R	230.49	X

TOTAL	\$	35,868.94
10%	\$	3,586.89
	\$	32,282.05

Special Nett

1	1SET	PARKING AID	\$	Short	700.00	—
2	1SET	REAR BUMPER CLIP	\$	NR	66.00	—
3	1SET	BUMPER BRACKET CTR CLIP	\$	NR	33.00	—
4	1SET	BUMEP R BRACKET SIDE CLIP RH RR	\$	NR	10.00	X
5	1SET	BUMEP R RETAINER RH CLIP RR	\$	NR	20.00	X
6	1SET	BUMEP R BRACKET SIDE CLIP LH RR	\$	NR	10.00	X
7	1SET	BUMEP R RETAINER CLIP LH RR	\$	NR	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	NR	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	NR	66.00	—
10	1	EXHAUST MOUNTING REAR	\$	Sm	17.82	X
11	1SET	BOOT FINISHER CLIP	\$	NR	24.20	X
12	1	BOOT STICKER "Trans-cab"	\$	NR	30.00	—
13	1	BOOT STICKER "6555-3333"	\$	NR	30.00	—
14	1	BOOT INNER TRIM CLIP	\$	NR	45.00	X
15	1SET	FENDER WHEELARCH REAR RH CLIP	\$	NR	35.00	X
16	1SET	FENDER WHEELARCH REAR LH CLIP	\$	NR	35.00	X
17	1	FENDER INNER TRIM CLIP LH	\$	NR	28.00	X
18	1	FENDER INNER TRIM CLIP LH	\$	NR	28.00	X
19	1	TAILLAMP CLIP RH	\$	NR	5.00	X
20	1	TAILLAMP CLIP LH	\$	NR	5.00	—
21	2	REAR WINDSCREEN SELANT	\$	NR	80.00	X
22	1	WINDSCREEN MOULDING	\$	NR	100.00	X
23	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	NR	100.00	X
24	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	Sm	385.00	X
25	1	SPARE TYRE	\$	Sm	330.00	X

TRANS-CAB AUTO SERVICES PTE LTD

AAD1802-233

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO 201019626G

SHC5360S -

TOTAL	\$	2,225.02
TOTAL PARTS	\$	34,507.07

Putty And Spray Painting Of The Affected Portion.	\$	4,500.00	6601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	6001
To Rust-Proofing Of The Affected Areas.	\$	170.00	601
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To repair and realign rear exhaust pipe.	\$	170.00	u~
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	} X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	601
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	u~ X
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00	u~ X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	u~ X
Towing Fees	\$	120.00	u~ X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	u~ X
To check steering geometry and computer wheel alignment	\$	220.00	u~ X

TOTAL	\$	11,160.00
Over All Total	\$	45,667.07

Repair Days**15 Days**

5 days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation International (FIA) - Equips En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FC18003888/Ktbe2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 14-03-2018	
		Code : FC12	
1. Policy Particulars - THIRD PARTY CLAIM			
Insured Veh.	SHA 39P	Veh. Inspected	SHC 5360S
Policy No.	D-18088937MFSH	Coverage (\$)	0.00
Claim No.	D18001674MFSH	Excess (\$)	0.00
Assign From	LURENE JAW	Assign Date	27/02/2018
2. Vehicle Particulars - Condition			
Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	VF1ABL15AUC279599	Colour	METALLIC WHITE / RED
Odometer	302217	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	GITI	8 mm
L/H Front Tyre	215/60 R16	GITI	8 mm
R/H Rear Tyre	215/60 R16	GITI	8 mm
L/H Rear Tyre	215/60 R16	GITI	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	26/02/2018	Inspection Date	28/02/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5360S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Qty Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER COVER REAR	BUCKLED	1,108.46	1,108.46
1	BUMPER LOWER REAR	DISTORTED / DENTED	768.84	768.84
1	BUMPER BRACKET CTR REAR	DISTORTED	113.47	113.47
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR LH	CRACKED	43.61	43.61
1	BUMPER BEAM REAR	BENT	777.52	777.52
1	BUMPER BEAM BRACKET LH REAR	BENT	225.95	225.95
1	BUMPER BEAM BRACKET RH REAR	DISTORTED	225.95	225.95
1	BOOT REAR	BUCKLED	2,872.68	2,872.68
1	BOOT FINISHER	SERVICEABLE	470.06	-
1	BOOT WEATHERSTRIP	SERVICEABLE	323.05	-
1	BOOT REFLECTOR LAMP LH	SERVICEABLE	493.35	-
1	BOOT REFLECTOR LAMP RH	SERVICEABLE	493.35	-
1	BOOT BADGE 'RENAULT'	NECESSARY	225.36	225.36
1	BOOT BADGE	NECESSARY	225.36	225.36
1	BOOT STRUT LH	SERVICEABLE	276.08	-
1	BOOT STRUT RH	SERVICEABLE	276.08	-
1	BOOT HINGE LH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT INNER TRIM	SERVICEABLE	586.45	-
1	BOOT SWITCH	SERVICEABLE	168.13	-
1	BOOT LOCK	TO REPAIR SEE LABOUR	202.67	-
1	BOOT LOCK CATCH	TO REPAIR SEE LABOUR	74.40	-

Report Ref No. CS/FCI18003888/Ktbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	LICENCE PLATE LAMP	SERVICEABLE	50.52	-
2	BOOT RUBBER PLUG	SERVICEABLE	221.81	-
1	FENDER PANEL INNER TRIM REAR LH	SERVICEABLE	671.45	-
1	FENDER PANEL REAR LH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR LH	SERVICEABLE	543.47	-
1	FENDER PANEL INNER TRIM REAR RH	SERVICEABLE	671.45	-
1	FENDER PANEL REAR RH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR RH	SERVICEABLE	543.47	-
1	TAILLAMP RH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	-
1	TAILLAMP LH	MTG CRACKED	552.55	552.55
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	986.70	-
1	OUTER PANEL REAR (END PANEL)	BENT	1,471.77	1,471.77
1	OUTER PANEL REAR (END PANEL) TRIM	CRACKED	404.56	404.56
1	SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	TO REPAIR SEE LABOUR	2,189.88	-
1	SPARE WHEEL PANEL TRIM	SERVICEABLE	612.21	-
1	EXHAUST REAR	TO REPAIR SEE LABOUR	7,489.05	-
1	EXHAUST CAP REAR	TO REPAIR SEE LABOUR	230.49	-
	LESS 10% DISCOUNT		-3,586.89	-901.61
			32,282.03	8,114.47
	SPECIAL NETT ITEMS			
1	SET PARKING AID (SN)	SHORTED	700.00	700.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-

Report Ref No. CS/FCI18003888/Ktbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Oil Adjusted (\$)
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
1	EXHAUST MOUNTING REAR (SN)	SERVICEABLE	17.82	-
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	24.20	-
1	BOOT STICKER "TRANS-CAB" (SN)	NECESSARY	30.00	30.00
1	BOOT STICKER "6555-3333" (SN)	NECESSARY	30.00	30.00
1	BOOT INNER TRIM CLIP (SN)	NOT NECESSARY	45.00	-
1	SET FENDER WHEELARCH REAR RH CLIP (SN)	NOT NECESSARY	35.00	-
1	SET FENDER WHEELARCH REAR LH CLIP (SN)	NOT NECESSARY	35.00	-
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-
1	TAILLAMP CLIP RH (SN)	NOT NECESSARY	5.00	-
1	TAILLAMP CLIP LH (SN)	NOT NECESSARY	5.00	5.00
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	SPARE TYRE RIM (ROUE 7J 16H 2547) (SN)	SERVICEABLE	385.00	-
1	SPARE TYRE (SN)	SERVICEABLE	330.00	-
			2,225.02	930.00
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,500.00	660.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BOOT HINGE LH, BOOT HINGE RH, BOOT LOCK, BOOT LOCK CATCH, FENDER PANEL REAR LH, FENDER PANEL REAR RH, TAILLAMP PANEL RH, TAILLAMP PANEL LH, SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL), EXHAUST REAR AND EXHAUST CAP REAR.		4,200.00	600.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	60.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-

Report Ref No. CS/FCI18003888/Ktbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (S)	Est. Adjusted (S)
	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TOWING FEES.	NOT NECESSARY	120.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
			11,160.00	1,500.00
	GRAND TOTAL		45,667.05	10,544.47

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			8,450.00
---	--	--	-----------------

Report Ref No. CS/FC18003888/Ktbe2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.