

22/03/2018

ASS. REC. BY:

REF:

CS/CTI18003891/Tinb

Special Instruction:

Surveyor:

Tanjah

ASSIGNMENT (Office)

Momen

From (Person):

Irene Tay

of

CTI

Date/Time:

28/02/2018 12:26pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBC 2917C

Insured:

GZ 3837M

at Workshop m/s

Falcon - Air

Tel:

6719 5665.

of

No. 8 Pandan Loop (Blk K / Blk 1)

Policy No:

DMCVSN13067891700

Claim No:

SNM18D01041C02

Sum Insured:

Excess:

Make of Veh:

D.O.A.

24/02/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'Wp'

01/03/2018

H.O.D. Endorsement:

Date/Time:

28/02/2018 1:05pm

Person Contacted:

Andy

Vehicle ☒ IN / ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	GBC 2917C - X
	GZ 3837M - X
	Confirm L/S \$8300 @ 12 days
	Redi \$ 3377.72 , 291.

Station Tampin CTI

ASSIGNMENT

Date 01/03/18

Vehicle GBC 2917C Reg 2011 Oct

Type MCar MCycle Bus Truck Tram Motorcycle

DD TP WS / TR RES / OD RES / EVA / INV / MV

To inspect vehicle No GBC 2917C

at Worksite on Falcon - Air

at No. 8 Pandan Loop (Blk K / Blk L)

Insured

Policy No

Claims No


Sum Insured Excess

Client's Record Andy @ 6779 5665

Make of Vehicle

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value \$34

Q42 Accident Report Consistent? Yes or No

Q43 PP Seen Consistent? Yes or No

Est. Repairs days Fee Yes or No

Sum Insured % G Val Yes or No

CA / REV / REP / 24 HRS lwp

Date Person Contacted Andy Vehicle IN / OUT

Date / Time Action / Instruction

Truck / Trailer

Make Nissan Urvan

Colour Silver Reg 29153

Self Insuring 201801 "Rate Insured Side N / L"

Eng No

Ch No

Gen Cond 6 Paint / Body / Bump

Steering / Brakes 3 Jammed / Leaked / Burnt

Brake 3 Jammed / Leaked / Burnt

Mod 0 / S / R / STD / A / R / M

Tyre Size

R

BS / DUN / EXNOVA / G / FS / L / Z / M / O / HTSU / R / S / M

TOYO / YOKO /

Front

R / S

L / S

Q / Q

Surveyed at

Det. of Damages Fr Rear DS NS UC Roofed

The UIC / Chassis frame / Body Structure affected due to collect

RECEIVED 21 JUN 2018

Cost Time / Fee / Part



Prel. Report
Final Report

Days Of Repair 12

Resurvey No. of Trip 1

Add Fee



Storage
Transport
Towing
...

Region / Format

7P

Sum 8300



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18003891/T1rb

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 28-02-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GZ 3837M	Veh. Inspected	GBC 2917C
Policy No.	DMCVSN3067891700	Coverage (\$)	0.00
Claim No.	SNM18D01041C02	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAY)	Assign Date	28/02/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	24/02/2018	Inspection Date	01/03/2018
Survey held at	FALCON-AIR AUTO SERVICES PTE LTD BLK 8 PANDAN LOOP SINGAPORE 128226		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Feb 2018		28 Feb 2018 14:20 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:			
Main Claimant:	CBL AIRCON ENGINEERING PTE LTD		
Vehicle Reg. No.:	GBC2917C	Date of Loss:	24/02/2018 17:00 - :59
Claim Type:	TP / SNM18D01041C02	Policy/Cover Note No.:	DMCVSN3067891700
Vehicle Reg. No. (Insured):	GZ3837M	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Falcon-Air Auto Services Pte Ltd (Pandan) No 8 Pandan Loop, Clementi - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 09/03/2018]		
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Catherine Chong (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Wednesday, 28 February, 2018 12:26 PM
To: ANDY
Cc: assignments@lkkauto.com
Subject: CTP REF NO. SNM18D01041C02 - GBC2917C CLAIMING TP VS GZ3837M (CHINA TAIPING) DOA 24/02/2018 / OUR REF: TBA

WITHOUT PREJUDICE

Dear Mdm,

We refer to the above matter and your email below.

We will inform LKK, MARCUS Chua to survey.

Regards,

Irene Tay
Claims Department
China Taiping Insurance (Singapore) Pte. Ltd.
3, Anson Road, #16-00
Springleaf Tower,
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389-6192
Fax: 6224 7175
Email: claimsdept@sg.cntaiping.com
Email: irene.tay@sg.cntaiping.com
Website: www.sg.cntaiping.com

28/02/2018 @ 10:53pm
Andy with in

-----Original Message-----

From: ANDY [mailto:andy@falconair.com.sg]
Sent: Wednesday, 28 February, 2018 12:03 PM
To: Irene Tay <irene.tay@sg.cntaiping.com>
Subject: FW: GBC2917C CLAIMING TP VS GZ3837M (CHINA TAIPING) DOA 24/02/2018 / OUR REF: TBA

-----Original Message-----

From: ANDY [mailto:andy@falconair.com.sg]
Sent: Tuesday, February 27, 2018 1:58 PM
To: 'Chong Boon Sen' <boonsen.chong@sg.cntaiping.com>
Subject: RE: GBC2917C CLAIMING TP VS GZ3837M (CHINA TAIPING) DOA 24/02/2018 / OUR REF: TBA

Dear Chong Boon Sen,

Kindly appoint Marcus Chua for this case

Regards
Andy
Falcon-Air Auto Services Pte Ltd

Add : No. 8 Pandan Loop (Blk K / Blk 1) Singapore 128226 Tel No : +65 6779 5665
Fax No : +65 6779 1110

-----Original Message-----

From: Chong Boon Sen [mailto:boonsen.chong@sg.cntaiping.com]

Sent: Tuesday, February 27, 2018 1:38 PM

To: ANDY <andy@falconair.com.sg>

Cc: 'Falcon-Air Pandan ' <pandan@falconair.com.sg>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Lucas Lee <lucas.lee@sg.cntaiping.com>; Angie Foo <angie.foo@sg.cntaiping.com>

Subject: RE: GBC2917C CLAIMING TP VS GZ3837M (CHINA TAIPIING) DOA 24/02/2018 / OUR REF: TBA

WITHOUT PREJUDICE

Dear Andy,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop.

We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

TAY BENG HEE
SAMUEL PHUN
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
DEREK OH SIONG WEE
KALVIN ANG
MARCUS CHUA
SIMON HO
LOW SAR HUEI
HONG FOOK CHOY

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Kindly let us hear from you.

REMARKS:

Kindly take note, the claim handler on this case is Irene Tay 6389 6192.

Thank you.

Regards,
Chong Boon Sen
Claims Executive
Claims

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower

Singapore 079909
Co. Reg. No. 200208384E
DID: 63896171
Fax: 62247175
Email: boonsen.chong@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

-----Original Message-----

From: ANDY [mailto:andy@falconair.com.sg]
Sent: Tuesday, 27 February, 2018 11:33 AM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: 'Falcon-Air Pandan ' <pandan@falconair.com.sg>
Subject: GBC2917C CLAIMING TP VS GZ3837M (CHINA TAIPING) DOA 24/02/2018

Good afternoon Sir / Madam,

I refer to the above-mentioned tp claim against your insured GZ3837M.
Appended within this email are the GIA report and estimate for GBC2917C .

Please arrange for survey at Pandan loop (vehicle in workshop) and advise liability.

Thank you.

Best Regards

Andy

Falcon-Air Auto Services Pte Ltd

Add : No. 8 Pandan Loop (Blk K / Blk 1) Singapore 128226 Tel No : +65 6779 5665

Fax No : +65 6779 1110

Your message is ready to be sent with the following file or link attachments:

GBC2917C ESTIMATE

Note: To protect against computer viruses, e-mail programs may prevent sending or receiving certain types of file attachments. Check your e-mail security settings to determine how attachments are handled.


• This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4175E
Vehicle Details	
Vehicle No.:	GBC2917C
Vehicle to be Exported:	No
Intended De-registration Date:	02 Mar 2018
Vehicle Make:	NISSAN
Vehicle Model:	URVAN PANEL LWB 3.0 5DR 4AT ABS A/B 2WD
Primary Colour:	Silver
Manufacturing Year:	2011
Engine No.:	ZD30295534K
Chassis No.:	JN1MG4E25Z0796710
Maximum Power Output:	-
Open Market Value:	\$31,379.00
Original Registration Date:	13 Oct 2011
First Registration Date:	13 Oct 2011
Transfer Count:	0
Actual ARF Paid:	\$1,569.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	12 Oct 2021
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$34,502.00
COE Rebate Amount:	\$12,455.00
Total Rebate Amount:	\$12,455.00

The information contained herein is correct as at 02 Mar 2018

OK



Start With AdWords Today

Our Specialists Are Here
Answer Your Questions
You Started With AdWords

Advanced Search

Home » Used Cars » Skylink Auto Pte Ltd » Nissan Urvan

- Tools & Tips
- Car Buying
 - Car Selling
 - Car Aftermarket
 - Car Ownership
 - On The Move
 - Lifestyle

Commercial Vehicle



CNY PROMO
1 MONTH FOC RENTAL
TOYOTA HILUX \$1,350
SUZUKI CARRY \$1,300
ALL ALER 8481300 DYLAN 8702300

Nissan Urvan

- Overview
- Financial
- Accessories
- Similar
- Research
- Photos
- Map

- Add to Shortlist
- Add to Compare
- Add a Note
- Report Error
- More Actions
- Share

Car Details

Price	\$36,800	?
Depreciation	\$9,610 /yr <small>View models with similar depreciation</small>	?
Reg Date	30-Dec-2011 <small>(3yrs 9mths 27days COE left)</small>	?
Manufactured	2011	?
Mileage	-	?
Transmission	Manual	?
Engine Cap	2,953 cc	?
Curb Weight	1,800 kg	?
Fuel type	Diesel	?
Features	Excellent Well Maintained. Good Conditions. Servicing Done Regularly.	?
Accessories	Radio, Reverse Sensor.	?
Description	Please Call To Arrange For Viewing.	?
COE	\$37,011	?
OMV	\$29,461	?
ARF	\$1,474	?
Dereg Value	\$14,176 as of today (change)	?
No. of Owners	1	?
Type of Veh	Van	?
Category	-	?
Availability	Available	?

- Add to Shortlist
- Add to Compare
- Add a Note

Posted on: 30-Jan-2018 | Last Updated on: 30-Jan-2018
Tags: Nissan Urvan, 2011 Nissan Urvan, Nissan, Urvan, Used Nissan



Location Map

Price Analysis

Seller Information

Company	Skylink Auto Pte Ltd
	• dealer's pricelist
	• 9 vehs sold 8 vehs available
Address	21 Toh Guan Road East #01-12 <small>Search cars nearby this location</small>
Location	Toh Guan Centre
Office No	62665858
Contact Person(s)	Ah Keong 83801118 Ks Fong 87781561 Ivan 97267664 Nelson 81887141

Upfront Payment

• more Financial Info

Transfer Fee	\$25	?
Down Payment	\$3,680 (change)	Maximum 90% Loan ?
1st Instalment	\$830	?
Total Upfront Payment	\$4,535 (excluding insurance)	?

Estimates based on 90% loan at 3.4% interest rate. Check with seller for exact figure.

Items for Nissan Urvan


• View All

Bridgestone Potenza Adrenalin RE001...
\$1,600

Bidded Complete For Sale
\$8,888


Compare

Useful Services

**STA**
STANDARD TARIFF AGREEMENT

Make sure of this car condition with STA Evaluation.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 26/02/2018 11:19
 Date Of Accident 24/02/2018 17:30
 Exact Location Of Accident TOH GUAN RD
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBC2917C
Insured/Policyholder
 Name Of Registered Owner CBL AIRCON ENGINEERING PTE LTD
 Co Reg No 200714175E
 Email Address NOEMAIL
 Mobile Phone No
 Alternative Phone No OFFICE-88131020

Vehicle Particulars

Manufacturer NISSAN
 Model URVAN-2.4 D (M)
 Exact Purpose for which vehicle was being used at time of accident
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number 5079635201-01
 Cover Note Number

Driver

Name of Driver LIM KENG KWANG
 NRIC No S1429700F
 Date Of Birth 20/10/1960
 Occupation OUTDOOR
 Date Of Driving Pass 22/10/1991
 Driving Experience 26 YEARS AND 4 MONTHS
 Gender MALE
 Mobile Number
 Fax Number
 Contact Number
 EMail Address NOEMAIL

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

Approximate Age

Injuries Sustain

Injured person in which vehicle? GZ3837M

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode



FALCON-AIR

CBL AIRCON ENGINEERING PTE LTD
48 TOH GUAN ROAD E SINGAPORE
608586

Attention : Motor Claim Department

Contact : 65159907 88131020

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

Estimate : ES003122

Date : 27/02/2018
Vehicle Num. : GBC2917C
Make/Model : NISSAN URVAN-2011
Chassis/Eng# : JN1MG4E25Z0796710
Accident Date : 27/02/2018
Claim No. :
Reference : TP NTUC VS CHINA
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

		NETT ITEMS :		
1.	1	RH REAR FENDER		1,972.70 <i>bu</i>
2.	1	TAILGATE		1,916.20 <i>bt</i>
3.	1	TAILGATE LOGO		59.70 <i>nei</i>
4.	1	RH TAILLAMP		230.80 <i>cr</i>
5.	1	TAILLAMP PANEL		346.50 <i>bt</i>
6.	1	TAILGATE WEATHERSTRIP		180.80 <i>tr</i>
7.	1	REAR END PANEL		270.00 <i>bt</i>
8.	2	TAILGATE HINGE	71.80	143.60 <i>7 x m</i>
9.	1	REAR BUMPER		660.60 <i>de</i>
10.	1	REAR BUMPER SIDE RETAINER		71.00 <i>nei</i>
11.	1	FUEL LID		123.30 <i>bt</i>
12.	1	TAILGATE STICKER 3.0 DTI		20.00 <i>na</i>
13.	1	TAILGATE STICKER URVAN		20.00 <i>nei</i>
14.	1	RH REAR FENDER INNER PANEL		1,062.60 <i>bt</i>
15.	1	RH REAR FENDER BOARD		353.00 <i>cr</i>
Nett Total S\$:				7,430.80
10.00% Discount S\$:				743.08
				6,687.72
1.	1	SPECIAL NETT ITEMS :		
		REVERSE SENSOR		200.00 <i>An</i>

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of FalconAir Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

CBL AIRCON ENGINEERING PTE LTD
48 TOH GUAN ROAD E SINGAPORE
608586

Attention : Motor Claim Department

Contact : 65159907 88131020

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

Estimate : ES003122

Date : 27/02/2018
Vehicle Num. : GBC2917C
Make/Model : NISSAN URVAN-2011
Chassis/Eng# : JN1MG4E25Z0796710
Accident Date : 27/02/2018
Claim No. :
Reference : TP NTUC VS CHINA
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

2.	1	70 KM/HR STICKER	10.00	10.00 <i>new</i>
3.	1	REAR FENDER BODY STICKER (COMPANY LOGO)	900.00	900.00 <i>? price check</i>
4.	1	TAILGATE STICKER (COMPANY LOGO)	200.00	200.00 <i>? check price</i>
5.	1	SEALANT	40.00	40.00 <i>new</i>
6.	1	11 PAX STICKER	10.00	10.00 <i>new</i>

Special Nett Total S\$:

1,360.00

LABOUR :

TO REMOVE/REPLACE REVERSE SENSOR & CHECK WIRING
TO RUSTPROOF ON ACCIDENT DAMAGE AREAS
TO TRANSFER TAILGATE PARTS/MECHANISM
TO REMOVE/REFIX REAR WINDSCREEN GLASS
TO CUT OUT / REWELD RH REAR FENDER INNER/OUTER
REAR END PANEL, TAILLAMP PANEL, REPAIR REAR CHASSIS
INCLUDES KNOCKING & REPLACEMENT OF PARTS
SPRAY PAINTING ON ACC DAMAGED AREAS INNER/ OUTER

80.00 *40*
180.00 *120*
50.00 *40*
120.00 *100*

1,800.00 *1500*
1,400.00 *1200*

Labour Total S\$:

3,630.00

E. & O.E.

Total S\$: 11,677.72



for FALCON AIR AUTO SERVICES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanjilkh 9749 5749
WP

1/3/18 e 3pm

Lumpsum

Resurvey after repair

12 days

2/3/18 sure lkk auto
com

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD #15-02 SPRINGLEAF TOWER
SINGAPORE 079909

Attention : Motor Claim Department
Contact : 63896111 Fax No. : 62221033

Estimate : ES003122

Date : 01/03/2018
Vehicle Num. : GBC2917C
Make/Model : NISSAN URVAN-2011
Chassis/Eng# : JN1MG4E25Z0796710
Accident Date : 27/02/2018
Claim No. :
Reference : TP NTUC VS CHINA
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
<hr/>				
		NETT ITEMS :		
1.	1	RH REAR FENDER		1,972.70
2.	1	TAILGATE		1,916.20
3.	1	TAILGATE LOGO		59.70
4.	1	RH TAILLAMP		230.80
5.	1	TAILLAMP PANEL		346.50
6.	1	TAILGATE WEATHERSTRIP		180.80
7.	1	REAR END PANEL		270.00
8.		TAILGATE HINGE X		X
9.	1	REAR BUMPER		660.60
10.	1	REAR BUMPER SIDE RETAINER		71.00
11.	1	FUEL LID		123.30
12.	1	TAILGATE STICKER 3.0 DTI		20.00
13.	1	TAILGATE STICKER URVAN		20.00
14.	1	RH REAR FENDER INNER PANEL		1,062.60
15.	1	RH REAR FENDER BOARD		353.00
				<hr/>
Nett Total S\$:				7,287.20
10.00% Discount S\$:				728.72
				<hr/>
				6,558.48
<hr/>				
		SPECIAL NETT ITEMS :		
1.	1	REVERSE SENSOR		200.00

CONTINUE / ...

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD #15-02 SPRINGLEAF TOWER
SINGAPORE 079909

Attention : Motor Claim Department
Contact : 63896111 Fax No. : 62221033

Estimate : ES003122

Date : 01/03/2018
Vehicle Num. : GBC2917C
Make/Model : NISSAN URVAN-2011
Chassis/Eng# : JN1MG4E25Z0796710
Accident Date : 27/02/2018
Claim No. :
Reference : TP NTUC VS CHINA
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
2.	1	70 KM/HR STICKER		10.00
3.	1	REAR FENDER BODY STICKER (COMPANY LOGO)		450.00
4.	1	TAILGATE STICKER (COMPANY LOGO)		120.00
5.	1	SEALANT		40.00
6.	1	11 PAX STICKER		10.00
Special Nett Total S\$:				830.00
LABOUR :				
TO REMOVE/REPLACE REVERSE SENSOR & CHECK WIRING				40.00
TO RUSTPROOF ON ACCIDENT DAMAGE AREAS				120.00
TO TRANSFER TAILGATE PARTS/MECHANISM				40.00
TO REMOVE/REFIX REAR WINDSCREEN GLASS				100.00
TO CUT OUT / REWELD RH REAR FENDER INNER/OUTER				
REAR END PANEL, TAILLAMP PANEL, REPAIR REAR CHASSIS				1,500.00
INCLUDES KNOCKING & REPLACEMENT OF PARTS				1,200.00
SPRAY PAINTING ON ACC DAMAGED AREAS INNER/ OUTER				
Labour Total S\$:				3,000.00

E. & O.E.	Total S\$:	10,388.48
-----------	-------------	-----------

for FALCON AIR AUTO SERVICES PTE LTD

L/S less 20% - 2077.69

8310.78

L/S 8300.00

14 DAYS












































...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Feb 2018		28 Feb 2018 14:20 Edit Adj Rpt	S\$8,300.00 Edit Estimates	S\$8,300.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, ID: -								
Main Claimant:	CBL AIRCON ENGINEERING PTE LTD								
Vehicle Reg. No.:	GBC2917C	Date of Loss:	24/02/2018 17:00 - :59 [76 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D01041C02	Policy/Cover Note No.:	DMCVSN3067891700						
Vehicle Reg. No. (Insured):	GZ3837M	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Falcon-Air Auto Services Pte Ltd (Pandan) No 8 Pandan Loop, Clementi - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 09/03/2018]								
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBC2917C (SNM18D01041C02)
[GZ3837M]
TP
CBL AIRCON ENGINEERING PTE LTD
Feb 24 2018 5:00PM
[-]
Falcon-Air Auto Services Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images						3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	21/06/18 14:28	General View					Load JPG	<input checked="" type="checkbox"/>	
2	21/06/18 14:28	General View					Load JPG	<input checked="" type="checkbox"/>	
3	21/06/18 14:28	General View					Load JPG	<input checked="" type="checkbox"/>	
4	21/06/18 14:28	General View					Load JPG	<input checked="" type="checkbox"/>	
5	21/06/18 14:28	General View					Load JPG	<input checked="" type="checkbox"/>	
6	21/06/18 14:28	General View					Load JPG	<input checked="" type="checkbox"/>	
7	21/06/18 14:28	General View					Load JPG	<input checked="" type="checkbox"/>	
8	21/06/18 14:28	General View					Load JPG	<input checked="" type="checkbox"/>	
9	21/06/18 14:28	General View					Load JPG	<input checked="" type="checkbox"/>	
10	21/06/18 14:28	General View					Load JPG	<input checked="" type="checkbox"/>	
11	21/06/18 14:28	General View					Load JPG	<input checked="" type="checkbox"/>	
12	21/06/18 14:28	General View					Load JPG	<input checked="" type="checkbox"/>	
13	21/06/18 14:28	General View					Load JPG	<input checked="" type="checkbox"/>	
14	21/06/18 14:28	General View					Load JPG	<input checked="" type="checkbox"/>	
15	21/06/18 14:28	General View					Load JPG	<input checked="" type="checkbox"/>	
16	21/06/18 14:28	General View					Load JPG	<input checked="" type="checkbox"/>	
17	21/06/18 14:28	General View					Load JPG	<input checked="" type="checkbox"/>	
18	21/06/18 14:28	General View					Load JPG	<input checked="" type="checkbox"/>	
19	21/06/18 14:28	General View					Load JPG	<input checked="" type="checkbox"/>	
20	21/06/18 14:28	General View					Load JPG	<input checked="" type="checkbox"/>	
21	21/06/18 14:28	General View					Load JPG	<input checked="" type="checkbox"/>	
22	21/06/18 14:28	General View					Load JPG	<input checked="" type="checkbox"/>	
23	21/06/18 14:28	General View					Load JPG	<input checked="" type="checkbox"/>	
24	21/06/18 14:28	General View					Load JPG	<input checked="" type="checkbox"/>	
25	21/06/18 14:28	General View					Load JPG	<input checked="" type="checkbox"/>	
26	21/06/18 14:28	General View					Load JPG	<input checked="" type="checkbox"/>	
27	21/06/18 14:28	General View					Load JPG	<input checked="" type="checkbox"/>	
28	21/06/18 14:28	General View					Load JPG	<input checked="" type="checkbox"/>	
29	21/06/18 14:28	General View					Load JPG	<input checked="" type="checkbox"/>	
30	21/06/18 14:28	General View					Load JPG	<input checked="" type="checkbox"/>	
31	21/06/18 14:28	General View					Load JPG	<input checked="" type="checkbox"/>	
32	21/06/18 14:28	General View					Load JPG	<input checked="" type="checkbox"/>	
33	21/06/18 14:28	General View					Load JPG	<input checked="" type="checkbox"/>	
34	21/06/18 14:28	General View					Load JPG	<input checked="" type="checkbox"/>	
35	21/06/18 14:28	General View					Load JPG	<input checked="" type="checkbox"/>	
36	21/06/18 14:28	General View					Load JPG	<input checked="" type="checkbox"/>	
37	21/06/18 14:28	General View					Load JPG	<input checked="" type="checkbox"/>	
38	21/06/18 14:28	General View					Load JPG	<input checked="" type="checkbox"/>	
39	21/06/18 14:28	General View					Load JPG	<input checked="" type="checkbox"/>	
40	21/06/18 14:28	General View					Load JPG	<input checked="" type="checkbox"/>	
41	21/06/18 14:28	General View					Load JPG	<input checked="" type="checkbox"/>	
42	21/06/18 14:28	General View					Load JPG	<input checked="" type="checkbox"/>	
43	21/06/18 14:28	General View					Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
44	21/06/18 14:29	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
45	21/06/18 14:29	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
46	21/06/18 14:29	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
47	21/06/18 14:29	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
48	21/06/18 14:29	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
49	21/06/18 14:29	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
50	21/06/18 14:29	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
51	21/06/18 14:29	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118003891/T1RBQ2

Date: 29/06/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN3067891700

Claimant
Vehicle No : GBC2917CInsured Vehicle
No : GZ3837M

Date of Loss: 24/02/2018

Nature of Claim: TP

Claim
No: SNM18D01041C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBC2917C**

Make & Model: NISSAN URVAN, 2.4 D (M)

Engine No: ZD30295534K

Reg. Date: 13/10/2011 (Man. Year: 2011)

Chassis No: JN1MG4E25Z0796710

Colour: Silver

Odometer: 206801 km

Engine Capacity: 2953 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size:

195 R15

Front Left Side: Michelin 6 mm

Rear Left Side:

Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side:

Michelin 6 mm

The above values represent the remaining tyre treads depth.

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,047.72	7,388.48	659.24	8.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,630.00	3,000.00	630.00	17.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,677.72	10,388.48	1,289.24	11.04
Approved Total (Overridden) (S\$)		8,300.00		
(S\$)	11,677.72	8,300.00	3,377.72	28.92
+ GST 7.00/7.00% (S\$)	817.44	581.00	236.44	28.92
Nett Amount (S\$)	12,495.16	8,881.00	3,614.16	28.92

INSPECTION

Date of Assignment: 28/02/2018

Date Inspected: 01/03/2018 Inspected At:

Falcon-Air Auto Services Pte Ltd
(Pandan)
No 8 Pandan Loop
Singapore

Estimated Period of Repair: 12.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 28 Jun 2018)	
Parts:	N/A	NISSAN URVAN 2.4 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC2917C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH REAR FENDER	Buckled	1,972.70 FN	*1,972.70 FN
2	1		*TAILGATE	Bent	1,916.20 FN	*1,916.20 FN
3	1		*TAILGATE LOGO	Necessary	59.70 FN	*59.70 FN
4	1		*RH TAILLAMP	Cracked	230.80 FN	*230.80 FN
5	1		*TAILLAMP PANEL	Bent	346.50 FN	*346.50 FN
6	1		*TAILGATE WEATHERSTRIP	Twisted	180.80 FN	*180.80 FN
7	1		*REAR END PANEL	Bent	270.00 FN	*270.00 FN
8	2		*TAILGATE HINGE	Not Necessary	143.60 FN	*- FN
9	1		*REAR BUMPER	Deformed	660.60 FN	*660.60 FN
10	1		*REAR BUMPER SIDE RETAINER	Necessary	71.00 FN	*71.00 FN
11	1		*FUEL LID	Bent	123.30 FN	*123.30 FN
12	1		*TAILGATE STICKER 3.0 DTI	Necessary	20.00 FN	*20.00 FN
13	1		*TAILGATE STICKER URVAN	Necessary	20.00 FN	*20.00 FN
14	1		*RH REAR FENDER INNER PANEL	Bent	1,062.60 FN	*1,062.60 FN
15	1		*RH REAR FENDER BOARD	Cracked	353.00 FN	*353.00 FN
16	1		*REVERSE SENSOR	Not Working	200.00 FS	*200.00 FS
17	1		*70KM/HR STICKER	Necessary	10.00 FS	*10.00 FS
18	1		*REAR FENDER BODY STICKER (COMPANY LOGO)	Necessary	900.00 FS	*450.00 FS
19	1		*TAILGATE STICKER (COMPANY LOGO)	Necessary	200.00 FS	*120.00 FS
20	1		*SEALANT	Necessary	40.00 FS	*40.00 FS
21	1		*11 PAX STICKER	Necessary	10.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	8,790.80	8,117.20
- Nett Item Discount on N Items 10.00/10.00% (S\$)	743.08	728.72
Total Parts (S\$)	8,047.72	7,388.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE/REPLACE REVERSE SENSOR & CHECK WIRING	New	80.00	40.00
2	TO RUSTPROOF ON ACCIDENT DAMAGE AREAS	New	180.00	120.00
3	TO TRANSFER TAILGATE PARTS /MECHANISM	New	50.00	40.00
4	TO REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	100.00
5	TO CUT /OUT /REWELD RH REAR FENDER INNER /OUTER REAR END PANEL ,TAILLAMP PANEL, REPAIR REAR CHASSIS INCLUDES KNOCKING & REPLACEMENT OF PARTS	New	1,800.00	1,500.00
6	SPRAY PAINTING ON ACC DAMAGED AREAS INNER /OUTER	New	1,400.00	1,200.00
Gross Labour Cost (S\$)			3,630.00	3,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >