







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC6/EQ118003903/kb3

5 MAXWELL ROAD  
#17-00 TOWER BLOCK  
MND COMPLEXSINGAPORE 069110

Date : 28-02-2018



Code : EQI

### 1. Policy Particulars :- THIRD PARTY CLAIM

|              |          |                |            |
|--------------|----------|----------------|------------|
| Insured Veh. | YN 8370J | Veh. Inspected | SFV 833B   |
| Policy No.   |          | Coverage (\$)  | 0.00       |
| Claim No.    |          | Excess (\$)    | 0.00       |
| Assign From  |          | Assign Date    | 28/02/2018 |

### 2. Vehicle Particulars & Condition

|              |        |              |   |
|--------------|--------|--------------|---|
| Make & Model |        | c.c          | 0 |
| Engine No.   | HIDDEN | Year of Reg. |   |
| Chassis No.  |        | Colour       |   |
| Odometer     | -      | Steering     |   |
| Brakes       |        | Modification |   |
| General      |        |              |   |

### 3. Conditions of Tyres

|                | Size | Make | Balance |
|----------------|------|------|---------|
| R/H Front Tyre |      |      | mm      |
| L/H Front Tyre |      |      | mm      |
| R/H Rear Tyre  |      |      | mm      |
| L/H Rear Tyre  |      |      | mm      |

### 4. Description of Damages

|  |
|--|
|  |
|--|

### 5. General Information

|                |   |                 |  |
|----------------|---|-----------------|--|
| Accident Date  | 23/02/2018  | Inspection Date |  |
| Survey held at | LI SHENG AUTOMOBILE TRADING<br>BLK 1, PANDAN LOOP,<br>#01-16<br>SINGAPORE 128219. |                 |  |

### 5a. Remarks

|   |
|---|
| A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|---|



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE. 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your ref: To Be Advised  
Our ref: CC6/EQ118003903/T1kb3

Date: 02.03.2018

The Motor Claims Department  
M/s EQ INSURANCE COMPANY LTD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SFV833B**

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 01.03.2018 at the premises of M/s Li Sheng Automobile Trading and have the following to report:-

|                          |       |                 |
|--------------------------|-------|-----------------|
| Workshop Estimate Amount | : S\$ | <u>8,564.24</u> |
| Revised Estimate Amount  | : S\$ | <u>7,914.24</u> |
| "Check" Items Amount     | : S\$ | <u>-</u>        |
| Market Value             | : S\$ | <u>-</u>        |
| LTA Reimbursement Value  | : S\$ | <u>-</u>        |
| Nett Value               | : S\$ | <u>-</u>        |

Description of Damage:  
The vehicle sustained damages at the  
O/S portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 1 days

Yours faithfully,

MOHD. TAUFIKH  
Licensed Appraiser

# Estimate



## Li Sheng Automobile Trading

Please arrange to survey at  
 Blok K, Pandan Loop 201-16 /18 S(128236)

Date: 27/2/2018  
 Vehicle No: SFV833B  
 Model: AUDI RS6  
 Date of loss: 23/2/2018  
 Our ref: LSA255TJS  
 Year: 2016

### EQ INSURANCE

Your Ref Vehicle No:  
 YN8370J - TP

| Qty  | Description                |
|------|----------------------------|
| 1.00 | RH WING MIRROR             |
| 1.00 | RH WING MIRROR COVER       |
| 1.00 | RH WING MIRROR SIGNAL LAMP |

| List Price  | Remarks           |
|-------------|-------------------|
| \$ 2079     | out - check price |
| \$ 5,781.40 | in -              |
| \$ 156.70   | out -             |

|           |             |         |
|-----------|-------------|---------|
| TOTAL:    | \$ 9,580.30 | 8017.10 |
| LESS 20%: | \$ 1,916.06 | 400.85  |
| 5%        | \$ 7,664.24 | 7616.25 |

### LABOUR AND PAINT

| Qty  | Description                        |
|------|------------------------------------|
| 1.00 | LABOUR FOR REPAIR ON AFFECTED AREA |
| 1.00 | SPRAY PAINT ON AFFECTED AREA       |
| 1.00 | CHECK WIRING                       |
| 1.00 | SUNDARIES                          |

| Unit Price | Remarks |
|------------|---------|
| \$ 500.00  | 200     |
| \$ 300.00  | ✓ 100   |
| \$ 50.00   | 30      |
| \$ 50.00   | 20      |

TOTAL: \$ 900.00

SUBTOTAL: \$ 8,564.24

Estimate prepared by: WINSON

Telephone: 97684247

winsonls@yahoo.com

\$7866.25 #  
 01 day

Tayfik 92495749  
 'wp'

1/3/18 @ 3pm

Resurvey new parts

01 day

Surv @ lkkauto.com

Total: \$7,866.25

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

# Estimate



## Li Sheng Automobile Trading

Please arrange to survey at  
Blk K, Pandan Loop #01-16 /18 S(128236)

### EQ INSURANCE

Your Ref Vehicle No:  
YN8370J - TP

Date: 27/2/2018  
Vehicle No: SFV833B  
Model: AUDI RS6  
Date of loss: 23/2/2018  
Our ref: LSA255TJS  
Year: 2016

| Qty           | Description                | List Price  | Remarks            |
|---------------|----------------------------|-------------|--------------------|
| 1.00          | RH WING MIRROR             | \$ 2,840.70 | <i>in</i>          |
| 1.00          | RH WING MIRROR COVER       | \$ 5,781.40 | <i>in</i>          |
| 1.00          | RH WING MIRROR SIGNAL LAMP | \$ 958.20   | <i>out</i>         |
| TOTAL: \$     |                            |             | 9,580.30           |
| LESS 20 %: \$ |                            |             | 1,916.06           |
|               |                            |             | <u>\$ 7,664.24</u> |

*} check price.*

### LABOUR AND PAINT

| Qty  | Description                        | Unit Price | Remarks    |
|------|------------------------------------|------------|------------|
| 1.00 | LABOUR FOR REPAIR ON AFFECTED AREA | \$ 500.00  | <i>200</i> |
| 1.00 | SPRAY PAINT ON AFFECTED AREA       | \$ 300.00  | <i>x</i>   |
| 1.00 | CHECK WIRING                       | \$ 50.00   | <i>30.</i> |
| 1.00 | SUNDARIES                          | \$ 50.00   | <i>20</i>  |

TOTAL: \$ 900.00

SUBTOTAL: \$ 8,564.24

Estimate prepared by: WINSON

Telephone : 97684247

[winsonts@yahoo.com](mailto:winsonts@yahoo.com)

*Tajhik 97495749*  
*'wp'*  
*1/3/18 @ 3pm*  
*Resurvey new parts*  
*01 day*  
*Surv @ (LKKauto.com)*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

## Shu Pei (LKKAuto)

---

**From:** Janet Tan <janet.tan@eqinsurance.com.sg>  
**Sent:** Thursday, 1 March 2018 9:20 AM  
**To:** Shu Pei (LKKAuto)  
**Cc:** Zaini (LKK Auto); Hsiao Tong (LKKAuto); Admin A  
**Subject:** FW: Direct Settlement - Accident Involving YN8370J (OI : EQI - TBA) and SFV833B (TP : LKK REF - CC6/EQI18003903/kb3 ) on 23.02.2018  
**Attachments:** TP GIA REPORT.PDF; YN8370J.PDF

Dear Shu Pei

OI report as attached.

Regards,

**Janet Tan**  
Senior Executive | Claims



### EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110  
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190  
[www.eqinsurance.com.sg](http://www.eqinsurance.com.sg)

 A Member of Citystate

*Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.*

---

**From:** Shu Pei (LKKAuto) [mailto:shupeil@lkkauto.com]  
**Sent:** Wednesday, February 28, 2018 5:50 PM  
**To:** Janet Tan <janet.tan@eqinsurance.com.sg>  
**Cc:** Zaini (LKK Auto) <Zaini@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>  
**Subject:** Direct Settlement - Accident Involving YN8370J (OI : EQI - TBA) and SFV833B (TP : LKK REF - CC6/EQI18003903/kb3 ) on 23.02.2018

### WITHOUT PREJUDICE

Dear Janet,

We refer to the above matter.

This is a TP direct settlement case from M/s Li Sheng Automobile Trading.

Enclosed for your perusal is:  
- TP GIA report

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Our case handler in-charge is Zaini and he can be contacted at DID: 6841-2132.

Thank you.

Best Regards,

Shu Pei | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366-0055 | email: [shupeei@lkkauto.com](mailto:shupeei@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC6/EQI18003903/T1jb3s2

5 MAXWELL ROAD  
#17-00 TOWER BLOCK  
MND COMPLEXSINGAPORE 069110

Date : 17-08-2018



Code : EQI

## 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                 |                |            |
|--------------|-----------------|----------------|------------|
| Insured Veh. | YN 8370J        | Veh. Inspected | SFV 833B   |
| Policy No.   | DMCSHQ17-000003 | Coverage (\$)  | 0.00       |
| Claim No.    |                 | Excess (\$)    | 0.00       |
| Assign From  |                 | Assign Date    | 01/03/2018 |

## 2. Vehicle Particulars & Condition

|              |                   |              |            |
|--------------|-------------------|--------------|------------|
| Make & Model | AUDI RS6          | c.c          | 3993       |
| Engine No.   | HIDDEN            | Year of Reg. | 2017       |
| Chassis No.  | WUAZZZ4G0HN900326 | Colour       | BLUE       |
| Odometer     | 7334              | Steering     | IN ORDER   |
| Brakes       | IN ORDER          | Modification | SPORTS RIM |
| General      | GOOD              |              |            |

## 3. Conditions of Tyres

|                | Size      | Make   | Balance |
|----------------|-----------|--------|---------|
| R/H Front Tyre | 285/30R21 | DUNLOP | 6 mm    |
| L/H Front Tyre | 285/30R21 | DUNLOP | 6 mm    |
| R/H Rear Tyre  | 285/30R21 | DUNLOP | 6 mm    |
| L/H Rear Tyre  | 285/30R21 | DUNLOP | 6 mm    |

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S WING MIRROR.  
DAMAGES SEE DETAILS.

## 5. General Information

|                |   |                 |            |
|----------------|---|-----------------|------------|
| Accident Date  | 23/02/2018  | Inspection Date | 01/03/2018 |
| Survey held at | LI SHENG AUTOMOBILE TRADING<br>BLK 1, PANDAN LOOP,<br>#01-16<br>SINGAPORE 128219. |                 |            |

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **1 Working Days**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFV 833B

| Qty                                | Description of Parts                | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|-------------------------------------|---------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b>        |                                     |               |                           |                   |
| 1                                  | RH WING MIRROR                      | CUT           | 2,079.00                  | 2,079.00          |
| 1                                  | RH WING MIRROR COVER                | CRACKED       | 5,781.40                  | 5,781.40          |
| 1                                  | RH WING MIRROR SIGNAL LAMP          | CUT           | 156.70                    | 156.70            |
|                                    | LESS 20% DISCOUNT                   |               | -1,603.42                 | -                 |
|                                    | LESS 5% DISCOUNT                    |               | -                         | -400.85           |
|                                    |                                     |               | 6,413.68                  | 7,616.25          |
| <b>SPECIAL NETT ITEMS</b>          |                                     |               |                           |                   |
| 1                                  | SUNDRIES (SN)                       | NECESSARY     | 50.00                     | 20.00             |
|                                    |                                     |               | 50.00                     | 20.00             |
| <b>LABOUR</b>                      |                                     |               |                           |                   |
|                                    | LABOUR FOR REPAIR ON AFFECTED AREA. |               | 500.00                    | 200.00            |
|                                    | SPRAY PAINT ON AFFECTED AREA.       | NOT NECESSARY | 300.00                    | -                 |
|                                    | CHECK WIRING.                       |               | 50.00                     | 30.00             |
|                                    |                                     |               | 850.00                    | 230.00            |
| <b>GRAND TOTAL</b>                 |                                     |               | <b>7,313.68</b>           | <b>7,866.25</b>   |
| <b>RECOMMENDED COST OF REPAIRS</b> |                                     |               |                           | <b>7,866.25</b>   |

Report Ref No. CC6/EQ18003903/T1jb3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.