

# Estimate



## Li Sheng Automobile Trading

Please arrange to survey at  
Blk K, Pandan Loop #01-16 /18 S(128236)

### EQ INSURANCE

Your Ref Vehicle No:  
YN8370J - TP

Date: 27/2/2018  
Vehicle No: SFV833B  
Model: AUDI RS6  
Date of loss: 23/2/2018  
Our ref: LSA255TJS  
Year: 2016

Qty	Description	List Price	Remarks
1.00	RH WING MIRROR	\$ 2,840.70	End ✓
1.00	RH WING MIRROR COVER	\$ 5,781.40	and ✓
1.00	RH WING MIRROR SIGNAL LAMP	\$ 958.20	out ✓
TOTAL:		\$ 9,580.30	} check price.
LESS 20 %:		\$ 1,916.06	
\$		<u>7,664.24</u>	

### LABOUR AND PAINT

Qty	Description	Unit Price	Remarks
1.00	LABOUR FOR REPAIR ON AFFECTED AREA	\$ 500.00	200
1.00	SPRAY PAINT ON AFFECTED AREA	\$ 300.00	x
1.00	CHECK WIRING	\$ 50.00	30.
1.00	SUNDARIES	\$ 50.00	20
TOTAL:		\$ 900.00	
SUBTOTAL:		\$ 8,564.24	

Estimate prepared by: WINSON

Telephone : 97684247

[winsonls@yahoo.com](mailto:winsonls@yahoo.com)

Tayfik 97495749  
- WP -  
1/3/18 @ 3pm  
Resurvey new parts  
@ 1 day  
Suw @ lkkauto.com

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: