



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
 Spray-Painting, Mechanical Repair And Customizing of Cars
 BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
 BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
 TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
 Bus. Reg. No. 251513/00M

FWD/AIG(12/02/2018@1330

DOA: 12/02/2018@1330

AIG ASIA PACIFIC INSURANCE PTE LTD

28/2/2018

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM
 ESTIMATE COST OF REPAIR FOR VEHICLE NO:
 SKX 7206 X - HONDA VEZEL 1.5X CVT
 CHASSIS NO: RU11106709 (2015)

1 pc	Front fender RH	\$ 558.70	ht-
1 pc	Front fender inner shield RH	\$ 130.90	de-
10 pcs	Front fender inner shield clips	\$ 3.90	nd-
1 pc	Front fender protector RH	\$ 150.30	mis-
5 pcs	Front fender protector clips	\$ 3.90	nd-
1 pc	Front headlamp RH	\$ 1,850.10	?
1 pc	Front bumper	\$ 927.50	de-
1 pc	Front bumper retainer RH	\$ 17.00	nd-
3 pcs	Front bumper side protector clips	\$ 5.50	nd-
1 pc	Front bumper lower garnish	\$ 351.00	T.
1 pc	RH rocker panel garnish	\$ 377.50	Rx
20 pcs	RH rocker panel garnish clips	\$ 3.90	nd-
1 pc	RH side mirror assy	\$ 650.50	Rx
1 pc	RH side mirror cover	\$ 80.10	Rx
		<u>\$ 5,110.80</u>	
	LESS 20%	<u>\$ 1,022.16</u>	
		\$ 4,088.64	
	Alignment	\$ 60.00	✓
	Repair, putty and respray front rim RH	\$ 100.00	50
	Check wiring function		
	Remove necessary parts: jacking, panel beating, repair and straighten front inner panel, front bonnet, front fender RH, front bumper, front door RH, RH 'A' pillar, RH side mirror and affected areas.	\$ 700.00	600



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars

BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724

BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723

TEL: 62747854; 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg

Bus. Reg. No. 251513/00M

Putty and respray front inner panel, front bonnet, front fender RH, front bumper, front door RH, RH 'A' pillar, RH side mirror and affected areas.

ADD 7% GST

800
200

\$	900.00
\$	5,848.64
\$	409.40
\$	<u>6,258.04</u>

Note: The above is an estimate only. IF other parts requested during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

Page 2 of 2

Tan Jhm 97495745
WP

9/3/18 @ 1230

*Resurvey before paint

6 days

sur@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: