

CHARN'S CUSTOMGRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars

BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724

BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723

TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg

Bus. Reg. No. 251513/00M

FWD/AIG(12/02/2018@1330

DOA: 12/02/2018@1330

AIG ASIA PACIFIC INSURANCE PTE LTD

28/2/2018

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:

SKX 7206 X - HONDA VEZEL 1.5X CVT

CHASSIS NO: RU11106709 (2015)


1 pc	Front fender RH	\$ 558.70
1 pc	Front fender inner shield RH	\$ 130.90
10 pcs	Front fender inner shield clips	\$ 3.90
1 pc	Front fender protector RH	\$ 150.30
5 pcs	Front fender protector clips	\$ 3.90
1 pc	Front headlamp RH	\$ 1,850.10
1 pc	Front bumper	\$ 927.50
1 pc	Front bumper retainer RH	\$ 17.00
3 pcs	Front bumper side protector clips	\$ 5.50
1 pc	Front bumper lower garnish	\$ 351.00
1 pc	RH rocker panel garnish	\$ 377.50
20 pcs	RH rocker panel garnish clips	\$ 3.90
1 pc	RH side mirror assy	\$ 650.50
1 pc	RH side mirror cover	\$ 80.10
		<hr/>
		\$ 5,110.80
	LESS 20%	\$ 1,022.16
		<hr/>
		\$ 4,088.64

Alignment \$ 60.00

Repair, putty and respray front rim RH \$ 100.00

Check wiring function

Remove necessary parts: jacking, panel beating, repair and straighten front inner panel, front bonnet, front fender RH, front bumper, front door RH, RH 'A' pillar, RH side mirror and affected areas. \$ 700.00



創 CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars

BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724

BLOCK 1409, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723

TEL: 62747654, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg

Bus. Reg. No. 251513/00M

Putty and respray front inner panel, front bonnet, front
fender RH, front bumper, front door RH, RH 'A' pillar,
RH side mirror and affected areas.

\$ 900.00

\$ 5,848.64

ADD 7% GST

\$ 409.40

\$ 6,258.04

Note: The above is an estimate only. IF other parts requested
during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

.....