

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Joslin Lim

Date: 01 Mar 2018

**Preliminary Advice**

|                    |                                                                                |                         |                |
|--------------------|--------------------------------------------------------------------------------|-------------------------|----------------|
| Vehicle No         | : SKN2595H                                                                     | Accident Date           | : 25/02/2018   |
| Make               | : VOLKSWAGEN JETTA                                                             | Policy No.              | : A80430752AVW |
| Assignment Date    | : 28/02/2018                                                                   | Excess                  | : S\$500.00    |
| Date of Inspection | : 28/02/2018                                                                   | Est. Duration of Repair | : 0.00         |
| Inspection At      | : VOLKSWAGEN CENTRE SINGAPORE - TUAS (HQ)<br>17 TUAS AVE 9<br>SINGAPORE 639197 |                         |                |

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and undercarriage. The chassis frame affected due to collision and parts claimed are consistent to the accident.

|                             |      |            |
|-----------------------------|------|------------|
| Repairer's Estimate (Gross) | :S\$ | 70,000.00  |
| Revised Amount              | :S\$ | TOTAL LOSS |
| Check Items (Estimated)     | :S\$ | 0.00       |
| Total                       | :S\$ | 0.00       |

|                 |      |  |
|-----------------|------|--|
| Lump Sum Repair | :S\$ |  |
|-----------------|------|--|

**Total Loss Consideration**

|                    |      |           |
|--------------------|------|-----------|
| New for Old Value  | :S\$ |           |
| Pre-Accident Value | :S\$ | 66,000.00 |
| COE / PARF Rebate  | :S\$ | 47,467.00 |
| Salvage Value      | :S\$ |           |
| Margin for Repair  | :S\$ | 18,533.00 |

**Remarks**

( x ) The vehicle is not economical for repair.

( ) The above survey was conducted on a 'without prejudice' basis.