Please arrange to survey vehicle at 8 KAKI BUKIT AVENUE 4 - GATE 2 #07-48 PREMIER @ KAKI BUKIT SINGAPORE 415875



LINDA LIAO

ABWIN SERVICE PTE LTD

DID: 67139417

Fax: 67139415 HP: 97519596

Date TP Vehicle No. : SKT- 58-Z

: 01/03/2018

To

: AIG ASIA PACIFIC INSURANCE PTE LTD

Attn

: Motor Claim Department

Owner

: ALOY & JEM SERVICES

NTUC INCOME INSURANCE CO-OPERATIVE LTD

Certificate No. : 5073472433-02

Vehicle No.

: GBE- 617-X

Make & Model : TOYOTA HIACE 3.0 DX M

Accident Date: 28/02/2018

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP
List Ite	<u>m</u>		,
1	RH FRONT DOOR	\$1,498.50	\sim
	Sub Total	\$1,498.50	
	Discount 25% on Parts	(\$374.63)	
		\$1,123.88	
Special	Nett		
1	RH FROTN DOOR STICKER	Nec \$65.00	30
	Sub Total	\$65.00	
Labour	& Misc		
	TO STRAIGHTEN AND PANEL BEAT ACCIDNET AREAS	\$300.00	100
	TO TRANSFER AND REFIX FRONT DOOR FIXTURE	1 1 \$250.00	X
	TO SPRAY PAINT ON AFFECTED AREAS	\$300.00	200
	TO SPRAY PAINT ON RH CORNER PANEL	11 \$150.00	X
	Sub Total	\$1,000.00	
	Sub Total	\$2,188.88	
	GST 7%	\$153.22	
	Total	\$2,342.10	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts orices are subject to confirmation
- Third party survey is an a "Without Prejudice" basis
- No illegal modification(s) is altrived.
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Luch After report