

Payee 3: (Strike if N.A.)	\$	Name 3:	
---------------------------	----	---------	--

(08/11/13) wef  
ASS. REC. BY: *MORIS*

REF:

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *GRG 8178H*

at Workshop m/s *YA* *02-16*

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

ICAC Accident Report Consistent? : Yes or No

ICAC / PR Seen Consistent? : Yes or No

Est. Repairs: *4* days Res.: Yes or No

Lum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: *GRG 8178H* Yr Ragn: *11 17*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or *CU*

Make: *Toyota Dyna* c.c. *2982*

Colour: *silver* A/C: Insured / Std / NI / NA

Sp. Reading: *11903* T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: *JTFAT35/XOK 209172*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: *NI* / S/Rim / STD A/Rim or

Tyre Size: F: *195/75R15*

R: *155R12*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal: *6* mm R/Bal: *6/6* mm

L/Bal: *6* mm L/Bal: *6/6* mm

D.O.A: *27/2/18* D.O.J: *5/3/18*

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

*Rec*  
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction  
*5/3/18 Confined 2/5 + 3000 with Jany.*

(*red 83044.50 / 50.36*)

Date/Time: File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time: File Return to?

3)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee

Transportation

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

) \$ + RS \$

) Photos

) Others

Report Format :

Lump Sum / I.B.I: (\$

TOTAL



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CC4/III18003953/yb3		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 01-03-2018		
		Code : III2		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHC 8383G	Veh. Inspected	GBG 8178H	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	01/03/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	27/02/2018	Inspection Date		
Survey held at	JA AUTOCARE PTE LTD 8 KAKI BUKIT AVE 4 #02-37 PREMIER@KAKI BUKIT SINGAPORE 415875			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

**JA AUTOCARE PTE LTD**

8 Kaki Bukit Ave 4

#02-37 Premier@Kaki Bukit

Singapore 415875

tel : 94513429

email : elivacassandra@hotmail.com

not Afford  
 2 hrs  
 r/s \$3000/sb/s  
 4 days  
 to ght. After 14.

India Int'l Insurance Pte Ltd  
 64 Cecil Street  
 #04 02 IOB Building  
 Singapore 049711

**ESTIMATE**

Date 01.03.2018  
 Vehicle no GBG 8178H  
 Model: Toyota Dyna  
 DOA 27.02.2018

**Parts**

- 01) Tail gate drop panel  
 02) Tail gate hinges @120.00 x 4  
 03) Tail gate side metal @\$420.00 x 2 148.10  
 04) Tail lamp rh  
 05) Exhaust pipe 781.10  
 06) Toyota logo  
 07) Dyna logo

20/dec	\$	1,680.00	—
2	\$	480.00	α
01/Jan	\$	840.00	α
cr	\$	250.80	—
20/dec	\$	980.50	—
20	\$	120.00	—
20	\$	35.00	—
	\$	4,386.30	3015
Less 25%	\$	1,096.50	2261.25
	\$	3,289.50	

**S/Nett items**

- 09) 8pax sticker  
 10) 70KM/H  
 11) 1set Reverse sensor  
 12) Rear number plate Emboss  
 13) Rear step garnish

20	\$	20.00	10
20	\$	20.00	10
shut	\$	250.00	200
1.4	\$	65.00	30
2	\$	250.00	α
	\$	605.00	

**Labour charges**

- 14) To check wiring  
 15) To dismantle exhaust  
 16) To knock out dents on affected areas  
 renew parts  
 17) To Putty & Respray painting

\$	150.00	20
\$	200.00	60
\$	1,000.00	600
\$	800.00	600
\$	2,150.00	

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

for JA AutoCare Pte Ltd

Total \$ 6,044.50

3791.25  
 3033



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2221N
Vehicle Details	
Vehicle No.:	GBG8178H
Vehicle to be Exported:	No
Intended De-registration Date:	05 Mar 2018
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 5MT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	1KD2751820
Chassis No.:	JTFAT35YX0K209172
Maximum Power Output:	-
Open Market Value:	\$27,084.00
Original Registration Date:	08 Nov 2017
First Registration Date:	08 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$1,355.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	07 Nov 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$32,490.00
COE Rebate Amount:	\$31,425.00
<b>Total Rebate Amount:</b>	<b>\$31,425.00</b>

The information contained herein is correct as at 05 Mar 2018

OK

## Nivitha (LKK Auto)

---

**From:** Motor Claim - III <motorclaim@iii.com.sg>  
**Sent:** Thursday, 1 March 2018 9:51 AM  
**To:** Jen Eliva; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)  
**Cc:** Sundari Nagarajan - III  
**Subject:** RE: GBG 8178H & SHC 8383G on 27.02.2018

11-2 sam @ 1/3/18  
vehicle not in  
person @ jenny

Dear Sir / Mdm,

Please conduct a survey on TP vehicle GBG8178H and let us have your report urgently.

This claim will be handled by Ms Sundari.

\*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,  
Gabriel Wee  
Motor Claims Dept.  
India International Insurance Pte Ltd  
64 Cecil Street | #05 IOB Building | Singapore 049711  
Tel: 6347 6100, Ext - 248

-----Original Message-----

**From:** Jen Eliva [mailto:elivacassandra@hotmail.com]  
**Sent:** 28 February, 2018 12:38 PM  
**To:** Motor Claim - III <motorclaim@iii.com.sg>  
**Cc:** admin-a@lkkauto.com  
**Subject:** GBG 8178H & SHC 8383G on 27.02.2018

Hi,

We are the authorise workshop for GBG 8178H to claims against your insured SHC8383G.

We would like to appoint LKK consultant (Marcus Chua ) to conduct the PRI at :

JA AutoCare Pte Ltd  
8 Kaki Bukit Ave 4  
#02-16 Premier @Kaki Bukit  
Singapore 415875

Thank you

Best Regards  
Jenny Chew -94513429  
For JA AutoCare Pte Ltd

✓ Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful.

Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

## Print Received Message

This mail is associated with :

**\*GBG8178H (MCT18020889)**

**[SHC8383G]**

TP

EKOWATT PTE LTD

Feb 27 2018 12:00PM

[COMFORT TRANSPORTATION PTE LTD]

Ja Autocare Pte Ltd

**From** India International Insurance Pte Ltd (HQ) (III\_SG), sent on 13/04/2018 14:27 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$3500.00) - GBG8178H - Claim Handler: Sundari Nagarajan

Approved:3500.00.



JA AutoCare Pte Ltd  
8 Kaki Bukit Ave 4  
#02-37 Premier@Kaki Bukit  
Singapore 415875  
Email : elivacassandra@hotmail.com

13.08.2018

India Int'l Insurance Pte Ltd  
64 Cecil Street  
#04-02 IOB Building  
Singapore 049711

**Attn: Motor Claims Department**

Dear Sir/Mdm,

**ACCIDENT INVOLVING VEHICLE: GBG 8178H & SHC 8383G ON 27.02.2018**

We are the authorized repair workshop for the owner of motor vehicle no: **GBG 8178H**, which was involved in the captioned accident with your insured vehicle: **SHC 8383G**. The vehicle owner has requested and authorized us to assist him in presenting his/her claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving, we are submitting these claims for your consideration on behalf of the owner/claimant.

01)	Cost of Repair	\$	3,000.00
02)	Loss of use \$100.00 x 5days	\$	500.00
		<u>\$</u>	<u>3,500.00</u>

We enclosed herewith the following documents to support the claims:-

- a) Letter of Authorisation / GIA report(s) / Insurance Certificate, etc...
- b) Final Repair Bill

Kindly look into the matter and let us hear from you on the settlement of our customer's claims as soon as possible.

**Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.**

Thank you  
Yours faithfully

Jenny Chew  
For JA AutoCare Pte Ltd

## Letter of Authorisation

To: JA AutoCare Pte Ltd

Re: ACCIDENT ON 27/02/18 INVOLVING GBG 8738H / SILC F3834  
ALONG/AT MARINE BOULEVARD SHIP RD TND5 MEX


I/We EKOWATT Pte Ltd (NRIC NO): 201532221N  
Of \_\_\_\_\_

- 01) The owner of motor vehicle no: GBG 8738H hereby authorise **JA AutoCare Pte Ltd** to commence repairs of the said vehicle forthwith. I/We agreed to assign the whole proceeds my/our third party claim to **JA Autocare Pte Ltd**. My/our solicitors (To be appointed by **JA AutoCare Pte Ltd** on my/our behalf) shall accept this as my/our irrevocable authority to pay the amount compensated direct to **JA Autocare Pte Ltd** after deduction of their cost on a solicitors & client basis. I/we undertake to Co-operate fully with **JA AutoCare Pte Ltd** and/or solicitors also with a true Motor Accident Report /Police Report until the claim to a successful conclusion including court proceedings, failing which, I/We undertake to bear the all costs incurred.
- 02) I/We authorise **JA AutoCare Pte Ltd** to sign all discharge voucher/indemnity forms and all necessary papers on my/our behalf in connection with the above claim.
- 03) In the event that third party insurer issued the Agreed Settlement Cheque to me/us, I/We undertake to either give the said cheque to **JA AutoCare Pte Ltd** or bank into our account and re-issue the cheque amount to **JA AutoCare Pte Ltd**.

DATED THIS 27 DAY OF 02 2018

  
SIGNATURE OF OWNER



  
SIGNATURE OF WITNESS  
NAME: for chw

## EXPRESS SETTLEMENT

Without Prejudice  
to any claim for  
personal injury

### DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: MLT18040889  
Claimant Ref: GBG 8178H

We/I, JA AUTOCARE PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 3,000.00 (repair cost), S\$ 500.00 (loss of use/rental), S\$ - (search fee), vehicle no. GBG 8178H that was damaged pursuant to the accident which occurred on 27/02/2018 (date) at SLIP ROAD OF MARINA BOULEVARD TO MCE (location) involving vehicle no. SHC 8383G (insured vehicle). This is pursuant to the inspection conducted on 05/03/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner EKOWATT PTE LTD ("the third party claimant") of vehicle no. GBG 8178H to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to GBG 8178H (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 3,500.00 to JA AUTOCARE PTE LTD

Dated this 25 day of April 20 18

#### CLAIMANT:

Signature: \_\_\_\_\_

Name: \_\_\_\_\_

NRIC: \_\_\_\_\_

Address: \_\_\_\_\_

Nationality: \_\_\_\_\_

Occupation: \_\_\_\_\_

  
Signed by "the workshop" (with chop)  
Jenchen  
57527785

110 81 Kaki Bukit Ave 4  
# 02-57 Premier @ Kaki Bukit

Manager

#### WITNESS:

Signature: \_\_\_\_\_

Name: \_\_\_\_\_

NRIC: \_\_\_\_\_

Address: \_\_\_\_\_

Nationality: \_\_\_\_\_

Occupation: \_\_\_\_\_

 LKS

Signed by appointed Surveyor

LKK AUTO CONSULTANTS PTE LTD

199607198R

51 UBI AVENUE 1 #01-25

PAYA UBI INDUSTRIAL PARK (S) 408933

**JA AUTOCARE PTE LTD**

8 Kaki Bukit Ave 4

#02-37 Premier@Kaki Bukit

Singapore 415875

tel : 94513429

email : elivacassandra@hotmail.com

India Int'l Insurance Pte Ltd  
64 Cecil Street  
#04 02 IOB Building  
Singapore 049711


TAX INVOICE	03/18/INS/007
Date	14.03.2018
Vehicle no	GBG 8178H
Model:	Toyota Dyna
DOA	27.02.2018

To Proceed on Lump Sum Repair

\$ 3,000.00

---

Total	<u>\$ 3,000.00</u>
-------	--------------------

---

for JA AutoCare Pte Ltd

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement






































### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Mar 2018 <a href="#">Edit Reg</a>		05 Mar 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$3,000.00</b> <a href="#">Edit Estimates</a>	<b>S\$3,000.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>COMFORT TRANSPORTATION PTE LTD</b> , Co. Reg. No.: -								
Main Claimant:	<b>EKOWATT PTE LTD</b> , Co. Reg. No.: 201532221N								
Vehicle Reg. No.:	<b>GBG8178H</b>	Date of Loss:	27/02/2018 12:00 - :59 [3 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / MCT18020889</b>	Policy/Cover Note No.:	MC0M0015						
Vehicle Reg. No. (Insured):	<b>SHC8383G</b>	Policy No. (Claimant):	DMCHQ17-006444						
		Excess:							
Repairer:	<b>Ja Autocare Pte Ltd</b> ( ) 8 KAKI BUKIT AVE 4, #02-37 PREMIER@KAKI BUKIT, 415875 Kaki Bukit - Tel:								
Handling Insurer:	<b>India International Insurance Pte Ltd (HQ)</b> - Tel: 63476100 ... [Handled by <b>Sundari Nagarajan</b> - 6347 6071]								
Claimant's Insurer:	<b>EQ Insurance Company Ltd (HQ)</b> - Tel: 6223 9433								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... [Final Rpt due 12/03/2018]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>III_SG (13/04/2018): Alert - Adj Mandate Approved (S\$3500.00) - GBG8178H - Claim Handler: Sundari Nag...</li> <li>III_SG (02/03/2018): Alert - Adj Mandate Approved (S\$0.00) - GBG8178H - Claim Handler: Sundari Nagara...</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*GBG8178H (MCT18020889)  
 [SHC8383G]  
 TP  
 EKOWATT PTE LTD  
 Feb 27 2018 12:00PM  
 [COMFORT TRANSPORTATION PTE LTD]  
 Ja Autocare Pte Ltd

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LXX Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/03/18 18:32	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
2	05/03/18 18:32	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
3	05/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
4	05/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
5	05/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
6	05/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
7	05/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
8	05/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
9	05/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
10	05/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
11	05/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
12	05/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
13	05/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
14	05/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
15	05/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
16	05/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
17	05/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
18	05/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
19	05/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
20	05/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
21	05/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
22	05/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
23	05/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
24	05/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
25	05/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
26	05/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
27	05/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
28	05/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
29	05/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
30	05/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
31	05/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
32	05/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
33	05/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
34	05/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
35	05/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
36	05/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>
37	05/03/18 18:32	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	05/03/18 18:32	General View		Load JPG <input checked="" type="checkbox"/>
39	05/03/18 18:32	General View		Load JPG <input checked="" type="checkbox"/>
40	05/03/18 18:32	General View		Load JPG <input checked="" type="checkbox"/>
41	05/03/18 18:32	General View		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/03/18 12:37	EMAIL FROM III DD 01032018		Load PDF
2	01/03/18 12:41	TP GIA REPORT		Load PDF
3	06/03/18 17:48	TP ESTIMATE- MARKED		Load PDF
4	20/03/18 14:54	WORKSHOP INVOICE		Load PDF
5	20/03/18 14:54	LOD		Load PDF
6	08/05/18 09:40	AUTHORISATION TO ACT FORM		Load PDF
7	08/05/18 09:40	DISCHARGE VOUCHER		Load PDF
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	02/03/18 08:41	Singapore Accident Statement		Load PDF

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18003953/UMB3Q2

Date: 08/05/2018

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

MC0M0015

Claimant Vehicle No: GBG8178H

Insured Vehicle No:

SHC8383G

Date of Loss: 27/02/2018

Nature of Claim:

TP

Claim No: MCT18020889

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBG8178H

Make &amp; Model: TOYOTA DYNA 150, 3.0 D (M)

Engine No: 1KD2751820

Reg. Date: 08/11/2017 (Man. Year: 2017)

Chassis No: JTFAT35YX0K209172

Colour: Silver

Odometer: 11903 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/75 R15

Rear Tyre Size: 155 R12 (D)

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6/6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth.

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,894.72	2,511.25	1,383.47	35.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,150.00	1,280.00	870.00	40.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,044.72</b>	<b>3,791.25</b>	<b>2,253.47</b>	<b>37.28</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,000.00</b>		
<b>Nett Amount (S\$)</b>	<b>6,044.72</b>	<b>3,000.00</b>	<b>3,044.72</b>	<b>50.37</b>
<b>+ Loss of Use (5.0 x S\$100.00/day) (S\$)</b>		<b>500.00</b>		
<b>Nett Liability (S\$)</b>		<b>3,500.00</b>		

### INSPECTION

Date of Assignment: 05/03/2018

Date Inspected: 05/03/2018 Inspected At:

Ja Autocare Pte Ltd  
8 KAKI BUKIT AVE 4, #02-37  
PREMIER@KAKI BUKIT  
Singapore 415875

Estimated Period of Repair: 4.0 days



---

**Adjuster:** MARCUS CHUA**Manager:** Lim Chin Siong Bevan

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 20 Mar 2018)	
<b>Parts:</b>	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBG8178H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE DROP PANEL	Dented / Bent	1,680.00 FL	*1,680.00 FL
2	2		*TAIL GATE HINGES	Repair	480.00 FL	*- FL
3	1		*TAIL GATE SIDE METAL	O/S Bent	840.00 FL	*148.10 FL
4	1		*TAIL LAMP RH	Cracked	250.80 FL	*250.80 FL
5	1		*EXHAUST PIPE	Dented / Deformed	980.50 FL	*781.10 FL
6	1		*TOYOTA LOGO	Necessary	120.00 FL	*120.00 FL
7	1		*DUNA LOGO	Necessary	35.00 FL	*35.00 FL
8	1		*8PAX STICKER	Necessary	20.00 FS	*10.00 FS
9	1		*70KM/H	Necessary	20.00 FS	*10.00 FS
10	1		*SET REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
11	1		*REAR NUMBER PLATE EMBOSS	Bent	65.00 FS	*30.00 FS
12	1		*REAR STEP GARNISH	Repair	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,991.30</b>	<b>3,265.00</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>1,096.58</b>	<b>753.75</b>
<b>Total Parts (\$\$)</b>	<b>3,894.72</b>	<b>2,511.25</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	150.00	20.00
2	TO DISMANTLE EXHAUST	New	200.00	60.00
3	TO KNOCK OUT DENTS ON AFFECTED AREAS RENEW PARTS	New	1,000.00	600.00
4	TO PUTTY & RESPRAY PAINTING	New	800.00	600.00
Gross Labour Cost (S\$)			2,150.00	1,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >