

JA AUTOCARE PTE LTD

8 Kaki Bukit Ave 4

#02-37 Premier@Kaki Bukit

Singapore 415875

tel : 94513429

email : elivacassandra@hotmail.com

not Aduh
 2/5 #3000h 5/3/18
 4 day
 ah yhl. After rep.

India Int'l Insurance Pte Ltd
 64 Cecil Street
 #04 02 IOB Building
 Singapore 049711

ESTIMATE

Date 01.03.2018
 Vehicle no GBG 8178H
 Model: Toyota Dyna
 DOA 27.02.2018

Parts

- 01) Tail gate drop panel
 02) Tail gate hinges @120.00 x 2
 03) Tail gate side metal @ \$420.00 x 2 148.10
 04) Tail lamp rh
 05) Exhaust pipe 781.10
 06) Toyota logo
 07) Dyna logo

100/duy \$ 1,680.00
 n \$ 480.00
 o/shu \$ 840.00
 cru \$ 250.80
 10/me \$ 980.50
 ru \$ 120.00
 ru \$ 35.00
 \$ 4,386.30
 Less 25% \$ 1,096.50
 \$ 3,289.50

3015
 2261.25

S/Nett items

- 09) 8pax sticker
 10) 70KM/H
 11) 1st Reverse sensor
 12) Rear number plate Emboss
 13) Rear step garnish

ru \$ 20.00 10
 ru \$ 20.00 10
 shu \$ 250.00 200
 ru \$ 65.00 30
 ru \$ 250.00 2
 \$ 605.00

Labour charges

- 14) To check wiring
 15) To dismantle exhaust
 16) To knock out dents on affected areas
 renew parts
 17) To Putty & Respray painting

\$ 150.00 20
 \$ 200.00 60
 \$ 1,000.00 600
 \$ 800.00 600
 \$ 2,150.00

for JA AutoCare Pte Ltd

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total \$ 6,044.50

3791.25
 3033