

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT STEET 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHB 7609T - EQ**Andrea***Not Authorized
6/1/2014*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB 7609T - Andrea

KL1LA69RJBB075037*

CHEVROLET

EPICA 2.0

06.01.2014

EQ

		PART		LIST
1	1	Front Bumper	\$	Th 1,202.00 ✓
2	1	Front Bumper Reinforcement	\$	R 295.25 X
3	1	Front Bumper Lower Absorber	\$	Sm 180.00 X
4	1	Front Bumper Lower Grille	\$	Sm 78.00 X
5	1	Front Bumper Retainer RH	\$	Sm 102.00 X
6	1	Front Bumper Retainer LH	\$	cm 102.00 ✓
7	1	Front Bumper Lower Stiffener	\$	R 134.37 X
8	1	Front Headlamp RH	\$	816.00 ?
9	1	Front Headlamp LH	\$	Bo 816.00 ✓
10	1	Front Bumper Fog Lamp Outer Cover LH	\$	nif 32.40 —
11	1	Front Support Panel Assy (Panel A-Frt)	\$	Bt 1,222.32 ✓
12	1	Bonnet (Panel A-Hood)	\$	Bt 1,250.00 —
13	1	Bonnet Centre 'CHEVROLET' Logo Badge	\$	Nr 144.30 X
14	1	Bonnet Moulding	\$	Sm 257.00 X
15	1	Bonnet Insulator	\$	Sm 84.63 X
16	1	Bonnet hinge RH	\$	R 36.00 X
17	1	Bonnet hinge LH	\$	R 36.00 X
18	1	Bonnet cable	\$	Sm 150.00 X
19	1	Bonnet lock	\$	R 200.00 X
20	1	Bonnet insulator	\$	Sm 400.00 X
21	1	Front Shock Absorber Assy RH	\$	216.17 ?
22	1	Front Shock Absorber Top Mounting RH	\$	48.32 ?
23	1	Front Shock Absorber Assy LH	\$	Bt 216.17 ✓
24	1	Front Shock Absorber Top Mounting LH	\$	Bt 48.32 —
25	1	Front Lower Arm RH	\$	283.00 ?
26	1	Front Lower Arm LH	\$	Bt 283.00 ✓
27	1	Front Knuckle Arm RH	\$	Bt 230.00 ✓
28	1	Front Knuckle Arm LH	\$	Bt 230.00 —
29	1	Front Stabilizer Bar Link RH	\$	51.79 ?
30	1	Front Stabilizer Bar Link LH	\$	51.79 ?
31	1	Front Stabilizer Bar Bracket LH	\$	Dis 105.75 ✓
32	1	Front Stabilizer Bar Bush LH	\$	66.00 ?
33	1	Front Beam A - Impact LH	\$	214.00 ?

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT STEET 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHB 7609T - EQ**Andrea**

34	1	Front Drive Shaft RH (Shaft A-Axle, Frt, RH) (S	\$	R	900.00 X
35	1	Front Drive Shaft LH (Shaft A-Axle, Frt, LH) (Lc	\$	B	900.00 ✓
36	1	Steering Rack End (Spring A-Clock) LH	\$	B	88.56 —
37	1	Steering Tie-Rod End (End -Tie Rod)	\$	M	67.00 —
38	1	W/Harnes S-I/P FUSE BOX	\$		1,903.05 ?
39	1	Cross member	\$		1,030.71 ?
40	1	Interm Axle Shaft (Centre)	\$		241.14 ?
41	1	Front Seat Belt RH (Belt A-Frt Seat RH)	\$	Sen	402.50 X
42	1	Front safety belt cover garnish	\$	Sen	125.00 X
43	1	Front Seat Belt LH (Belt A-Frt Seat LH)	\$	Sen	402.50 X
44	1	Front safety belt cover garnish	\$	Sen	125.00 X
45	1	Front Fender RH	\$	B	837.60 ✓
46	1	Front Fender LH	\$	B	837.60 ✓
47	1	Front Fender Liner RH	\$	Sen	47.00 X
48	1	Front Fender Liner LH	\$	T	47.00 ✓
49	1	Fender Insulation RH	\$	Sen	39.00 X
50	1	Fender Insulation LH	\$	D	39.00 ✓
51	1	Front Fender RR Bracket RH	\$	R	7.10 X
52	1	Front Fender RR Bracket LH	\$	M	7.10 ✓
53	1	Front Fender Inner Wheel House Panel LH	\$	R	1,437.00 ?
54	1	HORN LH	\$	Sen	159.20 X
55	1	Radiator Grille (Grille A-Rad)	\$	Sen	367.00 X
56	1	Radiator Assembly (Radiator A)	\$	Sen	618.00 X
57	1	Aircon Condenser (Conderser A)	\$	Sen	600.00 X
58	1	Air Intercooler (Cooler A-Air Charge)	\$	Sen	652.00 X
59	1	Fan Blade (Fan A-Auxiliary (Diesel) Small)	\$	Sen	536.00 X
60	1	Fan Blade (Fan A-Eng Cool (Diesel) Big)	\$	Sen	634.00 X
61	1	Fuse Box	\$		716.00 ?
62	1	Air Cleaner Assembly (Cleaner A-Air)	\$	Sen	112.00 X
63	1	Air intake resonator (beside fender)	\$	cm	20.01 ✓
64	1	Air intake resonator hose (bottom)	\$	Sen	60.90 X
65	1	Air intake resonator tank top bracket	\$		45.00 ?
66	1	Resonator A-A/CL	\$		37.00 ?
67	1	Engine Splash Cover RH (Cover A-Engine)	\$	Sen	168.00 X
68	1	Engine Splash Cover LH (Cover A-Engine)	\$		168.00 ?
69	1	Front Seat Belt RH (Belt A-Frt Seat RH)	\$	Sen	402.50 X
70	1	Front safety belt cover garnish	\$	Sen	125.00 X
71	1	Front Seat Belt LH (Belt A-Frt Seat LH)	\$	Sen	402.50 X
72	1	Front safety belt cover garnish	\$	Sen	125.00 X
73	1	Front Door RH (Panel A-Frt DR RH)	\$	B	1,133.00 ✓
74	1	Front Door Hinge Upper RH	\$	R	35.00 X
75	1	Front Door Hinge Lower RH	\$	R	35.00 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT STEET 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHB 7609T - EQ**Andrea**

76	1	Front Door Weatherstrip RH	\$	Sur 38.79 X
77	1	Front Door Check / Arrestor RH	\$	Sur 19.00 X
78	1	Front Door Pillar Out Panel RH	\$	R 715.00 X
79	1	Front Door Pillar Inner Panel RH	\$	R 850.00 X
80	1	Front Door LH (Panel A-Frt DR LH)	\$	R 1,133.00 ✓
81	1	Front Door Outer Moulding LH	\$	220.00 ?
82	1	Front Door Outer Handle LH	\$	R 60.00 X
83	1	Front Door Handle Support LH	\$	R 40.00 X
84	1	Front Door outer handle inner seal LH	\$	R 45.00 X
85	1	Front Door outer key lock LH	\$	Sur 25.00 X
86	1	Front Door Hinge Upper LH	\$	R 35.00 X
87	1	Front Door Hinge Lower LH	\$	R 35.00 ✓
88	1	Front Door inner lock LH	\$	R 586.00 X
89	1	Front Door Inner Lock Latch LH	\$	R 206.00 X
90	1	Front Door Check / Arrestor LH	\$	Sur 19.00 X
91	1	Front Door Weatherstrip LH	\$	S 38.79 ?
92	1	Front Door glass channel weatherstrip LH	\$	Sur 160.00 X
93	1	Front Door inner trim board LH	\$	Sur 455.69 X
94	1	Front Door Power Window Motor (Master) Motor	\$	284.97 ?
95	1	Front Door power window motor switch	\$	145.00 ?
96	1	Front Door Window Regulator Gear LH	\$	R 84.58 X
97	1	Front Door Pillar Out Panel LH	\$	R 715.00 X
98	1	Front Door Pillar Inner Panel LH	\$	R 850.00 X
99	1	Front Door Pillar Center Panel LH	\$	R 635.15 X
100	1	Front Side View Mirror RH (Mirror A o/s RH)	\$	Sur 939.00 X
101	1	Front Side Rocker Panel Garnish LH	\$	mir 236.40 ✓
102	1	Front Side Rocker Panel Outer LH	\$	R 600.00 X
103	1	Front Side Rocker Panel Garnish RH	\$	Sur 236.40 X
104	1	Front Windscreen (Glass A-W/ Shield)	\$	1,304.00 ?
105	1	Front Windscreen Moulding (Moulding A-W/ Si	\$	196.00 ?
106	1	Rear Bumper	\$	R 1,202.00 X
107	1	Rear Fender RH	\$	R 1,145.00 X
108	1	Rear Fender Inner Cowling RH	\$	Sur 298.00 X
109	1	Rear Fender Inner Trim RH	\$	Sur 418.44 X
110	1	Rear Door RH	\$	R 1,133.00 ✓
111	1	Rear Door LH	\$	R 1,133.00 X
112	1	Roof top out side panel LH	\$	R 356.85 X

TOTAL	\$	42,811.61
10%	\$	4,281.16
	\$	38,530.45

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT STEET 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHB 7609T - EQ**Andrea****Specical Nett**

1Set	Front Bumper Fastener Clip	\$	24.00 ✓
1Set	Front Licence Plate With Holder	\$	192.00 X
2	Front windscreen sealant	\$	80.00 ?
1	Front windscreen inner sponge seal	\$	100.00 ?
6	Bonnet under weatherstrip seal clips	\$	30.00 ✓
2	Front ERP Sticker	\$	40.00 ?
1Set	Roof lining Clip	\$	45.00 X
1Set	Bonnet Insulator Clip	\$	40.00 ✓
1Set	Radiator Grille Clip	\$	18.00 X
1Set	Bootlid inner trim board Clip	\$	40.00 X
1Set	Radiator Grille Top Cover Clip	\$	10.00 X
1Set	Front Fender Liner Clip	\$	40.00 ✓
1Set	Engine Splash Cover Clip RH	\$	12.00 X
1Set	Engine Splash Cover Clip LH	\$	12.00 ?
1Set	Rear Bumper Fastener Clip	\$	30.00 X
2	Door Sticker " Trans-cab "	\$	120.00 ✓
2	Door Sticker " 6555-3333 "	\$	120.00 ✓
1Set	Front door inner trim board LH Clip	\$	45.00 X
1Set	Front door inner trim board RH Clip	\$	45.00 X
1	Front Tyre RH	\$	360.00 301m
1	Front Wheel Rim RH	\$	254.00 501m
1	Front Tyre LH	\$	360.00 291m
1	Front Wheel Rim LH	\$	254.00 501m
1	Rear Tyre RH	\$	180.00 X
1	Rear Tyre Rim RH	\$	126.00 X
1	Tyre hub cap RH	\$	35.00 X
2	Hub Cup Rim	\$	70.00 X

TOTAL \$ 2,682.00**TOTAL PARTS \$ 41,212.45**

Panel Beating, Knocking And Straightening
The Necessary Portion, Remove And
Renewal Of Parts, Adjust And Realign The
Same

\$ 5,600.00 1400

To Check Electrical Lighting Concerned.

\$ 170.00 401

To Rust-Proofing Of The Affected Areas.

\$ 170.00 ✓

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT STEET 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHB 7609T - EQ**Andrea**

<i>Putty And Spray Painting Of The Affected Portion.</i>	\$	5,400.00 ²⁰⁰⁰
<i>To Remove And Refit Front W/ Screen Glass To Facilitate Bodywork Repair.</i>	\$	170.00 ?
<i>To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.</i>	\$	380.00 ²⁵⁰
<i>To transfer of door and roof panel fittings and conduct water seepage test.</i>	\$	340.00 ¹⁸⁰
<i>To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.</i>	\$	380.00 ¹⁰⁰
<i>To check steering geometry and computer wheel alignment</i>	\$	220.00 ⁶⁰
<i>To transfer of tire, rim and on wheel balancing.</i>	\$	170.00 ⁴⁰
<i>Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.</i>	\$	^{Required} 380.00 X
<i>To dismantle and refit front end suspension, undercarriage parts, final checking and testing.</i>	\$	120.00 ✓
<i>To check ABS brake efficiency, final checking and testing.</i>	\$	380.00 ⁵⁰
<i>To remove and refit ABS pump relay to enable repair.</i>	\$	ⁿⁿ 380.00 X
<i>To remove and refit air bag system and reset.</i>	\$	480.00 ?
<i>To vacuum, replace, refix and recharge air condenser</i>	\$	380.00 ¹⁰⁰

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT STEET 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHB 7609T - EQ**Andrea***To replace, refix and top up coolant for
radiator*

\$

170.00 *501**To vacuum, replace, refix and recharge Air
Intercooler*

\$

Repair 170.00 *X**Towing Fees.*

\$

120.00 *501*\$14,740.00**TOTAL**\$55,952.45**Repair Days***20 Days**10*