

Surveyor: Tauhikh

Meinmer

ASSIGNMENT (Office)

From (Person): Chong Boon Sen

of CTI

Date/Time: 11/3/18 @ 9:51am

Estimated Cost:

Bill to:

☒ OD / ☐ R / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV / ☐ CS

To Inspect Vehicle No:

PC 2124H

Insured:

at Workshop m/s

UCB Engineering

Tel:

62681281

of

2c jalan Pesuwat

Policy No:

DMBJSN1748311700

Claim No:

SNM18D01067C01

Sum Insured:

Excess:

\$2,000.00

Make of Veh:

(Client's Record)

D.O.A.

25/2/2018

CA /

☒ REV

/ REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:37am @ 11/3/18

Person Contacted:

Siang

Vehicle

☒ IN ☐ OUT

Date/Time

Action/Instruction

(☒) Estimate

PC 2124H - x

2/3/18

Sgt poli thru meinmer, seek mandate

6/3/18

Pathouse repair & inform upriver to proceed and excess

Confirm with Ah Siang, L/S \$19,600.00, 12 days

Red: \$12,126.00, 38%

Tanjin

CTI

ASSIGNMENT

PC2124M

2013 Dec

Date 1/3/18

Estimated Cost  
① TP / WS / TP RES / CD RES / EVA / INV / MV  
To inspect vehicle No. **PC 2124 H**  
at Addressed to **UCB Engineering**  
of **2c jalan persawat, 619359**  
Insured:  
Policy No:  
Claims No:  
Sum Insured **\$2000.00**  
Excess  
Claims Record **Siang @ 62681281**  
Make of vehicle

NS	DIS

Policy Condition  
Remark: The veh had commenced its repair at the time of inspection.  
Est. or Market Value **\$55K**  
ICAD Accident Report Consistent? Yes or No  
G/A / PR Seen Consistent? Yes or No  
Est. Repairs days Yes or No  
Cum Sum to G Val Yes or No  
CA / REV REP. / 24 HRS  
Date Person Contacted Vehicle IN / OUT

Year Make **Yutong** **EK6930H** **6695**  
Color **Green**  
Seating  
Eng No  
Chassis **LZYTCTD66C1033687**  
Gen Cont **Good** / Paint / Body / Bump  
Steering Indicator Jammed / Leaked / Burnt  
Brake Indicator Jammed / Leaked / Burnt  
Mod **MT** / S / R / STD A / R / M  
Tyre Size **275 / 70R22.5**  
BS / DUN / EXNOVA / GH / FS / LIZ / MIC / OHSU / PR / SUM  
TOYO / YOKO  
Front  
R/Ba **8** / **8/8**  
L/Ba **8** / **8/8**  
D/OA  
Surveyed at **UCB Eng**  
Date of Damages **Fr** / **Rear** / **DIS** / **NS** / **OC** / **Roofed** /  
**Fvt** / **o/s**  
The U/C Chassis frame Body Structure affected due to collision

Date Time Action Instruction **Battery weak**

RECEIVED 20 APR 2018

Date Time File Pass (P)  
**typist**  
Date Time File Return (P)  
Report Format **OP**  
Cumulative Sum **19,600.00**

Days Of Repair **12**  
Resurvey No. of Trip **1**

Add Fee  
Site Fee  
Fuel  
Travel  
Regist

220
220

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth ed	Status
Main	28 Feb 2018 <a href="#">Sendback Est</a>	28 Feb 2018 10:04 <b>S\$31,726.00</b>	01 Mar 2018 09:51 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

Insured:	KAT TRANSPORTATION & TRADING, Co. Reg. No.: 53078397E		
Vehicle Reg. No.:	PC2124H	Date of Loss:	25/02/2018 23:00 - :59
Claim Type:	OD / SNM18D01067C01	Policy/Cover Note No.:	DMB1SN1748311700 (Comprehensive)
		Excess:	S\$2,000.00
Repairer:	UCB Engineering Pte Ltd (HQ) 2C Jalan Pesawat, 619359 Jurong East - Tel: 62681281		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 12/03/2018]		
Driver/Custodian:	WU WEI (35 / Male), NRIC: G8204260T, Tel: +6598692285		
Adj Asg. Remarks:	SURVEY REVERT		

### ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18003961/T1rd3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 01-03-2018	
		Code : CTI	
<b>1. Policy Particulars :- OWN DAMAGE</b>			
Insured Veh.		Veh. Inspected	PC 2124H
Policy No.	DMB1SN1748311700	Coverage (\$)	0.00
Claim No.	SNM18D01067C01	Excess (\$)	2,000.00
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	01/03/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	25/02/2018	Inspection Date	01/03/2018
Survey held at	UCB ENGINEERING PTE LTD 2C, JALAN PESAWAT, JURONG, SINGAPORE 619359		
<b>5a. Remarks</b>			
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Chong Boon Sen

Date: 02 Mar 2018

## Preliminary Advice

Vehicle No	: PC2124H	Accident Date	: 25/02/2018
Make	: YUTONG ZK6930H	Policy No.	: DMB1SN1748311700
Assignment Date	: 01/03/2018	Excess	: S\$2,000.00
Date of Inspection	: 01/03/2018	Est. Duration of Repair	: 12.00
Inspection At	: UCB ENGINEERING PTE LTD (HQ) 2C JALAN PESAWAT SINGAPORE 619359		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	31,726.00
Revised Amount	:S\$	22,261.90
Check Items (Estimated)	:S\$	2,281.50
Total	:S\$	24,543.40
Lump Sum Repair	:S\$	19,600.00

### Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	55,000.00
COE / PARF Rebate	:S\$	30,845.00
Salvage Value	:S\$	
Margin for Repair	:S\$	24,155.00

Brake System	: In Order
Steering Condition	: In Order
Tyre Condition (Front)	: 8/8 mm
Tyre Condition (Rear)	: 8/8 mm

### Remarks

- ( x ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : The vehicle repair on Lump Sum basis.

## Print Received Message

This mail is associated with :

**PC2124H (SNM18D01067C01)**

OD

Feb 25 2018 11:00PM

[KAT TRANSPORTATION & TRADING]

UCB Engineering Pte Ltd

**From** China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA\_TAIPING), sent on 02/03/2018 16:21 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$19600.00) - PC2124H - Claim Handler: Chong Boon Sen

Approved:19600.00.

**Janice Lee (LKKAuto)**

---

**From:** Janice Lee (LKKAuto)  
**Sent:** Tuesday, March 06, 2018 9:35 AM  
**To:** 'unitedcb@singnet.com.sg'  
**Cc:** SUR  
**Subject:** PC 2124H CTI OD DOA: 25.02.2018

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **PC 2124H (excess \$2,000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

**Jannice Lee (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [janicelee@lkkauto.com](mailto:janicelee@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	8397E
Vehicle Details	
Vehicle No.:	PC2124H
Vehicle to be Exported:	No
Intended De-registration Date:	02 Mar 2018
Vehicle Make:	YUTONG
Vehicle Model:	ZK6930H M
Primary Colour:	Silver
Manufacturing Year:	2012
Engine No.:	ISBE425022054728
Chassis No.:	LZYTCTD66C1033687
Maximum Power Output:	-
Open Market Value:	\$94,713.00
Original Registration Date:	31 Dec 2013
First Registration Date:	31 Dec 2013
Transfer Count:	2
Actual ARF Paid:	\$4,736.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Dec 2023
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$51,112.00
COE Rebate Amount:	\$30,845.00
<b>Total Rebate Amount:</b>	<b>\$30,845.00</b>

The information contained herein is correct as at 02 Mar 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	27/02/2018 10:32
Date Of Accident	25/02/2018 23:30
Exact Location Of Accident	TAMPINES AVE 9 HEAVY VEHICLE CARPARK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	PC2124H
<b>Insured/Policyholder</b>	
Name Of Registered Owner	KAT TRANSPORTATION & TRADING
Co Reg No	53078397E
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-97221311
<b>Vehicle Particulars</b>	
Manufacturer	YUTONG
Model	ZK6930H-6.7 D (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	BUS
<b>Insurance Company</b>	
Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	
<b>Driver</b>	
Name of Driver	WU WEI
Passport No/FIN	G8204260T
Date Of Birth	12/01/1983
Occupation	OUTDOOR
Date Of Driving Pass	03/05/2008
Driving Experience	9 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98692285
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address

BLK 9006 TAMPINES STREET93, #04-202, SINGAPORE 528840

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

### General Information of the Accident

Type Of Accident

COLLIDED INTO PARKED VEHICLE

Weather Conditions

CLEAR

Road Surface

DRY

### Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

### Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

### Circumstances of Accident

REFER TO ATTACHMENT

### Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

PC3135U

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

BUS

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## Sketch Plan

### SKETCH PLAN


#### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "**Purposes**").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

*Attachment*

*XO*

*R22ev*

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature  
Date & Time:

*3/1*

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Sketch Plan #3

A = PC 3134 H


B = PC 3135 U

on 25/2/18,

At 2330 hrs, I was returning to the carpark.

As I was ~~turning~~<sup>slowly</sup> turning into the carpark lot,

I accidentally stepped on the accelerator instead of the brake, and hit onto the stationary vehicle



## UCB Engineering Pte Ltd (Co. Reg. No. 199501338G)

2C Jalan Pesawat  
Singapore 619359

Tel: 62681281 Fax: 62681282 Email: unitedcb@singnet.com.sg

INSURER: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMB1SN1748311700	Date of Loss:	25/02/2018
Vehicle Reg. No.:	PC2124H	Driveable?	
Driver Age/Info:	35 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	KAT TRANSPORTATION & TRADING		
Driver:	WU WEI		
Make/Model:	YUTONG ZK6930H, 6.7 D (M)	Vehicle Reg. Date:	31/12/2013
Vehicle Colour:	GREEN	Chassis No:	LZYTCTD66C1033687
Engine No:	ISBE425022054728		
Odometer:	0 KM		
Paint Type:			
Total Loss?	<b>NO</b>		
Est. Duration of Repair (day)	12		
Description of Accident/Loss	REFER TO ATTACHMENT		
Present Location:	UCB ENGINEERING PTE LTD (HQ)		

**COST OF CLAIMS**

	Amount
Parts	21,906.00
Miscellaneous Items	0.00
Labour	7,620.00
Paintwork Labour	2,200.00
Towing	0.00
<b>Gross Total (\$)</b>	<b>31,726.00</b>
<b>+ GST 7.00% (\$)</b>	<b>2,220.82</b>
<b>Nett Amount (\$)</b>	<b>33,946.82</b>

This claim is handled by: **TAN SIAM HIONG**

Generated using Merimen e-Claims Internet Estimation &amp; Adjusting System

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufik 97495749

Ex 2000

Revert - Not Authorise

1/3/18 @ 2pm

Lumpsum

Resurvey check items

Resurvey after repair

sur@lkkauto.com

12 days.

**REPAIR DETAILS****Reference****Part Source:** (Last Synchronised: 28 Feb 2018)**Parts:** N/A YUTONG ZK6930H 6.7 D (M) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for PC2124H)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Est Amount
1	1		*FRONT WINDSCREEN	0.00	0.00	crs ✓ *4,000.00 F
2	10		*SEALANT	0.00	0.00	ng ✓ *350.00 F
3	1		*ERP BRACKET	0.00	0.00	ng ✓ *26.00 F
4	1		*FRONT PANEL	0.00	0.00	bc ✓ *3,200.00 F
5	1		*FRONT BUMPER	0.00	0.00	del ✓ *2,250.00 F
6	1		*FRONT HEADLAMP - R	0.00	0.00	int ✓ *680.00 F
7	1		*REAR VIEW MIRROR - R	0.00	0.00	crs ✓ *1,850.00 F
8	1		*REAR VIEW MIRROR REFLECTOR LIGHT	0.00	0.00	crs ✓ *85.00 F
9	1		*WIPER ARM	0.00	0.00	bc ✓ *325.00 F
10	1		*WIPER BLADE - R	0.00	0.00	int ✓ *125.00 F
11	1		*WIPER BLADE - L	0.00	0.00	int ✓ *125.00 F
12	1		*WIPER LINK	0.00	0.00	bt ✓ *285.00 F
13	1		*FRONT BODY IRON STRUCTURE	0.00	0.00	KX ✓ *1,080.00 F
14	1		*RHS BODY PANEL	0.00	0.00	bc ✓ *2,600.00 F
15	1		*DRIVERS SIDE WINDOW	0.00	0.00	crs ✓ *1,500.00 F
16	3		*SEALANT	0.00	0.00	ng ✓ *105.00 F
17	1		*FRONT METER BOX - BIG	0.00	0.00	del ✓ *2,250.00 F
18	1		*FRONT METER BOX - SMALL	0.00	0.00	cut ✓ *520.00 F
19	1		*INTERIOR COVER	0.00	0.00	del ✓ *550.00 F

F=Franchise part.

**Total Parts (S\$)****21,906.00**Report was unsubmitted during this print-out.  
Generated using **Merimen e-Claims IEAS**

-10% parts price.

20826

10% 20826

18743.40

Labour 5800

24543.40

1/5 \$19600

12 days.

## Estimates on Miscellaneous Items

- There are no new miscellaneous items selected.

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Paintwork Labour</b>			
1	TO PUTTY, SPRAY BASE COAT & SPRAY PAINTING ONTO COMPLETE FRONT BODY AND RHS BODY PANEL	New	1200 2,200.00
<b>Labour Items</b>			
2	LABOUR CHARGES FOR DISMANTLE & ASSEMBLE FRONT WINDSCREEN	New	600 1,150.00
3	LABOUR CHARGES FOR REMOVE & REPLACE THE DAMAGED PARTS, CHECKING ALIGNMENT & PATCHING FIBREGLASS ONTO AFFECTED AREAS	New	2400 4,800.00
4	LABOUR CHARGES FOR REMOVE & REPLACE THE NETER BOX & INTERIOR ACCESSORIES ITEMS	New	600 800.00
5	LABOUR CHARGES FOR REPLACE DRIVER WINDOW FRAM & GLASS	New	200 320.00
6	WIRING CHARGES	New	200 550.00
Gross Labour Cost (\$\$)			<b>9,820.00</b>

Report was unsubmitted during this print-out.  
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

**REPAIR DETAILS****Reference**

**Part Source:** (Last Synchronised: 28 Feb 2018)  
**Parts:** N/A YUTONG ZK6930H 6.7 D (M) (Model not available in database)  
**Labour:** Repairer's (Price-denominated Standard List)  
**Print Code:** (Unsubmitted, no print-code for PC2124H)  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT WINDSCREEN	0.00	0.00	0.00
2	10		*SEALANT	0.00	0.00	*4,000.00 F
3	1		*ERP BRACKET	0.00	0.00	*350.00 F
4	1		*FRONT PANEL	0.00	0.00	*26.00 F
5	1		*FRONT BUMPER	0.00	0.00	*3,200.00 F
6	1		*FRONT HEADLAMP - R	0.00	0.00	*2,250.00 F
7	1		*REAR VIEW MIRROR - R	0.00	0.00	*680.00 F
8	1		*REAR VIEW MIRROR REFLECTOR LIGHT	0.00	0.00	*1,850.00 F
9	1		*WIPER ARM	0.00	0.00	*85.00 F
10	1		*WIPER BLADE - R	0.00	0.00	*325.00 F
11	1		*WIPER BLADE - L	0.00	0.00	*125.00 F
12	1		*WIPER LINK	0.00	0.00	*125.00 F
13	1		*FRONT BODY IRON STRUCTURE	0.00	0.00	*285.00 F
14	1		*RHS BODY PANEL	0.00	0.00	*1,080.00 F
15	1		*DRIVERS SIDE WINDOW	0.00	0.00	*2,600.00 F
16	3		*SEALANT	0.00	0.00	*1,500.00 F
17	1		*FRONT METER BOX - BIG	0.00	0.00	*105.00 F
18	1		*FRONT METER BOX - SMALL	0.00	0.00	*2,250.00 F
19	1		*INTERIOR COVER	0.00	0.00	*520.00 F
				0.00	0.00	*550.00 F
Total Parts (S\$)						21,906.00

F=Franchise part.

Report was unsubmitted during this print-out.  
 Generated using Merimen e-Claims IEAS

10% off

Part 21906.00  
 Less 10% 2190.60  
 19715.40  
 Labour 5800.00  
 25,515.40  
 Less 20%  
 Lump Sum Repair 5103.08  
 20,412.32  
 =

Lump sum at 20,400/-

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Feb 2018 <a href="#">Sendback Est</a>	28 Feb 2018 10:04 <b>S\$31,726.00</b>	01 Mar 2018 09:51 <a href="#">Edit Adj Rpt</a>	<b>S\$19,600.00</b> <a href="#">Edit Estimates</a>	<b>S\$19,600.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>									
Insured: <b>KAT TRANSPORTATION &amp; TRADING</b> , Co. Reg. No.: 53078397E									
Vehicle Reg. No.: <b>PC2124H</b>		Date of Loss: 25/02/2018 23:00 - :59 <b>[49 Months and 25 Days From LTA Reg Date (Man Yr)]</b>							
Claim Type: <b>OD / SNM18D01067C01</b>		Policy/Cover Note No.: DMB1SN1748311700 (Comprehensive)							
		Excess: S\$2,000.00							
Repairer: <b>UCB Engineering Pte Ltd (HQ)</b> 2C Jalan Pesawat, 619359 Jurong East - Tel: 62681281									
Handling Insurer: <b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... <b>[Final Rpt due 12/03/2018]</b>									
Driver/Custodian: WU WEI (35 / Male), NRIC: G8204260T, Tel: +6598692285									
Adj Asg. Remarks: SURVEY REVERT									
<b>ASSOCIATED MAIL RECEIVED</b>									
				<a href="#">View All</a>					
• CHINA_TAIPING (02/03/2018): <b>Alert - Adj Mandate Approved (S\$19600.00) - PC2124H - Claim Handler: Chong Boon ...</b>									
<b>ALL ASSOCIATED TASKS</b>									
				<a href="#">View All</a>					
<a href="#">Search Tasks</a>									
<a href="#">Create New Task</a>									
<a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**PC2124H (SNM18D01067C01)**  
**OD**  
**Feb 25 2018 11:00PM**  
**[KAT TRANSPORTATION & TRADING]**  
**UCB Engineering Pte Ltd**

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

**View** View in Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
UCB Engineering Pte Ltd (HQ)					
1	27/02/18 10:56	Accident Statement	1	Load HTM	
2	28/02/18 10:04	Repairer Estimates	2	Load HTM	
LKK Auto Consultants Pte Ltd (HQ)					
No	Finalized On			Thumbnail	Print
1	02/03/18 12:01	Adjuster Immediate Advice	1	Load HTM	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
UCB Engineering Pte Ltd (HQ)					
1	27/02/18 10:52	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
2	27/02/18 10:52	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
3	27/02/18 10:52	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
4	27/02/18 10:52	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
5	27/02/18 10:52	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
6	27/02/18 10:52	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
7	27/02/18 10:52	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
8	27/02/18 10:52	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
9	27/02/18 10:52	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
10	27/02/18 10:52	Driving License [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
LKK Auto Consultants Pte Ltd (HQ)					
No	Relabel/Reorder			Thumbnail	Print
1	02/03/18 14:51	General View	1	Load PDF	
2	20/04/18 10:17	Reinspection Photo	1	Load PDF	

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
UCB Engineering Pte Ltd (HQ)					
1	27/02/18 10:53	Sketch Plan [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
2	27/02/18 10:53	Sketch Plan #2 [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
3	27/02/18 10:53	Sketch Plan #3 [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
LKK Auto Consultants Pte Ltd (HQ)					
No	Relabel/Reorder			Thumbnail	Print
1	02/03/18 13:40	PC 2124H ESTIMATE	1	Load PDF	

## Linked Accident Report Documents

**View** View in Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
UCB Engineering Pte Ltd (HQ)					
1	27/02/18 10:56	Accident Statement	1	Load HTM	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
---------------	--	--	--	------------	-------------------------------------

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	UCB Engineering Pte Ltd (HQ)		Thumbnail Print
No	Finalized On	UCB Engineering Pte Ltd (HQ)		Thumbnail Print
1	27/02/18 10:52	Accident Photo		Load JPG <input checked="" type="checkbox"/>
2	27/02/18 10:52	Accident Photo		Load JPG <input checked="" type="checkbox"/>
3	27/02/18 10:52	Accident Photo		Load JPG <input checked="" type="checkbox"/>
4	27/02/18 10:52	Accident Photo		Load JPG <input checked="" type="checkbox"/>
5	27/02/18 10:52	Accident Photo		Load JPG <input checked="" type="checkbox"/>
6	27/02/18 10:52	Accident Photo		Load JPG <input checked="" type="checkbox"/>
7	27/02/18 10:52	Accident Photo		Load JPG <input checked="" type="checkbox"/>
8	27/02/18 10:52	Accident Photo		Load JPG <input checked="" type="checkbox"/>
9	27/02/18 10:52	Accident Photo		Load JPG <input checked="" type="checkbox"/>
10	27/02/18 10:52	Driving License		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	UCB Engineering Pte Ltd (HQ)		Thumbnail Print
1	27/02/18 10:53	Sketch Plan		Load JPG <input checked="" type="checkbox"/>
2	27/02/18 10:53	Sketch Plan #2		Load JPG <input checked="" type="checkbox"/>
3	27/02/18 10:53	Sketch Plan #3		Load JPG <input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

Our File No: CS/CT118003961/T1RD3E2

Date: 26/04/2018

### REFERENCE

Insured/Claimant:	KAT TRANSPORTATION & TRADING	Policy No:	DMB1SN1748311700	Claim No:	SNM18D01067C01
Date of Loss:	25/02/2018	Nature of Claim:	OD		

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC2124H	Engine No:	ISBE425022054728
Make & Model:	YUTONG ZK6930H, 6.7 D (M)	Chassis No:	LZYTCTD66C1033687
Reg. Date:	31/12/2013 (Man. Year: 2012)	Odometer:	0 km
Colour:	Green		
Engine Capacity:	6695 cc		
Market Value/New Car Price:	S\$55,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5 (D)
Front Left Side:	Aeolus 8 mm	Rear Left Side:	Aeolus 8/8 mm
Front Right Side:	Aeolus 8 mm	Rear Right Side:	Aeolus 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,906.00	18,743.40	3,162.60	14.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,620.00	4,600.00	3,020.00	39.63
Paintwork Labour	2,200.00	1,200.00	1,000.00	45.45
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>31,726.00</b>	<b>24,543.40</b>	<b>7,182.60</b>	<b>22.64</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>19,600.00</b>		
<b>- Excess (S\$)</b>	0.00	2,000.00	-2,000.00	
<b>(S\$)</b>	31,726.00	17,600.00	14,126.00	44.52
<b>+ GST 7.00/7.00% (S\$)</b>	2,220.82	1,232.00	988.82	44.52
<b>Nett Amount (S\$)</b>	<b>33,946.82</b>	<b>18,832.00</b>	<b>15,114.82</b>	<b>44.52</b>

### INSPECTION

Date of Assignment:	01/03/2018	Present Location:	UCB Engineering Pte Ltd (HQ)
Date Inspected:	01/03/2018	Inspected At:	2C Jalan Pesawat Singapore 619359
Estimated Period of Repair:	12.0 days		

---

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** Janice Lee Si Hua

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 26 Apr 2018)	
Parts:	N/A	YUTONG ZK6930H 6.7 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC2124H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN	Cracked	4,000.00 F	*4,000.00 FL
2	10		*SEALANT	Necessary	350.00 F	*350.00 FL
3	1		*ERP BRACKET	Necessary	26.00 F	*26.00 FL
4	1		*FRONT PANEL	Bent	3,200.00 F	*3,200.00 FL
5	1		*FRONT BUMPER	Deformed	2,250.00 F	*2,250.00 FL
6	1		*FRONT HEADLAMP - R	Cut	680.00 F	*680.00 FL
7	1		*REAR VIEW MIRROR - R	Cracked	1,850.00 F	*1,850.00 FL
8	1		*REAR VIEW MIRROR REFLECTOR LIGHT	Cracked	85.00 F	*85.00 FL
9	1		*WIPER ARM	Bent	325.00 F	*325.00 FL
10	1		*WIPER BLADE - R	Cut	125.00 F	*125.00 FL
11	1		*WIPER BLADE - L	Cut	125.00 F	*125.00 FL
12	1		*WIPER LINK	Bent	285.00 F	*285.00 FL
13	1		*FRONT BODY IRON STRUCTURE	Repair	1,080.00 F	*- FL
14	1		*RHS BODY PANEL	Buckled	2,600.00 F	*2,600.00 FL
15	1		*DRIVERS SIDE WINDOW	Cracked	1,500.00 F	*1,500.00 FL
16	3		*SEALANT	Necessary	105.00 F	*105.00 FL
17	1		*FRONT METER BOX - BIG	Deformed	2,250.00 F	*2,250.00 FL
18	1		*FRONT METER BOX - SMALL	Cut	520.00 F	*520.00 FL
19	1		*INTERIOR COVER	Deformed	550.00 F	*550.00 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>21,906.00</b>	<b>20,826.00</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	<b>0.00</b>	<b>2,082.60</b>
<b>Total Parts (\$\$)</b>	<b>21,906.00</b>	<b>18,743.40</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Paintwork Labour</u></b>				
1	TO PUTTY, SPRAY BASE COAT & SPRAY PAINTING ONTO COMPLETE FRONT BODY AND RHS BODY PANEL	New	2,200.00	1,200.00
<b><u>Labour Items</u></b>				
2	LABOUR CHARGES FOR DISMANTLE & ASSEMBLE FRONT WINDSCREEN	New	1,150.00	600.00
3	LABOUR CHARGES FOR REMOVE & REPLACE THE DAMAGED PARTS, CHECKING ALIGNMENT & PATCHING FIBREGLASS ONTO AFFECTED AREAS	New	4,800.00	3,000.00
4	LABOUR CHARGES FOR REMOVE & REPLACE THE NETER BOX & INTERIOR ACCESSORIES ITEMS	New	800.00	600.00
5	LABOUR CHARGES FOR REPLACE DRIVER WINDOW FRAM & GLASS	New	320.00	200.00
6	WIRING CHARGES	New	550.00	200.00
Gross Labour Cost (S\$)			<b>9,820.00</b>	<b>5,800.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >