

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 8293H

DATE 28/2/2018 10:21

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper ✓			\$ 603.60
	Rear Bumper Reinforcement ?			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH) ?		\$ 180.00	\$ 360.00
	Rear Bumper Side Bracket			\$ 49.00
	Rear Bumper Clips ✓			\$ 22.00
	Rear Bumper Sponge ?			\$ 143.40
	Rear Bumper Under Cover ✓			\$ 225.00
	Rear Bumper Reflector Lamp (LH) ✕			\$ 32.00
	SUB TOTAL			\$ 1,939.35
	LESS 20%			\$ 387.87
	DISCOUNTED TOTAL			\$ 1,551.48
	Rear Bumper Reverse Sensor ✕			\$ 135.70
				\$ 135.70
	Labour Charge			
	Panel Beating			\$ 380.00 200
	Spray Painting Charge			\$ 200.00 180
	Wiring Charge			\$ 50.00 ✕
	R/Refix Reverse Sensor			\$ 120.00 20
	TOTAL LABOUR			\$ 750.00
	ESTIMATE TOTAL			\$ 2,437.18

Ka Lu 16/11/14
 28/2/18 10:50hr
 2 Days
 P/P
 Before Part photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for survey
- Parts prices are subject to survey
- Third party survey is on a "Without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary parts must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.