



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



Co Reg No : 199405410K

**ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
MR KHOR LIANG QUAN	Cust No/Name /MR KHOR LIANG QUAN
BLK 151 YISHUN ST 11	Reg No/Reg Date SGL5099L / 15/04/201
#08-32	Date In/Mileage / 0
SINGAPORE 760151	Chassis No KNAFZ411MG5580236
Contact No Mobile: 98805181	Engine No G4FGFH609767
	Make/Model KIA/FORTE K3 1.6 A SX ADQ
	Colour/Trim ABP / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	27/02/2018/ 13:30	TLC	442 / CocoLu	23934			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								2200.00
TO RENEW REAR BUMPER, BOOTLID, REPAIR REAR END PANEL								
E PNT98000								1680.00
TO SPRAY PAINT FOR REAR BUMPER, BOOTLID, REAR END PANEL								
M SUNDRY								30.00
C&C LOGO								
A 90000001								20.00
TO CHECK WIRING & ELECTRICAL SYSTEM								
A 90000001								200.00
TO CONDUCT DIAGNOSTIC CHECK FOR THE CAR SYSTEM								
A 90000001								250.00
TO RENEW REAR EXHAUST SYSTEM								
E PNT88000								100.00
TO REMOVE & INSTALL PARKING SENSOR								
M SUNDRY								220.00
PARKING SENSOR								
M SUNDRY								50.00
REAR NUMBER PLATE WITH FRAME								
M SUNDRY								20.00
Sundry								
P COVER-RR BUMPER					1.00	791.00	00.00	791.00
M COVER-RR BUMPER,UPR					1.00	245.00	00.00	245.00
M WIRING HARNESS-BWS EXT					1.00	173.00	00.00	173.00
M ULTRASONIC SENSOR ASSY-FBWS					4.00	172.00	00.00	688.00
M BRACKET-RR BEAM LWR MTG					1.00	5.00	00.00	5.00
M BRACKET-RR RAIL UPR MTG,RH					1.00	4.00	00.00	4.00
M STAY-RR BUMPER RH					1.00	75.00	00.00	75.00
M STAY-RR BUMPER LH					1.00	75.00	00.00	75.00
M BEAM-RR BUMPER					1.00	365.00	00.00	365.00
M PANEL ASSY-TRUNK LID					1.00	1297.00	00.00	1297.00
M HINGE ASSY-TRUNK LID,RH					1.00	68.00	00.00	68.00
M HINGE ASSY-TRUNK LID,LH					1.00	68.00	00.00	68.00
M LOGO ASSY-KIA SUB					1.00	37.00	00.00	37.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
MR KHOR LIANG QUAN	Cust No/Name /MR KHOR LIANG QUAN
BLK 151 YISHUN ST 11	Reg No/Reg Date SGL5099L / 15/04/201
#08-32	Date In/Mileage / 0
SINGAPORE 760151	Chassis No KNAFZ411MG5580236
Contact No Mobile: 98805181	Engine No G4FGFH609767
	Make/Model KIA/FORTE K3 1.6 A SX ADQ
	Colour/Trim ABP / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	27/02/2018/ 13:30	TLC	442 / CocoLu	23934
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M FORTE EMBLEM		1.00	40.00	00.00	40.00
M TRIM-TRANSVERSE RR		1.00	58.00	00.00	58.00
M LAMP ASSY-REAR COMB INSIDE,RH		1.00	710.00	00.00	710.00
M LAMP ASSY-REAR COMB INSIDE,LH		1.00	710.00	00.00	710.00
M LAMP ASSY-REAR COMBINATION,RH		1.00	788.00	00.00	788.00
M LAMP ASSY-REAR COMBINATION,LH		1.00	788.00	00.00	788.00
M LAMP ASSY-LICENSE PLATE,RH		1.00	18.00	00.00	18.00
M LAMP ASSY-LICENSE PLATE,LH		1.00	18.00	00.00	18.00
M MUFFLER ASSY-REAR		1.00	729.00	00.00	729.00
<h1>Estimate</h1>					

Confirm &amp; accepted by

7% GST on	Nett 12520.00	12,520.00 876.40
Total Payable		13,396.40

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.