

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522

PC4738Z Toyota Hiace

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy X N N	\$ 1,260.00
2	1	Rear bumper right bracket X N N	\$ 86.00
3	1	Rear bumper inner beam X N N	\$ 287.00
4	1	Rear tailgate assy .X Svc	\$ 1,862.00
5	1	Rear tailgate lock mechanism X N N	\$ 266.00
6	1	Rear tailgate inner board X N N	\$ 190.00
7	1	Rear tailgate lock actuator X N N	\$ 189.00
8	1	Rear right taillamp X N N	\$ 785.00
9	2	Rear taillamp lower panel X N N	\$ 120.00
10	1	Rear right fender panel assy X P	\$ 11,800.00
			<u>\$ 16,845.00</u>
Less 25%			<u>\$ 4,211.25</u>
			<u>\$ 12,633.75</u>

Special Nett Items

1	10	Rear bumper clips X N N	\$ 50.00
2	12	Rear tailgate inner board clips X N N	\$ 30.00
3	1	Rear right quarter glass sealant X N N	\$ 80.00
4	1	Rear right fender panel sticker X N N	\$ 80.00
5	1	Rear right fender panel sealant X N N	\$ 80.00
6	1	Rear bumper reverse sensor X N N	\$ 250.00
7	1	Rear right wheel rim X N N	\$ 450.00
8	1	Rear right tyre X N N	\$ 280.00
9	1	Rear no plate X N N	\$ 80.00
			<u>\$ 1,380.00</u>

Total Parts

\$ 14,013.75

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522

PC4738Z Toyota Hiace

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten rear affected area and replace rear right damaged parts.	\$ 1,600.00 200
2	To putty and spray painting rear right and rear portion.	\$ 1,600.00 280
3	To check rear lighting and wiring.	\$ 50.00 X
4	To remove and install rear tailgate lock mechanism.	\$ 80.00 X
5	To remove and install rear inner trim to facilitate the repair.	\$ 150.00 X
6	To apply anti rust proofing to rear affected area.	\$ 120.00 X
7	To remove and install rear bumper reverse sensor.	\$ 60.00 X
8	To balance rear right wheel.	\$ 50.00 X
9	To conduct wheel alignment.	\$ 80.00 X
10	To remove and install rear right quarter glass to facilitate the repair.	\$ 120.00 X
11	Towing service.	\$ 100.00 X
Total labour :		\$ 4,010.00

Total parts : \$ 14,013.75

Total labour : \$ 4,010.00

Total repair cost : \$ 18,023.75

With Prejudice

Lump Sum

Parts Price Subject To Confirmation

Parts Dismantling Resurvey

Resurvey After Paint
2 Days Repairs.

Wilson, LKK

Tel: 67418434

Wilson @ lkk auto . com

[Signature]
2/3/8

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: