

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHF488A
 Ref. No : TAX/02/18/2161
 Reg. Date : 30/09/2014
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : CHUA KOON CHAI(CAI KUNCAI)
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 27/02/2018 06:20:00 PM
 Accident Reported Date / Time : 28/02/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024094800
 Special Instruction to ARC,if any :
 SKA139Z
 Prepared Date : 28/02/2018 10:57:46 AM



4 Days.

lump sum repair.

After repair photos.

Gm. Qian - 82880282

01/3/18.

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U905751882

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	676.00	0.00
Total Spray Painting Charges :	756.00	0.00
Total Material Charges :	846.06	846.06
Other Charges :	340.00	0.00
TOTAL :	2,618.06	0.00
Lum Sum Total :	2,600.00	0.00
No. of Repair Days :	4.00	0.00
Prepared / Adjusted By :		
Arc / Surveyor Sing Off Date :	28/02/2018 07:31:12 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 28/02/2018 07:31:12 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH FRONT PORTION	676.00	0.00
Total Labour	676.00	0.00 300

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT FENDER LH	378.00	0.00 200
TO REPSRAY FRONT BUMPER	378.00	0.00 200
Total Spray Painting & Panel Beating	756.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 60
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	340.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
53802-47050		6505558	FENDER FRT/LH <i>BT</i>	1	723.40	25.00	542.55	Replace	Replace	No
75374-47051			NAME PLATE (HYBRID) <i>MBL</i>	1	51.90	25.00	38.92	Replace	Replace	No
52119-47930		6505517	BUMPER FRT <i>MBL</i>	1	482.00	25.00	361.50	Replace	Replace	No
52116-47040		6505516	BUMPER SUPPORT F/LH <i>MBL</i>	1	76.40	25.00	57.30	Replace	Replace	No
TOTAL MATERIALS							1,000.28	1,000.27		
TOTAL MATERIALS(Discounted)							846.06	846.06		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									