

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 #01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building
 78 Shenton Way #07-16
 Singapore 079120
 Tel : 6419 - 3000
 Fax : 6835 - 7416

VIC

Quotation

DATE : 06.03.2018
 VEH NO : SGU6188J
 MODEL : Mazda 2
 D O A : 24.02.2018
 YR REF : SLT760S

Attn: Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE: ESTIMATE FOR ACCIDENT REPAIR SGU6188J (MAZDA 2)

| <u>Item</u> | <u>Description</u> | <u>Qty</u> | <u>Amt</u> |
|-------------|--|------------|-------------------------|
| <u>NO</u> | <u>LIST ITEMS</u> | | |
| 1 | Rear Bumper <i>deland</i> | 1 | 650.40 ✓ |
| 2 | Rear Bumper Clips <i>n</i> | 1 set | 30.00 ✓ |
| 3 | Rear Bumper Side Holder - LH & RH <i>n</i> | 2 | 51.20 ✓ |
| 4 | Rear End Panel <i>Repair</i> | 1 | 354.20 ✗ |
| 5 | Rear End Panel Top Garnish <i>deland</i> | 1 | 86.30 ✓ |
| 6 | Taillamp - LH & RH <i>then</i> | 2 | 645.00 ✗ |
| 7 | Tailgate <i>dent</i> | 1 | 968.60 ✓ |
| 8 | Tailgate Lock <i>Dead</i> | 1 | 254.60 ✓ |
| 9 | Tailgate Weatherstripe <i>new</i> | 1 | 88.00 ✗ |
| 10 | Tailgate Glass Moulding <i>n</i> | 1 | 115.20 ✓ |
| 11 | Mazda Logo | 1 | 28.90 ✓ |
| 12 | Mazda 2 Wording | 1 | 54.20 ✓ |
| 13 | SP Wording | 1 | 29.90 ✓ |
| 14 | Tools Tray <i>new</i> | 1 | 295.70 ✓ |
| | | | <hr/> |
| | | | 3,652.20 |
| | | Less 20% | (730.44) |
| | | | <hr/> |
| | | | \$ 2,921.76 |
| | <u>S/NET ITEMS</u> | | |
| 1 | Reverse Sensor <i>Dead</i> | 1 | 280.00 260 ✓ |
| 2 | Rear End Panel Sealant <i>then</i> | 1 | 60.00 ✗ |
| 3 | Tailgate Glass Sealant <i>then</i> | 1 | 60.00 ✓ |
| | | | <hr/> |
| | | | \$ 400.00 |
| | | | <hr/> |
| | Total Parts | | \$ 3,321.76 |

RE : ESTIMATE FOR ACCIDENT REPAIR SGU6188J (MAZDA 2)

LABOUR CHARGE

| | | | |
|---|---|---------|-------------------------|
| 1 | To knocking & pull out rear portion & renew above parts | \$ | 1,000.00 500 |
| 2 | To putty & spray up paint works | \$ | 850.00 600 |
| 3 | To check wiring | \$ | 50.00 30 |
| 4 | To underseal | \$ | 150.00 x. |
| 5 | To remove reverse sensor | \$ | 100.00 50 |
| 6 | To remove upholstery | 1420 \$ | 150.00 40 |
| 7 | To transfer tailgate fittings | \$ | 150.00 80 |
| 8 | To remove tailgate glass | \$ | 180.00 120 |
| | Total Labour | \$ | 2,630.00 |
| | Grand Total | \$ | 5,951.76 |

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total : 3495.44
L/S : 2.8K .
04 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: