

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0264/2018/GW
Date : 2-Mar-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Chan Z'R-Liang
Address : Blk 189B Rivervale Drive
#11-1004
Singapore 542189
Telephone : HP +65 96311100
Type of Claim : Third Party Claims
Policy No. : 2100420660-02000
Vehicle No : **SGZ 390 D**
Model Code : Audi A6 2.0 TFSI S-Tronic
Model / Year : May-15
Engine No : CYP 002084
Chassis No : WAUZZZ4G0FN062662
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 1-Mar-18
Place of Accident : Traffic Light Junct Of Woodlands Ave 12 & Ave 5

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGZ 390 D.

| S/n | Nature of Jobs | Estimated Charges | Surveyor's Recommendation |
|----------------------|---|--------------------------|---------------------------|
| 1 | To remove and transfer rear parking aid and rear lid kick open sensors. | S/N \$ 360.00 ✓ | |
| 2 | To remove trunk fittings, dismantle and renew rear bumper and lower bumper. Inspect for damages on reinforcement and end panelling. Re-install all parts removed. | \$ 900.00 500 | |
| 3 | To respray paint on rear bumper. | \$ 900.00 550 | |
| 4 | To carry out diagnostic check. | S/N \$ 192.00 ✓ | |
| TOTAL LABOUR CHARGES | | : \$ 2,352.00 | |

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGZ 390 D

| S/N | Parts Description | Damaged Parts & Prices | |
|---------------------------|---|------------------------|--------|
| | | S/Nett | Remark |
| 1 | REAR BUMPER <i>Repair</i> | \$ 2,300.00 | * |
| 2 | REAR BUMPER FIXING PARTS <i>1 set</i> | \$ 234.00 | * |
| 3 | REAR BUMPER SPOILER <i>1 set</i> | \$ 416.00 | ✓ |
| 4 | REAR BUMPER SECURING STRIP <i>1 set</i> | \$ 191.00 | * |
| 5 | SUNDRIES <i>?</i> | \$ 180.00 | ? |
| TOTAL SPARE PARTS CHARGES | | \$ 3,321.00 | |
| TOTAL LABOUR CHARGES | | \$ 2,352.00 | |
| GRAND TOTAL | | \$ 5,673.00 | |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 09/03/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 03 Days

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant