

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0255/2018/GW
Date : 28-Feb-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Christopher Chong Chi
Address : 39 Jurong East Avenue 1
#14-02
Singapore 609776
Telephone : HP +65 81888166
Type of Claim : Own Damage Claims
Policy No. : 2100471730-01
Vehicle No : **SLC 7709 K**
Model Code : Audi Q7 2.0 TFSI Qu
Model / Year : Jun-16
Engine No : CYR 015333
Chassis No : WAUZZZ4M1GD064854
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 24-Feb-18
Place of Accident : Turning Into 60 Dunearn Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLC 7709 K.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer both LHS door's power window device power latch device, multi lock system, audio equipment etc wing mirror assy.	S/N \$ 800.00	/
2	To remove and renew lhs front door, repair & shape rear door, transfer old fittings to renew door. Renew both door cover, fender, reinstall all parts removed.	\$ 2,400.00	1200
3	To respray both lhs front and rear door, both door cover, wing mirror cover.	\$ 3,200.00	1600
4	To carry out diagnostic.	S/N \$ 192.00	/
TOTAL LABOUR CHARGES		: \$ <u>6,592.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLC 7709 K.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT DOOR-LH <i>Dented.</i>	\$ 3,274.00	✓
2	FRONT OUTER DOOR SEAL-LH <i>Nec</i>	\$ 218.00	✓
3	BONDING AGENT ?	\$ 43.00	?
4	CLEANING SOLUTION ?	\$ 64.00	?
5	GROMMET ?	8 \$ 18.00	?
6	SOUND ABSORBER ?	2 \$ 216.00	?
7	FRONT ALUMINIUM COVER TRIM-LH <i>wt</i>	\$ 335.00	✓
8	TRIM PILLAR B ?	\$ 195.00	?
9	FRONT DOOR COVER-LH <i>xm</i>	\$ 608.00	✓
10	REAR DOOR COVER-LH <i>missing</i>	\$ 514.00	✓
11	FRONT EXTERIOR MIRROR MOUNTING-LH <i>Rem</i>	\$ 1,325.00	X
12	FRONT MIRROR CAP-LH <i>Rem</i>	\$ 159.00	X
13	SUNDRIES ?	\$ 400.00	?
TOTAL SPARE PARTS		\$ 7,369.00	
TOTAL LABOUR CHARGES		\$ 6,592.00	
GRAND TOTAL		\$ 13,961.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian G*
Surveyed Date : *01/03/18*
Authorised Date :
Excess Cost :
Liability :
Remarks : *not authorised, OSAs*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant