



方商昭噴漆 POON SIANG SEOW

Sin Ming Autocity, No. 160 Sin Ming Drive, #05-13, Singapore 575722.
Tel: 6453 7511 Fax: 6453 8046 Email: sitti1@singnet.com.sg Regn. No. 05396600K

Ma Chin Chew
Apt Blk 6 Toh Yi Drive
#06-243
Singapore 590006

Dear sir

Estimate cost of repair to vehicle no. SKV 4654 R

To supply

1. Tail gate	B ₁	1,100.90	✓
2. Tail gate lock	R	185.90	X
3. Tail gate damper x2	Sm	360.00	X
4. Tail gate rubber	Sm	96.80	X
5. Rear w/s moulding	me	186.50	✓
6. Tail gate badge	nn	55.60	X
7. Tail gate logo	me	50.00	✓
8. Tail gate outer handle	Sm	220.00	X
9. Tail lamp		468.80	?
10. Tail gate reflector	SLR	240.00	✓
11. Rear panel	B ₁	415.60	✓
12. Rear panel top garish		192.30	?
13. Rear spare tyre panel	B ₁ /B ₂	1,130.60	✓
14. Rear spare tyre panel cover	Sm	235.00	X
15. Rear tool box	cmf	550.00	✓
16. Rear bumper	B ₁	762.70	✓
17. Rear bumper side x2	NLS B ₂	390.00	✓
18. Rear bumper sensor x4	SLR	450.00	320sm
19. Rear bumper reflector x2	NLS ?	270.00	
20. Rear bumper chips x10	me	15.00	✓
21. Cross member	R	580.00	X
22. Rear board cover		350.00	?

208

Labour Charges

Rust proofing	100.00	901
Panel beating	1,800.00	12001
Painting	1,200.00	9001
To remove and refit w/s and cushion	350.00	2201
Number plate plate	Sm 80.00	X
Total		

Your faithfully

ALBERT POON

Not Authorised
1-B1
Purway B4 perim
10 days