

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST63 SINGAPORE 569111
 TEL NO. 6287 6666 FAX NO. 6257 1330
 CO/GST REG NO. 201019626G
SHB9710U -

AAD1802-262

Not Authored
L/Ring & Hood

Vehicle No.:	SHB9710U - JHOW
Chassis No.:	VF1ABL15AUC273291
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	27.02.2018
Third Party Insurer :	AIG

PART			LIST	
1	1	BUMPER COVER REAR	\$	<i>R</i> 1,108.46 —
2	1	BUMPER LOWER REAR	\$	<i>Od/Bur</i> 768.84 —
3	1	BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47 X
4	1	BUMEPR BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97 X
5	1	BUMEPR RETAINER RH REAR	\$	<i>Sn CMA</i> 44.99 X
6	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97 X
7	1	BUMEPR RETAINER LH REAR	\$	<i>Sn</i> 44.99 X
8	1	BUMPER REFLECTOR LH	\$	<i>CMA</i> 43.61 —
9	1	BUMPER BEAM REAR	\$	<i>R</i> 777.52
10	1	BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95
11	1	BOOT REAR	\$	<i>R</i> 2,872.68
12	1	BOOT FINISHER	\$	<i>Sn</i> 470.06
13	1	BOOT WHEATERSTRIP	\$	<i>Sn</i> 323.05
14	1	BOOT REFLECTOR LAMP LH	\$	<i>Sn</i> 493.35
15	1	BOOT BADGE 'RENAULT'	\$	<i>nn</i> 225.36
16	1	BOOT BADGE	\$	<i>nn</i> 225.36
17	1	BOOT STRUT LH	\$	<i>Sn</i> 276.08
18	1	BOOT HINGE LH	\$	<i>R</i> 367.84 X
19	1	BOOT SWITCH	\$	<i>R</i> 168.13
20	1	BOOT LOCK	\$	<i>R</i> 202.67
21	1	BOOT LOCK CATCH	\$	<i>R</i> 74.40
22	2	LICENCE PLATE LAMP	\$	<i>Sn</i> 50.52
23	2	BOOT RUBBER PLUG	\$	<i>Sn</i> 221.81
24	1	FENDER PANEL INNER TRIM REAR LH	\$	<i>Sn</i> 671.45
25	1	FENDER PANEL REAR LH	\$	<i>R</i> 3,299.13
26	1	WHEELARCH REAR LH	\$	<i>Sn</i> 543.47
27	1	TAILLAMP LH	\$	<i>Sn</i> 552.55
28	1	TAILLAMP PANEL LH	\$	<i>R</i> 986.70
29	1	OUTER PANEL REAR (End Panel)	\$	<i>R</i> 1,471.77
30	1	OUTER PANEL REAR (End Panel)TRIM	\$	<i>Sn</i> 404.56

TOTAL	\$	17,300.72
10%	\$	1,730.07
	\$	15,570.65

TRANS-CAB AUTO SERVICES PTE LTD

AAD1802-262

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TÉL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB9710U -

Special Nett

1	1SET	PARKING AID	\$	<i>0d/15/07</i>	700.00	✓
2	1SET	REAR BUMPER CLIP	\$	<i>nn</i>	66.00	✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	<i>nn</i>	33.00	✓
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	<i>nn</i>	10.00	X
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	<i>nn</i>	20.00	X
6	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	<i>nn</i>	10.00	X
7	1SET	BUMEPR RETAINER CLIP LH RR	\$	<i>nn</i>	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	<i>nn</i>	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	<i>nn</i>	66.00	✓
11	1SET	BOOT FINISHER CLIP	\$	<i>nn</i>	24.20	} X
12	1	BOOT STICKER "Trans-cab"	\$	<i>nn</i>	30.00	
13	1	BOOT STICKER "6555-3333"	\$	<i>nn</i>	30.00	
16	1SET	FENDER WHEELARCH REAR LH CLIP	\$	<i>nn</i>	35.00	
18	1	FENDER INNER TRIM CLIP LH	\$	<i>nn</i>	28.00	
20	1	TAILLAMP CLIP LH	\$	<i>nn</i>	5.00	
21	2	REAR WINDSCREEN SELANT	\$	<i>nn</i>	80.00	
22	1	WINDSCREEN MOULDING	\$	<i>nn</i>	100.00	
23	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i>	100.00	

TOTAL	\$	1,379.20
TOTAL PARTS	\$	16,949.85

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	<i>4400</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,800.00	<i>3000</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>nn</i> 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	<i>600</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	X

TRANS-CAB AUTO SERVICES PTE LTD

AAD1802-262

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB9710U -

Towing Fees	\$	<i>nn</i> 120.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nn</i> 170.00 X
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 X

TOTAL	\$	7,370.00
Over All Total	\$	24,319.85

(PARTS BY PARTS)

Repair Days

~~10~~ Days

2 days