

INS. CASE OWNER:

CC 4, EQ11800 4029, T1 00382

LKK:
IDAC:

Surveyor:

Tan Jiah

DOI:

ASSIGNMENT

11/7/18

Date / Time:

28/12/2017

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SAV 717S

Name of Insured:

Muhammad Fadzli Bin Sahim

Insured Tel No.:

HP:

96938107

Excess Sec II :SS

D.O.A.:

15/11/2017

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

DM17H0 025701JT

Policy No.:

DMPPH217-005676

Make / Model:

7-Vellfire

Place of Accident:

Gulaf Tanah Rd

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SKX 2893P



INSRS:

WSP:

Tel:

Liability:

RMKS:

Hong Seh
motor

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

URGENT

Date/ Time

14/12/17

SKX 2893P - MEATUP 170 219221Y ; DVA: 15/11/2017

SAV 717S - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

THRU By Email
28/12

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

28/3/18

TP suddenly break and he unable to break
in time and collided onto TP vehicle.

4/12/18

Filepart to type mandale.

mmpm - RE -> MK to

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No. : 27

If NO or B 28, Ass. Lia :

Repair Cost:

W/hst

SS

54905.02

Loss of Rental (LOR):

SS

(days)

Loss of Use (LOU):

SS

6000.00 (\$ 20 x 30 days)

Loss of Income (LOI):

SS

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

Total:

SS

60005.02

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

60005.02

Name 1:

Hong Seh Motors Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$400

Tan/ln

EQI

Call him to arrange the time before go.

ASSIGNMENT

Room Date 01/03/18

Estimated Cost:

OD/TS/WS/TP/RES/OD/RES/EVA/INV/INV

To inspect vehicle No SKX 2993P

at Workshop No Hong Seh Motor

10 Fourth Lok Yang Rd.

Insured

Policy No

Damage

Sum Insured

Excess

Clients Record Sam @ 9630 2180

Make of Van

Policy Condition

Remark: The van had commenced its repair at the time of inspection.



Bel. or Market Value 9/68K.

QAC Accident Report Consistent? Yes or No

QAC PP Seen Consistent? Yes or No

Est. Repairs 10 days Rep Yes or No

Sum Sum % QVal Yes or No

QA / REV / REP / 24 HRS / up

Date Person Contacted

Vehicle IN / OUT

Date Time Action Instruction Check time

PIP \$ 5133.10 (Real \$ 6242 / 11%)

13th 15:01 / 2018

SKX 2993P

2011 Jan

Type 100 M Type Bus Van Lorry Taxi Prime Mover

Truck Trailer

Make Maserati GranTurismo 4-2 4244

Colour Black

St Reading 111142

Engine

Cyls 2 AM 4.45000054119

Gen Cond Good Fair Poor Burnt

Steering Inboard Jammed Leaked Burnt or

Brake Inboard Jammed Leaked Burnt or

Mod Nil 99 STD A/Rim or

Tyre Size 285/40R19

BS/DUN/EXNOVA/GH/PS/LIZA/MC/OHTSU/PR/SUM

TOYO/YOKO or

Front

R/Ba

6

L/Ba

6

Q/OA

Surveyed at

Hong Seh Motor

Des of Damages Frt Res DS NS UD Rchhd or

The U/O Chassis frame Body Structure affected due to accident

Date Time File Pass or

☐

Final Report

Date Time File Return or

Days Of Repair

Resurvey No. of Trip

Surf. Fee

Inspector or

Add Fee

☐

Steering

Brake

Engine

Chassis

Record Return

Sum Sum



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD		Ref : CC4/EQI18004029/T1ua3		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 02-03-2018		
		Code : EQI		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SGV 717S	Veh. Inspected	SKX 2993P
	Policy No.	DMPPHQ17-005676	Coverage (\$)	0.00
	Claim No.	DM17HO02570/JT	Excess (\$)	0.00
	Assign From		Assign Date	02/03/2018
2. Vehicle Particulars & Condition				
	Make & Model	c.c 0		
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date	15/11/2017	Inspection Date	01/03/2018
	Survey held at	HONG SEH MOTORS PTE LTD 10 FOURTH LOK YANG ROAD JURONG TOWN SINGAPORE 628631		
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Motor Claim Department.
First Capital Insurance Ltd.
36, Robinson Road, #16-01
City House.
Singapore 068877

motor_claims@first-insurance.com.sg

14-Aug-17

Dear Sir / Madam

Re: Maserati GranTurismo 4.2 Auto, Vehicle Reg No.SKX2993P , Chassis ZAMGH45C000054119.

We are pleased to submit quotation for the repair of the above-mentioned vehicle:

A) Labour Description	Part Cost	Labour Cost
1 Renew rear rocket panel include cut, weld & reshape right luggage compartment floor panel. <i>1400/day</i>	2800	\$ 3,200.00
2 Remove & reinstall, both tail lamp, rear bumper, luggage compartment carpet finishing, spare wheel compartment, heat shield, both wheel arch cover and electronic handbrake system both exhaust to facilitate repair	4200	\$ 4,800.00
3 Remove & renew rear bumper, parking sensor, sensor harness	1800	\$ 2,100.00
4 Remove & Renew boot cover include alignment transfer wiring harness, locking device.	1000	\$ 1,500.00
5 Respray primer & paint to body colour rear bumper, rear bumper sensor rear rocket panel and luggage compartment floor panel both rear fender & boot cover <i>1400/panel</i>	5600	\$ 7,200.00
6 Reset all system with SD3 computer tester		\$ 950.00

B) Parts

	Qty	
1 RH Rear Silencer	1	\$ 4,455.00 <i>?bt</i>
2 LH Rear Silencer	1	\$ 4,455.00 <i>?bt</i>
3 Support	4	\$ 232.00 <i>?ner</i>
4 Rear Hood Bonnet	1	\$ 3,415.00 <i>era</i>
5 Small Block - M145	2	\$ 12.70 <i>ner</i>
6 Rear Boot Gasket	1	\$ 240.00 <i>ner</i>
7 Rivet	11	\$ 28.05 <i>ner</i>
8 Screw	4	\$ 4.80 <i>ner</i>
9 Clip	9	\$ 73.80 <i>ner</i>
10 Rr Boot Lock Mechanism	1	\$ 318.35 <i>?bt</i>
11 Screw	2	\$ 4.40 <i>ner</i>
12 Striker	1	\$ 23.60 <i>ner</i>
13 Cable	1	\$ 52.20 <i>ner</i>
14 Screw	2	\$ 3.00 <i>ner</i>
15 456Gt/A Washer, Enzo	2	\$ 2.40 <i>ner</i>

16 Battery Covering Case
 17 Screw
 18 Washer
 19 Screw
 20 Plate
 21 Luggage Compartment Carpet-Grey
 22 Screw Cover
 23 Insulation
 24 Special Screw
 25 BLOCK
 26 Striker
 27 Premium Emergency Kit
 28 Fix and Go Tyre Repair Kit
 29 R.H.Rear Lamp Mobile Side-M145 - sealant
 30 L.H.Rear Lamp Mobile Side-M145 - sealant
 31 Upper Rear Panel
 32 Lower Rear Panel
 33 Rivet
 34 Complete Rear Bumper
 35 Rh Bracket
 36 LH Bracket
 37 Rear bumper plate
 38 Screw
 39 Gasket
 40 Wiring Parking Sensor
 41 Parking Sensor
 42 Parking Sensor Gasket
 43 Support Parking Sensor
 44 Spare Wheel Housing
 45 Screw Cover
 46 Washer
 47 Wheel Shield
 48 RH Tail pipe Heatshield
 49 Cat. Converter Shield Washer
 50 LH Silencer Heat Shield
 51 Cat. Converter Shield Washer
 52 Emblem "Maserati" Rear Boot
 53 Rear Hood Bonnet Handle - M145
 54 Number Plate Light
 55 Screw
 56 Rear Boot Moulding tape
 57 RH Rear Covering tape
 58 LH outer boot Covering tape
 59 Button
 60 Rear reg plate.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1	\$	636.00	del
4	\$	11.20	del
4	\$	10.00	del
1	\$	1.60	del
1	\$	115.05	del
1	\$	406.20	del
4	\$	51.20	del
1	\$	92.00	del
4	\$	234.40	del
4	\$	7.20	del
1	\$	2.15	del
1	\$	608.00	del
1	\$	550.00	del
1	\$	380.00	del
1	\$	380.00	del
1	\$	2,950.00	del
1	\$	2,800.00	del
5	\$	60.00	del
1	\$	6,420.00	del
1	\$	75.50	del
1	\$	75.50	del
1	\$	530.00	del
22	\$	231.00	del
8	\$	13.20	del
1	\$	1,625.00	del
2	\$	1,462.50	del
4	\$	96.00	del
4	\$	122.00	del
1	\$	1,500.00	del
18	\$	231.30	del
16	\$	14.40	del
1	\$	1,000.00	del
1	\$	312.00	del
4	\$	7.20	del
1	\$	315.00	del
4	\$	6.00	del
1	\$	78.00	del
1	\$	495.00	del
2	\$	221.00	del
4	\$	13.20	del
1	\$	218.00	del
1	\$	70.50	del
1	\$	70.50	del
6	\$	27.00	del
1	\$	60.00	del

TOTAL:

\$ 37,905.10 \$ 19,750.00

Total Labour	:	\$ 19,750.00
Total Parts	:	\$ 37,905.10
		\$ 57,655.10
Plus 7% GST	:	\$ 4,035.86
Grand Total	:	\$ 61,690.96

57709.10

Should this repair job require any additional parts, we will inform you and bill you accordingly. Please confirm acceptance of this quotation by sending us a return fax with your signature and company stamp on it.

Yours sincerely,

I agree and accept the above quotation



Workshop Department

Signature & Company stamp

Tanfiah 97495749
- WP

1/3/18 @ 1615

Resurvey

To check repair limit

* Resurvey check items
* Resurvey before/after paint

10 days

sun@lkkauto.com
tanfiah@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Supp
Auto Handralce Module Mounting \$54.00 ✓

DM17H002570/ST



Page

1



Service Tax Invoice

GST Reg. No. : M2-0055566-0

EQ Insurance Co Ltd		
NAME	IN	OUT
Accounts		
RT		
GPS		
VL		
VT		
JL		
FH		
FT		
CG		
ES		
KJ		
Claims		

Invoice Details			
To : EQ Insurance Company Limited		Account Number	Invoice Number
5 Maxwell Road #17-00		CUST2402	INVP18090017
Tower Block MND Complex		Service Order Number	Invoice Date
Singapore 069110		SO18020003-R	17/09/18
Vehicle Details			
Model	Mileage (km)	Registration number	Chasis Number
Granturismo 4.2 Auto M	111,141	SKX2993P	ZAMGH45C000054119
Vehicle Owner	Date/Time In	Make	Warranty Start/End Date
CUST2402	05/02/18 / 3:32:40	MASERATI	14/01/11 / 14/01/16

Job Details						
Category	Description	Qty (Unit)	Unit Price	Price	Disc %	Amount
Labor	Remove & Renew Boot Cover, Device & harness Line 4	1	1,000.00	1,000.00		1,000.00
Labor	Renew Rear Bumper Parking Sensor & Harness, Line 3	1	1,800.00	1,800.00		1,800.00
Labor	Renew Rear Rocket Panel Include Reshape, Line 1	1	2,800.00	2,800.00		2,800.00
Labor	Reset All System With SD3 Tester, Line 6	1	950.00	950.00		950.00
Labor	Rear Reg Number Plate	1	30.00	30.00		30.00
Labor	Remove & Install Rear Section To Faciliate Repair,	1	4,200.00	4,200.00		4,200.00
Labor	Respray Rear Section Accident/Bumper/Boot Cover,	1	5,600.00	5,600.00		5,600.00
SubTotal:-						16,380.00
Item	15)456G/A Washer , Enzo	2	1.20	2.40		2.40
Item	45)Screw 5*18	18	12.85	231.30		231.30
Item	17)Screw	4	2.80	11.20		11.20
Item	8) Screw	4	1.20	4.80		4.80
Item	18)Washer	4	2.50	10.00		10.00
Item	25)Block	4	1.80	7.20		7.20
Item	50) Washer	16	0.80	12.80		12.80
Item	55) Screw	4	3.30	13.20		13.20
Item	19)Screw	1	1.60	1.60		1.60
Item	14)Screw	2	1.50	3.00		3.00
Item	11) Screw	2	2.20	4.40		4.40
Item	54) Number Plate Light	2	110.50	221.00		221.00
Item	3) Support	4	58.00	232.00		232.00
Item	41)Parking Sensor	3	487.50	1,462.50		1,462.50
Item	42)Parking Sensor Gasket	4	24.00	96.00		96.00
Item	40)Wiring Parking Sensor	1	1,625.00	1,625.00		1,625.00
Item	9) Clip	9	8.20	73.80		73.80
Item	1) RH Rear Silencer	1	4,455.00	4,455.00		4,455.00
Item	2) LH Rear Silencer	1	4,455.00	4,455.00		4,455.00
Item	Auto Handbrake module Mounting (Supplimentary)	4	13.50	54.00		54.00
Item	39)Gasket	8	1.65	13.20		13.20
Item	38)Screw	22	10.50	231.00		231.00
Item	32)Lower Rear Panel	1	2,800.00	2,800.00		2,800.00
Sum carried forward						16,020.40

Customer Signature
(Receipt Acknowledgement)

Hong Seh Motors Pte Ltd
Company Reg. No. 198203320D
10 Fourth Lok Yang Road Singapore 629707
tel +65 6266 1555 fax +65 6265 9595

Authorised Signature
(Workshop Dept)



Service Tax Invoice

GST Reg. No. : M2-0055566-0

Invoice Details

To : EQ Insurance Company Limited 5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110	<u>Account Number</u>	<u>Invoice Number</u>
	CUST2402	INVP18090017
	<u>Service Order Number</u>	<u>Invoice Date</u>
	SO18020003-R	17/09/18

Vehicle Details

<u>Model</u>	<u>Mileage (km)</u>	<u>Registration number</u>	<u>Chasis Number</u>
Granturismo 4.2 Auto M	111,141	SKX2993P	ZAMGH45C000054119
<u>Vehicle Owner</u>	<u>Date/Time In</u>	<u>Make</u>	<u>Warranty Start/End Date</u>
CUST2402	05/02/18 / 3:32:40	MASERATI	14/01/11 / 14/01/16

Job Details

Category	Description	Qty (Unit)	Unit Price	Price	Disc %	Amount
Item	52) Emblem "Maserati" Rear Boot	1	78.00	78.00		78.00
Item	24)Special Screw	4	58.60	234.40		234.40
Item	22)Screw Cover	4	12.80	51.20		51.20
Item	26)Striker	1	2.15	2.15		2.15
Item	44)Spare Wheel Housing	1	1,500.00	1,500.00		1,500.00
Item	6)Rear Boot Gasket	1	240.00	240.00		240.00
Item	31)Upper Rear Panel	1	2,950.00	2,950.00		2,950.00
Item	33)Rivet For Body Panel	5	12.00	60.00		60.00
Item	19)Screw	1	115.05	115.05		115.05
Item	10)Rr Boot Lock Mechanism	1	318.35	318.35		318.35
Item	12)Striker	1	23.60	23.60		23.60
Item	53) Rear Hood Bonnet Handle - M145	1	495.00	495.00		495.00
Item	51) Wheel Shield	1	1,000.00	1,000.00		1,000.00
Item	35)Rh Bracket	1	75.50	75.50		75.50
Item	36)LH Bracket	1	75.50	75.50		75.50
Item	4) Rear Hood Bonnet	1	3,415.00	3,415.00		3,415.00
Item	5) Small Block - M145	2	6.35	12.70		12.70
Item	13)Cable	1	52.20	52.20		52.20
Item	7) Rivet	11	2.55	28.05		28.05
Item	23)Insulation	1	92.00	92.00		92.00
Item	43)Support Parking Sensor	4	30.50	122.00		122.00
Item	57) RH Rear Covering	1	70.50	70.50		70.50
Item	58) LH outer boot Covering	1	70.50	70.50		70.50
Item	59) Button	6	4.50	27.00		27.00
Item	56) Rear Boot Moulding	1	218.00	218.00		218.00
Item	16)Battery Covering Case	1	636.00	636.00		636.00
Item	34)Complete Rear Bumper	1	6,420.00	6,420.00		6,420.00
Item	37)Rear bumper plate	1	530.00	530.00		530.00
SubTotal:-						34,933.10

Customer Signature
(Receipt Acknowledgement)

Hong Seh Motors Pte Ltd
Company Reg. No. 198203320D
10 Fourth Lok Yang Road Singapore 629707
tel +65 6266 1555 fax +65 6265 9595

Authorised Signature
(Workshop Dept)



Service Tax Invoice

GST Reg. No. : M2-0055566-0

Invoice Details		
To : EQ Insurance Company Limited 5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110	<u>Account Number</u>	<u>Invoice Number</u>
	CUST2402	INVP18090017
	<u>Service Order Number</u>	<u>Invoice Date</u>
	SO18020003-R	17/09/18

Vehicle Details			
<u>Model</u>	<u>Mileage (km)</u>	<u>Registration number</u>	<u>Chasis Number</u>
Granturismo 4.2 Auto M	111,141	SKX2993P	ZAMGH45C000054119
<u>Vehicle Owner</u>	<u>Date/Time In</u>	<u>Make</u>	<u>Warranty Start/End Date</u>
CUST2402	05/02/18 / 3:32:40	MASERATI	14/01/11 / 14/01/16

Job Details						
Category	Description	Qty (Unit)	Unit Price	Price	Disc %	Amount
(SGD - FIFTY FOUR THOUSAND NINE HUNDRED FIVE AND TWO CENTS ONLY)						
Clause:- Kindly remove all your personal belongings when sending your car for servicing or repairs. Any personal belongings left in the car or at our premises are at your own risk. The management is NOT liable for any damage or loss. Any objections or queries to the validity of these charges must be made within 7 days from the date of the invoice otherwise it is assumed the repair is deemed satisfactory. Payment is required before release of vehicle. Late payment interest of 1.5% per month will be added into the invoice amount after 2 weeks from date of invoice. Vehicle must be collected within 7 working days upon completion of job, otherwise a minimum store rent of \$35/day not inclusive of insurance will be imposed.						
				Total SGD	:	51,313.10
				7% GST	:	3,591.92
				Less	:	
				Amount Due (SGD)	:	54,905.02

Customer Signature
(Receipt Acknowledgement)

Hong Seh Motors Pte Ltd
Company Reg. No. 198203320D
10 Fourth Lok Yang Road Singapore 629707
tel +65 6266 1555 fax +65 6265 9595

Authorised Signature
(Workshop Dept)



VEHICLE DISCHARGE VOUCHER

I hereby certify that my **Maserati GranTurismo 4.2 Auto**, Registration No, **SKX2993P**, Chassis No, **ZAMGH45C000054119** sustained an accident, and has been repaired to my satisfaction by **Hong Seh Motors Pte Ltd**.

I took delivery of my vehicle registration No, **SKX2993P** on, **13th April 2018** in good order and condition.



Gabriel Peter.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC4/EQI18004029/T1ua3

Date: 02.03.2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

PRELIMINARY ADVICE OF VEHICLE NO.

SKX 2993P


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 01.03.2018 at the premises of M/s Hong Seh Motors Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	57,655.10
Revised Estimate Amount	: S\$	33,484.90
"Check" Items Amount	: S\$	19,597.20
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 10.0 days

Yours faithfully,

MOHD. TAUFIKH
Licensed Appraiser

R	?	X	
2,800.00		400.00	
4,200.00		600.00	
1,800.00		300.00	
1,000.00		500.00	
5,600.00		1,600.00	
950.00			
16,350.00	-	3,400.00	19,750.00

16,350.00	-	3,400.00	19,750.00
17,134.90	19,597.20	1,173.00	37,905.10
33,484.90	19,597.20	4,573.00	57,655.10

57,655.10

33,484.90 ✓

19,597.20 ? ✓

R	?	X	
3,415.00		4,455.00	608.00
12.70		4,455.00	550.00
240.00		232.00	15.00
28.05		318.35	
4.80		115.05	
73.80		406.20	
4.40		51.20	
23.60		380.00	
52.20		380.00	
3.00		2,950.00	
2.40		2,800.00	
636.00		60.00	
11.20		1,625.00	
10.00		312.00	
1.60		7.20	
92.00		315.00	
234.40		6.00	
7.20		495.00	
2.15		221.00	
6,420.00		13.20	
75.50			
75.50			
530.00			
231.00			
13.20			
1,462.50			
96.00			
122.00			
1,500.00			
231.30			
14.40			
1,000.00			
78.00			
218.00			
70.50			
70.50			
27.00			
45.00			
17,134.90	19,597.20	1,173.00	37,905.10

CAJ
9/3/18

Catherine Chong (LKK Auto)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Wednesday, 28 February, 2018 5:03 PM
To: assignments
Subject: FW: DM17HO02570/JT-Accident in between SKX2993P & SGV717S on 15 Nov 2017 at 1145 hrs at Bukit Timah Road toward Balmoral Plaza.
Attachments: SKX2993P_15112017.PDF(NEW).pdf; img-226152445-0001.pdf

9.46am @ 01/3/2018
vehicle in
person @ sam
sur @ faulikh

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Janet Tan [mailto:janet.tan@eqinsurance.com.sg]
Sent: Wednesday, 28 February 2018 4:24 PM
To: Admin A <admin-a@lkkauto.com>
Cc: samtan@hongseh.com.sg
Subject: DM17HO02570/JT-Accident in between SKX2993P & SGV717S on 15 Nov 2017 at 1145 hrs at Bukit Timah Road toward Balmoral Plaza.

Without Prejudice
Save As To Costs

Dear all,

Please arrange to attend to the PRS.

Liability is cleared. Proceed to direct settle, if possible.

Regards,

Janet Tan
Senior Executive | Claims



EQ Insurance Company Limited
5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of this message.

From: Evon Thoo

Sent: Monday, February 26, 2018 4:02 PM

To: Janet Tan <janet.tan@eqinsurance.com.sg>

Cc: Bazlin Ahmad <bazlin.ahmad@eqinsurance.com.sg>; Rose Koh <rose.koh@eqinsurance.com.sg>

Subject: FW: Accident in between SKX2993P & SGV717S on 15 Nov 2017 at 1145 hrs at Bukit Timah Road toward Balmoral Plaza.

Dear Janet

FYNA

Regards,

Evon Thoo

Customer Service




EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

tel 65 62239433 | fax 65 6224 3903

www.eqinsurance.com.sg

 A Member of Citystate



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of this message.

From: Sam Tan [<mailto:samtan@hongseh.com.sg>]

Sent: Monday, February 26, 2018 3:49 PM

To: Marketing

Subject: Accident in between SKX2993P & SGV717S on 15 Nov 2017 at 1145 hrs at Bukit Timah Road toward Balmoral Plaza.

Dear Sir / Mdm,

Accident in between SKX2993P & SGV717S on 15 Nov 2017 at 1145 hrs at Bukit Timah Road toward Balmoral Plaza.

I have been instructed by the owner of SKX2993P to liaise with EQ Insurance Company Ltd with the above matter.

Attached is the accident report by the owner of SKX2993P insure under Liberty Insurance Pte Ltd and the repair estimate.

The prima facie evidence suggests that SGV717S had caused the accident. You may wish to look into the matter and confirm if EQ Insurance Company Ltd is open to a direct settlement for this claim.

I would appreciate you could reply ASAP.

Best regards.
Sam Tan
Service Advisor



Hong Seh Motors Pte Ltd

10 Fourth Lok Yang Road Singapore 629707

Tel: +65 6266 1555 Fax: +65 6265 9595

DID: +65 6316 5916

HP: +65 96302180

Email: samtan@hongseh.com.sg

Mei Kwan (LKKAUTO)

From: Janet Tan <janet.tan@eqinsurance.com.sg>
Sent: Tuesday, 13 March, 2018 8:37 AM
To: Mei Kwan (LKKAUTO)
Cc: Admin A; Thin Thin (LKKAUTO)
Subject: FW: DM17HO02570/JT-Accident in between SKX2993P & SGV717S on 15 Nov 2017 at 1145 hrs at Bukit Timah Road toward Balmoral Plaza.
Attachments: Preliminary Advice.pdf; TP ESTIMATE - MARKED.pdf; SGV717S.pdf
Follow Up Flag: Follow up
Flag Status: Completed
Categories: HMK

Dear Mei Kwan

As attached.

Regards,

Janet Tan
Senior Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the :

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Friday, March 9, 2018 10:13 AM
To: Janet Tan <janet.tan@eqinsurance.com.sg>
Cc: Admin A <admin-a@lkkauto.com>; Thin Thin (LKKAUTO) <thinthin@lkkauto.com>
Subject: RE: DM17HO02570/JT-Accident in between SKX2993P & SGV717S on 15 Nov 2017 at 1145 hrs at Bukit Timah Road toward Balmoral Plaza.

Your ref: DM17HO02570/JT
LKK ref: CC4/EQI18004029/T1ua3

WITHOUT PREJUDICE

Dear Janet,

We refer to the above matter.

Liability is cleared. Proceed to direct settle, if possible.

Regards,

Janet Tan

Senior Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190

www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the :

From: Evon Thoo

Sent: Monday, February 26, 2018 4:02 PM

To: Janet Tan <janet.tan@eqinsurance.com.sg>

Cc: Bazlin Ahmad <bazlin.ahmad@eqinsurance.com.sg>; Rose Koh <rose.koh@eqinsurance.com.sg>

Subject: FW: Accident in between SKX2993P & SGV717S on 15 Nov 2017 at 1145 hrs at Bukit Timah Road toward Balmoral Plaza.

Dear Janet

FYNA

Regards,

Evon Thoo

Customer Service



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

tel 65 62239433 | fax 65 6224 3903

www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of it.

From: Sam Tan [<mailto:samtan@hongseh.com.sg>]

Sent: Monday, February 26, 2018 3:49 PM

To: Marketing



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
 6 Raffles Quay #18-00 Singapore 048580
 Tel (65) 6224 0010 Fax (65) 6224 0030
 Operating Hours : Monday to Friday, 09:00 – 17:00
 UEN: 56650020G / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MBHH17152189 Vehicle Registration No : SGV7175
 Name(as shown in NRIC) : MUHAMMAD FADZLI BIN SALIM NRIC/FIN/Passport No : S7919738F
 (*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
 Address : _____ Singapore()
 Contact (Tel) : _____ Mobile No. : 98938147
 Email Address : FADZLISALIM4LIFE@GMAIL.COM
 Date of Accident : 15/11/2017 Time of Accident : 23:40
 Place of Accident : ALONG BUKIT TIMAH RD
 Insurance Company : EQ INSURANCE COMPANY LTD

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

AMEND TO OWN DAMAGED CLAIMS

AMEND EMAIL ADDRESS : FADZLISALIM4LIFE@GMAIL.COM

N.A

Policyholder / Driver's Signature
 Date:

Reporting Centre Personnel's Signature
 Name: NOR ATIKA
 NRIC/FIN No.: G2055450P
 Date: 21/11/2017

Hsiao Tong (LKKAUTO)

From: Mei Kwan (LKKAUTO)
Sent: Tuesday, 11 December 2018 1:54 PM
To: Hsiao Tong (LKKAUTO)
Subject: FW: DM17HO02570/JT-Accident in between SKX2993P & SGV717S on 15 Nov 2017 at 1145 hrs at Bukit Timah Road toward Balmoral Plaza.

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir / Madam,

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Taufikh (LKK Auto) <taufikh@lkkauto.com>
Sent: Tuesday, 11 September, 2018 6:04 PM
To: Sam Tan <samtan@hongseh.com.sg>
Cc: Thin Thin (LKKAUTO) <thinthin@lkkauto.com>
Subject: RE: DM17HO02570/JT-Accident in between SKX2993P & SGV717S on 15 Nov 2017 at 1145 hrs at Bukit Timah Road toward Balmoral Plaza.

Hi Sam,

COR \$51,313.10 , 10 days.

Regards

Taufikh

Lkk Auto

From: Sam Tan [<mailto:samtan@hongseh.com.sg>]
Sent: Tuesday, 4 September 2018 11:49 AM
To: Thin Thin (LKKAUTO); Taufikh (LKKAUTO)
Cc: CS A Team
Subject: RE: DM17HO02570/JT-Accident in between SKX2993P & SGV717S on 15 Nov 2017 at 1145 hrs at Bukit Timah Road toward Balmoral Plaza.

Hi Thin Thin,

Kindly advice on the finalization ?

Best regards.

Sam Tan

Service Advisor



Hong Seh Motors Pte Ltd

10 Fourth Lok Yang Road Singapore 629707

Tel: +65 6266 1555 Fax: +65 6265 9595

DID: +65 6316 5916

HP: +65 96302180

Email: samtan@hongseh.com.sg

From: Sam Tan

Sent: Friday, 31 August, 2018 11:26 AM

To: 'Thin Thin (LKKAUTO)'; Taufikh (LKKAUTO)

Cc: CS A Team

Subject: RE: DM17HO02570/JT-Accident in between SKX2993P & SGV717S on 15 Nov 2017 at 1145 hrs at Bukit Timah Road toward Balmoral Plaza.

Hi Thin Hlaing,

I had e mail all the necessary pictures and invoice to Taufikh.
Please assist to get it from him.

Thanks a lot .

Sam Tan

Service Advisor



Hong Seh Motors Pte Ltd

10 Fourth Lok Yang Road Singapore 629707

Tel: +65 6266 1555 Fax: +65 6265 9595

DID: +65 6316 5916

HP: +65 96302180

Email: samtan@hongseh.com.sg

From: Thin Thin (LKKAUTO) [<mailto:thinthin@lkkauto.com>]

Sent: Friday, 31 August, 2018 10:43 AM

To: Sam Tan; Taufikh (LKKAUTO)

Cc: CS A Team

Subject: RE: DM17HO02570/JT-Accident in between SKX2993P & SGV717S on 15 Nov 2017 at 1145 hrs at Bukit Timah Road toward Balmoral Plaza.

Hi Sam,

Kindly forward the invoice to us for finalisation and before & after repair & painting pictures .

Best Regards,

Thin Thin Hlaing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2360 | email: thinthin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sam Tan <samtan@hongseh.com.sg>

Sent: Thursday, 30 August 2018 6:19 PM

To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>; CS A Team <cs-a@lkkauto.com>

Subject: RE: DM17HO02570/JT-Accident in between SKX2993P & SGV717S on 15 Nov 2017 at 1145 hrs at Bukit Timah Road toward Balmoral Plaza.

Hi Taufikh ,

Any news of closing ???

Best regards.

Sam Tan

Service Advisor



Hong Seh Motors Pte Ltd

10 Fourth Lok Yang Road Singapore 629707

Tel: +65 6266 1555 Fax: +65 6265 9595

DID: +65 6316 5916

HP: +65 96302180

Email: samtan@hongseh.com.sg

From: Sam Tan

Sent: Thursday, 19 July, 2018 10:23 AM

To: 'Taufikh (LKK Auto)'; 'cs-a@lkkauto.com'

Subject: RE: DM17HO02570/JT-Accident in between SKX2993P & SGV717S on 15 Nov 2017 at 1145 hrs at Bukit Timah Road toward Balmoral Plaza.

Hi Dato Taufikh ,

Any news ?

Best regards.

Sam Tan

Service Advisor



Hong Seh Motors Pte Ltd

10 Fourth Lok Yang Road Singapore 629707

Tel: +65 6266 1555 Fax: +65 6265 9595

DID: +65 6316 5916

HP: +65 96302180
Email: samtan@hongseh.com.sg

From: Sam Tan
Sent: Wednesday, 11 July, 2018 10:54 AM
To: 'Taufikh (LKK Auto)'
Subject: RE: DM17HO02570/JT-Accident in between SKX2993P & SGV717S on 15 Nov 2017 at 1145 hrs at Bukit Timah Road toward Balmoral Plaza.

Hi Dato Taufikh ,

Any news ?

My boss is going to knock at your boss door already.

Please help

Best regards.
Sam Tan
Service Advisor



Hong Seh Motors Pte Ltd

10 Fourth Lok Yang Road Singapore 629707
Tel: +65 6266 1555 Fax: +65 6265 9595
DID: +65 6316 5916
HP: +65 96302180
Email: samtan@hongseh.com.sg

From: Sam Tan
Sent: Wednesday, 30 May, 2018 3:13 PM
To: 'Taufikh (LKK Auto)'
Subject: RE: DM17HO02570/JT-Accident in between SKX2993P & SGV717S on 15 Nov 2017 at 1145 hrs at Bukit Timah Road toward Balmoral Plaza.

Hi Taufikh ,

Kindly advise asap. Need to closed the account asap.

Best regards.
Sam Tan
Service Advisor



Hong Seh Motors Pte Ltd

10 Fourth Lok Yang Road Singapore 629707
Tel: +65 6266 1555 Fax: +65 6265 9595
DID: +65 6316 5916

HP: +65 96302180
Email: samtan@hongseh.com.sg

From: Sam Tan
Sent: Thursday, 10 May, 2018 7:36 PM
To: 'Taufikh (LKK Auto)'
Subject: FW: DM17HO02570/JT-Accident in between SKX2993P & SGV717S on 15 Nov 2017 at 1145 hrs at Bukit Timah Road toward Balmoral Plaza.

Hi Taufikh,

Please find attach preview invoice for your finalisation.
Before & after repair & painting pictures .

Best regards,
Sam Tan
Service Advisor



Hong Seh Motors Pte Ltd

10 Fourth Lok Yang Road Singapore 629707
Tel: +65 6266 1555 Fax: +65 6265 9595
DID: +65 6316 5916
HP: +65 96302180
Email: samtan@hongseh.com.sg

From: Bryan Ang (LKKAuto) [<mailto:bryanang@lkkauto.com>]
Sent: Wednesday, 4 April, 2018 5:58 PM
To: Sam Tan; Veron Chen (LKKAuto); Thin Thin (LKKAuto)
Cc: CS A Team; Admin A; SUR
Subject: RE: DM17HO02570/JT-Accident in between SKX2993P & SGV717S on 15 Nov 2017 at 1145 hrs at Bukit Timah Road toward Balmoral Plaza.

Dear Sam

I have reviewed the photos.

End panel lower observed to be dented.
End panel upper observed to be dented.

Please replace both parts with photos to be taken accordingly.

Best Regards,

Bryan Ang

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: bryanang@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sam Tan [<mailto:samtan@hongseh.com.sg>]
Sent: Wednesday, 4 April 2018 5:52 PM
To: Bryan Ang (LKKAuto) <bryanang@lkkauto.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Thin Thin (LKKAuto) <thinthin@lkkauto.com>

Cc: CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: RE: DM17HO02570/JT-Accident in between SKX2993P & SGV717S on 15 Nov 2017 at 1145 hrs at Bukit Timah Road toward Balmoral Plaza.

Hi Bryan,

Thank you for your speedy response.

Attached are the pictures of the damage end panel for your approval.

Best regards,

Sam Tan

Service Advisor



Hong Seh Motors Pte Ltd

10 Fourth Lok Yang Road Singapore 629707

Tel: +65 6266 1555 Fax: +65 6265 9595

DID: +65 6316 5916

HP: +65 96302180

Email: samtan@hongseh.com.sg

From: Bryan Ang (LKKAuto) [<mailto:bryanang@lkkauto.com>]

Sent: Wednesday, 4 April, 2018 5:44 PM

To: Sam Tan; Veron Chen (LKKAuto); Thin Thin (LKKAuto)

Cc: CS A Team; Admin A; SUR

Subject: RE: DM17HO02570/JT-Accident in between SKX2993P & SGV717S on 15 Nov 2017 at 1145 hrs at Bukit Timah Road toward Balmoral Plaza.

Dear Sam

Taufik is on leave. Please forward me the photos of the end panel.

Dear Thin Thin

Can I see this file please.

Best Regards,

Bryan Ang

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: bryanang@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sam Tan [<mailto:samtan@hongseh.com.sg>]

Sent: Wednesday, 4 April 2018 5:42 PM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Thin Thin (LKKAuto) <thinthin@lkkauto.com>

Cc: CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: RE: DM17HO02570/JT-Accident in between SKX2993P & SGV717S on 15 Nov 2017 at 1145 hrs at Bukit Timah Road toward Balmoral Plaza.

Hi Guys ,

Please advise asap.