



Motor Claim Department.
First Capital Insurance Ltd.
36, Robinson Road, #16-01
City House.
Singapore 068877

motor_claims@first-insurance.com.sg

14-Aug-17

Dear Sir / Madam

Re: Maserati GranTurismo 4.2 Auto, Vehicle Reg No.SKX2993P , Chassis ZAMGH45C000054119.

We are pleased to submit quotation for the repair of the above-mentioned vehicle:

A) <u>Labour Description</u>	<u>Part Cost</u>	<u>Labour Cost</u>
1 Renew rear rocket panel include cut, weld & reshape right luggage compartment floor panel.		\$ 3,200.00
2 Remove & reinstall, both tail lamp, rear bumper, luggage compartment carpet finishing, spare wheel compartment, heat shield, both wheel arch cover and electronic handbrake system both exhaust to facilitate repair		\$ 4,800.00
3 Remove & renew rear bumper, parking sensor, sensor harness		\$ 2,100.00
4 Remove & Renew boot cover include alignment transfer wiring harness, locking device.		\$ 1,500.00
5 Respray primer & paint to body colour rear bumper, rear bumper sensor rear rocket panel and luggage compartment floor panel both rear fender & boot cover		\$ 7,200.00
6 Reset all system with SD3 computer tester		\$ 950.00

B) <u>Parts</u>	<u>Qty</u>	
1 RH Rear Silencer	1	\$ 4,455.00
2 LH Rear Silencer	1	\$ 4,455.00
3 Support	4	\$ 232.00
4 Rear Hood Bonnet	1	\$ 3,415.00
5 Small Block - M145	2	\$ 12.70
6 Rear Boot Gasket	1	\$ 240.00
7 Rivet	11	\$ 28.05
8 Screw	4	\$ 4.80
9 Clip	9	\$ 73.80
10 Rr Boot Lock Mechanism	1	\$ 318.35
11 Screw	2	\$ 4.40
12 Striker	1	\$ 23.60
13 Cable	1	\$ 52.20
14 Screw	2	\$ 3.00
15 456Gt/A Washer, Enzo	2	\$ 2.40

16 Battery Covering Case	1	\$	636.00
17 Screw	4	\$	11.20
18 Washer	4	\$	10.00
19 Screw	1	\$	1.60
20 Plate	1	\$	115.05
21 Luggage Compartment Carpet-Grey	1	\$	406.20
22 Screw Cover	4	\$	51.20
23 Insulation	1	\$	92.00
24 Special Screw	4	\$	234.40
25 BLOCK	4	\$	7.20
26 Striker	1	\$	2.15
27 Premium Emergency Kit	1	\$	608.00
28 Fix and Go Tyre Repair Kit	1	\$	550.00
29 R.H.Rear Lamp Mobile Side-M145	1	\$	380.00
30 L.H.Rear Lamp Mobile Side-M145	1	\$	380.00
31 Upper Rear Panel	1	\$	2,950.00
32 Lower Rear Panel	1	\$	2,800.00
33 Rivet	5	\$	60.00
34 Complete Rear Bumper	1	\$	6,420.00
35 Rh Bracket	1	\$	75.50
36 LH Bracket	1	\$	75.50
37 Rear bumper plate	1	\$	530.00
38 Screw	22	\$	231.00
39 Gasket	8	\$	13.20
40 Wiring Parking Sensor	1	\$	1,625.00
41 Parking Sensor	3	\$	1,462.50
42 Parking Sensor Gasket	4	\$	96.00
43 Support Parking Sensor	4	\$	122.00
44 Spare Wheel Housing	1	\$	1,500.00
45 Screw Cover	18	\$	231.30
46 Washer	18	\$	14.40
47 Wheel Shield	1	\$	1,000.00
48 RH Tail pipe Heatshield	1	\$	312.00
49 Cat. Coverter Shield Washer	4	\$	7.20
50 LH Silencer Heat Shield	1	\$	315.00
51 Cat. Coverter Shield Washer	4	\$	6.00
52 Emblem "Maserati" Rear Boot	1	\$	78.00
53 Rear Hood Bonnet Handle - M145	1	\$	495.00
54 Number Plate Light	2	\$	221.00
55 Screw	4	\$	13.20
56 Rear Boot Moulding	1	\$	218.00
57 RH Rear Covering	1	\$	70.50
58 LH outer boot Covering	1	\$	70.50
59 Button	6	\$	27.00
60 Rear reg plate.	1	\$	60.00

TOTAL:

\$ 37,905.10 \$ 19,750.00

Total Labour	:	\$ 19,750.00
Total Parts	:	\$ 37,905.10
		<u>\$ 57,655.10</u>
Plus 7% GST	:	\$ 4,035.86
Grand Total	:	<u><u>\$ 61,690.96</u></u>

Should this repair job require any additional parts, we will inform you and bill you accordingly. Please confirm acceptance of this quotation by sending us a return fax with your signature and company stamp on it.

Yours sincerely,

I agree and accept the above quotation

Workshop Department

Signature & Company stamp