

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5714E - III**AAD1802-261/263***Not Authored**1/1/2018*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC5714E - CANDY

VF1ABL15AUC280319

RENAULT

LATITUDE

27.02.2018

III

PART			LIST	
1	1	BUMPER COVER FRT	\$	<i>Bu</i> 1,259.42 ✓
2	1	BUMPER SPOILER FRT	\$	<i>Sn</i> 181.75 X
3	1	BUMPER ABSORBER FRT	\$	394.68 ✓
4	1	BUMPER RETAINER FRT LH	\$	<i>Dis</i> 151.41 ✓
5	1	BUMPER SUPPORT FRT	\$	<i>Sn</i> 123.88 X
6	1	BUMPER RETAINER FRT RH	\$	<i>Dis</i> 150.77 ✓
7	1	BUMPER SUPPORT FRT	\$	<i>Sn</i> 123.88 X
8	1	BUMPER UNDERTRAY FRT	\$	<i>Sn</i> 472.83 X
9	1	BUMPER GRILLE LOWER FRT	\$	<i>Sn</i> 266.80 X
10	1	BUMPER FOG LAMP GRILLE LH	\$	<i>Sn</i> 207.21 ✓
11	1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sn</i> 207.21 X
12	1	BUMPER BEAM FRT	\$	914.08 ?
13	1	TOW COVER FRT	\$	<i>Sn</i> 28.61 X
14	1	RADAIOR GRILLE	\$	<i>mg cm</i> 1,707.78 ✓
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>na</i> 225.36 ✓
16	1	RADAIOR GRILLE FRAME	\$	<i>cm</i> 1,353.75 ✓
17	1	FRAME FULL SUPPORT PANEL	\$	<i>cm</i> 615.90 ✓
18	1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79 X
19	1	FRONT BRACE PANEL	\$	<i>R</i> 177.22 X
20	1	HORN	\$	<i>Sn</i> 314.17
21	1	HORN BRACKET	\$	<i>R</i> 40.45
22	1	HEADLAMP LH	\$	<i>Sn</i> 1,184.43
23	1	HEADLAMP RH	\$	<i>Sn</i> 1,184.43
24	1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 152.15
25	1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15
26	1	BONNET	\$	<i>R</i> 1,941.63
27	1	BONNET INSULATOR	\$	<i>Sn</i> 405.73
28	1	BONNET STRUT LH	\$	<i>Sn</i> 88.61
29	1	BONNET STRUT RH	\$	<i>Sn</i> 88.61
30	1	BONNET HINGE LH	\$	<i>R</i> 348.31
31	1	BONNET HINGE RH	\$	<i>R</i> 348.31
32	1	BONNET LOCK	\$	<i>R</i> 305.48
33	1	BONNET CABLE	\$	<i>Sn</i> 119.19
34	1	BONNET CABLE COVER	\$	<i>Sn</i> 161.03

TRANS-CAB AUTO SERVICES PTE LTD
AAD1802-261/263

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5714E - III

35	1	BONNET SEAL OUTER	\$	Sn	92.36	
36	1	FENDER PANEL FRT LH	\$	Sn	783.83	
37	1	FENDER PANEL FRT RH	\$	Sn	783.83	
38	1	WHEELARCH FRT LH	\$	Sn	278.84	
39	1	WHEELARCH FRT RH	\$	Sn	278.84	
40	1	FENDER BRACKET LOWER LH	\$	Sn	15.79	
41	1	FENDER BRACKET LOWER RH	\$	Sn	15.79	
42	1	FENDER INSULATOR LH	\$	Sn	130.84	
43	1	FENDER INSULATOR RH	\$	Sn	130.84	
44	1	A/C CONDENSER	\$	Sn	2,020.37	
45	1	A/C CONDENSER GARNISH LH UPPER	\$	Sn	39.67	
46	1	A/C CONDENSER GARNISH RH UPPER	\$	Sn	39.67	
47	1	A/C CONDENSER GARNISH LH	\$	Sn	58.81	
48	1	A/C CONDENSER GARNISH RH	\$	Sn	59.60	
49	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	Sn	208.39	
50	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$	Sn	658.72	
51	1	A/C PIPE COMPRESSOR	\$	Sn	334.29	
52	1	A/C PIPE	\$	Sn	658.72	
53	1	A/C COMPRESSOR	\$	Sn	2,684.61	
54	1	AIR COOLER	\$	Sn	792.60	
55	1	AIR INTERCOOLER HOSE (LONG)	\$	Sn	1,014.13	
56	1	AIR INTERCOOLER HOSE (Short)	\$	Sn	375.14	
57	1	TRANSMISSION COOLER	\$	Sn	1,219.30	
58	1	TRANSMISSION COOLER PAD	\$	Sn	17.96	
59	1	RADIATOR	\$	Sn	1,202.20	
60	2	RADIATOR STUD UPPER	\$	Sn	14.41	
61	2	RADIATOR BUSH UPPER	\$	Sn	50.12	
62	2	RADIATOR MTG LOWER	\$	Sn	55.85	
63	1	RADIATOR FAN COWLING	\$	Sn	820.54	
64	1	RADIATOR FAN MOTOR LH	\$	Sn	967.36	
65	1	RADIATOR FAN MOTOR RH	\$	Sn	1,479.46	
66	1	RADIATOR TANK	\$	Sn	324.62	
67	1	RADIATOR HOSE UPPER	\$	Sn	240.56	
68	1	RADIATOR HOSE LOWER	\$	Sn	491.18	
69	1	RADIATOR TANK HOSE	\$	Sn	61.18	
70	1	WINDSCREEN FRT	\$	Sn	1,364.06	
71	1	ROTARY SWITCH	\$	Sn	1,253.11	
72	1	BUMPER COVER REAR	\$	Tr	1,108.46	✓
73	1	BUMPER LOWER REAR	\$	Sn	768.84	✓
74	1	BUMPER BRACKET CTR REAR	\$	Sn	113.47	X
75	1	BUMPER BRACKET SIDE LH REAR	\$	Sn	135.97	✓
76	1	BUMPER BRACKET CTR LH REAR	\$	Sn	44.99	X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5714E - III

AAD1802-261/263

77	1	BUMEPB BRACKET SIDE RH REAR	\$	R	135.97	X
78	1	BUMEPB BRACKET CTR RH REAR	\$	Sn	44.99	X
79	1	BUMPER BEAM REAR	\$	R	777.52	✓
80	1	BUMPER BEAM BRACKET LH REAR	\$	R	225.95	✓
81	1	BUMPER BEAM BRACKET RH REAR	\$	R	225.95	X
82	1	BUMPER REFLECTOR LH	\$	R	43.61	✓
83	1	BUMPER REFLECTOR RH	\$	Sn	43.61	X
84	1	BOOT REAR	\$	R	2,872.68	✓
85	2	BOOT RUBBER PLUG	\$	Sn	221.81	X
86	1	BOOT FINISHER	\$	Sn	470.06	X
87	1	BOOT SWITCH	\$	Sn	168.13	X
88	1	BOOT TRIM BOARD	\$	R	914.87	X
89	1	BOOT LOCK	\$	R	202.67	X
90	1	BOOT LOCK CATCH	\$	R	74.40	X
91	1	BOOT LOCK LINKAGE	\$	Sn	34.53	X
92	1	BOOT LOCK LINKAGE HOLDER	\$	Sn	154.52	X
93	1	BOOT LOCK CATCH TRIM BOARD	\$	Sn	249.24	X
94	1	BOOT WHEATERSTRIP	\$	D.I/L	323.05	✓
95	1	BOOT REFLECTOR LAMP LH	\$	CM	493.35	✓
96	1	BOOT REFLECTOR LAMP RH	\$	Sn	493.35	X
97	1	BOOT BADGE 'RENAULT'	\$	R	225.36	✓
98	1	BOOT BADGE	\$	R	225.36	✓
99	1	BOOT STRUT LH	\$	Sn	276.08	} X
100	1	BOOT STRUT RH	\$	Sn	276.08	
101	1	BOOT HINGE LH	\$	R	367.84	
102	1	BOOT HINGE RH	\$	R	367.84	
103	2	LICENCE PLATE LAMP	\$	Sn	50.52	
104	1	WINDSCREEN REAR	\$	Sn	1,463.28	} X
105	1	WINDSCREEN GARNISH INNER LH	\$	Sn	263.74	
106	1	WINDSCREEN GARNISH INNER RH	\$	Sn	263.74	
107	1	TAILLAMP LH	\$	R	552.55	✓
108	1	TAILLAMP PANEL LH	\$	R	986.70	✓
109	1	TAILLAMP RH	\$	Sn	552.55	X
110	1	TAILLAMP PANEL RH	\$	R	986.70	X
111	1	CHASSIS PANEL REAR LH	\$	R	3,766.43	X
112	1	FENDER PANEL REAR LH	\$	R	3,299.13	✓
113	1	FENDER PANEL REAR RH	\$	R	3,299.13	X
114	1	WHEELARCH REAR LH	\$	EM	543.47	✓
115	1	WHEELARCH REAR RH	\$	Sn	543.47	X
116	1	FENDER PANEL INNER TRIM REAR LH	\$	Not	671.45	✓
117	1	FENDER WHEEL HOUSE PANEL REAR LH	\$	R	3,039.04	X
118	1	LOWER ARM REAR LH	\$	Sn	905.99	X

TRANS-CAB AUTO SERVICES PTE LTD

AAD1802-261/263

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5714E - III

119	1	KUCKLE ARM REAR LH	\$	Sm	736.67	}
120	1	ABSORBER REAR LH	\$	Sm	389.75	
121	1	ABSORBER BOLT REAR LH	\$	Sm	52.10	
122	1	ABSORBER DUST COVER REAR LH	\$	Sm	92.16	
123	1	REAR AXLE	\$	Sm	4,167.03	
124	1	AXLE ARM ROD	\$	Sm	117.22	
125	1	AXLE ARM LH	\$	Sm	117.22	
126	1	AXLE ARM RH	\$	Sm	117.22	
127	1	AXLE ARM SHIELD LH	\$	Sm	9.08	
128	1	AXLE ARM SHIELD RH	\$	Sm	9.08	
129	1	AXLE SPRING ARM LH	\$	Sm	376.92	
130	1	AXLE SPRING ARM RH	\$	Sm	376.92	
131	1	STABILIZER BAR REAR	\$	Sm	604.65	
132	1	STABILIZER LINK REAR LH	\$	Sm	92.36	
133	1	STABILIZER LINK REAR RH	\$	Sm	92.36	
134	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88	}
135	1	SPARE WHEEL PANEL TRIM (Luggage Floor Panel)	\$	Sm	612.21	
136	1	SPARE WHEEL PANEL BRACKET LH	\$	R	123.73	
137	1	SPARE WHEEL PANEL BRACKET RH	\$	R	121.36	
138	1	OUTER PANEL REAR (End Panel)	\$	R	1,471.77	
139	1	OUTER PANEL REAR (End Panel)TRIM	\$	cm	401.02	
140	1	EXHAUST REAR	\$	R	7,489.05	
141	1	EXHAUST CAP REAR	\$	R	230.49	
142	1	EXHAUST MOUNTING REAR	\$	Sm	31.97	
143	1	EXHAUST BRACKET REAR	\$	R	39.86	
144	1	EXHAUST HEAT SHIELD REAR	\$	R	99.06	
145	1	SHIELD - HEAT - TUNNEL	\$	Sm	225.16	
146	1	FUEL FLAP	\$	Sm	343.57	
147	1	FUEL TANK NECK	\$	Sm	684.77	
148	1	FUEL CAP	\$	Sm	233.02	
149	1	DOOR PANEL REAR LH	\$	R	2,844.66	
150	1	DOOR SEAL REAR LH	\$	R	187.08	

TOTAL	\$	94,452.46
10%	\$	9,445.25
	\$	85,007.21

Specical Nett

1	1SET	RADAIOR GRILLE FRAME CLIP	\$	mc	52.00	✓
2	1SET	BUMPER CLIP FRT	\$	mc	66.00	✓
3	1	BUMPER BRACKET CLIP FRT LH	\$	mc	12.00	X
4	1	BUMPER SUPPORT CLIP FRT LH	\$	mc	10.50	✓

TRANS-CAB AUTO SERVICES PTE LTD

AAD1802-261/263

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5714E - III

5	1	BUMPER BRACKET CLIP FRT RH	\$	nn	12.00	
6	1	BUMPER SUPPORT CLIP FRT RH	\$	nn	10.50	
7	1	TOW COVER FRT	\$	sn	14.50	
8	1SET	RADAI TOR GRILLE SCREW	\$	nn	16.00	
9	1SET	BUMPER GRILLE LOWER CLIP	\$	nn	69.00	
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00	
11	2	FRAME FULL SUPPORT PANEL NUT	\$	nn	20.00	
12	2	FRAME FULL SUPPORT PANEL STUD	\$	nn	30.00	
13	1SET	WHEELARCH CLIP FRT LH	\$	nn	30.50	
14	1SET	WHEELARCH CLIP FRT RH	\$	nn	29.40	
15	1SET	BUMPER RR CLIP	\$	nn	66.00	
16	1SET	BUMPER BEAM BOLT	\$	nn	22.22	X
17	1SET	PARKING AID	\$	nn	600.00	
18	1	BUMPER BRACKET CLIP CTR REAR	\$	nn	15.00	
19	1	BUMEPR BRACKET SIDE CLIP LH REAR	\$	nn	12.00	
20	1	BUMEPR RETAINER CLIP LH REAR	\$	nn	10.40	
21	1	BUMEPR BRACKET SIDE CLIP RH REAR	\$	nn	12.00	
22	1	BUMEPR RETAINER CLIP RH REAR	\$	nn	10.40	
23	1	CAP HUB LH RR	\$	sn	35.00	
24	1	RIM LH RR	\$	sn	385.00	
25	1	TYRE LH RR	\$	sn	330.00	
26	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	sn	385.00	
27	1	SPARE TYRE	\$	sn	330.00	
28	1SET	BOOT FINISHER CLIP	\$	nn	25.10	
29	1	Rear boots sticker "trans-cab"	\$	nn	30.00	
30	1	Rear boots sticker "6555-3333"	\$	nn	30.00	
31	1	FENDER PANEL INNER TRIM CLIP REAR LH	\$	nn	22.00	X
32	1SET	WHEELARCH CLIP LH RR	\$	nn	32.34	X
33	1SET	WHEELARCH CLIP RH RR	\$	nn	32.34	X
34	2	Rear windscreen sealant	\$	nn	80.00	40sn
35	1	Windscreen moulding	\$	nn	100.00	
36	1	Rear Windscreen Inner Sponge Seal	\$	nn	100.00	30sn
37	1	EXHAUST MOUNTING REAR	\$	sn	65.50	X
38	1	EXHAUST BRACKET REAR	\$	sn	22.22	X
39	1SET	Front licence plate with holder	\$	sn	80.00	45sn
40	1SET	Rear licence plate with holder	\$	sn	80.00	X
41	1	DOOR STICKER "6555-3333" LH	\$	nn	80.00	X
42	1	BUMPER ADVERTISEMENT STICKER	\$	nn	200.00	X
43	1	FENDER ADVERTISEMENT STICKER RR LH	\$	nn	300.00	X

TOTAL \$ 3,934.92**TOTAL PARTS \$ 88,942.13**

TRANS-CAB AUTO SERVICES PTE LTD**AAD1802-261/263**

.NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5714E - III

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,200.00 ¹⁷⁰⁰
Towing Fees.	\$	120.00 ⁵⁰¹
To apply paint protection system (PPS) maintain and enhancement	\$	ⁿⁿ 380.00 ^X
Putty and spray painting of the affected portion.	\$	4,500.00 ¹³²⁹
To rust-proofing of the affected areas.	\$	170.00 ⁹⁰¹
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00 ¹²⁰¹
To check steering geometry and computer wheel alignment	\$	220.00 ⁶⁰¹
To transfer of tire, rim and on wheel balancing.	\$	ⁿⁿ 170.00 ^X
To Check Electrical Lighting Concerned.	\$	170.00 ⁴⁰¹
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00 } ²⁵⁰¹
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	ⁿⁿ 170.00 ^X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	ⁿⁿ 170.00 ^X
To supply and re-do rear luggage floor panel insulation padding.	\$	ⁿⁿ 380.00 ^X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 ⁶⁰¹
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	ⁿⁿ 380.00 ^X

TRANS-CAB AUTO SERVICES PTE LTD

AAD1802-261/263

.NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5714E - III

To transfer of tailgate fittings and conduct water seepage test.	\$	170.00	601
To transfer of rear windscreen fittings, attachments and perform water seepage test.	\$	380.00	1201
To reinstall rear bumper parking sensor.	\$	170.00	601
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	280.00	nn X
To repair and realign rear exhaust pipe.	\$	170.00	nn X
To dismantle and refit rear undercarriage parts, final checking and testing.	\$	380.00	nn X
To dismantle and refit rear axle housing assy, remove and renewal of parts, final checking and testing.	\$	380.00	nn X
To drop rear axle assy, remove and renewal of the necessary parts	\$	380.00	nn X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	nn X
To vacuum, replace, refix and recharge air condenser	\$	380.00	1001
To replace, refix and top up coolant for radiator	\$	170.00	501
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00	501
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	170.00	nn X
To remove and replace corporate sticker	\$	330.00	nn X

TOTAL	\$	16,250.00
Over All Total	\$	105,192.13

Repair Days

15
15 DAYS ✓
16