



Thatcham ecribe


National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



| | | | | |
|--|--|-----------------|--------------------|---|
| NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18004037/Gqbn2 | | | | |
| 73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556 | | | Date: 11-04-2018 |  |
| | | | Code: INC4 | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | SKA 7181D | Veh. Inspected | SHB 5366G | |
| Policy No. | 5081546442-01 | Coverage (\$) | 0.00 | |
| Claim No. | MT/0984098-002 | Excess (\$) | 0.00 | |
| Assign From | | Assign Date | 01/03/2018 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | CHEVROLET EPICA | c.c | 1991 | |
| Engine No. | HIDDEN | Year of Reg. | 2012 | |
| Chassis No. | KL1LA69RJBB136068 | Colour | MAROON | |
| Odometer | 567328 | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | STANDARD ALLOY RIM | |
| General | GOOD | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 205/65 R15 | FALKEN | 5 mm | |
| L/H Front Tyre | 205/65 R15 | FALKEN | 5 mm | |
| R/H Rear Tyre | 205/65 R15 | FALKEN | 5 mm | |
| L/H Rear Tyre | 205/65 R15 | FALKEN | 5 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 28/02/2018 | Inspection Date | 01/03/2018 | |
| Survey held at | SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705 | | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | 5 Working Days | | |