


ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD TP/WS/TP RES/OD RES/EVA/INV/MV
 To inspect Vehicle No: _____
 at Workshop m/s SMRT
 of _____
 Insured: YN 5496A
 Policy No. 5066368442-03 080717-090718
 Claims No. MT/283942-002
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 11 ~~10~~ days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHR 687M Yr Regn: 12 Sep 2014
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Tyota Prius c.c. 1798
 Colour: Maroon A/C: Insured / Std / NI / NA
 Sp. Reading: - T. Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JTDKN364 205749066
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / SRim / STD A/Rim or
 Tyre Size: F: 195 / 65 R18
 R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FALKEN

Front 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 01-03-18

Survey held at w/s 5:30 pm
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

17/5 11:00am NS 31013018537 Gibez
YN 5496A - X

17/5 12:00pm

17/5 11:00am Confirmed LS \$11,050/- ; 11 days with Poh Guan.
Red: \$16/55.22, 59%.

RECEIVED 10 MAY 2018

Date/Time: File Pass to? ☐ : Preli. Report

1) typist ☒ : Final Report

Date/Time: File Return to?

2)

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Insp (\$

☐ : Weekend (\$

Days Of Repair: 11

Resurvey No. of Trip: 2

Survey Fee: 160

Transportation

1) \$ + RS (\$

2) Photos

3) Others

TOTAL

35

195

Report Format: TP

Lump Sum / I.B.I.: (\$ 11,050/-

TP Claims against NTUC Income: Follow-Through Survey

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident
1	MT/0994868-001	SMRT TAXIS PTE LTD	SHB 522E	SIQ 2939X	17/04/2018
2	MT/0991087-002	SMRT TAXIS PTE LTD	SHB 1772T	SLG 5592X	19/04/2018
3	MT/0983942-002	SMRT TAXIS PTE LTD	SHB 687M	YN 5496A	26/2/2018
4	MT/0992660-002	SMRT TAXIS PTE LTD	SHC 4568S	SJL 9197A	1/5/2018
5	MT/0992640-002	SMRT TAXIS PTE LTD	SHB 1108L	PC 2403C	30/4/2018
6	MT/0993012-002	SMRT TAXIS PTE LTD	SHB 8Z	SKA 5770S	2/5/2018
7	MT/0992770-002	SMRT TAXIS PTE LTD	SHC 4741H	SHC 6357X	3/5/2018



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18004038/Grb

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 02-03-2018

189556



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 5496A	Veh. Inspected	SHB 687M
Policy No.	5066368442-03	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	01/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	26/02/2018	Inspection Date	01/03/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#) [Change Password](#) [Log Out](#)[My Desktop](#)
[Notice of Loss](#)

Policy Query

Policy No. Date of Accident

Vehicle No.(For Motor)

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☒	5066368442-03	YONG HOE ENTERPRISE PTE LTD	199800039H	GCV	Comprehensive	YN5496A	YN5496A	08/07/2017	07/07/2018

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	5369K

Vehicle Details

Vehicle No.:	SHB687M
Vehicle to be Exported:	No
Intended De-registration Date:	02 Mar 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2014
Engine No.:	2ZR6136078
Chassis No.:	JTDKN36U205749066
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$32,920.00
Original Registration Date:	12 Sep 2014
First Registration Date:	12 Sep 2014
Transfer Count:	0
Actual ARF Paid:	\$8,088.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Sep 2022
PARF Rebate Amount:	\$6,066.00

Intended COE Rebate Details

COE Expiry Date:	11 Sep 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,704.00
COE Rebate Amount:	\$28,679.00
Total Rebate Amount:	\$34,745.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 02 Mar 2018

OK

Celine Fong (LKKAUTO)

From: Celine Fong (LKKAUTO)
Sent: Thursday, 17 May 2018 11:07 AM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC); Guo Qiang (LKKAUTO)
Cc: SUR; CS A Team
Subject: RE: SHB687M

Dear Poh Suan,

Confirmed lump sum \$11,050.00, 11 days.

Best Regards,

Celine Fong

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: celinefong@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) [mailto:YeoPohsuan@smrt.com.sg]

Sent: Monday, 2 April 2018 8:59 AM

To: Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>

Cc: SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>

Subject: SHB687M

Hi Guo Qiang,

Attached herewith the repair estimate of SHB 687M having Case No: TAX/02/18/2169.

There is no change to the approved amount of \$11,050 @ 11 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards

Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)

Sent: Tuesday, 27 March 2018 3:04 PM

To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)

Subject: Scan Data from FX-D421D6

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GlA Records Management Centre established by the General Insurance Association of Singapore (GlA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/02/2018 17:38
Date Of Accident	26/02/2018 12:25
Exact Location Of Accident	SLE TOWARDS CTE (NEAR BRADDELL EXIT)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB687M
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-17087562MFSH
Cover Note Number	

Driver

Name of Driver	LEE KEE BOON
NRIC No	S0673545B
Date Of Birth	28/05/1946
Occupation	OUTDOOR
Date Of Driving Pass	15/12/1964
Driving Experience	53 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 08-1817
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - RELIEF
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? YES
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: : KWOK RAYMOND
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name YISHUN NORTH NEIGHBOURHOOD POLICE CENTRE
 Police Station Address ROAD: 31 YISHUN CENTRAL , POSTCODE: 768827 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-8529999 - FAX NO: 68522299
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT - T/20180228/2091

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YN5496A
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name LEE KEE BOON

Approximate Age

Injuries Sustain

Injured person in which vehicle? SHB687M

Were seat belts worn?

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

DETAILS OF INJURED PERSON 2

Name KWOK RAYMOND

Approximate Age

Injuries Sustain

Injured person in which vehicle? SHB687M


Were seat belts worn?

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

SLE towards Braddell

[illegible]

1(24): 28/02/2018

28/2/2018

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:

1/3/2018, 28/02/2018
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

28/2/2018
 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20180228/2091

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

1 of 3

Report No. T/20180228/2091

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 28/02/2018 16:21			Vide Report No.:		Station Diary No.: 93
Informant's Particulars					
Name of Informant: LEE KEE BOON			Address: APT BLK 411 YISHUN RING ROAD #08-1817 SINGAPORE 760411		
ID Type / ID No.: NRIC'NO / S0673545B			Contact No.: Home/Office: Mobile: 93720997		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 71	Date of Birth: 28/05/1946	Type of Informant: Driver		
Race: Chinese			Language: English	Institution / School Name:	
Occupation: Taxi driver			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 26/02/2018 12:25	Type of Location: Straight Road
Location: Along Road 1 SELETAR EXPRESSWAY TOWARDS CENTRAL EXPRESSWAY NEAR TO BRADDELL EXIT				
Weather: Clear	Road Surface: Dry	Road Speed Limit: 90 Km/h		
Traffic Flow: One Way	Traffic Control: Not Controlled	Traffic Volume: Light		
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SHB687M	Car	TOYOTA		Maroon	Seriously Damaged	1
YN5496A	Lorry	HINO		White	Slightly Damaged	0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20180228/2091

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

2 of 3
Report No. T/20180228/2091

CONTINUATION OF REPORT

Driver			
Name	LEE KEE BOON	ID No.	S0673545B
Related Vehicle	SHB687M (Car)	Contact No.	93720997
Hospital/Clinic	TAN TOCK SENG HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	26/02/2018	Date Discharge	28/02/2018
No. of Days granted Medical Leave	17	Degree of Injury	Serious

Brief Details.

On 26.2.2018 at about 1225hrs, I was driving my company taxi registration no. SHB687M (Toyota Maroon Prius SMRT taxi). I had a passenger seating behind namely Mr. Kwok Raymond Tel: 91927266. I was along SLE towards CTE (Near to Braddell Exit). As I was driving on the clear traffic, suddenly I realized that there's a speeding white lorry about less than 50 meters behind me. I tried to speed up but not fast enough to avoid collision. The said white lorry collided onto the rear of my vehicle with great impact, I was forced forward and hit the steering wheel hard. My passenger was also impacted hard by the collision. I did not realized anything after that as I was in total shock and pain at that time. My passenger and I was conveyed to Tan Tock Seng Hospital by ambulance. The white lorry registration number is YN5496A (White "HINO" lorry). I am not sure who drove the lorry. I was given 17 days of hospitalization leave by TTSH and sustained right forehead lacerations. My vehicle was seriously damaged on its rear.



**SINGAPORE
POLICE FORCE**



T/20180228/2091

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

3 of 3

Report No. T/20180228/2091

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan


IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / Staff Sgt GHAZALI BIN IBRAHIM	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 28/02/2018 16:21
Officer In Charge Of Case: TP / GIT / Sr Staff Sgt MOHAMMAD ABDILLAH BIN PALIL Contact No.: 65476246	Classification Of Case: SN 085
Authentication Stamp NP188	Signature: Singapore Police Force

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB687M
 Ref. No : TAX/02/18/2169
 Reg. Date : 12/09/2014
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : LEE KEE BOON
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 26/02/2018 12:25:00 PM
 Accident Reported Date / Time : 28/02/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time : 26/02/2018
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024094793
 Special Instruction to ARC, if any :
 TOWED TO TP COMPOUND / YN5496A
 Prepared Date : 28/02/2018 05:26:30 PM



10 Days.

Lump Sum Repair.

After repair photos.

Gino Qiang - 8288 2822

01/3/18.

[Signature]
23/1/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : Mileage : 0

Work Shop : Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	2,366.00	0.00
Total Spray Painting Charges :	3,492.00	0.00
Total Material Charges :	18,062.46	18,431.08
Other Charges :	3,236.00	0.00
TOTAL :	27,156.46	0.00
Lum Sum Total :	27,150.00	0.00
No. of Repair Days :	14.00	0.00
Prepared / Adjusted By :		
Arc / Surveyor Sing Off Date :	01/03/2018 01:30:00 PM	01/01/1900 12:00:00 AM



repaired / Adjusted Date :

emarks :

repaired Date : 01/03/2018 01:30:00 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	2,366.00	0.00
Total Labour	2,366.00	0.00 900 /

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200 /
TO RESPRAY REAR PANEL	180.00	0.00 100 /
TO RESPRAY REAR SPARE TYRE PANEL	180.00	0.00 2 x NN
TO RESPRAY TAIL GATE	378.00	0.00 200 /
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0.00 100 /
TO RESPRAY REAR SPOILER	180.00	0.00 100 /
TO RESPRAY REAR MEMBER,LH	180.00	0.00 X
TO RESPRAY REAR MEMBER,RH	180.00	0.00 X } x NN
TO RESPRAY REAR FLOOR SIDE PANEL LH	180.00	0.00 X
TO RESPRAY REAR FLOOR SIDE PANEL RH	180.00	0.00 X
TO RESPRAY ROOF TOP PANEL	378.00	0.00 200 /
TO RESPRAY TROUGH BACK DOOR RH	180.00	0.00 100 /
TO RESPRAY RH REAR WHEEL HOUSE	180.00	0.00 100 /
TO RESPRAY RIM	180.00	0.00 X } x NN
TO RESPRAY FRONT DOOR RH	378.00	0.00 X
Total Spray Painting & Panel Beating	3,492.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
OWING CHARGE	126.00	0.00 X x
O CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 30 /
O APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 60 /
O TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 40 /
REMOVE AND REPLACE BOTH RR EXHAUST MUFFLER	120.00	0.00 R x NN
O TRANSFER REAR TAILGATE MECHANISM	120.00	0.00 60 /
O REMOVE AND REFIX REAR WINDSCREEN	120.00	0.00 100 /
O PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	600.00	0.00 / 600
O REMOVE AND REFIT WIRE HARDESS	150.00	0.00 R x NN
O REMOVE & REFIT ROOF LINING	350.00	0.00 150 /
O ALIGN CHASSIS	350.00	0.00 R x NN
O REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 60 /
O INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00 30 /
O REMOVE & REFIT REAR QUARTER GLASS RH	120.00	0.00 40 /
O REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00 x
O REMOVE AND REFIT TYRE	120.00	0.00 x
O TRANSFER DOOR MECHANISM	120.00	0.00 x
O REMOVE AND REFIX WING MIRROR	120.00	0.00 x
O REPLACE SUNDRY PARTS	100.00	0.00 x
O WASH AND VACUUM	60.00	0.00 x
Total Other Costs	3,236.00	0.00

38872.18

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
2159-7905		6505548	BUMPER REAR / RL	1	458.60	25.00	343.95 /	Replace	Replace	No
2023-2240		6505547	BUMPER REINFORCEMENT REAR / BT	1	205.70	25.00	154.27 /	Replace	Replace	No
2576-7020		6505550	BUMPER SIDE RETAINER RR/LH / MCL	1	94.80	25.00	71.10 /	Replace	Replace	No
2575-7020		6505549	BUMPER SIDE RETAINER RR/RH / MCL	1	94.80	25.00	71.10 /	Replace	Replace	No
2016-7030			ARM SUB-ASSY, RR BUMPER LH X NV	1	139.60	25.00	104.70 X	Replace	Replace	No
2015-7050			ARM SUB-ASSY, RR BUMPER RH X / BT	1	139.60	25.00	104.70 /	Replace	Replace	No
			SENSOR REVERSE / DM	1	180.00	0.00	180.00 /	Replace	Replace	No
9997-0070			ANTENNA, ELECTRICAL LOWER REAR X / DM	1	157.40	10.00	141.66 /	Replace	Replace	No
6891-7020		6505619	BUMPER LIP REAR X NV	1	228.90	25.00	171.67 X	Replace	Replace	No
6088-7020		6505617	BUMPER LIP COVER RR/LH X NV	1	72.20	25.00	54.15 X	Replace	Replace	No
6087-7020		6505618	BUMPER LIP COVER RR/RH X / RADA	1	118.10	25.00	88.57 / 88.55	Replace	Replace	No
8308-7011			UNDER COVER SUB-ASSY, RR FLOOR X NV	1	514.50	25.00	385.87 /	Replace	Replace	No
7430-7380			EXHAUST TAIL PIPE X NV	1	656.20	25.00	492.15 X	Replace	Replace	No
7565-2030			SUPPORT, EXHAUST REAR X NV	2	33.60	25.00	50.40	Replace	Replace	No
8307-7060		6505522	END PANEL / Bue	1	602.10	25.00	451.57 /	Replace	Replace	No
	COMMON	4006314	SEALANT SIKAFLEX X NV	1	37.00	0.00	37.00 X	Replace	Replace	No
8311-7071		6505523	SPARE TYRE PANEL X NV	1	667.70	25.00	500.77 X	Replace	Replace	No
			PIXEL STICKER / MCL	2	60.00	0.00	120.00 /	Replace	Replace	No
7005-7241			TAILGATE ASY / Bue	1	1,007.90	25.00	755.92	Replace	Replace	No
3801-7070-B0			TAILGATE OUTSIDE GARNISH / RL	1	504.90	25.00	378.67	Replace	Replace	No
3085-7910		6505620	SPOILER REAR / MCL	1	953.70	25.00	715.27	Replace	Replace	No
1006-7011		6505464	3RD BRAKE LAMP / R/S	1	231.30	10.00	208.17 /	Replace	Replace	No
5374-7051			NAME PLATE (HYBRID) / MCL	1	51.90	25.00	38.92 /	Replace	Replace	No
5442-7030			NAME PLATE (PRIUS) / MCL	1	60.80	25.00	45.60	Replace	Replace	No
5443-7030			NAME PLATE (TOYOTA) / MCL	1	51.90	25.00	38.92	Replace	Replace	No
5310-7020		6505639	EMBLEM REAR / MCL	1	60.30	25.00	45.22	Replace	Replace	No
	COMMON		SMRT LOGO / BL	1	7.80	0.00	7.80	Replace	Replace	No
	COMMON		STICKER DECAL 65558888 / MCL	1	21.60	0.00	21.60	Replace	Replace	No
			NUMBER PLATE /	1	15.00	0.00	15.00	Replace	Replace	No

sch.

7921-50

Number			Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
			NUMBER PLATE FRAME / <i>SCC</i>	1	12.00	0.00	12.00 /	Replace	Replace	No
1271-3011		6505463	LICENSE PLATE LAMP <i>X NN</i>	2	35.70	10.00	64.26 <i>X</i>	Replace	Replace	No
5575-7030			MOULDING BACK WINDOW, LOWER NO.1 / <i>ACC</i>	1	29.40	25.00	22.05 /	Replace	Replace	No
4821-7030			TAILGATE LOWER WINDOW GLASS / <i>SM</i>	1	721.30	25.00	540.97 /	Replace	Replace	No
	COMMON		SEALANT W/SCREEN / <i>ACC</i>	1	37.00	0.00	37.00 /	Replace	Replace	No
5574-7020			TAIL GATE DOOR GLASS MOULDING, LH / <i>ACC</i>	1	29.40	25.00	22.05 /	Replace	Replace	No
5573-7080			TAIL GATE DOOR GLASS MOULDING, RH / <i>ACC</i>	1	29.40	25.00	22.05 /	Replace	Replace	No
8105-7122			TAILGATE DOOR GLASS / <i>SM</i>	1	1,090.90	25.00	818.17 /	Replace	Replace	No
	COMMON		SEALANT W/SCREEN / <i>ACC</i>	2	37.00	0.00	74.00 /	Replace	Replace	No
5241-7030			ARM, RR WIPER <i>X NN</i>	1	84.70	25.00	63.52 <i>X</i>	Replace	Replace	No
5130-7021			MOTOR ASSY, RR WIPER <i>X NN</i>	1	734.60	10.00	661.14 <i>X</i>	Replace	Replace	No
5242-7040			BLADE ASSY, REAR WIPER / <i>ant</i>	1	55.00	25.00	41.25 /	Replace	Replace	No
8810-7010			TAILGATE DOOR HINGE LH/RH / <i>BT</i>	2	58.30	25.00	87.45 /	Replace	Replace	No
3960-W532			TAILGATE DOOR STAY LH <i>X NN</i>	1	241.50	25.00	181.12 <i>X</i>	Replace	Replace	No
3950-W542			TAILGATE DOOR STAY RH <i>X NN</i>	1	241.50	25.00	181.12 <i>X</i>	Replace	Replace	No
7881-7022			TAILGATE DOOR WEATHER STRIP <i>X TW</i>	1	353.40	25.00	265.05 /	Replace	Replace	No
3350-7030			TAILGATE DOOR LOCK <i>X NN</i>	1	444.10	25.00	333.07 <i>X</i>	Replace	Replace	No
3415-7020			TAILGATE LOCK COVER <i>X NN</i>	1	15.70	25.00	11.77 <i>X</i>	Replace	Replace	No
3431-7010			STRIKER, BACK DOOR <i>X NN</i>	1	48.90	25.00	36.67 <i>X</i>	Replace	Replace	No
7938-7031C0			TAILGATE TRIM, LH <i>X</i>	1	85.90	25.00	64.42 /	Replace	Replace	No
751-7040C0			TAILGATE TRIM, LOWER <i>X NN</i>	1	180.70	25.00	135.52 <i>X</i>	Replace	Replace	No
7937-7031C0			TAILGATE TRIM, RH <i>X</i>	1	88.30	25.00	66.22 /	Replace	Replace	No
790-7030C0			TAILGATE TRIM, UPPER <i>X</i>	1	49.60	25.00	37.20 /	Replace	Replace	No
750-7071C0			TAILGATE, BOARD ASSY / <i>ACC</i>	1	246.90	25.00	185.17 /	Replace	Replace	No
718-7031B0			END PANEL COVER, DECK TRIM HOLE <i>X</i>	1	46.10	25.00	34.57 <i>X</i>	Replace	Replace	No
716-7031B0			END PANEL COVER, DECK TRIM, RR <i>X NN</i>	1	121.10	25.00	90.82 <i>X</i>	Replace	Replace	No
740-7031B2			PANEL ASSY, DECK LH <i>X NN</i>	1	307.00	25.00	230.25 <i>X</i>	Replace	Replace	No
730-7031B2			PANEL ASSY, DECK RH <i>X</i>	1	307.00	25.00	230.25 /	Replace	Replace	No
470-110B0			GARNISH ASSY, ROOF RH <i>X</i>	1	256.40	25.00	192.30 <i>X</i>	Replace	Replace	No

619.20

Number					(\$)	(%)	(\$)	Recommend d	Approved	Attached
12480- 17050-B0			GARNISH SIDE UPPER, LHR <i>X NN</i>	1	261.70	25.00	196.27 <i>X</i>	Replace	Replace	No
14993- 17020			BOX, DECK FLOOR, RR <i>X / CAA Re</i>	1	649.70	25.00	487.27 457.28 <i>✓</i>	Replace	Replace	No
18416- 17030B3			BOX, RR FLOOR, BOARD <i>X / Re</i>	1	679.60	25.00	509.70 <i>✓</i>	Replace	Replace	No
14997- 17020			BOX, DECK FLOOR, LH <i>X NN</i>	1	196.80	25.00	147.60 <i>x</i>	Replace	Replace	No
18418- 17070B0			BOX, DECK FLOOR COVER LH <i>X NN</i>	1	230.10	25.00	172.57 <i>x</i>	Replace	Replace	No
18490- 17140B0			BOARD ASSY, RR RH <i>X CAA</i>	1	379.20	25.00	284.40 <i>✓</i>	Replace	Replace	No
18415- 17030			BOARD, RR FLOOR <i>X NN</i>	1	392.30	25.00	294.22 <i>✓</i>	Replace	Replace	No
14910- 17020-B0			COVER ASSY, TONNEAU <i>X NN</i>	1	602.10	25.00	451.57 <i>✓</i>	Replace	Replace	No
18401- 17010-B1			BOARD SUB-ASSY, REAR FLOOR, NO.1 <i>X NN</i>	1	127.70	25.00	95.77 <i>x</i>	Replace	Replace	No
18402- 17010B1			BOARD SUB-ASSY, RR <i>X NN</i>	1	122.80	25.00	92.10 <i>✓</i>	Replace	Replace	No
12184- 17370			WIRE, BACK DOOR, NO.1 <i>X NN</i>	1	582.40	10.00	524.16 <i>✓</i>	Replace	Replace	No
			BATTERY <i>X Dis</i>	1	278.00	10.00	250.20 <i>✓</i>	Replace	Replace	No
14481- 17050			BATTERY CLAMP <i>X Re</i>	1	16.10	25.00	12.07 12.18 <i>✓</i>	Replace	Replace	No
14440- 17030			BATTERY TRAY <i>X Re</i>	1	42.80	25.00	32.10 <i>✓</i>	Replace	Replace	No
17604- 17030			MEMBER SUB-ASSY, RR LH <i>X</i>	1	174.10	25.00	130.57 <i>✓</i>	Replace	Replace	No
17603- 17030			MEMBER SUB-ASSY, RR RH <i>X</i>	1	174.10	25.00	130.57 <i>✓</i>	Replace	Replace	No
18303- 17301			FLOOR PANEL RR/LH <i>X</i>	1	102.00	25.00	76.50 <i>✓</i>	Replace	Replace	No
18302- 17030			FLOOR PANEL RR/RH <i>X</i>	1	209.90	25.00	157.42 <i>✓</i>	Replace	Replace	No
		6503707	TYRE <i>X NN</i>	1	126.74	0.00	126.74 <i>✓</i>	Replace	Replace	No
1931- 17020			CARRIER, SPARE <i>X NN</i>	1	19.70	25.00	14.77 <i>x</i>	Replace	Replace	No
1778- 17050			PROTECTOR, SPARE <i>X</i>	1	143.70	25.00	107.77 <i>✓</i>	Replace	Replace	No
18406718			SIGN WARNING TRIANGLE <i>X</i>	1	68.00	10.00	61.20 <i>✓</i>	Replace	Replace	No
18310- 17080B0			ROOF LINING ASSY, <i>X</i>	1	1,877.60	25.00	1,408.20 <i>✓</i>	Replace	Replace	No
18556- 17030			MLDG DRIP LH, ROOF <i>X Re</i>	1	78.80	25.00	59.10 <i>✓</i>	Replace	Replace	No
18555- 17030			MLDG DRIP RH, <i>X Re</i> ROOF	1	78.80	25.00	59.10 <i>✓</i>	Replace	Replace	No
18111- 17030			ROOF PANEL <i>X repair</i>	1	1,102.80	25.00	827.10 <i>x</i>	Replace	Replace	No
18563- 17010			TAIL LAMP BRACKET, LH <i>X NN</i>	1	30.70	25.00	23.02 <i>x</i>	Replace	Replace	No
18562- 17010			TAIL LAMP BRACKET, RH <i>X Re</i>	1	30.70	25.00	23.02 <i>✓</i>	Replace	Replace	No
18561- 170		6505461	TAIL LAMP LH <i>X NN</i>	1	548.40	10.00	493.56 <i>x</i>	Replace	Replace	No
18551- 1780		6505462	TAIL LAMP RH <i>X CAA</i>	1	557.80	10.00	502.02 <i>✓</i>	Replace	Replace	No
18604- 17090			FENDER RR/RH <i>X Re</i>	1	766.80	25.00	575.10 <i>✓</i>	Replace	Replace	No

10651.94

Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
	COMMON	SMRT LOGO / <i>ML</i>	1	7.80	0.00	7.80 /	Replace	Replace	No
	COMMON	STICKER DECAL 6555 8888 / <i>ML</i>	1	21.60	0.00	21.60 /	Replace	Replace	No
2710-7130		QUARTER GLASS RR/RH <i>X/ML</i>	1	846.50	25.00	634.87 <i>634.88</i> /	Replace	Replace	No
	COMMON	SEALANT W/SCREEN / <i>ML</i>	1	37.00	0.00	37.00 /	Replace	Replace	No
5637-7021		6505480 FENDER LINER RR/RH / <i>EL</i>	1	141.30	25.00	105.97 <i>105.98</i> /	Replace	Replace	No
5631-7041		SILL MEMBER PLATE RR/RH / <i>EL</i>	1	57.50	25.00	43.12 /	Replace	Replace	No
2591-7021		BUMPER SEAL, RR RH / <i>ML</i>	1	65.70	25.00	49.27 /	Replace	Replace	No
2940-6060		DUCT ASSY, QUARTER <i>X/CA</i>	1	70.40	25.00	52.80 /	Replace	Replace	No
1607-7060		PANEL SUB-ASSY, QTR <i>X/NN</i>	1	588.40	25.00	441.30 <i>X</i>	Replace	Replace	No
1621-7030		TROUGH, BACK DOOR / <i>BT</i>	1	110.90	25.00	83.17 /	Replace	Replace	No
17374700		? REINFORCEMENT, ROOF <i>X/NN</i>	1	60.30	25.00	45.22 <i>45.23</i> <i>X</i>	Replace	Replace	No
1743-7010		REINFORCEMENT, BACK <i>X/NN</i>	1	89.50	25.00	67.12 <i>67.13</i> <i>X</i>	Replace	Replace	No
1713-7020		REINFORCE, ROOF SIDE <i>X/NN</i>	1	91.90	25.00	68.92 <i>68.93</i> <i>X</i>	Replace	Replace	No
1625-7040		EXTENSION, QUARTER <i>X</i>	1	55.70	25.00	41.77 /	Replace	Replace	No
1623-7010		EXTENSION, QUARTER <i>X/NN</i>	1	83.50	25.00	62.62 /	Replace	Replace	No
1731-7020		PANEL, ROOF SIDE, <i>X</i>	1	134.80	25.00	101.10 <i>X</i>	Replace	Replace	No
1766-7020		REINFORCEMENT, BELT <i>X</i>	1	103.20	25.00	77.40 /	Replace	Replace	No
1733-7020		PANEL, ROOF SIDE INNER FRONT RH <i>X</i>	1	134.80	25.00	101.10 /	Replace	Replace	No
		6503707 TYRE <i>X/Cut</i>	1	126.74	0.00	126.74 <i>126.75</i> /	Replace	Replace	No
2611-7140		6505658 WHEEL, DISC <i>X</i>	1	1,490.20	25.00	1,117.65 /	Replace	Replace	No
7001-7070		6505528 DOOR FRT/RH <i>X/NN</i>	1	894.40	25.00	670.80 /	Replace	Replace	No
		STICKER DECAL SMRT (DOOR) <i>X</i>	1	60.00	0.00	60.00 <i>X</i>	Replace	Replace	No
7931-7200		MIRROR GLASS RH <i>X</i>	1	212.80	25.00	159.60 /	Replace	Replace	No
TOTAL MATERIALS						23,039.10	23,038.85		
TOTAL MATERIALS(Discounted)						18,062.46	18,431.08		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

5084 94

SMRT FORM 22 - SUPPLEMENTARY PART

Contractor:			
Accident Case Number	TAX/02/8/2163	Date of Collection	1 / 1
Vehicle No	SHB 687 M	Date of Request	06/03/2018
Vehicle Model	TOYOTA PRIMS	Number of Days to Extend (If any)	5 / 1

S/N	Part Number	Part Description	Quantity	Unit Price
		BOARD ASSY REAR RH	1pc	✓ CRA
		BATTERY	1pc	✓ P.S
		BATTERY CLAMP	1pc	✓ BT
		BATTERY TRAY	1pc	✓ CRA
		REAR QUARTER GLASS RH	1pc	✓ REC
		REAR Fender LINER RH	1pc	✓ RL

<<Please submit photographs for damaged parts>>

I, (Name) _____
(Position) _____

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

Signature of person making this declaration
[to be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	Guo Qiang
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

SUPPLEMENTARY PARTS

Contractor			
Accident Case Number	TAX/02/18/2169	Date of Collection	1 / 1
Vehicle No	SUB 687 M	Date of Request	06/03/2018
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend (If any)	5 / 1

S/N	Part Number	Part Description	Quantity	Unit Price
		REAR TYRE RH	1pc	SG\$50%
		FRONT MIRROR GLASS RH	1pc	?
		ANTENNA ELECTRICAL LOWER REAR	1pc	- PM
	TO Request ADDITIONAL REPAIR DAYS			

<<<Please submit photographs for damaged parts>>>

I, (Name) _____
(Position) _____

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

Signature of person making this declaration
[to be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	Eric QY
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

SMRT SUPPLEMENTARY PARTS

Contractor:		Date of Collection	1 / 1
Accident Case Number	TAX/02/18/2169	Date of Request	06/03/2018
Vehicle No	SHB 687 M	Number of Days to Extend (If any)	5
Vehicle Model	TOYOTA PRIUS		

S/N	Part Number	Part Description	Quantity	Unit Price
		ARM SUB ASSY, REAR BUMPER RH	1pc	/ BT
		REAR BUMPER LIP RH	1pc	/ CRA
		TAILGATE DOOR WHEELSTRIP	1pc	/ Twi
		END PANEL COVER, DECK TRIM HOLE	1pc	/ R2
		PANEL ASSY, DECK RH	1pc	/ TV
		GARNISH ASSY, ROOF RH	1pc	/ R2

<<<Please submit photographs for damaged parts>>>

I, (Name)

(Position)

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

Signature of person making this declaration
[to be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	Gene G. P.
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

Contractor:			Date of Collection	1 / 1
Accident Case Number	TAX/02/18/2169		Date of Request	15 10/2018
Vehicle No	SHB 687 M		Number of Days to Extend (if any)	1
Vehicle Model	TOYOTA PRIUS			

S/N	Part Number	Part Description	Quantity	Unit Price
	✓ 64493-14000	Box / DECOR FLOOR BOARD	1pc	✓
	✓ 58416-47000B3	Box / REAR FLOOR BOARD	1pc	✓

<<<Please submit photographs for damaged parts>>>

I, (Name) _____

(Position) _____

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

Signature of person making this declaration
[to be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

13-3-18 / 13:33

14-3-18 / 08:33

SMRT Accident Vehicle Repair Estimates


2-3-18 / 08:33

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB687M
Ref. No : TAX/02/18/2169
Reg. Date : 12/09/2014
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS
Name of Driver : LEE KEE BOON
Type of Accident : HEAD TO REAR
Date / Time of Accident : 26/02/2018 12:25:00 PM
Accident Reported Date / Time : 28/02/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by : Guo Qiang
Vehicle is Towed Back? : Yes
Towed Back Date/Time : 26/02/2018
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024094793
Special Instruction to ARC, if any :

TOWED TO TP COMPOUND / YN5496A - NTUC IDAC
AFTER REPAIR PHOTO, LUM SUM REPAIR, FOR CHECK ITEM and REPLACE ITEM PLEASE CALL
SURVEYOR GUO QIANG (LKK) / HP : 82880282 / Email: Guo.Qiang@lkkauto.com

Prepared Date : 28/02/2018 05:26:30 PM



15:00 15-3-18 reject

Recording Camera ☐ ☒

Radio Antenna ☐ ☒

1st witness Date 2-3-18

2nd witness Date 15-3-18

611968 16-3-18 12:00

1 1/4 1/2 3/4 1

① reject RH mirror glass no Solar film

② reject box rr floor RR (damage)

③ reject box rr floor board damage

LEE SHENG AUTO PTE LTD, 612001

Vehicle Return Date: 15-3-18

Vehicle Return Time: 14:47

SMRT staff sign:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : Mileage : 0

Work Shop : Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	2,366.00	900.00
Total Spray Painting Charges :	3,492.00	1,100.00
Total Material Charges :	18,237.22	10,643.26
Other Charges :	3,110.00	-1,593.26
TOTAL :	27,205.22	11,050.00
Lum Sum Total :	0.00	0.00
No. of Repair Days :	14.00	11.00
Prepared / Adjusted By :		GUO QIANG (LKK)
Arc / Surveyor Sing Off Date :	01/03/2018 01:30:00 PM	01/03/2018 04:47:06 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 01/03/2018 01:30:00 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	QN-1803-0615	Invoice No :	
Quotation Date :	26/3	Invoice Date :	
Invoice Amount :		Prepared Date :	

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	2,366.00	900.00
Total Labour	2,366.00	900.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	378.00	200.00
TO RESPRAY REAR PANEL	180.00	100.00
TO RESPRAY REAR SPARE TYRE PANEL	180.00	0.00
TO RESPRAY TAIL GATE	378.00	200.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	100.00
TO RESPRAY REAR SPOILER	180.00	100.00
TO RESPRAY REAR MEMBER,LH	180.00	0.00
TO RESPRAY REAR MEMBER,RH	180.00	0.00
TO RESPRAY REAR FLOOR SIDE PANEL LH	180.00	0.00
TO RESPRAY REAR FLOOR SIDE PANEL RH	180.00	0.00
TO RESPRAY ROOF TOP PANEL	378.00	200.00
TO RESPRAY TROUGH BACK DOOR RH	180.00	100.00
TO RESPRAY RH REAR WHEEL HOUSE	180.00	100.00
TO RESPRAY RIM	180.00	0.00
TO RESPRAY FRONT DOOR RH	378.00	0.00
Total Spray Painting & Panel Beating	3,492.00	1,100.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	60.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	40.00
REMOVE AND REPLACE BOTH RR EXHAUST MUFFLER	120.00	0.00
TO TRANSFER REAR TAILGATE MECHANISM	120.00	60.00
TO REMOVE AND REFIX REAR WINDSCREEN	120.00	100.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	600.00	600.00
TO REMOVE AND REFIT WIRE HARDESS	150.00	0.00
TO REMOVE & REFIT ROOF LINING	350.00	150.00
TO ALIGN CHASSIS	350.00	0.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	60.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	30.00
TO REMOVE & REFIT REAR QUARTER GLASS RH	120.00	40.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00
TO REMOVE AND REFIT TYRE	120.00	0.00
TO TRANSFER DOOR MECHANISM	120.00	0.00
TO REMOVE AND REFIX WING MIRROR	120.00	0.00
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
Lump Sum Adjustment by Surveyor	0.00	-2,763.26
Total Other Costs	3,110.00	-1,593.26

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace	No ✓
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.27	Replace	Replace	No ✓
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace	No ✓
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace	No ✓
52016-47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Check	No X
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Replace S	No ✓
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No ✓
89997-30070			ANTENNA, ELECTRICAL LOWER REAR	1	157.40	10.00	141.66	Replace	Replace S	No ✓
76891-47020		6505619	BUMPER LIP REAR	1	228.90	25.00	171.68	Replace	Check	No X
76088-47020		6505617	BUMPER LIP COVER RR/LH	1	72.20	25.00	54.15	Replace	Check	No X
76087-47020		6505618	BUMPER LIP COVER RR/RH	1	118.10	25.00	88.58	Replace	Replace S	No ✓
58308-47011			UNDER COVER SUB-ASSY, RR FLOOR	1	514.50	25.00	385.88	Replace	Check	No X
17430-37380			EXHAUST TAIL PIPE	1	656.20	25.00	492.15	Replace	Check	No X
17565-22030			SUPPORT, EXHAUST REAR	2	33.60	25.00	50.40	Replace	Check	No X
58307-47060		6505522	END PANEL	1	602.10	25.00	451.57	Replace	Replace	No ✓
	COMMON	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Check	No X
58311-47071		6505523	SPARE TYRE PANEL	1	667.70	25.00	500.78	Replace	Check	No X
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No ✓
67005-47241			TAILGATE ASY	1	1,007.90	25.00	755.92	Replace	Replace	No ✓
76801-47070-B0			TAILGATE OUTSIDE GARNISH	1	504.90	25.00	378.67	Replace	Replace	No ✓
76085-47910		6505620	SPOILER REAR	1	953.70	25.00	715.27	Replace	Replace	No ✓
81006-47011		6505464	3RD BRAKE LAMP	1	231.30	10.00	208.17	Replace	Replace	No ✓
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace	No ✓
75442-47030			NAME PLATE (PRIUS)	1	60.80	25.00	45.60	Replace	Replace	No ✓
75443-47030			NAME PLATE (TOYOTA)	1	51.90	25.00	38.92	Replace	Replace	No ✓
75310-47020		6505639	EMBLEM REAR	1	60.30	25.00	45.22	Replace	Replace	No ✓
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No ✓
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No ✓
			NUMBER PLATE	1	15.00	0.00	15.00	Replace	Replace	No ✓

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
			NUMBER PLATE FRAME	1	12.00	0.00	12.00	Replace	Replace	No ✓
81271-53011		6505463	LICENSE PLATE LAMP	2	35.70	10.00	64.26	Replace	Check	No X
75575-47030			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	25.00	22.05	Replace	Replace	No ✓
64821-47030			TAILGATE LOWER WINDOW GLASS	1	721.30	25.00	540.97	Replace	Replace	No ✓
	COMMON		SEALANT W/SCREEN	1	37.00	0.00	37.00	Replace	Replace	No ✓
75574-47020			TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	25.00	22.05	Replace	Replace	No ✓
75573-47080			TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	25.00	22.05	Replace	Replace	No ✓
68105-47122			TAILGATE DOOR GLASS	1	1,090.90	25.00	818.17	Replace	Replace	No ✓
	COMMON		SEALANT W/SCREEN	2	37.00	0.00	74.00	Replace	Replace	No ✓
85241-47030			ARM, RR WIPER	1	84.70	25.00	63.53	Replace	Check	No X
85130-47021			MOTOR ASSY, RR WIPER	1	734.60	10.00	661.14	Replace	Check	No X
85242-47040			BLADE ASSY, REAR WIPER	1	55.00	25.00	41.25	Replace	Replace	No ✓
68810-47010			TAILGATE DOOR HINGE LH/RH	2	58.30	25.00	87.45	Replace	Replace	No ✓
68960-0V532			TAILGATE DOOR STAY LH	1	241.50	25.00	181.13	Replace	Check	No X
68950-0V542			TAILGATE DOOR STAY RH	1	241.50	25.00	181.13	Replace	Check	No X
67881-47022			TAILGATE DOOR WEATHER STRIP	1	353.40	25.00	265.05	Replace	Replace S	No ✓
69350-47030			TAILGATE DOOR LOCK	1	444.10	25.00	333.08	Replace	Check	No X
69415-47020			TAILGATE LOCK, COVER	1	15.70	25.00	11.78	Replace	Check	No X
69431-47010			STRIKER, BACK DOOR	1	48.90	25.00	36.68	Replace	Check	No X
67938-47031C0			TAILGATE TRIM, LH	1	85.90	25.00	64.42	Replace	Replace	No ✓
67751-47040C0			TAILGATE TRIM, LOWER	1	180.70	25.00	135.53	Replace	Check	No X
67937-47031C0			TAILGATE TRIM, RH	1	88.30	25.00	66.22	Replace	Replace	No ✓
64790-47030C0			TAILGATE TRIM, UPPER	1	49.60	25.00	37.20	Replace	Replace	No ✓
67750-47071C0			TAILGATE, BOARD ASSY	1	246.90	25.00	185.17	Replace	Replace	No ✓
64718-47031B0			END PANEL COVER, DECK TRIM HOLE	1	46.10	25.00	34.58	Replace	Replace S	No ✓
64716-47031B0			END PANEL COVER, DECK TRIM, RR	1	121.10	25.00	90.83	Replace	Check	No X
64740-47031B2			PANEL ASSY, DECK LH	1	307.00	25.00	230.25	Replace	Check	No X
64730-47031B2			PANEL ASSY, DECK RH	1	307.00	25.00	230.25	Replace	Replace S	No ✓
62470-47110B0			GARNISH ASSY, ROOF RH	1	256.40	25.00	192.30	Replace	Replace S	No ✓
62480-47050-B0			GARNISH SIDE UPPER, LHR	1	261.70	25.00	196.28	Replace	Check	No X

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
64993-47020			BOX, DECK FLOOR, RR	1	649.70	25.00	487.28	Replace	Replace <i>S</i>	No <i>/</i>
58416-47030B3			BOX, RR FLOOR, BOARD	1	679.60	25.00	509.70	Replace	Replace <i>S</i>	No <i>/</i>
64997-47020			BOX, DECK FLOOR, LH	1	196.80	25.00	147.60	Replace	Check	No <i>X</i>
58418-47070B0			BOX, DECK FLOOR, COVER LH	1	230.10	25.00	172.58	Replace	Check	No <i>X</i>
58490-47140B0			BOARD ASSY, RR RH	1	379.20	25.00	284.40	Replace	Replace <i>S</i>	No <i>/</i>
58415-47030			BOARD, RR FLOOR	1	392.30	25.00	294.23	Replace	Check	No <i>X</i>
64910-47020-B0			COVER ASSY, TONNEAU	1	602.10	25.00	451.58	Replace	Check	No <i>X</i>
58401-47010-B1			BOARD SUB-ASSY, REAR FLOOR, NO.1	1	127.70	25.00	95.78	Replace	Check	No <i>X</i>
58402-47010B1			BOARD SUB-ASSY, RR	1	122.80	25.00	92.10	Replace	Check	No <i>X</i>
82184-47370			WIRE, BACK DOOR, NO.1	1	582.40	10.00	524.16	Replace	Check	No <i>X</i>
			BATTERY	1	278.00	10.00	250.20	Replace	Replace <i>S</i>	No <i>/</i>
74481-47050			BATTERY CLAMP	1	16.10	25.00	12.08	Replace	Replace <i>S</i>	No <i>/</i>
74440-47030			BATTERY TRAY	1	42.80	25.00	32.10	Replace	Replace <i>S</i>	No <i>/</i>
57604-47030			MEMBER SUB-ASSY, RR LH	0	174.10	25.00	0.00	Replace	Not given	No <i>X</i>
57603-47030			MEMBER SUB-ASSY, RR RH	0	174.10	25.00	0.00	Replace	Not given	No <i>X</i>
58303-47301			FLOOR PANEL RR/LH	0	102.00	25.00	0.00	Replace	Not given	No <i>X</i>
58302-47030			FLOOR PANEL RR/RH	0	209.90	25.00	0.00	Replace	Not given	No <i>X</i>
		6503707	TYRE	1	126.74	0.00	126.74	Replace	Check	No <i>X</i>
51931-47020			CARRIER, SPARE	1	19.70	25.00	14.78	Replace	Check	No <i>X</i>
64778-47050			PROTECTOR, SPARE	1	143.70	25.00	107.78	Replace	Check	No <i>X</i>
98406718			SIGN WARNING TRIANGLE	1	68.00	10.00	61.20	Replace	Check	No <i>X</i>
63310-47080B0			ROOF LINING ASSY,	0	1,877.60	25.00	0.00	Replace	Not given	No <i>X</i>
75556-47030			MLDG DRIP LH, ROOF	1	78.80	25.00	59.10	Replace	Replace	No <i>/</i>
75555-47030			MLDG DRIP RH, ROOF	1	78.80	25.00	59.10	Replace	Replace	No <i>/</i>
63111-47030			ROOF PANEL	1	1,102.80	100.00	0.00	Replace	Repair	No <i>R</i>
52563-47010			TAIL LAMP BRACKET, LH	1	30.70	25.00	23.03	Replace	Check	No <i>X</i>
52562-47010			TAIL LAMP BRACKET, RH	1	30.70	25.00	23.02	Replace	Replace	No <i>/</i>
81561-47170		6505461	TAIL LAMP LH	1	548.40	10.00	493.56	Replace	Check	No <i>X</i>
81551-47180		6505462	TAIL LAMP RH	1	557.80	10.00	502.02	Replace	Replace	No <i>/</i>
61604-47090			FENDER RR/RH	1	766.80	25.00	575.10	Replace	Replace	No <i>/</i>
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No <i>/</i>

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No ✓
62710-47130			QUARTER GLASS RR/RH	1	846.50	25.00	634.88	Replace	Replace S	No ✓
	COMMON		SEALANT W/SCREEN	1	37.00	0.00	37.00	Replace	Replace	No ✓
65637-47021		6505480	FENDER LINER RR/RH	1	141.30	25.00	105.98	Replace	Replace S	No ✓
65631-47041			SILL MEMBER PLATE RR/RH	1	57.50	25.00	43.12	Replace	Replace	No ✓
52591-47021			BUMPER SEAL, RR RH	1	65.70	25.00	49.27	Replace	Replace	No ✓
62940-16060			DUCT ASSY, QUARTER	1	70.40	25.00	52.80	Replace	Replace	No ✓
61607-47060			PANEL SUB-ASSY, QTR	1	588.40	25.00	441.30	Replace	Check	No X
61621-47030			TROUGH, BACK DOOR	1	110.90	25.00	83.17	Replace	Replace	No ✓
6173747020			REINFORCEMENT, ROOF	1	60.30	25.00	45.23	Replace	Check	No X
61743-47010			REINFORCEMENT, BACK	1	89.50	25.00	67.13	Replace	Check	No X
61713-47020			REINFORCE, ROOF SIDE	1	91.90	25.00	68.93	Replace	Check	No X
61625-47040			EXTENSION, QUARTER	1	55.70	25.00	41.78	Replace	Check	No X
61623-47010			EXTENSION, QUARTER	1	83.50	25.00	62.63	Replace	Check	No X
61731-47020			PANEL, ROOF SIDE,	1	134.80	25.00	101.10	Replace	Check	No X
61766-47020			REINFORCEMENT, BELT	1	103.20	25.00	77.40	Replace	Check	No X
61733-47020			PANEL, ROOF SIDE INNER FRONT RH	1	134.80	25.00	101.10	Replace	Check	No X
		6503707	TYRE	1	126.74	50.00	63.37	Replace	Replace S	No ✓
42611-47140		6505658	WHEEL, DISC	0	1,490.20	25.00	0.00	Replace	Not given	No X
67001-47070		6505528	DOOR FRT/RH	0	894.40	25.00	0.00	Replace	Not given	No X
			STICKER DECAL SMRT (DOOR)	0	60.00	0.00	0.00	Replace	Not given	No X
87931-47200			MIRROR GLASS RH	0	212.80	25.00	0.00	Replace	Not given	No X
TOTAL MATERIALS							18,237.31	10,643.26		
TOTAL MATERIALS(Discounted)							18,237.22	10,643.26		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

10,643.26
 + 900.00
 + 2,270.00

 13,813.26
 - 202

 11,050.58

L/S \$11,050.58

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

Thatcham *escribe*

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18004038/Grbe2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 25-05-2018	
Code: INC4				
1. Policy Particulars - THIRD PARTY CLAIM				
Insured Veh.	YN 5496A	Veh. Inspected	SHB 687M	
Policy No.	5066368442-03	Coverage (\$)	0.00	
Claim No.	MT/0983942-002	Excess (\$)	0.00	
Assign From		Assign Date	01/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	JTDKN36U205749066	Colour	MAROON	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	FALKEN	6 mm	
L/H Front Tyre	195/65 R15	FALKEN	6 mm	
R/H Rear Tyre	195/65 R15	FALKEN	6 mm	
L/H Rear Tyre	195/65 R15	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/02/2018	Inspection Date	01/03/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		11 Working Days		



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 687M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER REAR (DISC 25%)	DEFORMED	458.60	343.95
1	BUMPER REINFORCEMENT REAR (DISC 25%)	BENT	205.70	154.27
1	BUMPER SIDE RETAINER RR/LH (DISC 25%)	NECESSARY	94.80	71.10
1	BUMPER SIDE RETAINER RR/RH (DISC 25%)	NECESSARY	94.80	71.10
1	ARM SUB-ASSY, RR BUMPER RH (DISC 25%)	BENT	139.60	104.70
1	BUMPER LIP COVER RR/RH (DISC 25%)	CRACKED	118.10	88.58
1	END PANEL (DISC 25%)	BUCKLED	602.10	451.57
1	TAILGATE ASY (DISC 25%)	BUCKLED	1,007.90	755.92
1	TAILGATE OUTSIDE GARNISH (DISC 25%)	DEFORMED	504.90	378.67
1	SPOILER REAR (DISC 25%)	CRACKED	953.70	715.27
1	NAME PLATE (HYBRID) (DISC 25%)	NECESSARY	51.90	38.92
1	NAME PLATE (PRIUS) (DISC 25%)	NECESSARY	60.80	45.60
1	NAME PLATE (TOYOTA) (DISC 25%)	NECESSARY	51.90	38.92
1	EMBLEM REAR (DISC 25%)	NECESSARY	60.30	45.22
1	MOULDING BACK WINDOW, LOWER NO.1 (DISC 25%)	NECESSARY	29.40	22.05
1	TAILGATE LOWER WINDOW GLASS (DISC 25%)	SMASHED	721.30	540.97
1	TAIL GATE DOOR GLASS MOULDING, LH (DISC 25%)	NECESSARY	29.40	22.05
1	TAIL GATE DOOR GLASS MOULDING, RH	NECESSARY	29.40	22.05
1	TAILGATE DOOR GLASS (DISC 25%)	SMASHED	1,090.90	818.17
1	BLADE ASSY, REAR WIPER (DISC 25%)	CUT	55.00	41.25
2	TAILGATE DOOR HINGE LH/RH @\$58.30 (DISC 25%)	BENT	116.60	87.45
1	TAILGATE DOOR WEATHER STRIP (DISC 25%)	TWISTED	353.40	265.05
1	TAILGATE TRIM, LH (DISC 25%)	DEFORMED	85.90	64.42
1	TAILGATE TRIM, RH (DISC 25%)	CUT	88.30	66.22
1	TAILGATE TRIM, UPPER (DISC 25%)	DEFORMED	49.60	37.20
1	TAILGATE, BOARD ASSY (DISC 25%)	DEFORMED	246.90	185.17
1	END PANEL COVER, DECK TRIM HOLE (DISC 25%)	DEFORMED	46.10	34.58
1	PANEL ASSY. DECK RH (DISC 25%)	DENTED	307.00	230.25
1	GARNISH ASSY, ROOF RH (DISC 25%)	DEFORMED	256.40	192.30
1	BOX, DECK FLOOR, RR (DISC 25%)	DEFORMED	649.70	487.28

Report Ref No. NS/INC18004038/Grbe2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOX, RR FLOOR, BOARD (DISC 25%)	DEFORMED	679.60	509.70
1	BOARD ASSY, RR RH (DISC 25%)	CRACKED	379.20	284.40
1	BATTERY CLAMP (DISC 25%)	NECESSARY	16.10	12.08
1	BATTERY TRAY (DISC 25%)	NECESSARY	42.80	32.10
1	MLDG DRIP LH, ROOF (DISC 25%)	DEFORMED	78.80	59.10
1	MLDG DRIP RH, ROOF (DISC 25%)	DEFORMED	78.80	59.10
1	TAIL LAMP BRACKET, RH (DISC 25%)	DEFORMED	30.70	23.02
1	FENDER RR/RH (DISC 25%)	BUCKLED	766.80	575.10
1	QUARTER GLASS RR/RH (DISC 25%)	NECESSARY	846.50	634.88
1	FENDER LINER RR/RH (DISC 25%)	DEFORMED	141.30	105.98
1	SILL MEMBER PLATE RR/RH (DISC 25%)	DEFORMED	57.50	43.12
1	BUMPER SEAL, RR RH (DISC 25%)	NECESSARY	65.70	49.27
1	DUCT ASSY, QUARTER (DISC 25%)	CRACKED	70.40	52.80
1	TROUGH, BACK DOOR (DISC 25%)	BENT	110.90	83.17
1	ANTENNA, ELECTRICAL LOWER REAR (DISC 10%)	DAMAGED	157.40	141.66
1	3RD BRAKE LAMP (DISC 10%)	DISTORTED	231.30	208.17
1	BATTERY (DISC 10%)	DISTORTED	278.00	250.20
1	TAIL LAMP RH (DISC 10%)	CRACKED	557.80	502.02
1	SENSOR REVERSE (SN)	DAMAGED	180.00	180.00
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	NUMBER PLATE (SN)	SCRATCHED	15.00	15.00
1	NUMBER PLATE FRAME (SN)	SCRATCHED	12.00	12.00
1	SEALANT W/SCREEN (SN)	NECESSARY	37.00	37.00
2	SEALANT W/SCREEN @\$37.00 (SN)	NECESSARY	74.00	74.00
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	SEALANT W/SCREEN (SN)	NECESSARY	37.00	37.00
1	TYRE (SN)	CUT	126.74	63.37
1	ARM SUB-ASSY, RR BUMPER LH	NOT NECESSARY	139.60	-
1	BUMPER LIP REAR	NOT NECESSARY	228.90	-
1	BUMPER LIP COVER RR/LH	NOT NECESSARY	72.20	-

Report Ref No. NS/INC18004038/Grbe2

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	UNDER COVER SUB-ASSY, RR FLOOR	NOT NECESSARY	514.50	-
1	EXHAUST TAIL PIPE	NOT NECESSARY	656.20	-
2	SUPPORT, EXHAUST REAR @\$33.60	NOT NECESSARY	67.20	-
1	SEALANT SIKAFLEX	NOT NECESSARY	37.00	-
1	SPARE TYRE PANEL	NOT NECESSARY	667.70	-
2	LICENSE PLATE LAMP @\$35.70	NOT NECESSARY	71.40	-
1	ARM, RR WIPER	NOT NECESSARY	84.70	-
1	MOTOR ASSY, RR WIPER	NOT NECESSARY	734.60	-
1	TAILGATE DOOR STAY LH	NOT NECESSARY	241.50	-
1	TAIL GATE DOOR STAY RH	NOT NECESSARY	241.50	-
1	TAILGATE DOOR LOCK	NOT NECESSARY	444.10	-
1	TAILGATE LOCK, COVER	NOT NECESSARY	15.70	-
1	STRIKER, BACK DOOR	NOT NECESSARY	48.90	-
1	TAILGATE TRIM, LOWER	NOT NECESSARY	180.70	-
1	END PANEL COVER, DECK TRIM, RR	NOT NECESSARY	121.10	-
1	PANEL ASSY, DECK LH	NOT NECESSARY	307.00	-
1	GARNISH SIDE UPPER, LHR	NOT NECESSARY	261.70	-
1	BOX, DECK FLOOR, LH	NOT NECESSARY	196.80	-
1	BOX, DECK FLOOR, COVER LH	NOT NECESSARY	230.10	-
1	BOARD, RR FLOOR	NOT NECESSARY	392.30	-
1	COVER ASSY TONNEAU	NOT NECESSARY	602.10	-
1	BOARD SUB-ASSY, REAR FLOOR, NO.1	NOT NECESSARY	127.70	-
1	BOARD SUB-ASSY, RR	NOT NECESSARY	122.80	-
1	WIRE, BACK DOOR, NO.1	NOT NECESSARY	582.40	-
1	MEMBER SUB-ASSY, RR LH	NOT NECESSARY	174.10	-
1	MEMBER SUB-ASSY, RR RH	NOT NECESSARY	174.10	-
1	FLOOR PANEL RR/LH	NOT NECESSARY	102.00	-
1	FLOOR PANEL RR/RH	NOT NECESSARY	209.90	-
1	TYRE	NOT NECESSARY	126.74	-
1	CARRIER, SPARE	NOT NECESSARY	19.70	-
1	PROTECTOR, SPARE	NOT NECESSARY	143.70	-
1	SIGN WARNING TRIANGLE	NOT NECESSARY	68.00	-
1	ROOF LINING ASSY	NOT NECESSARY	1,877.60	-

Report Ref No. NS/INC18004038/Grbe2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAIL LAMP BRACKET, RH	NOT NECESSARY	30.70	-
1	TAIL LAMP LH	NOT NECESSARY	548.40	-
1	PANEL SUB-ASSY, QTR	NOT NECESSARY	588.40	-
1	REINFORCEMENT, ROOF	NOT NECESSARY	60.30	-
1	REINFORCEMENT, BACK	NOT NECESSARY	89.50	-
1	REINFORCE, ROOF SIDE	NOT NECESSARY	91.90	-
1	EXTENSION, QUARTER	NOT NECESSARY	55.70	-
1	EXTENSION, QUARTER	NOT NECESSARY	83.50	-
1	PANEL, ROOF SIDE	NOT NECESSARY	134.80	-
1	REINFORCEMENT, BELT	NOT NECESSARY	103.20	-
1	PANEL, ROOF SIDE INNER FRONT RH	NOT NECESSARY	134.80	-
1	WHEEL, DISC	NOT NECESSARY	1,490.20	-
1	DOOR FRT/RH	NOT NECESSARY	894.40	-
1	STICKER DECAL SMRT (DOOR)	NOT NECESSARY	60.00	-
1	MIRROR GLASS RH	NOT NECESSARY	212.80	-
1	ROOF PANEL	TO REPAIR	1,102.80	-
			29,778.18	10,643.29
	LABOUR			
	THATCHAM STANDARD REPAIR TIME ON BODY WORKS.		5,216.00	2,010.00
	THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.		3,592.00	1,160.00
	TOWING CHARGE.	NOT NECESSARY	126.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			9,094.00	3,170.00
GRAND TOTAL			38,872.18	13,813.29

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			11,050.00
---	--	--	------------------

Report Ref No. NS/INC18004038/Grbe2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.