

ASS. REC. BY:

REF: CS/MSG18004043/Uqd3m2 Special Instructions:

Surveyor:
Menimen

Marcus

ASSIGNMENT (Office)

From (Person):

Mund Ashik

of

MSIG

Date/Time:

01/03/18 @ 4:02pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YP272B

Insured:

SLG 9899K

at Workshop m/s

Torque 5

Tel:

64524457

of

No. 8 Kaki Bkt Ave 4 # 01-50

Policy No:

A288142474ANW

Claim No:

550981

Sum Insured:

Excess:

Make of Veh:

D.O.A.

28/2/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

1 up

H.O.D. Endorsement:

Date/Time:

9:51am @ 2/3/18

Person Contacted:

Stephanie

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	YP272B - x
	SLG 9899K - x

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

MSCH
ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

1/P2723

Yr Regn:

11/15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA

Make:

Isuzu NPR75

c.c

5793

Colour:

White

A/C:

Insured / Std / NI / NA

Sp. Reading

36987

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JAANPR75HF7105935

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

2.5 / 75.217.5

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6/6

mm

L/Bal.

6

mm

L/Bal.

6/6

mm

D.O.A.

28/2/18

D.O.I.

2/3/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

30/4/18 2/5 #2800 confirmed with steph.m
CPed 2780, 78%

RECEIVED 02 MAY 2018

Date/Time, File Pass to?



Preli. Report

Days Of Repair:

3

Resurvey No. of Trip:

1) 07/5 2/18



Final Report

Date/Time, File Return to?

2)

Add Fee:



Site Insp (\$

Survey Fee:

300

Transportation:

10



Interview (\$

Photos



Tech. Invs (\$

Others



Weekend (\$

TOTAL

310

Report Format:

WEP TP

Lump Sum / I.B.I. (\$

2800



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18004043/Uqd3		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 02-03-2018		
		Code : MSG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLG 9899K	Veh. Inspected	YP 272B	
Policy No.	A28814247ANW	Coverage (\$)	0.00	
Claim No.	550981	Excess (\$)	0.00	
Assign From	MERIMEN (MUHD ASHIK)	Assign Date	02/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	28/02/2018	Inspection Date	02/03/2018	
Survey held at	TORQUE 5 PTE LTD 8 KAKI BUKIT AVENUE 4 #01-50 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 05 Mar 2018

Preliminary Advice

Insured Vehicle No	: SLG9899K	Accident Date	: 28/02/2018
TP Vehicle No	: YP272B	Assignment Date	: 01/03/2018
Make	: ISUZU NPR75UH5A	Est. Duration of Repair	: 3.00
Date of Inspection	: 02/03/2018		
Inspection At	: TORQUE 5 PTE LTD (KAKI BUKIT) NO. 8 KAKI BUKIT AVE 4., #01-50 SINGAPORE 415875		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,400.00 (SN + LABOUR)
Revised Amount	:S\$	1,034.00
Check Items (Estimated)	:S\$	2,500.00
Total	:S\$	3,534.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.
PENDING FOR PARTS PRICES.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Mar 2018		01 Mar 2018 16:02 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	U UMA MAHASWARI, ID: S2668992I, Tel: +6593801758, Email: NOEMAIL		
Main Claimant:	WEG SINGAPORE PTE LTD, Co. Reg. No.: 2005104472H		
Vehicle Reg. No.:	YP272B	Date of Loss:	28/02/2018 16:00 - :59
Claim Type:	TP / 550981	Policy/Cover Note No.:	A28814247ANW (Comprehensive) Coverage: 29/08/2017 - 28/08/2018
Vehicle Reg. No. (Insured):	SLG9899K	Policy No. (Claimant):	
		Excess:	
Repairer:	Torque 5 Pte Ltd (Kaki Bukit) No. 8 Kaki Bukit Ave 4,, #01-50, 415875 Kaki Bukit - Tel: 64524457		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 02/03/2018]		
Driver/Custodian (Insured):	U UMA MAHASWARI (52 / Female), NRIC: S2668992I, Tel: +6593801758		
Adj Asg. Remarks:	request Adrian Ling for survey		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4472H
Vehicle Details	
Vehicle No.:	YP272B
Vehicle to be Exported:	No
Intended De-registration Date:	05 Mar 2018
Vehicle Make:	ISUZU
Vehicle Model:	NPR75UH5A
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	4HK1416809
Chassis No.:	JAANPR75HF7105935
Maximum Power Output:	-
Open Market Value:	\$32,954.00
Original Registration Date:	25 Nov 2015
First Registration Date:	25 Nov 2015
Transfer Count:	1
Actual ARF Paid:	\$1,648.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	24 Nov 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$4,672.00
COE Rebate Amount:	\$3,606.00
Total Rebate Amount:	\$3,606.00

The information contained herein is correct as at 05 Mar 2018

OK

Email: sm@idac.com.sg

Tel no: 6555 6888 Fax no: 6454 3279

Personal Particulars of Owner & Driver (Vehicle A)

Date of Accident: 28 / 02 / 2018 (dd/mm/yy) Time of Accident: 16 : 00 (24-HR-FORMAT)

Vehicle No.: YP 272B Vehicle Make & Model: ISUZU NPR 754HSA

Exact location of Accident: BKE towards SLE

Policyholder's Name / IC No.: Weg Singapore Pte Ltd / 200514472H

Driver's Name / IC No.: Chye Yoon Shoo / 515519412 (As Above) ☐

Driver's Contact No.: 9834 1729 Company Contact No: _____

Driver's Address: BK 952 Jurong West St 91 #06-729 S(640952)

Insurance Company: NTUC Email address (if any): _____

Relationship between Owner & Driver: (Please **CIRCLE** one only)

Owner / Spouse / Children / Friend / Parents / Sibling / Relative / Employee / Hirer or Others specify: _____

What do you wish to claim? (Please **TICK one only)**

☐ Own Insurance / ☒ Other Vehicle (The one you want to claim against) / ☐ Reporting (For Record Purpose)

Exact purpose for which the vehicle was being used at time of accident?

☐ Private use / ☒ Work purpose

Occupation (nature of job) ☐ Indoor / ☒ Outdoor

No. of Passengers (Including Driver): _____

Weather condition & Road conditions? (On the day of accident)

☒ Clear & Dry / ☐ Raining & Wet / ☐ After-Rain & Wet / ☐ Drizzling & Wet / Others: _____

Was there any video captured by your Car Camera? ☐ Yes / ☒ No

Any Injuries: ☐ Yes / ☒ No (If YES) Injured Person's Name: _____

Injuries Sustain: _____ Injured Person in Which Vehicle: _____

Police Report filed: ☐ Yes / ☒ No (If YES) Which Police Station: _____

The Other Party(s) Details:

1. Driver's Name / IC No: _____ Vehicle No: SLG 9899K ^(B)

Driver's Contact No: _____ Insurance Company (If any): _____

2. Driver's Name / IC No: _____ Vehicle No: YL 37675 ^(C)


Driver's Contact No: _____ Insurance Company (If any): _____

*Independent Witness (If Any): _____ Contact No: _____

Preferred Workshop Name: _____ Contact No: _____

* If no proper documents are produced, IDAC should not file the report. Information will be discarded after one week.

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time, I vehicle A slowed down as the vehicle in front slowed down^{too}. After few seconds, vehicle B hit onto my vehicle rear portion. I felt one impact. After I alighted I realized I'm in a chain collision.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Torque 5 Pte Ltd
 No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

1/5 2800/2

ESTIMATION REPORT

Vehicle No : YP272B
 Make & Model : ISUZU,NPR75UH5A,JAANPR75HF7105935
 Year of Manufacture : 2015

Estimation No. : E18030008
 DOA : 28/02/2018

Not Actual

No	Description	Qty	U/P	Amt
Section: List Items				
1	Tailgate	1.00	0.00	0.00 X
2	Tailgate hinge	4.00	0.00	0.00 X
3	Tailgate lock (LH)	1.00	0.00	0.00 X
4	Tailgate lock (RH)	1.00	0.00	0.00 X
5	Tail lamp (LH)	1.00	0.00	0.00 X
6	Tail lamp (RH)	1.00	0.00	0.00 X
7	Tail lamp bracket (LH)	1.00	0.00	0.00 X
8	Tail lamp bracket (RH)	1.00	0.00	0.00 X
9	Rear end panel	1.00	0.00	0.00 X
10	Rear floor panel assy	1.00	0.00	0.00 X
11	Spare wheel bracket	1.00	0.00	0.00 X
12	Spare wheel lock	1.00	0.00	0.00 X
13	Exhaust pipe	1.00	0.00	0.00 X
14	Exhaust pipe bracket	2.00	0.00	0.00 X
				Amt S\$ 0.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 0.00

2/3/18
3 day.

152

Section: Special Nett Items

15	Tailgate sticker - 60 km/h	1.00	30.00	30.00 X
16	Tailgate lower step wooden	1.00	1,500.00	1,500.00 400
17	Rear reinforcement bar - long w/bracket	1.00	2,500.00	2,500.00 1600
18	Rear number plate	1.00	50.00	50.00 145.00
19	Spare wheel	1.00	600.00	600.00 X

Continue on next page...

P- 510
157
433.50
S.W- 2094
14600 - 1020
3547.50
202
2838

P- 510
157
433.50



Torque 5 Pte Ltd
No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : YP272B
Make & Model : ISUZU,NPR75UH5A,JAANPR75HF7105935
Year of : 2015
Manufacture

Estimation No. : E18030008
DOA : 28/02/2018

No	Description	Qty	U/P	Amt
				Amt S\$ 4,680.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 4,680.00

Section: Labour Items

20	To R&R accident affected areas including panel heating	1.00	1,300.00	1,300.00	600
21	To putty & respray accident affected areas	1.00	1,000.00	1,000.00	400
22	To rust proof accident affected areas	1.00	60.00	60.00	X
23	To R&R tailgate mechanism	1.00	100.00	100.00	X
24	To check wiring layout of tail lamp	1.00	80.00	80.00	20
25	To R&R exhaust pipe assy	1.00	180.00	180.00	X

Amt S\$ 2,720.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 2,720.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

List Items Subtotal	S\$ 0.00
Special Nett Items	S\$
Subtotal	4,680.00
Labour Items Subtotal	S\$
	2,720.00
Total	S\$
	7,400.00

**Torque 5 Pte Ltd**

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

SUPPLEMENTARY REPORT

Vehicle No : YP272B
Make & Model : ISUZU,NPR75UH5A,JAANPR75HF7105935
Year of : 2015
Manufacture

Estimation No. : E18030041
DOA : 28/02/2018

No	Description	Qty	U/P	Amt
Section: List Items				
1	Rear number plate bracket	1.00	80.00	80.00 ✓
2	Chassis (Wooden)	1.00	1,500.00	1,500.00 ✓
3	Anti roll bar	1.00	3,000.00	3,000.00 ✓
Amt				S\$ 4,580.00
Discount (0.00%)				S\$ 0.00
Subtotal				S\$ 4,580.00

Section: Special Nett Items				
4	Spare wheel rim	1.00	600.00	600.00 ✓
Amt				S\$ 600.00
Discount (0.00%)				S\$ 0.00
Subtotal				S\$ 600.00

*P = 5120.00 - 15%
= 4360.50
500.00
2.1020.00
6294.5*

** 2/1000.0000 3 repair days*

List Items Subtotal S\$ 4,580.00
Special Nett Items Subtotal S\$ 600.00
Total S\$ 5,180.00

LKK Auto Consultants Pte Ltd (Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18004043/UQD3N2

Date: 03/05/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A28814247ANW
Claimant Vehicle No :	YP272B	Insured Vehicle No :	SLG9899K
Date of Loss:	28/02/2018	Nature of Claim:	TP
		Claim No:	550981

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP272B	Engine No:	4HK1416809
Make & Model:	ISUZU NPR75UH5A, 5.2 D (M)	Chassis No:	JAANPR75HF7105935
Reg. Date:	25/11/2015 (Man. Year: 2015)	Odometer:	36987 km
Colour:	White		
Engine Capacity:	5193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/75 R17.5	Rear Tyre Size:	215/75 R17.5 (D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6/6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	10,370.00	2,527.50	7,842.50	75.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,720.00	1,020.00	1,700.00	62.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,090.00	3,547.50	9,542.50	72.90
Approved Total (Overridden) (S\$)		2,800.00		
(S\$)	13,090.00	2,800.00	10,290.00	78.61
+ GST 7.00/7.00% (S\$)	916.30	196.00	720.30	78.61
Nett Amount (S\$)	14,006.30	2,996.00	11,010.30	78.61

INSPECTION

Date of Assignment:	01/03/2018	
Date Inspected:	02/03/2018	Inspected At: Torque 5 Pte Ltd (Kaki Bukit) No. 8 Kaki Bukit Ave 4., #01-50 Singapore 415875

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 03 May 2018)	
Parts:	N/A	ISUZU NPR75UH5A 5.2 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP272B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*TAILGATE (NPA)	Not Necessary	0.00 F	*- FL
2	4	*TAILGATE HINGE (NPA)	Not Necessary	0.00 F	*- FL
3	1	*TAILGATE LOCK (LH)(NPA)	Not Necessary	0.00 F	*- FL
4	1	*TAILGATE LOCK (RH)(NPA)	Not Necessary	0.00 F	*- FL
5	1	*TAIL LAMP (LH)(NPA)	Not Necessary	0.00 F	*- FL
6	1	*TAIL LAMP (RH)	Cracked	195.00 F	*195.00 FL
7	1	*TAIL LAMP BRACKET (LH)(NPA)	Not Necessary	0.00 F	*- FL
8	1	*TAIL LAMP BRACKET (RH)(NPA)	Not Necessary	0.00 F	*- FL
9	1	*REAR END PANEL (NPA)	Not Necessary	0.00 F	*- FL
10	1	*REAR FLOOR PANEL ASSY (NPA)	Not Necessary	0.00 F	*- FL
11	1	*SPARE WHEEL BRACKET & CHAIN }	Cracked	315.00 F	*315.00 FL
12	1	*SPARE WHEEL LOCK (NPA) }		0.00 F	*- FL
13	1	*EXHAUST PIPE (NPA)	Not Necessary	0.00 F	*- FL
14	2	*EXHAUST PIPE BRACKET (NPA)	Not Necessary	0.00 F	*- FL
15	1	*TAILGATE STICKER -60 KM/H	Not Necessary	30.00 FS	*- FS
16	1	*TAILGATE LOWER STEP WOODEN	Cracked	1,500.00 FS	*400.00 FS
17	1	*REAR REINFORCEMENT BAR -LONG W/BRACKET	Bent	2,500.00 FS	*1,600.00 FS
18	1	*REAR NUMBER PLATE	Bent	50.00 FS	*14.00 FS
19	1	*SPARE WHEEL	Repair	600.00 FS	*- FS
20	1	*REAR NUMBER PLATE BRACKET	Bent	80.00 FS	*80.00 FS
21	1	*CHASSIS (WOODEN)	Not Necessary	1,500.00 F	*- FL
22	1	*ANTI ROLL BAR	Repeated	3,000.00 F	*- FL
23	1	*SPARE WHEEL RIM	Repeated	600.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 10,370.00 2,604.00

- List Item Discount on L Items 0.00/15.00% (\$\$) 0.00 76.50

Total Parts (\$\$) 10,370.00 2,527.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO R&R ACCIDENT AFFECTED AREAS INCLUDING PANEL BEATING	New	1,300.00	600.00
2	TO PUTTY & RESPRAY ACCIDENT AFFECTED AREAS	New	1,000.00	400.00
3	TO RUST PROOF ACCIDENT AFFECTED AREAS	New	60.00	-
4	TO R&R TAILGATE MECHANISM	New	100.00	-
5	TO CHECK WIRING LAYOUT OF TAIL LAMP	New	80.00	20.00
6	TO R&R EXHAUST PIPE ASSY	New	180.00	-
Gross Labour Cost (S\$)			2,720.00	1,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >