



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLN 4169 E

Parts	(a) Cost / List Price Items	\$	79,628.31
	Plus/Less 25%	\$	19,907.08
	Total of Cost / List	\$	59,721.23
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	740.00
	Total Parts Cost	\$	60,461.23
	Labour	\$	10,870.00
	Total	\$	71,331.23

The above total will be subjected to 7% G.S.T.

Finalised.

49x92-57

12398.14

37194.43

6x5

37819.43

7050

44869.43

Name of Surveyor : _____

Company : _____

Survey conducted on : _____ at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : _____ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

App: Steven
Sent circle parts to #01-259

9 pages

arts

o. :
Model :
lo :
SLN 4169 E
TOYOTA PRIUS
JTDKB3FU203556663

Submit By : Carmen Lim
Year Manufacture : 2017
Engine No. :
Cost / List

	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front number plate	1	\$45.00	S-N	✓
2	Front number plate garnish X	1	\$45.00		✓
3	Bonnet X	1	\$812.40		✓
4	Bonnet lock	1	\$130.00		✓
5	Bonnet hinge LH	1	\$57.80		✓
6	Bonnet hinge RH	1	\$57.80		✓
7	Bonnet heat insulator	1	440.12 ✓		✓
8	Bonnet heat insulator clip	10	38 ✓		✓
9	Front support panel centre	1	\$338.50 ✓		✓
10	Front support panel LH	1	213.50 ✓		✓
11	Front support panel RH	1	213.50 ✓		✓
12	Headlamp panel LH	1	89.20 ✓		✓
13	Headlamp panel RH	1	89.20		✓
14	Support panel lower	1	387.50 ✓		✓
15	Front support panel top garnish	1	285.40 ✓		✓
16	Front support panel top garnish clip	10	38 ✓		✓
17	Air duct	1	195.40 ✓		✓
18	Air duct - inlet	1	109.75		✓
19	Brace panel	1	105.20 ✓		✓
20	Condenser	1	1544.70 ✓		✓
21	Radiator	1	1841.80 ✓		✓
22	Radiator fan motor RH	1	455.70		✓
23	Radiator fan motor LH	1	491.79		✓

of the quoted parts are recommended to be repaired, then an additional labour charge
ged accordingly under supplementary.

Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829
No. 200005485N / GST No. 20-0005485-N

Not Authorised
L1 Lp & 7, 1.B.1

6912-27

4x (S-N)

Spare Parts

Vehicle No. : **SLN 4169 E**
 Make & Model : **TOYOTA PRIUS**
 Chassis No : **JTDKB3FU203556663**

Submit By : **Carmen Lim**
 Year Manufacture : **2017**
 Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Radiator fan blade LH	1	197.80		?
25	Radiator fan blade RH	1	219.80		?
26	Radiator fan cowling	1	287.67		?
27	Radiator top hose	1	49.80		?
28	Radiator bottom hose	1	46.95		?
29	Radiator spare tank	1	186.70		?
30	Intake manifold	1	892.74		?
31	Headlamp LH CM	1	\$2,531.60		✓
32	Headlamp RH	1	\$2,531.60 ✓		✓
33	Front bumper B	1	450.80		✓
34	Front bumper clip A	10	40		✓
35	Front bumper reinforcement - upper X B	1	\$711.50		✓
36	Front bumper reinforcement - lower	1	\$245.30		?
37	Front bumper side retainer RH D	1	\$107.20		✓
38	Front bumper side retainer LH CM	1	\$107.20		✓
39	Front bumper upper grille CM	1	\$321.90		✓
40	Front bumper lower grille D	1	\$148.60		✓
41	Front bumper emblem R	1	87.10		✓
42	Front bumper tow cover RH D	1	\$25.70		✓
43	Front bumper tow cover LH A	1	\$25.70		✓
44	Front bumper sponge - upper CM	1	\$89.81		✓
45	Front bumper sponge - lower CM	1	\$135.70		✓
46	Fog lamp LH	1	\$910.70		?

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. :
 Make & Model :
 Chassis No. :

SLN 4169 E

TOYOTA PRIUS

JTDKB3FU203556663

Submit By :

Carmen Lim

Year Manufacture :

2017

Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
47	Fog lamp RH <i>Sn</i>	1	\$910.70		X
48	Engine under cover <i>Sn</i>	1	198-30		X
49	Engine under cover clip <i>Sn</i>	10	35		X
50	Air cleaner box	1	967.80 ✓		?
51	Washer tank	1	195-60		? X
52	Washer tank motor	1	196-74		? X
53	RH front fender <i>R</i>	1	868-70		X
54	RH front fender undershield <i>Sn</i>	1	185-64		X
55	RH front fender undershield clip <i>Sn</i>	10	25		X
56	RHF fender wording "HYBRID" <i>Sn</i>	1	44-17		X
57	LH front fender <i>Sn</i>	1	868-70		✓
58	LH front fender undershield	1	195-60		? X
59	LH front fender undershield clip <i>Sn</i>	10	25		✓
60	LHF fender wording "HYBRID" <i>Sn</i>	1	44-17		✓
61	LH front fender quarter garnish <i>Sn</i>	1	122-70		✓
62	Aircon compressor	1	2859-70		? X
63	Horn	1	150-40		? X
64	Air flow sensor	1	256.09		? X
65	Water pump	1	601-73		? X
66	Bonnet cable	1	74-60		? X
67	Engine mounting RH	1	298-70		? X
68	Radiator top garnish	1	54-24 ✓		?
69	Air resonator	1	195-74		? X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. :
 Make & Model :
 Chassis No. :

SLN 4169 E

TOYOTA PRIUS

JTDKB3FU203556663

Submit By :
 Year Manufacture :
 Engine No. :

Carmen Lim

2017

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
70	Throttle body hose	1	91-40		7 X
71	LH front door R	1	1121-75		X
72	LH front door hinge top R	1	78-30		X
73	LH front door hinge bottom R	1	78-30		X
74	LH front door weatherstrip S	1	211-69		X
75	LHF door glass outer moulding S	1	121-75		X
76	LH rear door B	1	1211-40		✓
77	LH rear door hinge top R	1	78-34		X
78	LH rear door hinge bottom R	1	78-34		X
79	LH rear door weatherstrip	1	198-70		7 X
80	LHR door glass outer moulding S	1	107-80		X
81	Rear windscreen moulding M	1	\$97.70		✓
82	Rear windscreen sealant M	1	\$50.00	S.N	Post
83	Rear windscreen top garnish CM	1	\$655.40		✓
84	Rear windscreen top quarter garnish LH D	1	189-60		✓
85	Rear windscreen top quarter garnish RH H	1	189-60		✓
86	Rear number plate M	1	\$45.00	S.N	✓
87	Reverse sensor T	1	\$200.00	S.N	✓
88	Rear bumper B	1	\$497.50		✓
89	Rear bumper clip M	10	\$40.00		✓
90	Rear bumper side retainer LH CM	1	\$112.70		✓
91	Rear bumper side retainer RH S	1	\$112.70		X
92	Rear bumper reinforcement B	1	\$398.90		✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

3392-80
 285 (S.N).

Spare Parts

Vehicle No. : **SLN 4169 E**
 Make & Model : **TOYOTA PRIUS**
 Chassis No : **JTDKB3FU203556663**

Submit By : **Carmen Lim**
 Year Manufacture : **2017**
 Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
93	Rear bumper lower garnish centre <i>CM</i>	1	\$582.60		✓
94	Rear bumper lower garnish LH <i>CM</i>	1	\$149.70		✓
95	Rear bumper lower garnish RH <i>PU</i>	1	\$149.70		X
96	Rear bumper tow cover <i>PU</i>	1	\$31.70		X
97	Rear bumper under cover <i>CM</i>	1	\$355.20		✓
98	Rear bumper under cover LH <i>hit</i>	1	187.66		✓
99	Rear bumper under cover RH <i>PU</i>	1	187.66		X
100	Rear bumper under cover clip <i>M</i>	4	\$14.00		✓
101	Tail door <i>By</i>	1	\$1,122.50		✓
102	Tail door lock <i>TM</i>	1	\$487.70		✓
103	Tail door emblem <i>M</i>	1	\$81.70		✓
104	Wording "PRIUS" <i>M</i>	1	\$51.90		✓
105	Wording "HYBRID" <i>M</i>	1	\$55.47		✓
106	Tail door hinge LH <i>PU</i>	1	87.60 ✓		?
107	Tail door hinge RH	1	87.60 ✓		?
108	Taildoor absorber LH <i>PU</i>	1	296.40		✓
109	Taildoor absorber RH	1	296.40		? X
110	Tail door plate garnish <i>CM</i>	1	\$782.50		✓
111	Tail door inner trim <i>BU</i>	1	\$278.90		✓
112	Tail door inner trim clip <i>M</i>	10	\$28.00		✓
113	Taildoor spoiler <i>hit</i>	1	\$1,587.83		✓
114	Tail end panel <i>By</i>	1	\$596.60		✓
115	Tail end panel garnish <i>M</i>	1	\$151.60		✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Attn: Steven
Sent '✓' item to AMK

3pg

Spare Parts

Vehicle No. : **SLN 4169 E**
Make & Model : **TOYOTA PRIUS**
Chassis No. : **JTDKB3FU203556663**

Submit By : **Carmen Lim**
Year Manufacture : **2017**
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
116	Tail end panel garnish clip <i>M</i>	10	\$35.00		✓
117	Boot weatherstrip <i>Ad/bw</i>	1	\$353.10		✓
118	Spare tyre well panel	1	\$793.15	✓	?
119	Spare tyre board	1	\$566.79	✓	?
120	Spare tyre compartment sponge LH	1	297.67	✓	?
121	Spare tyre compartment sponge RH	1	297.67		?
122	Spare tyre compartment centre	1	251.70		?
123	Tail lamp LH - UPPER <i>Br</i>	1	\$498.75		✓
124	Tail lamp RH - UPPER	1	\$498.75		?
125	Tail lamp LH - LOWER <i>Br</i>	1	\$511.60		✓
126	Tail lamp RH - LOWER	1	\$511.60		?
127	Taildoor glass × <i>S herford</i>	1	\$598.70		✓
128	Taildoor glass sealant <i>M</i>	1	\$50.00	S.N	✓
129	Tail door spoiler	1	\$1,567.83	✓	?
130	Third brake light <i>Br</i>	1	\$359.64		X
131	LH rear fender <i>Br</i>	1	883.60		✓
132	LH rear fender undershield <i>CM</i>	1	92.30		✓
133	LH rear fender undershield clip <i>M</i>	10	30		✓
134	LH rear fender air duct <i>Ad</i>	1	115.60		✓
135	LH rear inner trim upper <i>62480-47100 Re form</i>	1	386.75		✓
136	LH rear inner trim lower <i>64740-47100 "</i>	1	387.63		✓
137	LH rear lower arm <i>Br</i>	1	398.65		✓
138	LH rear knuckle arm <i>Br</i>	1	895.60		✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

8412.72
40 (S.N).

Spare Parts

Vehicle No. : **SLN 4169 E**

Make & Model : **TOYOTA PRIUS**

Chassis No : **JTDKB3FU203556663**

Submit By : **Carmen Lim**

Year Manufacture : **2017**

Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
139	LH rear knuckle bearing <i>na</i>	1	421-90		✓
140	LH rear wheel hub <i>B1</i>	1			✓
141	LH rear wheel hub lock nut	1	17-30		? +
142	LH rear shock absorber <i>B1</i>	1	389-40		✓
143	LH rear shock absorber top mouting <i>B1</i>	1	168-70		✓
144	LH rear shock absorber stopper	1	85-70 ✓		?
145	LH rear rim <i>na</i>	1	1555-10 ✓		✓
146	LH rear tyre <i>pu</i>	1	350	S.N	8085
147	RH rear fender <i>R</i>	1	883-60		X
148	RH rear fender undershield <i>pu</i>	1	92-30		X
149	RH rear fender undershield clip <i>na</i>	10	30		X
150	RH rear inner trim upper	1	386-75 ✓		?
151	RH rear inner trim lower	1	387-63		?
152	RH rear lower arm <i>pu</i>	1	398-65		X
153	RH rear knuckle arm <i>pu</i>	1	898-60		X
154	RH rear knuckle bearing <i>pu</i>	1	421-90		X
155	RH rear wheel hub <i>pu</i>	1			X
156	RH rear wheel hub lock nut <i>pu</i>	1	17-30		X
157	RH rear shock absorber <i>pu</i>	1	389-40		X
158	RH rear shock absorber top mouting <i>pu</i>	1	168-70		X
159	RH rear shock absorber stopper <i>pu</i>	1	85-70		X
160	Rear Axle	1	2257-40 ✓		?
161	Exhaust pipe <i>R</i>	1	854-10		X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

5231.95
210 (S.N).

Spare Parts

Vehicle No. :
 Make & Model :
 Chassis No. :

SLN 4169 E

TOYOTA PRIUS

JTDKB3FU203556663

Submit By :
 Year Manufacture :
 Engine No. :
Cost / List

Carmen Lim
 2017

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
162	Exhaust pipe mouting <i>Sm</i>	1	38.40		X
163	Exhaust insulator <i>R</i>	1	267.40		X
164	RH rear fender quarter garnish <i>"</i>	1	189.60		?
165	RH rear fender quarter garnish clip	6	24		?
166	LH rear fender quarter garnish	1	189.60		?
167	LH rear fender quarter garnish clip	6	24		?
168	Roof lining <i>Re form</i>	1	2237.40		✓
169	Roof lining clip <i>Re</i>	10	80		✓
170	Bootlid retraction cover	1	994.70		?
171	Hybrid battery	1	13652.74		?
172	Fuel tank cover <i>R</i>	1	198.64		X
173	Fuel tank cover rivet	1	10		?
174	Spare tyre lock nut	1	29.80		?
175	Rear chassic LH <i>R</i>	1	388.90		X
176	LH rear hub cab <i>new</i>	1	198.65		✓
177					
178					
179					
180					
181					
182					
183					
184					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

ESTEEM PERFORMANCE PTE LTD

BLK 5033 ANG MO KIO INDUSTRIAL PARK 2

#01-259 SINGAPORE 569536

Tel:64841221 Fax:64847829

Spare Parts

Vehicle No. : **SLN 4169 E**
Make & Model : **TOYOTA PRIUS**
Chassis No : **JTDKB3FU203556663**

Submit By : **CARMEN LIM**
Year Manufacture : **2017**
Engine No. :

Cost / List**Supplementary**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Taillamp panel LH	1	\$189.60		
2	LH side skirt	1	\$721.50		
3	Fuel tank cover motor	1	\$369.67		
4	Taillamp clip	3	\$13.50		
5	Taildoor stopper LH	1	\$14.21		
6	Taillamp cover LH	1	\$61.78		
7	Warning triangle box	1	\$45.00	S.N	
8	Support panel air guide LH upper	1	\$89.70		
9	Support panel air guide LH lower	1	\$89.70		
10	Headlamp ballast LH	1	\$551.97		
11	Wiper garnish	1	\$561.70		
12	Wiper garnish cover LH	1	\$75.80		
13	Rear brake caliber LH	1	\$751.60		
14	Leveling sensor	1	\$588.60		
15	Rear disc roto LH	1	\$321.70		
16	LH rear antiroll bar link	1	\$161.70		
17	Coil spring stopper top	1	\$59.80		
18	Coil spring stopper bottom	1	\$61.37		
19	LH rear trailing arm	1	\$303.70		
20	Floor panel LH	1	\$189.60		
21	Driver seat back rest rail	1	\$669.40		
22	Passenger seat back rest rail	1	\$669.40		
23	Taillamp soket assy LH	1	\$75.90		

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : **SLN 4169 E**
Make & Model : **TOYOTA PRIUS**
Chassis No : **JTDKB3FU203556663**

Submit By : **CARMEN LIM**
Year Manufacture : **2017**
Engine No. :
Cost / List

Supplementary

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear brake pad	1	\$195.40		
2					
3					
4					
5					
6					
7					
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

6787-30
4x (S.N)



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7020 Website: www.esteemperf.com.sg

Labour

Vehicle No. : SLN 4169 E Submit By : Carmen Lim
Make & Model : TOYOTA PRIUS Year of Manufacture : 2017

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (FRONT BUMPER,BONNET,SUPPORT PANEL, LHF FENDER,RHF FENDER,LHF DOOR,LHR DOOR,LHR FENDER,REAR BUMPER,TAILDOOR,END PANEL,SPARE TYRE COMPARTMENT,RHR FENDER,RHR DOOR, ROOF TOP,REAR CHASSIC LH)	\$3,800.00	2800
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (FRONT BUMPER,BONNET,SUPPORT PANEL, LHF FENDER,RHF FENDER,LHF DOOR,LHR DOOR,LHR FENDER,REAR BUMPER,TAILDOOR,END PANEL,SPARE TYRE COMPARTMENT,RHR FENDER,RHR DOOR, ROOF TOP,REAR CHASSIC LH)	\$3,400.00	2600
3	TO Check wiring & focus headlamp	\$50.00	40
4	To remove & refit radiator, condenser to assist work load, to top up A/C gas.	\$150.00	100
5	To remove & refit undercarriage to assist work load.	\$500.00	240
6	To do wheel alignment.	\$120.00	80
7	To remove & refit Door trim, door glass, window regulator, door lock to assist work load.	\$300.00	60

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

7050

LabourVehicle No. : **SLN 4169 E**Submit By : **Carmen Lim**Make & Model : **TOYOTA PRIUS**Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
8	To remove & refit rear windscreen.	\$120.00	✓
9	To tuff coat.	\$500.00	1800
10	To remove & refit inner seat & upholstery to assist work load.	\$250.00	1000
11	To remove & refit roof lining, inner trim to assist work load.	\$600.00	1200
12	To remove & refit exhaust system to assist work load.	\$150.00	800
13	To remove & refit petrol tank to assist work load.	\$150.00	600
14	To transfer boot mechanism to new boot	\$120.00	600
15	To conduct water leakage tests to ensure proper air and sealing	\$120.00	300
16	To re-align rear chassis	\$300.00	2500
17	Towing (B71)	\$120.00	? 90
18	To remove & refit Taildoor glass to assist work load	\$120.00	600

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.