

ASS. REC. BY:

REF: CS/FCI/8004046/Kvd302

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

(WS)

From (Person):

Aung Yin Min

of

FCI

Date/Time: 02/03/18 @ 9:38am

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLN 4169E

Insured:

SHD 8825T

at Workshop m/s

Esteem Performance

Tel:

64841221 / 8799 0066

of BLK 5033 AMK, Ind Prk 2 # 01-251 / 259

Policy No:

Claim No:

D18 00/666 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

26/2/2018

CA / REV / REP. / REV 24 HRS

1 up

Insp: Sin Ming 385, (Inside Vicom)

H.O.D. Endorsement:

Date/Time: 9:36am @ 2/3/18

Person Contacted:

Carmen

Vehicle: IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLN 4169E - X

SHD 8825T - 18/FCI/7020341/K6

D.O.A. 2/5/17

5/3/18

Email preli revised to FCI

22/11

842615.63 email

ASS. REC. BY:

REF: FCZ/Kenneth

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 8100k

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 24 days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLN 4189EYr Regn: 05.17Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: ToyPROUS

c.c.

1792Colour: M. P. White

A/C:

Insured / Std / NI / NA

Sp. Reading: _____

T/Radio:

Insured / Std / NI / NA

Eng No: _____

C/No: ITDKB 3F4 203 55663Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModl: Nil / S/Rlm / STD / A/Rlm or

Tyre Size: F: _____

R: _____

195/85R15BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 8 mmL/Bal. 8 mmD.O.A. 26/2/18

Rear

R/Bal. 8 mmL/Bal. 8 mmD.O.I. 2/3/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

5/3File pass to Carman11/12/18@ 9:15amFinal sig\$42,856.90confirmed with Carman,24 days(Red 33,647.06, 444)

RECEIVED 2 DEC 2018

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 21/12 - typistReport Format: CWSLump Sum / I.B.I. (\$) 42,856.90Days Of Repair: 24Resurvey No. of Trlp: 3

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech Invs (\$)

☐

: Weekend (\$)

Survey Fee:

Transportation:

S - RS - SI

Photos

Others

66x15 = 990170 + 9905050 + 50 + 50845801444

Survey Department Check List (Case Handler)

Reference No. : CS | FC 18004046 | Kve/3
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-Inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 21/12/18
 Case Handler Date

*C: Critical *N: Non-Critical

21/05/201



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18004046/Kvd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 02-03-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 8825T	Veh. Inspected	SLN 4169E
Policy No.		Coverage (\$)	0.00
Claim No.	D18001666MFSH	Excess (\$)	0.00
Assign From	CWS (AUNG YIN MIN)	Assign Date	02/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	26/02/2018	Inspection Date	02/03/2018
Survey held at	385 SIN MING DRIVE		
Repairer	ESTEEM PERFORMANCE PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

MOTOR SURVEY ASSIGNMENT

Date	27-02-2018	Our Ref No. D18001666MFSH
Accident Date	26-02-2018	Claim Type. Third Party
Insured Vehicle	SHD8825T	Third Party Vehicle. SLN4169E
Survey Location	BLK 5033 ANG MO KIO, IND PARK 2 #01-251/259	
Contact Person.	CARMEN LIM	
Contact No.	64841221/ 86195565	Fax No. 64847829
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ESTEEM PERFORMANCE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	AUNGYM	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/235392)



PRI Documents



Close



PRI Header Details

Claim No	D18001666MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & ESTEEM P
Workshop Name	ESTEEM PERFORMANCE PTE LTD (Contact Person : CARMEN LIM)	Survey Location & Contact Details	BLK 5033 ANG MO KIO, IND PARK 2 #01-251/259 Mobile: 86195565 , Phone: 64841221 , Fax: 6484782! EmailId: CARMEN@ESTEEMPERF.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHD8825T	TP Vehicle No	SLN4169E
PRI Recieved Date	01-03-2018 07:06:36 PM	Surveyor Appointed Date	02-03-2018 09:37:12 AM	Surveyor Accept Date	02-03-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	02-03-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 5 March 2018 3:45 PM
To: 'Claim Workflow System'
Cc: AUNGYINMIN@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18001666MFSH/1, SLN 4169E
Attachments: SLN 4169E PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLN 4169E
Date of survey: 2/3/2018

Please be informed that some of the parts pending for parts prices.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Friday, 2 March 2018 9:59 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: AUNGYINMIN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001666MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 2 March 2018 9:37 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; AUNGYINMIN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18001666MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18001666MFSH

Our ref: CS/FCII8004046/Kvd3

Date : 5/3/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLN 4169E


We thank for your instruction on 2/3/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 2/3/2018 at the premises of M/s ESTEEM PERFORMANCE PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$36,182.12
Revised Estimate Amount	: S\$18,863.85
"Check" Items Amount	: S\$ 6,093.17
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear and front portion.



Comments/Present Status:
Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	7200G

Vehicle Details

Vehicle No.:	SLN4169E
Vehicle to be Exported:	Yes
Intended De-registration Date:	02 Mar 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	22RS041774
Chassis No.:	JTDKB3FU203556663
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	03 May 2017
First Registration Date:	03 May 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 May 2027
PARF Rebate Amount:	\$3,750.00

Intended COE Rebate Details

COE Expiry Date:	02 May 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$54,406.00
COE Rebate Amount:	\$43,524.00
Total Rebate Amount:	\$47,274.00

The information contained herein is correct as at 01 Mar 2018

SGCARMART.COM
THE ONLY PLACE FOR SMART CAR BUYERS

Toyota Prius Alpha Hybrid 1.8A S


Price	\$116,800
Reg date	23-Oct-2017
Manufactured	2017
Mileage	12 km
Transmission	Auto
Engine Capacity	1,797 cc
Curb Weight	1,460 kg
Fuel Type	Petrol-Electric
Features	Airbags, ABS, Reliable And Fuel Efficient 1.8L 4 Cylinder DOHC 16V Hybrid Engine Producing 134Bhp, Multi Steering Controls, 7 Seaters MPV.
Accessories	Sports Rims, Leather Seats, In Car Camera Recorder Q7, Reverse Camera And Sensors.
Description	Almost New Toyota Prius Alpha Hybrid 1.8 (7-Seater). 10 Years Warranty Up To 200000KM.
COE	\$49,996
OMV	\$28,417
ARF	\$16,784
Depreciation	\$11,230 / year
No. of owners	1
Type of Vehicle	MPV
Availability	Available

Seller Information

Company	HY Automobile Pte Ltd » dealer's pricelist » 3 vehs sold (1 vehs available)	
Address	176 Sin Ming Drive #04-02	
Location	Sin Ming Autocare	
Office No	64514904	
Contact Person(s)	Ivan Neo	83336725

Posted on : 27-Jan-2018

Last Updated : 27-Jan-2018



All Prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

© 2004-2018 sgCarMart. All rights reserved.

MBHH18026709-01 / AJAX MARS PTE LTD - Bukit Merah
 ENTRY DATE & TIME: 26/03/2018 18:28
 SUBMITTED BY: Elizabeth

Your NCD will be affected due to late reporting
 Actual e-Filing Submission Date & Time: 01/03/2018 09:23

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/02/2018 19:28
Date Of Accident	26/02/2018 19:50
Exact Location Of Accident	ALONG AIRPORT BOULEVARD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN4169E
Insured/Policyholder	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201817200G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66550005
Vehicle Particulars	
Manufacturer	TOYOTA
Model	PRIUS HYBRID 1.8 CVT
Exact Purpose for which vehicle was being used at time of accident	HIRE & REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	A29069766MKF
Cover Note Number	N.A
Driver	
Name of Driver	LOW CHEN KOON
NRIC No	S1171655E
Date Of Birth	29/07/1956
Occupation	OUTDOOR
Date Of Driving Pass	24/10/1979
Driving Experience	38 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96832322
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address NIL
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? YES
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : PASSENGER 1
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of Intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I SLN4169E was driving along airport boulevard on the 2nd lane, it was a heavy traffic. While driving suddenly the traffic started to slow down and the vehicle in front of me make an e-brake, so I applied my e-brake and manage to stop on time, but the other party with unknown plate number the last vehicle did not manage to stop on time and bang onto my rear vehicle. The impact was strong and involved 3 others vehicles in front of me. 5 vehicles was involved.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number UNKNOWN SHD 88X57
 Vehicle Make/Model/Colour WHITE VEHICLE
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number UNKNOWN

Vehicle Make/Model/Colour TAXI 1

Details Of Properties

Vehicle Category TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number UNKNOWN

Vehicle Make/Model/Colour TAXI 2

Details Of Properties

Vehicle Category TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number UNKNOWN

Vehicle Make/Model/Colour TAXI 3

Details Of Properties

Vehicle Category TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name LOW CHEN KOON

Approximate Age

Injuries Sustain

Injured person in which vehicle? SLN4169E

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? YES

Address

Sketch Plan

SKETCH PLAN**IMPORTANT NOTICE**

1. Please read carefully the details of the accident to speed up the claims process.
2. The form must be submitted by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may cause insurers to repudiate policy liability.
4. The time and convenience of this form to insurance companies is not an admission of policy liability on the part of insurance companies.
5. All claims information must be referred to the Police for investigation.
6. The completion of this form by the insured or the Authorized Driver is not an admission of policy liability on the part of insurance companies.
7. By the completion of this form to the insurers, you hereby consent to the forwarding of this report to the insurers and to copies of this report being made available to insurers.
8. **General Data Protection Act (GDPA)**
 (a) The insurers, reinsurers and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal information for one or more of the purposes set out in this form and any other personal information provided by me or possessed by me, including but not limited to the "Personal Information" and details and traveler such Personal Information to all insurers who have insured my vehicle involved in this accident (all insurers) who have insured vehicles involved in this accident shall be collectively referred to as the "Insurers". The Insurers, reinsurers and the Monetary Authority of Singapore and any relevant government agency/authority (such as the Police, for the purposes of)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) settling the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) assessing and/or dealing with my claims (including the issuing of correspondence, statements, invoices, reports or copies to me, which could involve disclosure of certain personal data about me to bring about delivery of the sums as well as on the internal cover of insurances);
 - (v) processing and/or dealing with my claims in accordance with applicable law in administering, processing, handling and/or dealing with my claims.
9. The Insurers, reinsurers and the GIA may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above purposes; and
10. My Personal Information may also be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their reinsurers/agents), which may be also outside of Singapore, for one or more of the above purposes.

VERIFIED BY ALAK MARS
REPORTING OFFICER
MUHAMMAD SUKANDI SY
MOHD AFFANDI

Policyholder's Signature / Date & Time

Driver's Signature / Date & Time

Witnessed by Reporting Officer
Personnel

Common Statement Pg. 1

ACCIDENT STATEMENT (2000 characters)

I SLN4169E was driving along airport boulevard on the 2nd lane, it was a heavy traffic. While driving suddenly the traffic started to slow down and the vehicle in front of me made an e-brake, so I applied my e-brake and managed to stop on time, but the other party with Unknown plate number the last vehicle did not manage to stop on time and bang onto my rear vehicle. The impact was strong and involved 3 other vehicles in front of me. (5 vehicles were involved).

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MUHAMMAD SUMARDI BIN MOHD AFFANDI

MARS Officer

Registered Owner or Driver's Signature

Job Complete Date/Time

28 February 2018 2:57 pm

Date/Time:

28 February 2018 2:57 pm



ESTEEM PERFORMANCE PTE LTD

 Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536.
 Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteempart.com.sg
Spare Parts
 Vehicle No. : **SLN 4169 E**
 Make & Model : **TOYOTA PRIUS**
 Chassis No. : **JTDKB3FU203556663**

 Submit By : **Carmen Lim**
 Year Manufacture : **2017**
 Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front number plate <i>M1</i>	1	\$45.00		✓
2	Front number plate garnish <i>Pl</i>	1	\$45.00		✓
3	Bonnet <i>Bu</i>	1	\$812.40		✓
4	Bonnet lock <i>Tu</i>	1	\$130.00		✓
5	Bonnet hinge LH <i>D1</i>	1	\$57.80		✓
6	Bonnet hinge RH <i>D1</i>	1	\$57.80		✓
7	Bonnet heat insulator	1			?
8	Bonnet heat insulator clip	10			?
9	Front support panel centre	1	\$338.50		?
10	Front support panel LH	1			?
11	Front support panel RH	1			?
12	Headlamp panel LH <i>C1</i>	1			✓?
13	Headlamp panel RH	1			?
14	Support panel lower	1			?
15	Front support panel top garnish	1			?
16	Front support panel top garnish clip	10			?
17	Air duct	1			?
18	Air duct - inlet	1			?
19	Brace panel	1			?
20	Condenser	1			?
21	Radiator	1			?
22	Radiator fan motor RH	1			?
23	Radiator fan motor LH	1			?

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

1486.50

 Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829
 Company Reg No. 200005485N / GST No. 20-0005485-N

 Not Authorized
 C1 Ly & 7, 1.B.1

Spare Parts

Vehicle No. :
 Make & Model :
 Chassis No. :

SLN 4169 E

TOYOTA PRIUS
 JTDKB3FU203556663

Submit By :
 Year Manufacture :
 Engine No. :

Carmen Lim
 2017

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Radiator fan blade LH	1			?
25	Radiator fan blade RH	1			?
26	Radiator fan cowling	1			?
27	Radiator top hose	1			?
28	Radiator bottom hose	1			?
29	Radiator spare tank	1			?
30	Intake manifold	1			?
31	Headlamp LH CM	1	\$2,531.60		✓
32	Headlamp RH	1	\$2,531.60		✓
33	Front bumper B ₁	1			✓
34	Front bumper clip N ₂	10			✓
35	Front bumper reinforcement - upper B ₁	1	\$711.50		✓
36	Front bumper reinforcement - lower	1	\$245.30		?
37	Front bumper side retainer RH P ₁	1	\$107.20		✓
38	Front bumper side retainer LH CM	1	\$107.20		✓
39	Front bumper upper grille CM	1	\$321.90		✓
40	Front bumper lower grille D ₁	1	\$148.60		✓
41	Front bumper emblem R ₁	1			✓
42	Front bumper tow cover RH R ₁	1	\$25.70		✓
43	Front bumper tow cover LH N ₁	1	\$25.70		✓
44	Front bumper sponge - upper CM	1	\$89.81		✓
45	Front bumper sponge - lower CM	1	\$136.70		✓
46	Fog lamp LH	1	\$910.70		?

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

7892.51

Spare Parts

Vehicle No. : **SLN 4169 E**
 Make & Model : **TOYOTA PRIUS**
 Chassis No. : **JTDKB3FU203556663**

Submit By : **Carmen Lim**
 Year Manufacture : **2017**
 Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
47	Fog lamp RH <i>Sn</i>	1	\$910.70		X
48	Engine under cover <i>Sn</i>	1			X
49	Engine under cover clip <i>Sn</i>	10			X
50	Air cleaner box	1			?
51	Washer tank	1			?
52	Washer tank motor	1			?
53	RH front fender <i>R</i>	1			X
54	RH front fender undershield <i>Sn</i>	1			X
55	RH front fender undershield clip <i>Sn</i>	10			X
56	RHF fender wording "HYBRID" <i>Sn</i>	1			X
57	LH front fender <i>Sn</i>	1			✓
58	LH front fender undershield	1			?
59	LH front fender undershield clip <i>Sn</i>	10			✓
60	LHF fender wording "HYBRID" <i>Sn</i>	1			✓
61	LH front fender quarter garnish <i>Sn</i>	1			✓
62	Aircon compressor	1			?
63	Horn	1			?
64	Air flow sensor	1			?
65	Water pump	1			?
66	Bonnet cable	1			?
67	Engine mouting RH	1			?
68	Radiator top garnish	1			?
69	Air resonator	1			?

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

910-70

Spare Parts

Vehicle No. : **SLN 4169 E**
 Make & Model : **TOYOTA PRIUS**
 Chassis No. : **JTDKB3FU203556663**

Submit By : **Carmen Lim**
 Year Manufacture : **2017**
 Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
70	Throttle body hose	1			✓
71	LH front door R	1			X
72	LH front door hinge top R	1			X
73	LH front door hinge bottom R	1			X
74	LH front door weatherstrip Lm	1			X
75	LHF door glass outer moulding Lm	1			X
76	LH rear door Bt	1			✓
77	LH rear door hinge top R	1			X
78	LH rear door hinge bottom R	1			X
79	LH rear door weatherstrip	1			?
80	LHR door glass outer moulding Lm	1			X
81	Rear windscreen moulding Mm	1	\$97.70		✓
82	Rear windscreen sealant Mm	1	\$50.00	S.N	For Mm
83	Rear windscreen top garnish CM	1	\$655.40		✓
84	Rear windscreen top quarter garnish LH Mm	1			✓
85	Rear windscreen top quarter garnish RH Mm	1			✓
86	Rear number plate Mm	1	\$45.00	S.N	✓
87	Reverse sensor Tm	1	\$200.00	S.N	✓
88	Rear bumper Bt	1	\$497.50		✓
89	Rear bumper clip Mm	10	\$40.00		✓
90	Rear bumper side retainer LH CM	1	\$112.70		✓
91	Rear bumper side retainer RH Lm	1	\$112.70		X
92	Rear bumper reinforcement Bt	1	\$398.90		✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

2209.90

Spare Parts

Vehicle No. :
 Make & Model :
 Chassis No. :

SLN 4169 E

TOYOTA PRIUS

JTDKB3FU203556663

Submit By :
 Year Manufacture :
 Engine No. :
Cost / List

Carmen Lim
 2017

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
93	Rear bumper lower garnish centre <i>CRM</i>	1	\$582.60		✓
94	Rear bumper lower garnish LH <i>hit</i>	1	\$149.70		✓
95	Rear bumper lower garnish RH <i>Sm</i>	1	\$149.70		X
96	Rear bumper tow cover <i>Sm</i>	1	\$31.70		X
97	Rear bumper under cover <i>CRM</i>	1	\$355.20		✓
98	Rear bumper under cover LH <i>hit</i>	1			✓
99	Rear bumper under cover RH <i>Sm</i>	1			X
100	Rear bumper under cover clip <i>me</i>	4	\$14.00		✓
101	Tail door <i>Bj</i>	1	\$1,122.50		✓
102	Tail door lock <i>Tm</i>	1	\$487.70		✓
103	Tail door emblem <i>me</i>	1	\$81.70		✓
104	Wording "PRIUS" <i>me</i>	1	\$51.90		✓
105	Wording "HYBRID" <i>me</i>	1	\$55.47		✓
106	Tail door hinge LH <i>Pce</i>	1			?
107	Tail door hinge RH	1			?
108	Taildoor absorber LH <i>Pce</i>	1			✓
109	Taildoor absorber RH	1			?
110	Tail door plate garnish <i>CRM</i>	1	\$782.50		✓
111	Tail door inner trim <i>Bce</i>	1	\$278.90		✓
112	Tail door inner trim clip <i>me</i>	10	\$28.00		✓
113	Taildoor spoiler <i>hit</i>	1	\$1,567.83		✓
114	Tail end panel <i>Bj</i>	1	\$596.60		✓
115	Tail end panel garnish <i>me</i>	1	\$151.60		✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

6467.60

Spare Parts

Vehicle No. : **SLN 4169 E**
 Make & Model : **TOYOTA PRIUS**
 Chassis No. : **JTDKB3FU203556663**

Submit By : **Carmen Lim**
 Year Manufacture : **2017**
 Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
116	Tail end panel garnish clip <i>Ne</i>	10	\$35.00		✓
117	Boot weatherstrip <i>Ad / kg</i>	1	\$353.10		✓
118	Spare tyre well panel	1	\$793.15		?
119	Spare tyre board	1	\$566.79		?
120	Spare tyre compartment sponge LH	1			?
121	Spare tyre compartment sponge RH	1			?
122	Spare tyre compartment centre	1			?
123	Tail lamp LH - UPPER <i>Br</i>	1	\$498.75		✓
124	Tail lamp RH - UPPER	1	\$498.75		?
125	Tail lamp LH - LOWER <i>Br</i>	1	\$511.60		✓
126	Tail lamp RH - LOWER	1	\$511.60		?
127	Taildoor glass <i>Shatter</i>	1	\$598.70		✓
128	Taildoor glass sealant <i>Ne</i>	1	\$50.00	S.N	<i>Gain</i>
129	Tail door spoiler	1	\$1,567.83		?
130	Third brake light <i>Br</i>	1	\$359.64		X
131	LH rear fender <i>Br</i>	1			✓
132	LH rear fender undershield <i>Cr</i>	1			✓
133	LH rear fender undershield clip <i>Ne</i>	10			✓
134	LH rear fender air duct <i>Ad</i>	1			✓
135	LH rear inner trim upper <i>Re form</i>	1			✓
136	LH rear inner trim lower <i>n</i>	1			✓
137	LH rear lower arm <i>Br</i>	1			✓
138	LH rear knuckle arm <i>Br</i>	1			✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

6344.91

Spare Parts

Vehicle No. : **SLN 4169 E**

Make & Model : **TOYOTA PRIUS**

Chassis No. : **JTDKB3FU203556663**

Submit By : **Carmen Lim**

Year Manufacture : **2017**

Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
139	LH rear knuckle bearing <i>pu</i>	1			✓
140	LH rear wheel hub <i>Bz</i>	1			✓
141	LH rear wheel hub lock nut	1			?
142	LH rear shock absorber <i>Bz</i>	1			✓
143	LH rear shock absorber top mouting <i>Bz</i>	1			✓
144	LH rear shock absorber stopper	1			?
145	LH rear rim <i>pu</i>	1			
146	LH rear tyre <i>pu</i>	1			<i>6084</i>
147	RH rear fender <i>R</i>	1			X
148	RH rear fender undershield <i>pu</i>	1			X
149	RH rear fender undershield clip <i>nn</i>	10			X
150	RH rear inner trim upper	1			?
151	RH rear inner trim lower	1			?
152	RH rear lower arm <i>pu</i>	1			X
153	RH rear knuckle arm <i>pu</i>	1			X
154	RH rear knuckle bearing <i>pu</i>	1			X
155	RH rear wheel hub <i>pu</i>	1			X
156	RH rear wheel hub lock nut <i>pu</i>	1			X
157	RH rear shock absorber <i>pu</i>	1			X
158	RH rear shock absorber top mouting <i>pu</i>	1			X
159	RH rear shock absorber stopper <i>pu</i>	1			X
160	Rear Axle	1			?
161	Exhaust pipe <i>R</i>	1			X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : **SLN 4169 E**
 Make & Model : **TOYOTA PRIUS**
 Chassis No. : **JTDKB3FU203556663**

Submit By : **Carmen Lim**
 Year Manufacture : **2017**
 Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
162	Exhaust pipe mouting <i>Sm</i>	1			X
163	Exhaust insulator <i>R</i>	1			X
164	RH rear fender quarter garnish	1			?
165	RH rear fender quarter garnish clip	6			?
166	LH rear fender quarter garnish	1			?
167	LH rear fender quarter garnish clip	6			?
168	Roof lining <i>De form</i>	1			✓
169	Roof lining clip <i>Re</i>	10			✓
170	Bootlid retraction cover	1			?
171	Hybrid battery	1			?
172	Fuel tank cover <i>R</i>	1			X
173	Fuel tank cover rivet	1			?
174	Spare tyre lock nut	1			?
175	Rear chassic LH <i>R</i>	1			X
176	LH rear hub cab <i>2017</i>	1			✓
177					
178					
179					
180					
181					
182					
183					
184					

LJK Auto Care will hence notify the Repairer of the following:

- To reserve the car for spray painting
- To display damaged car(s) during repairs
- Parts prices are subject to confirmation
- Third party claims to be a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary work(s) must be rectified and is subject to final approval from Insurance Company

Acknowledged by Repairer

Date:

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5093 Ang Mo Kio, Ind Park 2 #01-251/250, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SLN 4169 E** Submit By : **Carmen Lim**
Make & Model : **TOYOTA PRIUS** Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (FRONT BUMPER,BONNET,SUPPORT PANEL, LHF FENDER,RHF FENDER,LHF DOOR,LHR DOOR,LHR FENDER,REAR BUMPER,TAILOOR,END PANEL,SPARE TYRE COMPARTMENT,RHR FENDER,RHR DOOR, ROOF TOP,REAR CHASSIC LH)	\$3,800.00	2800
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (FRONT BUMPER,BONNET,SUPPORT PANEL, LHF FENDER,RHF FENDER,LHF DOOR,LHR DOOR,LHR FENDER,REAR BUMPER,TAILOOR,END PANEL,SPARE TYRE COMPARTMENT,RHR FENDER,RHR DOOR, ROOF TOP,REAR CHASSIC LH)	\$3,400.00	2600
3	TO Check wiring & focus headlamp	\$50.00	40
4	To remove & refit radiator, condenser to assist work load, to top up A/C gas.	\$150.00	100
5	To remove & refit undercarriage to assist work load.	\$500.00	240
6	To do wheel alignment.	\$120.00	80
7	To remove & refit Door trim, door glass, window regulator, door lock to assist work load.	\$300.00	60

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

8320

Labour

Vehicle No. : **SLN 4169 E** Submit By : **Carmen Lim**
 Make & Model : **TOYOTA PRIUS** Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
8	To remove & refit rear windscreen.	\$120.00	✓
9	To tuff coat.	\$500.00	1800
10	To remove & refit inner seat & upholstery to assist work load.	\$250.00	1000
11	To remove & refit roof lining, inner trim to assist work load.	\$600.00	1200
12	To remove & refit exhaust system to assist work load.	\$150.00	600
13	To remove & refit petrol tank to assist work load.	\$150.00	600
14	To transfer boot mechanism to new boot	\$120.00	600
15	To conduct water leakage tests to ensure proper air and sealing	\$120.00	300
16	To re-align rear chassis	\$300.00	2500
17	Towing (Bill)	\$120.00	?
18	To remove & refit Taildoor glass to assist work load	\$120.00	600

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

550

36,180.12



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteempert.com.sg

Repair Estimates

SLN 4169 E

Parts	(a) Cost / List Price Items	\$ 79,628.31
	Plus/Less 25%	\$ 19,907.08
	Total of Cost / List	\$ 59,721.23
	(b) Nett Price Items	
	Less	
	Total of Nett Item	
	(c) Special Nett Items	\$ 740.00
Total Parts Cost		\$ 60,461.23
Labour		\$ 10,870.00
Total		\$ 71,331.23

The above total will be subjected to 7% G.S.T.

Finalised.

49592.57

12398.14

37194.43

625

37819.43

7050

~~44869.43~~

842615.63

Name of Surveyor : _____
Company : _____
Survey conducted on : _____ at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : _____ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____

Ann: Steven

Sent circle parts to #01-251

9 pages



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 669536.

Tel: +65-6484 1221 Fax: +65-6484 7820 Website: www.esteemperf.com.sg

arts

o. : SLN 4169 E
 odel : TOYOTA PRIUS
 lo : JTDKB3FU203556663

Submit By : Carmen Lim
 Year Manufacture : 2017
 Engine No. :
 Cost / List

Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1 Front number plate <i>Phil</i>	1	\$45.00	S-N	✓
2 Front number plate garnish X <i>Phil</i>	1	\$45.00		✓
3 Bonnet X <i>Phil</i>	1	\$812.40		✓
4 Bonnet lock <i>Tr</i>	1	\$130.00		✓
5 Bonnet hinge LH <i>Phil</i>	1	\$57.80		✓
6 Bonnet hinge RH <i>Phil</i>	1	\$57.80		✓
7 Bonnet heat insulator <i>398-10 return</i>	1	440.12 ✓		✓
8 Bonnet heat insulator clip <i>an</i>	10	38 ✓		✓
9 Front support panel centre <i>Bu</i>	1	\$338.50 ✓		✓
10 Front support panel LH <i>Bu</i>	1	213.50 ✓		✓
11 Front support panel RH <i>Bu</i>	1	213.50 ✓		✓
12 Headlamp panel LH <i>Bu</i> clip	1	89.20 ✓		✓
13 Headlamp panel RH <i>Phil</i>	1	89.20		✓
14 Support panel lower <i>Bu</i>	1	387.50 ✓		✓
15 Front support panel top garnish <i>Sn</i>	1	288.40 ✓	X	X
16 Front support panel top garnish clip <i>an</i>	10	38 ✓	X	X
17 Air duct <i>an</i>	1	198.40 ✓		✓
18 Air duct - inlet <i>an</i>	1	109.78		✓
19 Brace panel <i>Bu</i>	1	108.20 ✓		✓
20 Condenser <i>1336-60</i> <i>At/Pu</i>	1	1544.70 ✓		✓
21 Radiator <i>Pu</i>	1	1841.80 ✓		✓
22 Radiator fan motor RH <i>Sn</i>	1	488.70		X
23 Radiator fan motor LH <i>Sn</i>	1	491.79		X

of the quoted parts are recommended to be repaired, then an additional labour charge
 yed accordingly under supplementary.

3574.26

Mo Kio Industrial Park 2 #01-259 Singapore 369536 Tel: 64841221 Fax: 64847829
 No. 200005485N / GST No. 20-0005485-N

Not Authorize

C/Lp 87, 1.B.1

6912-27

48 (S-N)

2019-26
06 (C4)

Spare Parts

Vehicle No. : **SLN 4169 E**
 Make & Model : **TOYOTA PRIUS**
 Chassis No. : **JTDKB3FU203556663**

Submit By : **Carmen Lim**
 Year Manufacture : **2017**
 Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Radiator fan blade LH <i>SL</i>	1	197.80		<i>✓</i>
25	Radiator fan blade RH <i>SL</i>	1	219.80		<i>✓</i>
26	Radiator fan cowling <i>SL</i>	1	287.67		<i>✓</i>
27	Radiator top hose <i>SL</i>	1	44.80		<i>✓</i> X
28	Radiator bottom hose <i>SL</i>	1	46.98		<i>✓</i>
29	Radiator spare tank <i>SL</i>	1	186.70		<i>✓</i>
30	Intake manifold <i>SL</i>	1	892.74		<i>✓</i>
31	Headlamp LH <i>CM</i>	1	\$2,531.60		<i>✓</i>
32	Headlamp RH <i>CM</i>	1	\$2,531.60	<i>✓</i>	<i>✓</i>
33	Front bumper <i>B</i>	1	480.80		<i>✓</i>
34	Front bumper clip <i>SL</i>	10	40		<i>✓</i>
35	Front bumper reinforcement - upper X <i>B</i>	1	\$711.50		<i>✓</i>
36	Front bumper reinforcement - lower <i>R</i>	1	\$245.30		<i>✓</i>
37	Front bumper side retainer RH <i>P/S</i>	1	\$107.20		<i>✓</i>
38	Front bumper side retainer LH <i>CM</i>	1	\$107.20		<i>✓</i>
39	Front bumper upper grille <i>CM</i>	1	\$321.90		<i>✓</i>
40	Front bumper lower grille <i>Dis</i>	1	\$148.60		<i>✓</i>
41	Front bumper emblem <i>SL</i>	1	87.10		<i>✓</i>
42	Front bumper tow cover RH <i>SL</i>	1	\$25.70		<i>✓</i>
43	Front bumper tow cover LH <i>SL</i>	1	\$25.70		<i>✓</i>
44	Front bumper sponge - upper <i>CM</i>	1	\$89.81		<i>✓</i>
45	Front bumper sponge - lower <i>CM</i>	1	\$135.70		<i>✓</i>
46	Fog lamp LH <i>SL</i>	1	\$910.70		<i>✓</i>

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : **SLN 4169 E**
 Make & Model : **TOYOTA PRIUS**
 Chassis No : **JTDKB3FU203556663**

Submit By : **Carmen Lim**
 Year Manufacture : **2017**
 Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
47	Fog lamp RH <i>Sm</i>	1	\$910.70		X
48	Engine under cover <i>Sm</i>	1	198.20		X
49	Engine under cover clip <i>Sm</i>	10	35		X
50	Air cleaner box <i>CM</i>	1	967.80 ✓		?
51	Washer tank <i>Sm</i>	1	195.60		? X
52	Washer tank motor <i>Sm</i>	1	196.74		? X
53	RH front fender <i>R</i>	1	868.70		X
54	RH front fender undershield <i>Sm</i>	1	185.64		X
55	RH front fender undershield clip <i>Sm</i>	10	25		X
56	RHF fender wording "HYBRID" <i>Sm</i>	1	44.17		X
57	LH front fender <i>Sm</i>	1	868.70		✓
58	LH front fender undershield <i>Sm</i>	1	195.60		? X
59	LH front fender undershield clip <i>Sm</i>	10	25		✓
60	LHF fender wording "HYBRID" <i>Sm</i>	1	44.17		✓
61	LH front fender quarter garnish <i>Sm</i>	1	122.70		✓
62	Aircon compressor <i>Sm</i>	1	2859.70		? X
63	Horn <i>Sm</i>	1	150.40		? X
64	Air flow sensor <i>Sm</i>	1	256.09		? X
65	Water pump <i>Sm</i>	1	601.73		? X
66	Bonnet cable <i>Sm</i>	1	74.60		? X
67	Engine mouting RH <i>Sm</i>	1	298.70		? X
68	Radiator top garnish <i>CM</i>	1	54.24 ✓		?
69	Air resonator <i>Sm</i>	1	195.74		? X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. :
 Make & Model :
 Chassis No. :

SLN 4169 E

TOYOTA PRIUS
 JTDKB3FU203556863

Submit By :
 Year Manufacture :
 Engine No. :

Carmen Lim
 2017

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
70	Throttle body hose <i>Sn</i>	1	91.40		7 X
71	LH front door <i>R</i>	1	1121.75		X
72	LH front door hinge top <i>R</i>	1	78.30		X
73	LH front door hinge bottom <i>R</i>	1	78.30		X
74	LH front door weatherstrip <i>Sn</i>	1	211.69		X
75	LHF door glass outer moulding <i>Sn</i>	1	121.75		X
76	LH rear door <i>R B</i>	1	1211.40		X
77	LH rear door hinge top <i>R</i>	1	78.34		X
78	LH rear door hinge bottom <i>R</i>	1	78.34		X
79	LH rear door weatherstrip <i>Sn</i>	1	198.70		7 X
80	LHR door glass outer moulding <i>Sn</i>	1	107.80		X
81	Rear windscreen moulding <i>Sn</i>	1	\$97.70		✓
82	Rear windscreen sealant <i>Sn</i>	1	\$50.00	S.N	✓
83	Rear windscreen top garnish <i>CM</i>	1	\$655.40		✓
84	Rear windscreen top quarter garnish LH <i>CM</i>	1	189.60		✓
85	Rear windscreen top quarter garnish RH <i>CM</i>	1	189.60		✓
86	Rear number plate <i>CM</i>	1	\$45.00	S.N	✓
87	Reverse sensor <i>CM</i>	1	\$200.00	S.N	✓
88	Rear bumper <i>R</i>	1	\$497.50		✓
89	Rear bumper clip <i>R</i>	10	\$40.00		✓
90	Rear bumper side retainer LH <i>CM</i>	1	\$112.70		✓
91	Rear bumper side retainer RH <i>Sn</i>	1	\$112.70		X
92	Rear bumper reinforcement <i>R</i>	1	\$398.90		✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

5671.87

6

2181.40

3392.80
 285 (S.N).

Spare Parts

Vehicle No. :
 Make & Model :
 Chassis No. :

SLN 4169 E

TOYOTA PRIUS
 JTDKB3FU203556663

Submit By :
 Year Manufacture :
 Engine No. :
Cost / List

Carmen Lim
 2017

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
93	Rear bumper lower garnish centre	1	\$582.60		✓
94	Rear bumper lower garnish LH	1	\$149.70		✓
95	Rear bumper lower garnish RH	1	\$149.70		X
96	Rear bumper tow cover	1	\$31.70		X
97	Rear bumper under cover	1	\$355.20		✓
98	Rear bumper under cover LH	1	187.66		✓
99	Rear bumper under cover RH	1	187.66		X
100	Rear bumper under cover clip	4	\$14.00		✓
101	Tail door	1	\$1,122.50		✓
102	Tail door lock	1	\$487.70		✓
103	Tail door emblem	1	\$61.70		✓
104	Wording "PRIUS"	1	\$51.90		✓
105	Wording "HYBRID"	1	\$55.47		✓
106	Tail door hinge LH	1	87.60 ✓		✓
107	Tail door hinge RH	1	87.60 ✓		✓
108	Taildoor absorber LH	1	296.40		✓
109	Taildoor absorber RH	1	296.40		X
110	Tail door plate garnish	1	\$782.50		✓
111	Tail door inner trim	1	\$278.90		✓
112	Tail door inner trim clip	10	\$28.00		✓
113	Taildoor spoiler	1	\$1,587.83		✓
114	Tail end panel	1	\$596.80		✓
115	Tail end panel garnish	1	\$151.80		✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

7610.92

6945.46

6945.46

Att: Steven
Sent 'v' item to Ann

349

Spare Parts

Vehicle No. : **SLN 4169 E**
 Make & Model : **TOYOTA PRIUS**
 Chassis No. : **JTDKB3FU203556603**

Submit By : **Carmen Lim**
 Year Manufacture : **2017**
 Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
116	Tail end panel garnish clip	10	\$35.00		✓
117	Boot weatherstrip	1	\$353.10		✓
118	Spare tyre well panel	1	\$793.15	✓	✓
119	Spare tyre board	1	\$586.79	✓	✓
120	Spare tyre compartment sponge LH	1	297.67	✓	✓
121	Spare tyre compartment sponge RH	1	297.67		✓
122	Spare tyre compartment centre	1	251.70		✓
123	Tail lamp LH - UPPER	1	\$498.75		✓
124	Tail lamp RH - UPPER	1	\$498.75		✓
125	Tail lamp LH - LOWER	1	\$511.80		✓
126	Tail lamp RH - LOWER	1	\$511.80		✓
127	Taildoor glass X	1	\$598.70		✓
128	Taildoor glass sealant	1	\$50.00	S.N	✓
129	Tail door spoiler	1	\$1,567.83	✓	✓
130	Third brake light	1	\$359.84		X
131	LH rear fender	1	883.60		✓
132	LH rear fender undershield	1	92.30		✓
133	LH rear fender undershield clip	10	30		✓
134	LH rear fender air duct	1	115.60		✓
135	LH rear inner trim upper	1	386.75		✓
136	LH rear inner trim lower	1	387.63		✓
137	LH rear lower arm	1	398.65		✓
138	LH rear knuckle arm	1	898.60		✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

10,332.08

8412.72

8412.72
40 (S.N).

Spare Parts

Vehicle No. : **SLN 4169 E**
 Make & Model : **TOYOTA PRIUS**
 Chassis No. : **JTDKB3FU203556663**

Submit By : **Carmen Lim**
 Year Manufacture : **2017**
 Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
139	LH rear knuckle bearing <i>mc</i>	1	421-90		✓
140	LH rear wheel hub <i>B₁</i>	1			✓
141	LH rear wheel hub lock nut <i>Ln</i>	1	17-30		? +
142	LH rear shock absorber <i>B₁</i>	1	359-40		✓
143	LH rear shock absorber top mounting <i>B₁</i>	1	165-70		✓
144	LH rear shock absorber stopper <i>A₁</i>	1	85-70 ✓		?
145	LH rear rim <i>RL</i>	1	1555-10 ✓		✓
146	LH rear tyre <i>Pu</i>	1	350	S.N	210 6085
147	RH rear fender <i>R</i>	1	883-60		X
148	RH rear fender undershield <i>Ln</i>	1	92-30		X
149	RH rear fender undershield clip <i>nn</i>	10	30		X
150	RH rear inner trim upper <i>nd</i>	1	386-75 ✓		?
151	RH rear inner trim lower <i>Ln</i>	1	387-63		X
152	RH rear lower arm <i>Ln</i>	1	398-65		X
153	RH rear knuckle arm <i>Ln</i>	1	898-60		X
154	RH rear knuckle bearing <i>Ln</i>	1	421-90		X
155	RH rear wheel hub <i>Ln</i>	1			X
156	RH rear wheel hub lock nut <i>Ln</i>	1	17-30		X
157	RH rear shock absorber <i>Ln</i>	1	359-40		X
158	RH rear shock absorber top mounting <i>Ln</i>	1	165-70		X
159	RH rear shock absorber stopper <i>Ln</i>	1	85-70		X
160	Rear Axle <i>B₁</i>	1	2257-40 ✓		?
161	Exhaust pipe <i>R</i>	1	854-10		X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

984613

5231.95

5231.95
 210 (S.N).

Spare Parts

Vehicle No. :
 Make & Model :
 Chassis No :

SLN 4169 E

TOYOTA PRIUS

JTDKB3FU203556663

Submit By :

Carmen Lim

Year Manufacture :

2017

Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
162	Exhaust pipe mouting <i>Sm</i>	1	38.40		X
163	Exhaust insulator <i>R</i>	1	267.40		X
164	RH rear fender quarter garnish <i>Sm</i>	1	189.60		X
165	RH rear fender quarter garnish clip <i>nn</i>	6	24		X
166	LH rear fender quarter garnish <i>Sm</i>	1	189.60		X
167	LH rear fender quarter garnish clip <i>nn</i>	6	24		X
168	Roof lining <i>Deform</i>	1	2237.40		✓
169	Roof lining clip <i>nn</i>	10	80		✓
170	Bootlid retraction cover <i>Sm</i>	1	994.70		X
171	Hybrid battery <i>Sm</i>	1	13682.74		X
172	Fuel tank cover <i>R</i>	1	198.64		X
173	Fuel tank cover rivet <i>nn</i>	1	10		X
174	Spare tyre lock nut <i>Sm</i>	1	29.80		X
175	Rear chassic LH <i>R</i>	1	388.90		X
176	LH rear hub cab <i>175.80</i> <i>nn</i>	1	198.65		✓
177					
178					
179					
180					
181					
182					
183					
184					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

18,520.83

2493.20

2513.05



ESTEEM PERFORMANCE PTE LTD

Blk 6003 Ang Mo Kio, Ind Park 2 #01-251/260, 580536.
Tel: +65-6464 1221 Fax: +65-6464 7029 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SLN 4169 E** Submit By : **Carmen Lim**
Make & Model : **TOYOTA PRIUS** Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (FRONT BUMPER,BONNET,SUPPORT PANEL, LHF FENDER,RHF FENDER,LHF DOOR,LHR DOOR,LHR FENDER,REAR BUMPER,TAILOOR,END PANEL,SPARE TYRE COMPARTMENT,RHR FENDER,RHR DOOR, ROOF TOP,REAR CHASSIC LH)	\$3,800.00	2800
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (FRONT BUMPER,BONNET,SUPPORT PANEL, LHF FENDER,RHF FENDER,LHF DOOR,LHR DOOR,LHR FENDER,REAR BUMPER,TAILOOR,END PANEL,SPARE TYRE COMPARTMENT,RHR FENDER,RHR DOOR, ROOF TOP,REAR CHASSIC LH)	\$3,400.00	2600
3	TO Check wiring & focus headlamp	\$50.00	40
4	To remove & refit radiator, condenser to assist work load, to top up A/C gas.	\$150.00	100
5	To remove & refit undercarriage to assist work load.	\$500.00	240
6	To do wheel alignment.	\$120.00	80
7	To remove & refit Door trim, door glass, window regulator, door lock to assist work load.	\$300.00	60

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

7050

LabourVehicle No. : **SLN 4169 E**Submit By : **Carmen Lim**Make & Model : **TOYOTA PRIUS**Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
8	To remove & refit rear windscreen.	\$120.00	✓
9	To tuff coat.	\$500.00	1800
10	To remove & refit inner seat & upholstery to assist work load.	\$250.00	1000
11	To remove & refit roof lining, inner trim to assist work load.	\$800.00	1200
12	To remove & refit exhaust system to assist work load.	\$150.00	600
13	To remove & refit petrol tank to assist work load.	\$150.00	600
14	To transfer boot mechanism to new boot	\$120.00	600
15	To conduct water leakage tests to ensure proper air and sealing	\$120.00	300
16	To re-align rear chassis	\$300.00	2500
17	Towing (B.7.1)	\$120.00	? 900
18	To remove & refit Taildoor glass to assist work load	\$120.00	600

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

ESTEEM PERFORMANCE PTE LTD

BLK 5033 ANG MO KIO INDUSTRIAL PARK 2

#01-259 SINGAPORE 569536

Tel:64841221 Fax:64847829

Spare Parts

Vehicle No. :

SLN 4169 E

Submit By :

CARMEN LIM

Make & Model :

TOYOTA PRIUS

Year Manufacture :

2017

Chassis No. :

JTDKB3FU203556663

Engine No. :

Cost / List**Supplementary**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Taillamp panel LH	1	\$189.60		✓
2	LH side skirt	1	\$721.50		✓
3	Fuel tank cover motor	1	\$369.67		✓
4	Taillamp clip	3	\$13.50		✓
5	Taildoor stopper LH	1	\$14.21		✓
6	Taillamp cover LH	1	\$61.78		✓
7	Warning triangle box	1	\$45.00	S.N	✓
8	Support panel air guide LH upper	1	\$89.70		✓
9	Support panel air guide LH lower	1	\$89.70		✓
10	Headlamp ballast LH	1	\$551.97		✓
11	Wiper garnish	1	\$561.70		✓
12	Wiper garnish cover LH	1	\$75.80		✓
13	Rear brake caliber LH	1	\$751.60		✓
14	Leveling sensor	1	\$588.60		✓
15	Rear disc roto LH	1	\$321.70		✗
16	LH rear antiroll bar link	1	\$161.70		✓
17	Coil spring stopper top	1	\$59.80		✓
18	Coil spring stopper bottom	1	\$61.37		✓
19	LH rear trailing arm	1	\$303.70		✓
20	Floor panel LH	1	\$189.60		✓
21	Driver seat back rest rail	1	\$669.40		✓
22	Passenger seat back rest rail	1	\$669.40		✓
23	Taillamp socket assy LH	1	\$75.90		✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

6597.90

Spare Parts

Vehicle No. :
Make & Model :
Chassis No. :

SLN 4169 E**TOYOTA PRIUS****JTDKB3FU203556663**

Submit By :
Year Manufacture :
Engine No. :

CARMEN LIM**2017****Cost / List****Supplementary**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear brake pad <i>1-1/2</i>	1	\$195.40		<i>X</i>
2					
3					
4					
5					
6					
7					
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

6787-30
4x (S.N)



UNI Automotive Services Pte Ltd
 No. 36 Pioneer Road, #02-01, Singapore 625931
 Tel: (65) 6315 1461 Fax: (65) 6315 1462
 Email: UniAutomotive@gmail.com
 Reg No: 201528283K

Month: **MARCH**

Bill To: ESTEEM PERFORMANCE PTE LTD

	Date	Vehicle No	Vehicle Model	From	To	Amount	KD	REMARKS
1	1-Mar	SLF830P	PRIUS	8 BULIM AVE	5035 ANG MO KIO PK 2A	\$45		
2	1-Mar	1626	SHUTTLE	385 SIN MING DRIVE	AMK IND PR 2 #01-359	\$45		
3	2-Mar	SKL7366E	BMW525	SHELL @ OPP TAN TOCK SENG HOSP	ESTEEM @ SIN MING	\$45		
4	2-Mar	YN7162A	ISUZU	145 WEST COAST RD	385 SIN MING DR	\$70		ERP \$6
5	2-Mar	1626	SHUTTLE	AMK IND PR 2 #01-259	385 SIN MING DR	\$45		
6	3-Mar	SLN7304S	M/C180	MARIE PARADE	AMK ESTHEM	\$90	V	
7	5-Mar	SLN4169E	PRIUS	385 SINMING DRIVE	5035 ANG MO KIO PK 2A	\$90	V	
8	5-Mar	SLF5830P	PRIUS	5035 ANG MO KIO PK 2A	8 BULIM AVE	\$45		
9	7-Mar	SKV6653E	BMW X4	329 YONG AN PARK	BMW @ ALEXANDRA	\$90	V	
10	10-Mar	SLK2566X	PRIUS	VICOM @ SIN MING	BLK 5033 AMK IND PR 2	\$45		
11	12-Mar	GW3722B	DYNA	CHOA CHU KANG	385 SIN MING DRIVE	\$50		
12	12-Mar	SGL9999M	TOUAREG	CHANGI SOUTH AVE 1	385 SIN MING DR	\$90	V	
13	13-Mar	025979	CHR	195 PEARL'S HILL TERRACE	ESTEEM @ SIN MING	\$55	V	CP \$1
14	16-Mar	SLJ3135E	PRIUS	385 SIN MING DR	8 BULIM AVE	\$45		
15	16-Mar	SLN5287R	PRIUS	385 SIN MING DR	8 BULIM AVE	\$45		
16	19-Mar	SLK1766S	PRIUS	WOODLAND IND PR E8	CHANGE BATTERY	\$50		
17	19-Mar	SLH5300S	PRIUS	385 SIN MING DR	8 BULIM AVE	\$45		
18	22-Mar	048808	PRIUS	385 SIN MING DR	BLK 5033 AMK IND PR #01-25	\$45		
19	26-Mar	PC4841H	NV350	JURONG ISLAND	CANCELLATION FEE	\$30		
20	26-Mar	PC4841H	NV350	50 AIRPORT BOULEVARD	BLK5033 ANG MO KIO	\$50		
21	27-Mar	GBD5985E	MIT L200	TANAH MERAH COASTAL	3385 SINMING DRIVE	\$50		
22	27-Mar	GX6669Y	CANTER	RAEBURN PARK	KHENG KENG, 47 SUNGEI KADUT LOOP	\$55		
23	27-Mar	GV7943J	CANTER	RAEBURN PARK	KHENG KENG, 47 SUNGEI KADUT LOOP	\$55		CP \$2.20
24	27-Mar	SLH9084P	PRIUS	293 PUNGGOL CENTRAL	CHANGE BATTERY	\$50		
25	28-Mar	SLG958H	PRIUS	THE COTERIE @ HOLLAND	385 SINMING DRIVE	\$45		
26	31-Mar	SKV6653E	BMW X5	329 RIVER VALLEY ROAD	BMW AGENT, 303 ALEXANDRA ROAD	\$90	V	





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18004046/Kvd3e2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 26-12-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 8825T	Veh. Inspected	SLN 4169E	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18001666MFSH	Excess (\$)	0.00	
Assign From	AUNG YIN MIN	Assign Date	02/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS (A)	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FU203556663	Colour	METALLIC PEARL WHITE	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	YOKOHAMA	8 mm	
L/H Front Tyre	195/65 R15	YOKOHAMA	8 mm	
R/H Rear Tyre	195/65 R15	YOKOHAMA	8 mm	
L/H Rear Tyre	195/65 R15	YOKOHAMA	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/02/2018	Inspection Date	02/03/2018	
Survey held at	385 SIN MING DRIVE			
Repairer	ESTEEM PERFORMANCE PTE LTD			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		24 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 9

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 4169E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT NUMBER PLATE GARNISH	DENTED	45.00	45.00
1	BONNET	BUCKLED	812.40	812.40
1	BONNET LOCK	JAMMED	130.00	130.00
1	BONNET HINGE LH	DISTORTED	57.80	57.80
1	BONNET HINGE RH	DISTORTED	57.80	57.80
1	BONNET HEAT INSULATOR	DEFORMED	440.12	398.10
10	BONNET HEAT INSULATOR CLIP	NECESSARY	35.00	35.00
1	FRONT SUPPORT PANEL CENTRE	BUCKLED	338.50	338.50
1	FRONT SUPPORT PANEL LH	BENT	213.50	213.50
1	FRONT SUPPORT PANEL RH	BENT	213.50	213.50
1	HEADLAMP PANEL LH	BENT	89.20	89.20
1	HEADLAMP PANEL RH	TO REPAIR SEE LABOUR	89.20	-
1	SUPPORT PANEL LOWER	BENT	387.50	387.50
1	FRONT SUPPORT PANEL TOP GARNISH	SERVICEABLE	285.40	-
10	FRONT SUPPORT PANEL TOP GARNISH CLIP	NOT NECESSARY	35.00	-
1	AIR DUCT	DENTED	195.40	195.40
1	AIR DUCT - INLET	DENTED	109.75	109.75
1	BRACE PANEL	BENT	105.20	105.20
1	CONDENSER	BENT / PUNCTURE	1,544.70	1,336.60
1	RADIATOR	PUNCTURE	1,841.80	1,841.80
1	RADIATOR FAN MOTOR RH	SERVICEABLE	455.70	-
1	RADIATOR FAN MOTOR LH	SERVICEABLE	491.79	-
1	RADIATOR FAN BLADE LH	SERVICEABLE	197.80	-
1	RADIATOR FAN BLADE RH	SERVICEABLE	219.80	-
1	RADIATOR FAN COWLING	SERVICEABLE	287.67	-
1	RADIATOR TOP HOSE	SERVICEABLE	49.80	-
1	RADIATOR BOTTOM HOSE	SERVICEABLE	46.95	-
1	RADIATOR SPARE TANK	SERVICEABLE	186.70	-
1	INTAKE MANIFOLD	SERVICEABLE	892.74	-
1	HEADLAMP LH	CRACKED	2,531.60	2,531.60

Report Ref No. CS/FCI18004046/Kvd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	HEADLAMP RH	MTG CRACKED	2,531.60	2,531.60
1	FRONT BUMPER	BENT	450.80	450.80
10	FRONT BUMPER CLIP	NECESSARY	40.00	40.00
1	FRONT BUMPER REINFORCEMENT - UPPER	TO REPAIR SEE LABOUR	711.50	-
1	FRONT BUMPER REINFORCEMENT - LOWER	TO REPAIR SEE LABOUR	245.30	-
1	FRONT BUMPER SIDE RETAINER RH	DISTORTED	107.20	107.20
1	FRONT BUMPER SIDE RETAINER LH	CRACKED	107.20	107.20
1	FRONT BUMPER UPPER GRILLE	CRACKED	321.90	321.90
1	FRONT BUMPER LOWER GRILLE	DISTORTED	148.60	148.60
1	FRONT BUMPER EMBLEM	DENTED	87.10	87.10
1	FRONT BUMPER TOW COVER RH	DENTED	25.70	25.70
1	FRONT BUMPER TOW COVER LH	MISSING	25.70	25.70
1	FRONT BUMPER SPONGE - UPPER	CRACKED	89.81	89.81
1	FRONT BUMPER SPONGE - LOWER	CRACKED	135.70	135.70
1	FOG LAMP LH	SERVICEABLE	910.70	-
1	FOG LAMP RH	SERVICEABLE	910.70	-
1	ENGINE UNDER COVER	SERVICEABLE	198.30	-
10	ENGINE UNDER COVER CLIP	NOT NECESSARY	35.00	-
1	AIR CLEANER BOX	CRACKED	967.80	967.80
1	WASHER TANK	SERVICEABLE	195.60	-
1	WASHER TANK MOTOR	SERVICEABLE	196.74	-
1	RH FRONT FENDER	TO REPAIR SEE LABOUR	868.70	-
1	RH FRONT FENDER UNDERSHIELD	SERVICEABLE	185.64	-
10	RH FRONT FENDER UNDERSHIELD CLIP	NOT NECESSARY	25.00	-
1	RHF FENDER WORDING "HYBRID"	NOT NECESSARY	44.17	-
1	LH FRONT FENDER	BUCKLED	868.70	868.70
1	LH FRONT FENDER UNDERSHIELD	SERVICEABLE	195.60	-
10	LH FRONT FENDER UNDERSHIELD CLIP	NECESSARY	25.00	25.00
1	LHF FENDER WORDING "HYBRID"	NECESSARY	44.17	44.17
1	LH FRONT FENDER QUARTER GARNISH	DISTORTED	122.70	122.70
1	AIRCON COMPRESSOR	SERVICEABLE	2,859.70	-

Report Ref No. CS/FCI18004046/Kvd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 3 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	HORN	SERVICEABLE	150.40	-
1	AIR FLOW SENSOR	SERVICEABLE	256.09	-
1	WATER PUMP	SERVICEABLE	601.73	-
1	BONNET CABLE	SERVICEABLE	74.60	-
1	ENGINE MOUTING RH	SERVICEABLE	298.70	-
1	RADIATOR TOP GARNISH	CRACKED	54.24	54.24
1	AIR RESONATOR	SERVICEABLE	195.74	-
1	THROTTLE BODY HOSE	SERVICEABLE	91.40	-
1	LH FRONT DOOR	TO REPAIR SEE LABOUR	1,121.75	-
1	LH FRONT DOOR HINGE TOP	TO REPAIR SEE LABOUR	78.30	-
1	LH FRONT DOOR HINGE BOTTOM	TO REPAIR SEE LABOUR	78.30	-
1	LH FRONT DOOR WEATHERSTRIP	SERVICEABLE	211.69	-
1	LHF DOOR GLASS OUTER MOULDING	SERVICEABLE	121.75	-
1	LH REAR DOOR	TO REPAIR SEE LABOUR	1,211.40	-
1	LH REAR DOOR HINGE TOP	TO REPAIR SEE LABOUR	78.34	-
1	LH REAR DOOR HINGE BOTTOM	TO REPAIR SEE LABOUR	78.34	-
1	LH REAR DOOR WEATHERSTRIP	SERVICEABLE	198.70	-
1	LHR DOOR GLASS OUTER MOULDING	SERVICEABLE	107.80	-
1	REAR WINDSCREEN MOULDING	NECESSARY	97.70	97.70
1	REAR WINDSCREEN TOP GARNISH	CRACKED	655.40	655.40
1	REAR WINDSCREEN TOP QUARTER GARNISH LH	DISTORTED	189.60	189.60
1	REAR WINDSCREEN TOP QUARTER GARNISH RH	MISSING	189.60	189.60
1	REAR BUMPER	BENT	497.50	497.50
10	REAR BUMPER CLIP	NECESSARY	40.00	40.00
1	REAR BUMPER SIDE RETAINER LH	CRACKED	112.70	112.70
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	112.70	-
1	REAR BUMPER REINFORCEMENT	BENT	398.90	398.90
1	REAR BUMPER LOWER GARNISH CENTRE	CRACKED	582.60	582.60
1	REAR BUMPER LOWER GARNISH LH	MISSING	149.70	149.70

Report Ref No. CS/FCI18004046/Kvd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER LOWER GARNISH RH	SERVICEABLE	149.70	-
1	REAR BUMPER TOW COVER	SERVICEABLE	31.70	-
1	REAR BUMPER UNDER COVER	CRACKED	355.20	355.20
1	REAR BUMPER UNDER COVER LH	MISSING	187.66	187.66
1	REAR BUMPER UNDER COVER RH	SERVICEABLE	187.66	-
4	REAR BUMPER UNDER COVER CLIP	NECESSARY	14.00	14.00
1	TAIL DOOR	BENT	1,122.50	1,122.50
1	TAIL DOOR LOCK	JAMMED	487.70	487.70
1	TAIL DOOR EMBLEM	NECESSARY	61.70	61.70
1	WORDING "PRIUS"	NECESSARY	51.90	51.90
1	WORDING "HYBRID"	NECESSARY	55.47	55.47
1	TAIL DOOR HINGE LH	BENT	87.60	87.60
1	TAIL DOOR HINGE RH	BENT	87.60	87.60
1	TAIL DOOR ABSORBER LH	PUNCTURE	296.40	296.40
1	TAILDOOR ABSORBER RH	SERVICEABLE	296.40	-
1	TAIL DOOR PLATE GARNISH	CRACKED	782.50	782.50
1	TAIL DOOR INNER TRIM	BUCKLED	278.90	278.90
10	TAIL DOOR INNER TRIM CLIP	NECESSARY	28.00	28.00
1	TAILDOOR SPOILER	MISSING	1,567.83	1,567.83
1	TAIL END PANEL	BENT	596.60	596.60
1	TAIL END PANEL GARNISH	DENTED	151.60	151.60
10	TAIL END PANEL GARNISH CLIP	NECESSARY	35.00	35.00
1	BOOT WEATHERSTRIP	DENTED / CUT	353.10	353.10
1	SPARE TYRE WELL PANEL	BENT / BUCKLED	793.15	793.15
1	SPARE TYRE BOARD	DENTED	566.79	566.79
1	SPARE TYRE COMPARTMENT SPONGE LH	CRACKED	297.67	297.67
1	SPARE TYRE COMPARTMENT SPONGE RH	SERVICEABLE	297.67	-
1	SPARE TYRE COMPARTMENT CENTRE	SERVICEABLE	251.70	-
1	TAIL LAMP LH - UPPER	BROKEN	498.75	498.75
1	TAIL LAMP RH - UPPER	SERVICEABLE	498.75	-
1	TAIL LAMP LH - LOWER	BROKEN	511.60	511.60
1	TAIL LAMP RH - LOWER	SERVICEABLE	511.60	-
1	TAILDOOR GLASS	SHATTERED	598.70	598.70

Report Ref No. CS/FC118004046/Kvd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAIL DOOR SPOILER	CRACKED	1,567.83	1,567.83
1	THIRD BRAKE LIGHT	SERVICEABLE	359.64	-
1	LH REAR FENDER	BUCKLED	883.60	883.60
1	LH REAR FENDER UNDERSHIELD	CRACKED	92.30	92.30
10	LH REAR FENDER UNDERSHIELD CLIP	NECESSARY	30.00	30.00
1	LH REAR FENDER AIR DUCT	DENTED	115.60	115.60
1	LH REAR INNER TRIM UPPER	DEFORMED	386.75	386.75
1	LH REAR INNER TRIM LOWER	DEFORMED	387.63	387.63
1	LH REAR LOWER ARM	BENT	398.65	398.65
1	LH REAR KNUCKLE ARM	BENT	895.60	895.60
1	LH REAR KNUCKLE BEARING)	NECESSARY	421.90	421.90
1	LH REAR WHEEL HUB)	BENT	-	-
1	LH REAR WHEEL HUB LOCK NUT	SERVICEABLE	17.30	-
1	LH REAR SHOCK ABSORBER	BENT	359.40	359.40
1	LH REAR SHOCK ABSORBER TOP MOUNTING	BENT	165.70	165.70
1	LH REAR SHOCK ABSORBER STOPPER	BENT	85.70	85.70
1	LH REAR RIM	DENTED	1,555.10	1,555.10
1	RH REAR FENDER	TO REPAIR SEE LABOUR	883.60	-
1	RH REAR FENDER UNDERSHIELD	SERVICEABLE	92.30	-
10	RH REAR FENDER UNDERSHIELD CLIP	NOT NECESSARY	30.00	-
1	RH REAR INNER TRIM UPPER	DENTED	386.75	386.75
1	RH REAR INNER TRIM LOWER	SERVICEABLE	387.63	-
1	RH REAR LOWER ARM	SERVICEABLE	398.65	-
1	RH REAR KNUCKLE ARM	SERVICEABLE	895.60	-
1	RH REAR KNUCKLE BEARING)	NOT NECESSARY	421.90	-
1	RH REAR WHEEL HUB)	SERVICEABLE	-	-
1	RH REAR WHEEL HUB LOCK NUT	SERVICEABLE	17.30	-
1	RH REAR SHOCK ABSORBER	SERVICEABLE	359.40	-
1	RH REAR SHOCK ABSORBER TOP MOUNTING	SERVICEABLE	165.70	-
1	RH REAR SHOCK ABSORBER STOPPER	SERVICEABLE	85.70	-
1	REAR AXLE	BENT	2,257.40	2,257.40
1	EXHAUST PIPE	TO REPAIR SEE LABOUR	854.10	-

Report Ref No. CS/FC118004046/Kvd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:6 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	EXHAUST PIPE MOUTING	SERVICEABLE	38.40	-
1	EXHAUST INSULATOR	TO REPAIR SEE LABOUR	267.40	-
1	RH REAR FENDER QUARTER GARNISH	SERVICEABLE	189.60	-
6	RH REAR FENDER QUARTER GARNISH CLIP	NOT NECESSARY	24.00	-
1	LH REAR FENDER QUARTER GARNISH	SERVICEABLE	189.60	-
6	LH REAR FENDER QUARTER GARNISH CLIP	NOT NECESSARY	24.00	-
1	ROOF LINING	DEFORMED	2,237.40	2,237.40
10	ROOF LINING CLIP	NECESSARY	80.00	80.00
1	BOOTLID RETRATION COVER	SERVICEABLE	994.70	-
1	HYBRID BATTERY	SERVICEABLE	13,652.74	-
1	FUEL TANK COVER	TO REPAIR SEE LABOUR	198.64	-
1	FUEL TANK COVER RIVET	NOT NECESSARY	10.00	-
1	SPARE TYRE LOCK NUT	SERVICEABLE	29.80	-
1	REAR CHASSIS LH	TO REPAIR SEE LABOUR	388.90	-
1	LH REAR HUB CAB	MISSING	195.65	175.80
1	TAILLAMP PANEL LH (ADDITIONAL)	BENT	189.60	189.60
1	LH SIDE SKIRT (ADDITIONAL)	CRACKED	721.50	721.50
1	FUEL TANK COVER MOTOR (ADDITIONAL)	JAMMED	369.67	369.67
3	TAILLAMP CLIP (ADDITIONAL)	NECESSARY	13.50	13.50
1	TAILDOOR STOPPER LH (ADDITIONAL)	MISSING	14.21	14.21
1	TAILLAMP COVER LH (ADDITIONAL)	MISSING	61.78	61.78
1	SUPPORT PANEL AIR GUIDE LH UPPER (ADDITIONAL)	CRACKED	89.70	89.70
1	SUPPORT PANEL AIR GUIDE LH LOWER (ADDITIONAL)	CRACKED	89.70	89.70
1	HEADLAMP BALLAST LH (ADDITIONAL)	DENTED	551.97	551.97
1	WIPER GARNISH (ADDITIONAL)	DENTED	561.70	561.70
1	WIPER GARNISH COVER LH (ADDITIONAL)	MISSING	75.80	75.80
1	REAR BRAKE CALIBER LH (ADDITIONAL)	DENTED	751.60	751.60
1	LEVELING SENSOR (ADDITIONAL)	SHORTED	588.60	588.60
1	REAR DISC ROTO LH (ADDITIONAL)	BROKEN	321.70	321.70
1	LH REAR ANTIROLL BAR LINK (ADDITIONAL)	DISTORTED	161.70	161.70
1	COIL SPRING STOPPER TOP (ADDITIONAL)	MISSING	59.80	59.80

Report Ref No. CS/FCI18004046/Kvd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:7 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	COIL SPRING STOPPER BOTTOM (ADDITIONAL)	MISSING	61.37	61.37
1	LH REAR TRAILING ARM (ADDITIONAL)	BENT	303.70	303.70
1	FLOOR PANEL LH (ADDITIONAL)	BENT	189.60	189.60
1	DRIVER SEAT BACK REST RAIL (ADDITIONAL)	DISTORTED	669.40	669.40
1	PASSENGER SEAT BACK REST RAIL (ADDITIONAL)	DISTORTED	669.40	669.40
1	TAILLAMP SOKET ASSY LH (ADDITIONAL)	BROKEN	75.90	75.90
1	REAR BRAKE PAD (ADDITIONAL)	NOT NECESSARY	195.40	-
	LESS 25% DISCOUNT		-21,616.32	-11,727.30
			64,848.96	35,181.90
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	MISSING	45.00	45.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	REAR NUMBER PLATE (SN)	DENTED	45.00	45.00
1	REVERSE SENSOR (SN)	TORN	200.00	200.00
1	TAILDOOR GLASS SEALANT (SN)	NECESSARY	50.00	40.00
1	LH REAR TYRE (60%) (SN)	PUNCTURE	350.00	210.00
1	WARNING TRIANGLE BOX (SN) (ADDITIONAL)	CRACKED	45.00	45.00
			785.00	625.00
	<u>LABOUR</u>			
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (FRONT BUMPER, BONNET, SUPPORT PANEL, LHF FENDER, RHF FENDER, LHF DOOR, LHR DOOR, LHR FENDER, REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE COMPARTMENT, RHR FENDER, RHR DOOR, ROOF TOP, REAR CHASSIS LH)		3,800.00	2,800.00
	INCLUSIVE OF THE REPAIR OF HEADLAMP PANEL RH, FRONT BUMPER REINFORCEMENT - UPPER, FRONT BUMPER REINFORCEMENT - LOWER, RH FRONT FENDER, LH FRONT DOOR, LH FRONT DOOR HINGE TOP, LH FRONT DOOR HINGE BOTTOM, LH REAR DOOR, LH REAR DOOR HINGE TOP, LH REAR DOOR HINGE BOTTOM, RH REAR FENDER, EXHAUST PIPE, EXHAUST INSULATOR, FUEL TANK COVER AND REAR CHASSIS LH)		-	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:8 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (FRONT BUMPER, BONNET, SUPPORT PANEL, LHF FENDER, RHF FENDER, LHF DOOR, LHR DOOR, LHR FENDER, REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE COMPARTMENT, RHR FENDER, RHR DOOR, ROOF TOP, REAR CHASSIS LH)		3,400.00	2,600.00
	TO CHECK WIRING & FOCUS HEADLAMP		50.00	40.00
	TO REMOVE & REFIT RADIATOR, CONDENSER TO ASSIST WORK LOAD, TO TOP UP A/C GAS.		150.00	100.00
	TO REMOVE & REFIT UNDERCARRIAGE TO ASSIST WORK LOAD.		500.00	240.00
	TO DO WHEEL ALIGNMENT.		120.00	80.00
	TO REMOVE & REFIT DOOR TRIM, DOOR GLASS, WINDOW REGULATOR. DOOR LOCK TO ASSIST WORK LOAD.		300.00	60.00
	TO REMOVE & REFIT REAR WINDSCREEN.		120.00	120.00
	TO TUFF COAT.		500.00	180.00
	TO REMOVE & REFIT INNER SEAT & UPHOLSTERY TO ASSIST WORK LOAD.		250.00	100.00
	TO REMOVE & REFIT ROOF LINING, INNER TRIM TO ASSIST WORK LOAD.		600.00	120.00
	TO REMOVE & REFIT EXHAUST SYSTEM TO ASSIST WORK LOAD.		150.00	60.00
	TO REMOVE & REFIT PETROL TANK TO ASSIST WORK LOAD.		150.00	60.00
	TO TRANSFER BOOT MECHANISM TO NEW BOOT.		120.00	60.00
	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING.		120.00	30.00
	TO RE-ALIGN REAR CHASSIS.		300.00	250.00
	TOWING.		120.00	90.00
	TO REMOVE & REFIT TAILDOOR GLASS TO ASSIST WORK LOAD.		120.00	60.00
			-	-
			-	-
			10,870.00	7,050.00
GRAND TOTAL			76,503.96	42,856.90
RECOMMENDED COST OF REPAIRS				42,856.90

Report Ref No. CS/FCI18004046/Kvd3e2



Report Ref No. CS/FCI18004046/Kvd3e2

A handwritten signature in black ink, appearing to read 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.